


UNIVERSITY OF TORONTO



3 1761 00352814 8














512  
90

# THE METALLURGY OF IRON AND STEEL







Iron Blast Furnace and Hot Blast Stoves.

*(Frontispiece)*

# THE METALLURGY OF IRON AND STEEL

BY  
BRADLEY STOUGHTON, PH. B., B. S.

THIRD EDITION  
FIFTH IMPRESSION

257338  
27.7.31

McGRAW-HILL BOOK COMPANY, INC.  
NEW YORK: 370 SEVENTH AVENUE  
LONDON: 6 & 8 BOUVERIE ST., E. C. 4  
1923

TN  
705  
S88  
1923

COPYRIGHT, 1908, BY  
THE HILL PUBLISHING COMPANY

COPYRIGHT, 1911, 1923, BY  
MCGRAW-HILL BOOK COMPANY

Entered at Stationer's Hall, London, England.

PRINTED IN THE UNITED STATES OF AMERICA



## PREFACE TO THIRD EDITION

Extensive,—almost fundamental,—changes in iron and steel metallurgy, occurring in the past 8 years, make a new edition of this book imperative if it is to keep abreast of commercial and industrial progress. Developments in the science of metallography, teaching us more of the inner nature of steel: teaching us of hitherto “mysterious” defects; and finally, teaching us how to avoid what were once believed to be inevitable defects in large masses of steel, have increased the quality-demands even for large industrial uses. For many centuries super-excellent steel has been made in units of hundreds of pounds; today it is made in units of hundreds of tons.

Two factors have hastened the tonnage production of steel of higher quality. They are: First, increasingly large requirements of the automotive industry for high-grade steel; and second, wide-spread interest during 1916 to 1918 in excellent steel for munitions, coupled with the patriotic and generous spirit of those who knew how to make it in giving unstintedly of their knowledge to those who were learning to serve their country in this way.

But we think the expressed preference of American industry for quality steel antedates this decade, and is more fundamental than the two factors just mentioned: For two decades railroads have voluntarily paid a bonus for rails of higher standard; a prominent American steel plant, famous for its pure product and for the excellence of its research activities, has found an astonishingly rapid increase in the demands made upon its productivity, and in its profits; several manufacturers of malleable cast iron are supporting a joint research under the direction of an able investigator, with results which are already very gratifying commercially and indicate the greatest technical advance of the last hundred years in this particular industry.

And now we may hope that, in the next decade, even the large corporations will inaugurate research departments with powers commensurate with their importance to the industry. The American iron and steel industry has grown too fast for progress

always to keep pace with production, but the far-sighted executives realize that, however much may be made or saved by wise judgment in forecasting the market, by a fair labor policy, and by brilliant purchasing and selling departments, nevertheless technical skill is the basis of the industry, and the "monster" must constantly be fed with fresh brains, as well as with brawn, ore, flux and scrap. A healthy condition demands that improvements be developed from within even more actively than they are forced upon us from abroad. It will be noted that all the outstanding innovations mentioned in the next two pages are products of European development, even when (like the induction electric furnace, for example) they are invented in America. Every successful invention must have two parents: One to invent and the other to develop. For example, Bessemer is entitled to full credit for the conception of the pneumatic process, with honorable mention of Mushet, Goransson and others. It took him and his backers from 1855 to 1861 to make it a technical success. If, in 1847, the suggestion of William Kelly in America had been blessed with a second parent to nurse it through its infant troubles, how different might have been the course of history. Only when Bessemer had proved the commercial value of the process which rightly bears his name, did Americans accept and develop the primitive ideas of Kelly. Thus, the American mind up to now has been brilliant in conception and invention, but lacking in the laborious, far-sighted, patient and courageous work of research and development.

The last seven years have seen great improvements in the technique of blast furnace operation: Hearths have become wider, bosh walls steeper and production greater. Rules of thumb have yielded largely to science and to instruments of precision; recording instruments are more common; greater care and attention is given to regularity and uniformity of control; poorer ores and fuel are available but the smelting results obtained are better. The most prominent improvement is perhaps cleaning the gas, with resulting technical and commercial advantages. The American blast furnace has also become chiefly a producer of liquid metal instead of cast iron pigs.

A change similar to this has overtaken the Bessemer process, which now functions chiefly as an accessory to the basic open hearth, on which (in the great centers of the industry) is purified

a mixture of liquid pig iron from the blast furnace and what was described in the first edition of this book as "the technical equivalent of liquid steel scrap" from the Bessemer converter.

The story of the open hearth process is distinguished by greater skill in operation, better understanding of the danger points, and improved quality of product, as well as by liberal substitution of mechanical appliances for man power. Controversy on one question is ended and it is now universally admitted that acid open hearth steel is better than basic. The reasons for this superiority are also better understood. Metallography is chiefly responsible for this better comprehension, while the demand for munitions and for automotive manufacture, together with the competition from electric steel production, are stimuli to which open hearth metallurgists have responded skillfully.

Electrometallurgy has advanced so much as to be scarcely recognizable commercially for the child of a few years since. The prominent furnaces are still imported European types, but improved by American mechanical and electrical features. Technically the process is still one step behind the crucible process, because it is not so simple, and therefore, although electric steel of the highest quality is often made, it does not have the same degree of certitude of excellence. There is still room at the top, and the crucible process has not yet been pushed off the pinnacle to the doom that was predicted for it.

Metallography is now established, alongside of chemical analysis and mechanical testing, as a necessary servant of large producers and consumers. Hardness testing is much more practiced; the importance attached to dynamic testing is increasing. Examination by X-rays and by magnetic analysis is common, but not yet wide spread. Heat treating is much better understood and more often practiced, while double heat treating is common. The use of alloy steels is increasing rapidly, and is now almost universal for important parts of the best machinery, of automobiles, aeroplanes and even of large structures where strength is essential and lightness important.

These extensive developments have necessitated a complete reworking of the operating sections of this book, and especially of the chapters on Blast Furnace, Purification of Pig Iron, Open Hearth, Electrometallurgy, Malleable Cast Iron, Metallography and Alloy Steels. Also, so much more is now understood about

the phase of steel making between liquid metal in the ladle and the solid ingot or casting, that the chapter on "Defects in Ingots and Castings," has been completely rewritten under the caption: "The Ingot-Making Stage of Manufacture." The chapters on Mechanical Treatment, Foundry, Constitution of Iron, of Steel, and Heat Treatment have been revised and reset. All other parts have been revised in part and reset. In order to make room for these unavoidable increases in text without increasing the size of the book, the chapter on "Physics and Chemistry Introductory to Metallurgy" has been abandoned. While this may possibly be an inconvenience to some untechnical users among iron and steel operators, whose use of the book has been especially gratifying to the author, it is hoped that the reasons for the step may be deemed sufficient to justify the omission.

Besides the numerous acknowledgments made in the text, I desire especially to thank H. A. Schultz of the U. S. Steel Corporation and G. A. Reinhardt of the Youngstown Sheet & Tube Company for valued assistance in selecting and securing illustrations for this edition.

BRADLEY STOUGHTON.

BETHLEHEM, PA.,  
*September, 1923.*



## PREFACE TO SECOND EDITION

Developments in the Metallurgy of Iron and Steel have been so rapid during the past three years that a more thorough revision of the text of this volume than could be accomplished in conjunction with the usual reprinting for new impressions seemed not only desirable but necessary. Every department of manufacture has been improved in practice, in minor respects at least, and some branches, such as the duplex and special open-hearth processes, electric smelting and refining, use of dry blast, case-hardening, etc., have been advanced sufficiently to warrant an entire rewriting of the sections devoted to them. Opportunity has been taken of these revisions to make more or less extensive changes in all the text, with the result that it has been necessary to reset the type from cover to cover. I am especially indebted to J. E. Johnson, Esq., for valuable suggestions and revisions of the chapters on blast furnace, and chemistry and physics.

In addition to the changes mentioned above, the theory and chemistry of the Bessemer and open-hearth processes have been rewritten and enlarged, as well as the whole chapter on malleable cast iron. The section on blast furnace fuels has been taken from Chapter II, and this also has been rewritten and enlarged; with the section on open-hearth fuels from Chapter VI, it has been embodied in a new Chapter XIX, on Metallurgical Fuels. The references to literature have, in accordance with several suggestions, been taken from the end of the individual chapters and collected in an Appendix at the end of the volume, thus rendering it easier to turn to the index numbers at will.

In making these changes a constant and serious handicap has been the necessity of keeping the number of pages within a small compass in order not to disturb the price at which the book is sold, especially for the sake of student purses.

It will be noticed that the numbering of the illustrations is not quite consecutive, but a few numbers are left out at the

end of most of the chapters. The purpose of this arrangement is to allow additional cuts to be inserted from time to time if desired, without waiting until a third edition becomes necessary—if it ever does.

BRADLEY STOUGHTON.

NEW YORK CITY,  
*October, 1911.*

## PREFACE TO FIRST EDITION

The purpose of this book is to serve as a text-book, not only for college work, but for civil, mechanical, electrical, metallurgical, mining engineers and architects, and for those engaged in work allied to engineering or metallurgy. America now produces almost as much iron and steel as the rest of the world together, although less than eighteen years ago she held second rank in this industry. It seems fitting that the record of this progress should be brought together into one volume covering every branch of the art of extracting the metal from its ores and of altering its adaptable and ever-varying nature to serve the many requirements of civilized life.

I take pleasure in acknowledging here, with sincere thanks the assistance of many who have aided in the make-up of the volume, and especially The Adams Co., American Electric Furnace Co., American Sheet & Tinplate Co., Bethlehem Steel Co., Brown Specialty Machinery Co., Connersville Blower Co., Crocker-Wheeler Co., Francis G. Hall, Esq., Holland Linseed Oil Co., Chas. W. Hunt, Esq., Secretary, American Society of Civil Engineers, Professor James F. Kemp, Mackintosh, Hemphill & Co., Morgan Construction Co., National Tube Co., S. Obermayer Co., J. W. Paxson Co., Henry E. Pridmore, John A. Rathbone, each of whom have kindly loaned electrotypes. And of Dr. H. C. Boynton, the Brown Hoisting Machinery Co., Buffalo Furnace Works, H. H. Campbell, Esq., Professor William Campbell, Carnegie Steel Co., W. M. Carr, Esq., Central Iron & Steel Co., Crucible Steel Company of America, Fiske & Robinson, The Foundry, Harbison-Walker Refractories Co., Joseph Harts-horne, Esq., Professor Henry M. Howe, Lackawanna Steel Co., Marion Steam Shovel Co., Mesta Machine Co., Morgan Engineering Co., Professor A. H. Sexton, Wm. Swindell & Bros., United Coke & Gas Co., United Engineering & Foundry Co., Wellman-Seaver-Morgan Co., Whiting Foundry Equipment Co. And of O. S. Doolittle, Esq., for information upon paint, Frank E. Hall, Esq., for the analyses in Table XVIII, and W. J. Keep, Esq., for the figures in Table XXVI.

But especially I am indebted to the following gentlemen, each of whom has read a section of the book and made suggestions for its revision which have been very valuable to me: Messrs. W. Arthur Bostwick, Stanley G. Flagg, Jr., Alfred E. Hammer, Joseph Hartshorne, J. E. Johnson, Jr., Carleton S. Kock, Frank N. Speller. Herbert L. Sutton, and Hugh P. Tiemann.

*January, 1908.*

BRADLEY STOUGHTON.



# CONTENTS

---

	PAGE
PREFACE TO THIRD EDITION . . . . .	vii
CHAPTER I. INTRODUCTION—IRON AND CARBON . . . . .	1
Classification, 2. Definitions, 5.	
CHAPTER II. THE MANUFACTURE OF PIG IRON . . . . .	7
Varieties and distribution of iron ores, 8. United States deposits and transportation, 10. Handling raw material at a modern furnace, 15. The blast furnace and accessories, 17. Smelting practice and produces, 22. Making charcoal pig iron, 42. Calculating a blast-furnace charge, 43.	
CHAPTER III. THE PURIFICATION OF PIG IRON . . . . .	48
Miscellaneous purification processes, 56. Comparison of purification processes, 59. Distinguishing between the different products, 64. Fields of usefulness, of various classes of iron and steel, 68.	
CHAPTER IV. THE MANUFACTURE OF WROUGHT IRON AND CRUCIBLE STEEL. . . . .	70
The manufacture of wrought iron, 70. The carburization of wrought iron, 78.	
CHAPTER V. THE BESSEMER PROCESS . . . . .	87
CHAPTER VI. THE OPEN-HEARTH OR SIEMENS-MARTIN PROCESS. . .	122
Open-hearth plant, 122. Open-hearth furnace, 126. Basic open-hearth practice, 141. Acid open-hearth practice, 152. Special open-hearth processes, 159.	
CHAPTER VII. THE ELECTRO-METALLURGY OF IRON AND STEEL. . .	167
Electro-thermic iron ore smelting, 168. Melting steel scrap to produce "synthetic" pig iron, 175. Super-refining liquid steel in basic electric furnaces, 176. Melting pure steel scrap to produce electric steel, 185. Melting impure scrap to produce electric steel, 191. Melting and refining pig iron, 194. Electric melting in gray and malleable cast iron foundries, 194. Types and details of high temperature electric furnaces, 195. Electrolytic refining of cast iron or steel scrap, 199. Electrolytic iron direct from ore, 201. Indirect heating furnaces for temperatures up to 1100°C., 201.	
CHAPTER VIII. THE INGOT-MAKING STAGE OF MANUFACTURE. . .	203
CHAPTER IX. THE MECHANICAL TREATMENT OF STEEL. . . . .	221
The forging of metals, 224. The reduction of metals in rolls, 230. Parts of rolling mills, 238. Rolling-mill practice, 247. Wire drawing, 253. Pressing, 255. Comparison of mechanical methods, 257. Heating furnaces, 258.	

	PAGE
CHAPTER X. IRON AND STEEL FOUNDING. . . . .	263
The making of molds, 263. Design of patterns, 280. Cupola melting of iron for castings, 282. Comparative cupola practice, 298. Melting steel for castings, 303.	
CHAPTER XI. THE SOLUTION THEORY OF IRON AND STEEL . . . . .	308
The freezing of alloys of lead and tin, 311. The freezing of iron and steel, 319. The solid solution of iron and carbon, 324. The complete Roberts-Austen, Roozeboom diagram, 328.	
CHAPTER XII. THE CONSTITUTION OF STEEL . . . . .	331
The micro-constituents of steel, 339. The strength of steel, 331. Hardness and brittleness of steel, 346. Electric conductivity of steel, 348. Magnetic properties of steel, 349.	
CHAPTER XIII. THE CONSTITUTION OF CAST IRON. . . . .	351
The effect of carbon on cast iron, 355. The effect of silicon, sulphur, phosphorus, and manganese on pig iron, 359. The properties of cast iron, 364.	
CHAPTER XIV. MALLEABLE CAST IRON. . . . .	374
CHAPTER XV. THE HEAT TREATMENT OF STEEL. . . . .	393
Improper heating of steel, 393. Hardening of steel, 404. The constituents of hardened and tempered steels, 410. Practice in annealing, hardening and tempering, 415. Case hardening, carbonizing, or cementation, 420.	
CHAPTER XVI. ALLOY STEELS. . . . .	425
Nickel steels, 427. Manganese steel, 433. Chrome steel, 436. Self-hardening and high-speed tool steels, 438. Silicon steels, 443. Nickel-chrom steels, 446. Chrome-vanadium steels, 446. Alloy steels of highest qualities, 449.	
CHAPTER XVII. THE CORROSION OF IRON AND STEEL . . . . .	451
The cause and operation of corrosion, 451. Preservative coatings for iron and steel, 457.	
CHAPTER XVIII. THE METALLOGRAPHY OF IRON AND STEEL . . . . .	464
Preparation of samples for microscopic examination, 464. Developing the structure for examination, 467. Microscope and accessories, 469. Macroscopic metallography, 472.	
CHAPTER XIX. METALLURGICAL FUELS . . . . .	474
APPENDIX. IMPORTANT REFERENCE BOOKS . . . . .	493
INDEX . . . . .	501

# THE METALLURGY OF IRON AND STEEL

## CHAPTER I

### INTRODUCTION—IRON AND CARBON

**The Ferrous Metals.**—Iron and steel together form the largest manufactured product in the world, and each of them enters into every branch of industry and is a necessary factor in every phase of our modern civilization. Cast iron, because of the ease with which it can be melted, is produced in final form in almost every city in the United States, and only slightly less widely in other civilized countries. The manufacture of steel is more centralized, for economical reasons, but is several times as great as that of cast iron. Wrought iron is less in amount than either of the others, but has its own importance and uses. These three products—cast iron, steel, and wrought iron—together comprise the whole of the so-called “ferrous group of metals”—that is, the group which we classify together under the name of “iron and steel” (see Classification). They have two characteristics in common: First, that iron is present in all to the extent of at least 92 per cent; and second, that carbon is their next most important ingredient, and regulates and controls their chief qualities. Their manufacture represents nearly 15 per cent of all the world’s manufacturing wealth, and is far greater than any other like industry (see Table I).

**Cast Iron.**—Cast iron is impure, weak, and must be brought to its desired size and form by melting and casting in a mold. A typical example would contain about 94 per cent iron, 4 per cent carbon, and 2 per cent of other ingredients or impurities.

Pig iron is a raw form of cast iron, and malleable cast iron is a semi-purified form.

**Steel.**—Steel is purer than cast iron, much stronger, and may be produced in the desired size and form either by melting and casting in a mold or by forging at a red heat. It usually con-

## CLASSIFICATION OF IRON AND STEEL

Iron			
Generic term.....	Cast or obtained from a fluid mass		
How produced.....	Evidence of having been cast		
Characteristic.....	<div>Welded from a pasty mass. Not fluid when finished</div> <div>Contains slag</div> <div>Super-refined or deposited electrolytically</div> <div>Consists of over 98 per cent of iron. Contains less than 1 per cent of slag</div>		
Distinguishing quality.....	Non-malleable	Malleable	Will not harden by heat treatment
Species.....	Cast iron	Steel	Wrought iron
Varieties.....	(1) Cast-iron castings	(2) Malleable-iron castings	<div>(8) Wrought iron obtained by direct process from ore</div> <div>(9) Wrought iron obtained in puddling process, or finery hearth</div> <div>(10) Ingot iron</div> <div>(11) Electrolytic iron</div>

The numbers (1), (2), etc., refer to processes of manufacture, for which see Fig. 20, p. 48.

tains about 98 per cent or more of iron, and, in different samples, from 1.50 per cent down to almost no carbon, together with small amounts of other ingredients or impurities.

**Wrought Iron.**—Wrought iron is almost the same as the very low-carbon steels, except that it is never produced by melting and casting in a mold, but is always forged to the desired size and form. It usually contains less than 0.12 per cent of carbon. Its chief distinction from the low-carbon steels is that it is made by a process which finishes it in a pasty, instead of in a liquid form, and leaves about 1 or 2 per cent of slag mechanically disseminated through it.

**Iron.**—Iron as such—by which is meant pure iron—does not exist as an article of commerce, but appears in service and in the market only in the form of cast iron, steel, or wrought iron—that is, when contaminated with carbon and other impurities. Some of these impurities are present because they cannot cheaply be gotten rid of, and others, because, like carbon for example, they benefit the metal by giving it strength or some other desirable property. Pure iron is a white metal and one of the chemical elements. It is with one exception the commonest and most abundant metal in the earth, and almost all rocks contain it in greater or less degree, from which we extract it if it is large enough in amount to pay for working. It is almost never found in nature in the form of a metal, but is always united with oxygen to form either a blackish, brownish, reddish or yellowish substance. Indeed, if it should occur in metallic form it would very soon become oxidized by the action of air and moisture. Recently there has come into commerce in France electrolytic iron, made by dissolving scrap iron as an anode and depositing as the cathode iron in the form of tubes and 99.97 per cent pure. In America a similar process is used to make pure iron magnet cores.

It is the abundance of iron in the earth which is the chief cause of its cheapness, and therefore one reason why it is used more than any other manufactured material. The other reason is the ease with which we can confer upon it at will some of the qualities most useful to man, of which the most valuable is probably its strength, and the most wonderful its magnetism, in which it is not even approached by any other substance. What these two properties alone mean in modern structural and electrical engineering can scarcely be estimated.



TABLE I.—THE WORLD'S PRODUCTION OF PIG IRON IN METRIC TONS (2,204.6 Lb.), 1865 TO 1920

	United States	Great Britain	Germany	France	Belgium	Russia	Austria-Hungary	Sweden	Spain	Italy	Canada	Other countries	Total
1865	843,410	4,897,971	988,191	1,203,710	470,767	299,438	101,403	226,619	.....	.....	.....	68,037	9,099,666
1870	1,692,378	6,060,720	1,391,123	1,178,113	565,234	359,531 <sup>1</sup>	402,953	300,338	.....	.....	.....	309,520	12,259,910
1875	2,056,750	6,469,219	2,029,389	1,448,272	541,805	427,187	463,063	350,539	In 1876 { 44,491		.....	316,078	14,102,222
1880	3,897,840	7,875,545	2,792,038	1,725,293	608,084	448,596	464,234	405,713	85,939	.....	.....	306,946	18,547,228
1885	4,110,600	7,368,842	3,687,434	1,630,648	712,876	528,170	714,787	464,737	159,225	15,991	.....	398,583	19,791,893
1890	9,353,020	8,033,052	4,658,451	1,962,196	787,836	927,581	965,382	456,103	170,782	14,346	.....	301,959	27,030,712
1895	9,597,449	8,022,006	5,788,798	2,005,889	829,135	1,454,298	1,075,000	455,200	206,430	10,500 <sup>1</sup>	47,586	375,000 <sup>1</sup>	29,867,591
1900	14,009,870	9,003,046	7,519,655	2,714,298	1,161,180	2,895,636	1,311,949	556,868	289,788	23,990	87,612	625,000 <sup>1</sup>	40,198,892
1905	23,340,258	9,746,221	10,987,623	3,077,000	1,310,290	2,125,000	1,372,300	531,200	388,100	31,300	475,491	655,000 <sup>1</sup>	54,054,783
1910	27,636,687	10,380,212	14,794,649	4,032,459	1,803,500	2,740,000	2,010,000	604,300	367,000	215,000	752,053	525,000 <sup>1</sup>	65,860,260
1915	30,414,817	8,793,659	11,790,199	5,585,776	68,150	3,696,500	1,960,000	767,600	439,835	377,510	828,920	415,000	64,367,234
1920	37,520,495	8,136,827	5,550,000 <sup>1</sup>	3,468,000	1,116,400	98,000	800,000 <sup>1</sup>	470,550	251,000	88,072	989,137	1,377,616 <sup>1</sup>	59,870,552

<sup>1</sup> Estimated.

**Carbon.**—Carbon is also a chemical element and familiar to everyone; graphite, lampblack, charcoal, and diamond are the various allotropic forms in which it appears. It is a common substance and present in every form of organic matter, while its oxides—carbon monoxide ( $\text{CO}$ ); and carbon dioxide ( $\text{CO}_2$ )—are well-known gases. Its chemical affinity for iron is very great; iron practically always contains some amount, but if it is desired to remove it entirely, the last traces are eliminated only with extreme difficulty.

**Iron and Carbon.**—Carbon has the peculiarity of conferring on iron great strength, which, strange to say, it does not itself possess, and also hardness, which it possesses only in its diamond allotropic form. At the same time it takes away from the iron a part of its ductility, malleability, magnetism and electric conductivity. So important is the influence of carbon in regulating and controlling the characteristics of the ferrous metals, that they are individually and collectively classified according to the amount and condition of the carbon in them. The potent effect of carbon must be constantly borne in mind when we come to describe the manufacture of iron and steel and to discuss the methods of regulating the carbon (see p. 51, and Tables XXXV and XXXVI, pp. 341 and 342).

#### DEFINITIONS

The following definitions are selected from the report of Mar. 31, 1906, of the Committee on the Uniform Nomenclature of Iron and Steel of the International Association for Testing Materials, with slight changes:

**Cast Iron.**—Generically, iron containing so much carbon or its equivalent that it is not malleable at any temperature. Specifically, cast iron in the form of castings other than pigs, or remelted cast iron suitable for casting into such castings, as distinguished from pig iron, *i.e.*, cast iron in pigs.

The committee recommends drawing the line between cast iron and steel at 2.20 per cent carbon for the reason that this appears from the results of Carpenter and Keeling to be the critical percentage of carbon corresponding to the point *a* in the diagrams of Roberts-Austen and Roozeboom (see p. 329).

**Pig Iron.**—Cast iron which has been cast into pigs direct from the blast furnace. This name is also applied to molten cast iron which is about to be so cast into pigs, or is in a condition in which

it could readily be cast into pigs before it has ever been cast into any other form.

**Gray Pig Iron and Gray Cast Iron.**—Pig iron and cast iron in the fracture of which the iron itself is nearly or quite concealed by graphite, so that the fracture has the gray color of graphite.

**White Pig Iron and White Cast Iron.**—Pig iron and cast iron in the fracture of which little or no graphite is visible, so that their fracture is silvery and white.

**Mottled Pig Iron and Mottled Cast Iron.**—Pig iron and cast iron, the structure of which is mottled, with white parts in which no graphite is seen, and gray parts in which graphite is seen.

**Malleable Cast Iron.**—Iron which when first made is cast in the condition of cast iron, and is made malleable by subsequent treatment without fusion.

**Malleable Iron.**—The same as wrought iron. A name used in Great Britain, but not in the United States, except carelessly as meaning "Malleable cast iron."

**Steel.**—Iron which is malleable at least in some one range of temperature, and in addition is either (a) cast into an initially malleable mass; or (b) is capable of hardening greatly by sudden cooling; or (c) is both so cast and so capable of hardening.

**Wrought Iron.**—Slag-bearing, malleable iron, which does not harden materially when suddenly cooled.

In the definition of steel the first sentence ("is malleable at least in some one range of temperature") distinguishes steel from cast iron and pig iron; the second sentence ("is cast into an initially malleable mass") distinguishes it from malleable cast iron, and the third sentence ("is capable of hardening greatly by sudden cooling") distinguishes it from wrought iron. At the best, however, the definition of steel is in a shockingly bad condition, and has been brought to it by a series of events which shows the carelessness of the buying public and the greed of men who will appropriate the name for their product that will bring them the best price without regard to whether the name really fits or not.



## CHAPTER II

### THE MANUFACTURE OF PIG IRON

Whatever material we are to manufacture—cast iron, wrought iron, or steel—or for whatever purpose the metal is to be used, the first step in the operation is smelting iron ore in a blast furnace with fuel and flux, and obtaining cast iron or pig iron, terms used synonymously in the United States. The pig iron thus produced is an impure grade of iron, containing chiefly carbon, silicon, manganese, sulphur and phosphorus. The amount of pig iron made exceeds that of any other product manufactured by man. Blast furnace fuels are discussed in Chapter XIX.

TABLE II.—ANALYSIS OF VARIOUS GRADES OF PIG IRON

Name	Silicon, per cent	Sulphur, per cent	Phos- phorus, per cent	Manganese, per cent	Carbon, per cent	
Foundry irons <sup>1</sup>	No. 1.....	2.75 to 3.25	0.035	0.30 to 1.50	0.20 to 1.60	3.00 to 4.00
	No. 2.....	2.25 to 2.75	0.045	0.30 to 1.50	0.20 to 1.60	3.00 to 4.00
	No. 3.....	1.75 to 2.25	0.055	0.30 to 1.50	0.20 to 1.60	3.00 to 4.00
	No. 4.....	1.25 to 1.75	0.065	0.30 to 1.50	0.20 to 1.60	3.00 to 4.00
Forge iron <sup>2</sup> .....	0.75 to 1.75	0.05 to 0.30	0.30 to 3.00	0.20 to 1.50	3.00 to 4.00	
Bessemer—acid.....	0.80 to 2.00	0.03 to 0.08	under 0.10	0.30 to 0.50	3.50 to 4.00	
Bessemer—basic.....	under 1.00	under 0.10	1.75 to 3.50	1.00 to 2.00	3.50 to 4.00	
Open-hearth—acid...	0.75 to 2.50	under 0.05	under 0.05	0.30 to 0.50	3.50 to 4.00	
Open-hearth—basic..	under 1.00	under 0.10	0.10 to 2.00	1.00 to 2.00	3.50 to 4.00	
Ferromanganese <sup>3</sup> ...	0.50 to 1.00	under 0.03	0.10 to 1.00	80.00	5.00 to 7.00	
Ferromanganese <sup>3</sup> ....	under 1.00	under 0.03	0.10 to 0.50	40.00	5.00 to 6.00	
Spiegeleisen <sup>3</sup> .....	under 1.00	under 0.05	under 0.15	15.00 to 30.00	5.00 to 6.00	
Ferrosilicon <sup>4</sup> .....	8.00 to 15.00	under 0.07	0.10 to 0.50	.....	1.00 to 2.00	
Ferrosilicon <sup>4</sup> .....	50.00	under 0.02	under 0.08	.....	under 0.40	
Silico-spiegel <sup>5</sup> .....	5.00 to 15.00	under 0.02	under 0.15	15.00 to 25.00	1.00 to 1.50	
Ferrochrome <sup>7</sup> .....	1.00 to 5.00	about 0.04	0.02 to 0.05	.....	5.50 to 10.0	

<sup>1</sup> See also Chapter X, p. 263 and p. 37.

<sup>2</sup> Used for puddling (see Chap. IV, p. 70).

<sup>3</sup> Valued for its manganese.

<sup>4</sup> Valued for its silicon.

<sup>5</sup> This grade is made by electric smelting.

<sup>6</sup> Valued for its manganese and silicon.

<sup>7</sup> Valued for its chromium which is about 60 to 70 per cent.

The gangue of our iron ores consists usually of silica, alumina, etc., and, like the fuel ash, requires the addition of the correct

amount of limestone flux to make it into a fusible slag. In the Pittsburgh district we charge about 1,200 lb. of limestone, 2,200 lb. of coke, and 4,000 lb. of ore for every long ton of pig iron made. The amount of each is increasing, however, from time to time, as the higher-grade ores are becoming exhausted and there are more impurities to be fluxed and melted. Recently, enriching ores by wet concentration has been practiced more extensively, and "washers" at or near the mines decrease the proportion of useless impurities to be transported and to be treated in the furnace, while magnetic concentrators are important in the eastern United States.

#### VARIETIES AND DISTRIBUTION OF IRON ORES

The iron ores used for smelting consist of chemical compounds of iron and oxygen containing more or less water, either in the form of moisture or chemically combined as water of crystallization.

**Hematite** ( $\text{Fe}_2\text{O}_3$ ).—The best known of these ores is hematite, containing when pure 70 per cent of iron. The red or brown hematites are the richer varieties (Lake Superior deposits, containing, in some cases, as much as 68 per cent of iron), while the hydrated hematites, or limonites, usually contain a good deal of water of crystallization and are consequently poorer in iron, not often yielding much more than 50 per cent iron.

Oolitic hematite is a variety that exists in the form of spherical grains or nodules. It is important because it sometimes contains limestone and is, therefore, valuable not only for the iron but for the fluxing quality of the lime. The Minette ore of Lorraine, Luxemburg, and France is an enormous deposit of this oolitic hematite, running from 30 to 35 per cent iron and giving a pig iron containing about 2 per cent of phosphorus. This ore is the basis of the iron industry of Germany, France, and Belgium, and, upon judicious mixing of varieties when necessary, is self-fluxing.

**Magnetite** ( $\text{Fe}_3\text{O}_4$ ).—Magnetite contains, when pure, enough iron (72.4 per cent) to attract the magnet. In the United States it is often mixed with other impurities, such as silica, titanium and phosphorus, so as to render the ore either too poor in iron to be smelted profitably, or too high in phosphorus to make good steel, or so high in titanium as to unjustly<sup>1</sup> prejudice smelters against it through fear of sticky, infusible slags.

<sup>1</sup> See *Jour. Iron and Steel Inst.* No. 1, 1910, pp. 611-2.

But other magnetite ores—notably those of Sweden—are the purest ores that exist in large quantities anywhere, and form one of the sources of the Swedish iron and steel, which is famous all over the world for its purity, that is, for its freedom from the objectionable elements sulphur and phosphorus. It is these Swedish products which supply the steel industry of Sheffield with pure material for its tool steel and cutlery.

TABLE III.—SUMMARY OF IRON ORE DEPOSITS OF UNITED STATES  
(Compiled by JAMES F. KEMP)<sup>1</sup>

	Available metric tons	Probable addition metric tons
Archean magnetites (Appalachian):		
Lump ores .....	20,000,000	30,000,000
Concentrate equivalent from low- grade ore .....	40,000,000	10,000,000
Adirondack red hematites.....	2,000,000	2,000,000
Pennsylvania soft magnetites.....	40,000,000	
Cambro-ordovician brown hematites (Appalachian).....	65,000,000	181,000,000
Mesozoic and tertiary brown hematites (Ala., Tenn.).....	10,000,000	15,000,000
Alabama gray and red hematites.....	27,500,000	27,500,000
Clinton red hematites (largely Ala., Tenn., N. Y. and Wis.).....	505,320,000	1,368,000,000
Carbonate ores (Ohio, Pa. and Ky.)....		308,000,000
Lake Superior hematites (Minn., Mich., Wis.).....	3,500,000,000	72,000,000,000
Mississippi valley specular and red hematites (Mo.).....	15,000,000	5,000,000
Mississippi valley paleozoic brown hematites (Mo.).....	30,000,000	45,000,000
Mississippi valley tertiary brown hema- tites (La., Tex., Ark.).....	260,000,000	520,000,000
Cordilleran magnetites and hematites (Utah, Cal., Wyo., Nev., Colo.).....	63,800,000	55,000,000
Total.....	4,578,620,000	74,566,500,000
Titaniferous ores (Adirondacks and Lake Superior).....	90,000,000	128,500,000

<sup>1</sup> "Iron Ore Resources of the World," Stockholm, 1910.

TABLE IV.—WORLD'S SUMMARY OF IRON ORE RESERVES<sup>1</sup>  
(In million metric tons)

	Actual reserves		Potential reserves	
	Ore	Iron equiv- alent	Ore	Iron equiv- alent
Europe.....	12,032	4,733	41,029 +	12,029 +
America.....	9,855	5,154	81,822 +	40,731 +
Australia.....	136	74	69 +	37 +
Asia.....	260	156	457 +	283 +
Africa.....	125	75	much	much
Total.....	22,408	10,192	123,337 +	53,136 +

<sup>1</sup> "Iron Ore Resources of the World," Stockholm, 1910.

**Siderite** ( $\text{FeCO}_3$ ).—Another variety of iron ore is the so-called "spathic" iron ore, or siderite, which is, however, without any importance in the United States. The forms the famous "clay ironstone" of the Cleveland district in England. It is poor in iron and is therefore no longer smelted in any quantity in the United States in competition with the rich hematites. This ore is almost always calcined before smelting to expel the carbonic acid, in order to save the blast furnace the extra work of this expulsion in its upper levels.

#### UNITED STATES DEPOSITS AND TRANSPORTATION

In the United States ores of iron are very widely distributed, as will be seen by reference to the map, Fig. 1. This melting of ore also shows a wide distribution. Blast furnaces are in operation in 24 states, including Oregon, Minnesota and New York on the north; Colorado, Texas and Alabama on the west and south. The great pig-iron centers are: (1) The district that includes western Pennsylvania and Ohio, which produces more than one-half of the pig iron of the country; (2) Illinois, and (3) Alabama.

It is not to be supposed that all the deposits marked on the map are extensively worked for their iron. The rich hematite deposits of the Lake Superior district furnish annually about 60,000,000 tons, which yield more than three-quarters of the pig-iron production of the country. The only other districts which produce more than 1,000,000 tons a year are in the states of Alabama and New York. Most of the other deposits are mined



only for local treatment. In addition, a total of over 2,000,000 tons per year are imported from Cuba, Spain and other foreign countries, principally for smelting on or near the Atlantic coast, while Pacific coast furnaces receive ores from China.



(From Kemp's "Ore Deposits of the United States")

FIG. 1.—United States iron ore deposits.

**Ore Transportation.**—A peculiarity of the Lake Superior deposits is that most of the ore is transported a distance of 800 miles or more in order to bring it to the coke. Thus, western Pennsylvania, Ohio and South Chicago receive the bulk of the ore shipped from the Lake Superior mines. Since the weight of coke used in the blast furnaces is only about one-half the weight of the ore, it might seem uneconomical to carry the latter to the former. But coke is bulky in proportion to its weight; furthermore, it suffers a good deal of waste in transportation in consequence of its friability and of the fact that so much of it is broken down into pieces less than 1 in. in diameter (technically known as "breeze") which are not suitable for charging into the blast furnace. The ore, on the other hand, may be handled by the cheapest and most rapid labor-saving devices. Indeed, in many cases, the ore is never touched by shovels in the hands of man, but is mined, charged and discharged in units of several tons each by specially designed machinery.

The mining and transportation of this great amount of material is in itself a mighty industry, every advance in which has contributed in no small share to the increasing volume and impor-



(Courtesy, U. S. Steel Corp.)

FIG. 2.—A Lake Superior iron ore mine.



FIG. 3.—Steam shovel loading soft ore.

tance of the iron, steel and other industries of the United States.

**Mining.**—Some of the Lake Superior deposits lie near the surface and are therefore cheaply mined. This is especially true

of the soft, earthy deposits of the Mesabi range, which are sometimes worked in great open cuts, the ore being loaded upon cars by mammoth steam shovels, or sometimes by the caving method, the ore falling by gravity into cars situated in underground tunnels. The massive, or rock, ores are more costly to extract, and the utmost skill of American blast-furnace men has been exercised to employ as large a portion of the earthy ores as possible without choking up the furnace. The practice of agglomerating or sintering fine ores into lump form is becoming more prevalent.



(Courtesy, U. S. Steel Corp.)

FIG. 4.—Loading an ore boat.

**Transportation.**—On the lake the ore is transported in boats capable of taking a load of 10,000 or 13,000 tons of ore each. The hatches of these great boats are placed such a distance apart that the hinged ore chutes of the bins may be swung down and, when the gates are opened, the ore allowed to flow directly into the hold of the vessel. In a few minutes the vessel has received her full cargo and is ready to start on its long journey down the chain of inland lakes.

**Unloading.**—The unloading of boats is accomplished with almost as great celerity as the loading, and by means of mechanical unloading machinery a steamer containing as much as 10,300 tons of ore has been completely discharged in 4 hr. 30 min. Nor is any time wasted in coaling the vessel for a second journey up the lakes and back. Great machines pick up whole railroad cars of fuel and empty them bodily into the chute which connects with

the bunkers of the vessel, many of the ore steamers being so constructed that this wholesale loading of coal can go on at the same time that ore is being discharged.



FIG. 5.—Brown-hoist apparatus unloading an ore boat.



FIG. 6.—Hulett electric unloader.

**Prices.**—Iron ores are divided into two great classes, known as “Bessemer” and “Non-Bessemer;” in the former class are those ores in which the percentage of iron is more than 1,000 times the percentage of phosphorus. This name arises through the circumstance that only when the phosphorus is as low as this can we make from them a steel (with the blast furnace followed by the



acid Bessemer process) with phosphorus under 0.100 per cent. The price of Bessemer ores is about 75 cents per ton more than non-Bessemer ores on this account. At present (1922) Mesabi Bessemer ores sell at about \$6 per ton, which is twice the price they commanded 12 to 15 years ago.

### HANDLING RAW MATERIAL AT A MODERN FURNACE

Behind the blast furnace are situated long rows of storage bins, one of which is shown in elevation in Fig. 7. These bins are filled by bottom-dumping railroad cars which bring the ore to the furnaces, or by mechanical apparatus from the great piles of ore stored conveniently near. Between and under these two rows of bins runs a track on which ore larries are transferred back and forth, being first filled with a weighed amount of ore, limestone, or fuel, and then switched into a position from which they can deposit their contents into the loading skip of the blast furnace.

**Loading the Furnace.**—The next step in the handling of the raw material is to bring the ore, together with the necessary fuel and flux, into the mouth of the huge furnace that is to convert it into pig iron. In one of the big modern American furnaces, working at top speed, the amount of material which must be dumped into the top during 24 hr. will frequently exceed 2,000 tons, and the charging must go on for 365 days a year with never a delay of more than a few minutes at a time.

In the modern type of furnace this loading is accomplished altogether by mechanism operated and controlled from the ground level, and no men are required to work at the top of the furnace. In Fig. 7 is a section of such a furnace showing one method of loading—a double, inclined skipway extending above the top of the furnace. One skip is seen discharging its load of ore, or fuel and flux, into the hopper, while the second skip is at the bottom of the incline ready to be loaded with its charge.

**Double Bell and Hopper.**—The upper hopper of the furnace is closed at the bottom by an iron cone, known as a "bell." This bell is held against the bottom of the hopper by the counter-weighted lever shown, and is opened by operating the cylinder *M*, to allow the charge to fall into the main hopper *I* of the blast furnace. In this way the hopper of the furnace is progressively filled with ore, flux and fuel. This hopper *I* is also closed at the bottom by a similar bell *A*. The operation of this bell is also

controlled from the ground, and when a charge has been deposited in the hopper it is opened and the contents allowed to fall in an annular stream, distributing itself on top of the material already




FIG. 7.—Cross-section of blast furnace and skip hoist.

in the furnace which is within a few feet of the bottom of the bell. As the upper bell *B* is now held up against the bottom of the upper hopper, there is never a direct opening from the interior of the

blast furnace to the outer air, so that the escape of gas, resulting formerly in the long flame rising from the top of the blast furnace whenever material was dropped into the interior, no longer occurs at our modern plants.

This is not the only means of handling the raw material for the blast furnace. Several varieties of mechanism are extensively used, but the description given heretofore will serve to illustrate the general principles of labor-saving mechanisms in connection with charging the blast furnace. The details of the distribution are of the utmost importance and largely affect the production, the quality of iron, the coke consumption, and, above all, the life of the lining. Cases are on record where apparently trivial changes in this detail have revolutionized the work of the furnace.

**Stock Distribution.**—In dumping stock into a furnace it is obvious that the larger particles will run farther down hill than the fines. The first essential is therefore to design the bell so that it will distribute the material uniformly in the furnace. But, with mechanical delivery of stock to the hopper, the bell itself often received material unevenly distributed. This led to the use of a rotating distributor, which receives the stock from the hoisting skip and delivers it successively to different points within the hopper.

## THE BLAST FURNACE AND ACCESSORIES

The blast furnace itself consists of a tall cylindrical stack lined with an acid (silicious) refractory firebrick, the general form and dimensions being shown in Fig. 7. The hearth or crucible is the straight portion occupying the lower 8 ft. of the furnace. Above that extends the widening portion, called the bosh, which reaches to that portion in the furnace having the greatest diameter. The stack extends throughout the remainder of the furnace, from the bosh to the throat. The brickwork of the hearth is cooled by causing water to trickle over the outside surface.

**Tuyeres.**—Through the lining of the furnace, just at the top of the hearth, extend the tuyeres—8 to 16 pipes having an internal diameter of 4 to 7 in., through which hot blast is driven to burn the coke and furnish the heat for the smelting operation. The “tuyere notches,” or openings through which the tuyere pipes

enter, as well as the tuyeres themselves, are surrounded by hollow bronze rings, through which cold water is constantly flowing to protect them from melting at the inner ends. The number and size of the tuyeres is in proportion to the diameter of the hearth, the volume and pressure of the blast, etc., the blast being given sufficient velocity to carry it, distributed as evenly as possible, to the very center of the furnace.




FIG. 8.—Parts of a blast-furnace tuyere.

**Discharge Holes.**—On the side of the furnace, and 30 to 40 in. below the level of the tuyeres, the “cinder notch” or “monkey” is situated. This is protected by a water-cooled casting, and the hole is closed by forcing into it an iron plug around which the cinder chills and makes a tight joint. The level of the tuyeres is the point above which the cinder must not be allowed to accumulate.

In the front, or breast, at the very bottom level of the crucible, is the iron tap-hole, from which all the liquid contents of the furnace can be completely drained. This is a large hole in the brickwork, and is closed with several balls of clay.

**Bosh.**—The hottest part of the furnace is near the tuyeres and a few feet above them. In order to protect the brickwork of the bosh from this heat, a number of hollow wedge-shaped castings are placed therein, through which cold water circulates. The brickwork is furthermore protected by a deposition of a layer





FIG. 9.—A battery of blast-furnace blowing engines.


of carbon, similar to lampblack, on its internal surface, covered by a layer of a sort of slag, or cinder, replacing part of the brickwork. The deposition of carbon comes about through the reaction of the furnace operation itself, in the following manner: For the correct conduct of the smelting operation, and especially for carrying of the sulphur in the slag, it is necessary that a very powerful reducing influence exist; this reducing influence is produced by an excess of coke, and one of its results is the precipitation of finely divided carbon on the internal walls of the furnace. It is this thin layer of cinder and carbon which is most effective in protecting the acid lining of the furnace from the corrosive action of the basic furnace slag. Other methods of protecting the bosh walls are in use, one of the most successful being a plain steel jacket thoroughly cooled externally by sprays and lined with a single course of brick. This avoids the benching or stepping which occurs with the construction above described.

**Hot Blast.**—The air for smelting is driven into the furnace by immense blowing engines ranging up to 2,500 hp. each, and capable of compressing 50,000 to 65,000 cu. ft. ( $= 4,875 \text{ lb.}^1$ ) of free air per minute to a pressure of 15 to 30 lb. per square inch which is about what one furnace requires. It actually requires about 4 to 5 tons of air for each ton of iron produced by the furnace. After leaving the engines and before coming to the furnace, the air is heated to a temperature of 425 to 650°C. (800 to 1,200°F.) by being made to pass through the hot-blast stoves.

**Hot-blast Stoves.**—Each furnace is connected with four or five stoves. These are cylindrical tanks of steel about 110 ft. high and 22 ft. in diameter, containing two or more firebrick chambers. One of these chambers is open, and the others are filled with a number of small flues (see Fig. 10). Gas and air are received in the bottom of the open chamber *B* in which they burn and rise. They then pass downward through the several flues in the annular chamber surrounding *B*, and escape at the bottom to the chimney as waste products. In passing through the stove they give up the greater part of their heat to the brickwork. After this phase is ended, the stove is ready to heat the blast.

The blast from the blowing engine enters at the bottom of the flues *E*, passes up through the outer chamber, and down through *B* to the furnace. In this passage it takes up the heat left in the brickwork by the burning gas and air. Sometimes there are three

<sup>1</sup> At 70°F. and atmospheric pressure, each 1,000 cu. ft. of air weighs 75 lb.



(From Howe, "Iron, Steel and Other Alloys")

FIG. 10.—Hot-blast stove.

passes, instead of two as described. In a blast-furnace plant, one stove is heating the blast while the other three are simultaneously in the preparation stage, burning gas and air. By changing once an hour a fairly regular blast temperature is maintained. The gas used for the heating is the waste gas from the blast furnace itself, which amounts to about 90,000 cu. ft. per minute at a temperature of 235°C. (450°F.), and has a calorific power of about 85 to 95 B.t.u. per cubic foot. The latent and available heat of this gas is equivalent to approximately 50 per cent of that of the fuel charged into the furnace. Only about 30,000 cu. ft., or one-third of this gas, is needed for keeping the stoves hot, and the remaining two-thirds is used to produce power.

**Power from Waste Gas.**—The waste gas comes down the down-comer *T*, Fig. 11, deposits dirt in the dust catcher *W*, is carefully cleaned and scrubbed, and is then led to the stoves or power producer. This gas varies in composition, but will average about 61 per cent nitrogen, 10 to 17 per cent CO<sub>2</sub>, and 22 to 27 per cent CO. The latter can be burned with air to produce heat.

CO + O = CO<sub>2</sub> (generates 68,040 calories).

If burned under boilers, the available gas will generate enough power to operate the blowing engines, hoisting mechanism, and other machinery used in connection with the furnace. At several plants the gas available for power is cleaned carefully and utilized in gas engines, whereby much more power is obtained, the excess being usually converted into electricity and transmitted to more distant points.

### SMELTING PRACTICE AND PRODUCTS

The furnace is filled with alternate layers of fuel, flux and ore, down to the top of the smelting zone. The exact location of this zone will be dependent upon the volume and pressure of blast, size of furnace, character of slag made, etc., but will extend from the level of the tuyeres to a few feet above them, or about to the top of the bosh. It will require perhaps 15 hr. for the material to descend from the top of the furnace to the smelting zone. During this descent, it is upheld partly by the resistance of the uprushing column of hot gases,<sup>1</sup> partly by its friction on the walls of the

<sup>1</sup> The full drop from the blast pressure to practically atmospheric pressure at the throat represents the resistance of the stock to the upward passage of the gas and of course this represents also the resistance offered by the gas to the descent of the stock. This resistance is in many cases nearly equal to the weight of the stock.







FIG. 11.—Section of blast furnace while in operation.

furnace, and partly by the loose column of coke which extends through the smelting zone and to the bottom of the furnace, and which alone resists melting in the intense heat of this zone. The blast entering the furnace through the tuyeres, consists of 23 per cent by weight of oxygen and 77 per cent by weight of nitrogen, together with varying amounts of water vapor from moisture in the air (see p. 32). The nitrogen is practically inert chemically and performs no function other than that of absorbing heat in the smelting zone and giving it out at higher levels. The oxygen




(Courtesy, U. S. Steel Corp.)

FIG. 12.—Gas cleaning apparatus.

attacks all the coke in the smelting zone and as much of it below the level of the tuyeres as is not covered by accumulations of iron and slag in the hearth, producing a large volume of carbon monoxide gas (CO) and a temperature which may exceed 3,000°F.<sup>1</sup> The CO and nitrogen pass up between the particles of solid material, to which they give up the greater part of their heat. The former also performs certain chemical reactions, and

<sup>1</sup> It is of minor importance whether the CO gas is formed directly or as a result of the two following reactions:








FIG. 13.—Blowing engines operated by blast-furnace gas.


thus in both ways the rising column of gases prepares the charge for its final reduction in the smelting zone.



(From Howe, "Iron, Steel, and Other Alloys")


FIG. 14.—Section of blast furnace smelting zone.

**Chemical Reactions in the Upper Levels.**—As soon as the iron ore enters the top of the furnace, two reactions begin to take place between it and the gases:







and this continues with increasing rapidity as the material becomes hotter. The carbon formed by reaction No. 1 deposits in a form similar to that of lampblack on the outside and in the interstices of the ore. This reaction, however, is opposed by two reactions with carbon dioxide gas:




Reaction No. 3 begins at a temperature of about 300°C. (575°F.), which is met with about 3 or 4 ft. below the top level of the stock; and No. 4 begins at about 535°C. (1,000°F.), or 20 ft. below the stock line. Reaction No. 4 is so rapid that the deposition of carbon ceases at a temperature of 590°C. (1,100°F.). All the way down the ore is constantly losing a proportion of its oxygen to the gases. At higher temperatures than 590°C., FeO is stable and practically all of the Fe<sub>2</sub>O<sub>3</sub> has been reduced.



The reaction between iron oxide and solid carbon begins at 400°C. (750°F.).



At 700°C. (1,300°F.) solid carbon begins to reduce even FeO:



Practically all the iron is reduced to a spongy metallic form by the time the temperature of 800°C. (1,475°F.) is reached. This is about 45 ft. from the stock line and less than 30 ft. above the tuyeres. At 800°C. the limestone begins to be decomposed by the heat, and only CaO comes to the smelting zone:



The foregoing facts are summarized in Fig. 15, which is adapted from H. H. Campbell, with certain changes.<sup>1</sup> It is not to be supposed that these figures are exactly correct for the different levels, and it is probable that they change from day to day and from furnace to furnace, but a general idea may be obtained from this sketch. It will be seen that the upper 15 or 20 ft. of stock is a region of Fe<sub>2</sub>O<sub>3</sub> and Fe<sub>3</sub>O<sub>4</sub>, gradually being converted to FeO by CO gas, and forming quantities of CO<sub>2</sub> gas. If these reactions were the only ones, the top gases would contain no CO and would have no calorific power, but reaction No. 1 produces both metallic

<sup>1</sup> See pp. 54 and 62 of Book Ref. 2.

iron and carbon, both of which reduce  $\text{CO}_2$  and thus waste much energy, as far as the blast furnace is concerned:

Reaction No. 3,  $\text{Fe} + \text{CO}_2 = \text{FeO} + \text{CO}$ , absorbs 2,340 calories, but wastes 68,040 calories.

Reaction No. 4,  $\text{C} + \text{CO}_2 = 2\text{CO}$ , absorbs 38,880 calories.

From 20 to 35 ft. below the stock line is the region of  $\text{FeO}$ , gradually being converted to metallic iron sponge by carbon. At




FIG. 15.—Diagram showing chemical action in blast furnace.

the lower level of this zone the limestone loses its  $\text{CO}_2$ , which joins the other furnace gases. From 35 ft. down to the smelting zone is the region of metallic iron. This spongy iron is impregnated with deposited carbon which probably soaks into it and dissolves to some extent, in a manner similar in nature but not in degree to the way ink soaks into blotting-paper. This carburization of the iron reduces its melting point and causes it to become liquid at a higher point above the tuyeres than it otherwise would.

On reaching the smelting zone the iron melts and trickles quickly down over the column of coke, from which it completes its saturation with carbon. At a corresponding point the lime unites with the coke ash and impurities in the iron ore, forming a fusible slag which also trickles down and collects in the hearth. It is during this transit that the different impurities are reduced by the carbon, and the extent of this reduction determines the characteristics of the pig iron, for in this operation, as in all smelting, reduced elements are dissolved by the metal, while those in the oxidized form are dissolved by the slag. Only one exception occurs, namely, that iron will dissolve its own sulphide ( $\text{FeS}$ ) and, to a less extent, that of manganese ( $\text{MnS}$ ), but not that of other metals, as, for instance,  $\text{CaS}$ .

**Chemical Reactions in the Smelting Zone.**—There is always a large amount of silica present in the coke ash, and some of this is reduced according to the reaction:




The extent of this reaction will depend on the length of time the slag takes to drop through the smelting zone, the relative intensity of the reducing influence, and the avidity with which the slag takes up silica. A slag with a high melting point will trickle sluggishly through the smelting zone and cause the iron to do the same, to some extent, thus giving it more chance to take up silicon. A higher temperature in the smelting zone, which increases disproportionately the avidity of carbon for oxygen, will promote reaction No. 9. We can produce this higher temperature by supplying hotter blast. A larger proportion of coke to burden<sup>1</sup> will further promote this reaction, because this not only increases the amount of the reducing agent, but also raises the temperature and, therefore, the chemical activity of this agent. Thus the coke has both a physical and a chemical influence in increasing the intensity of the reduction in the smelting zone. A basic slag, because of its avidity for silica, will oppose reaction No. 9; it is one of the principal means of making low-silicon pig iron. This is in spite of the fact that the basic slags are sluggish, and therefore trickle slowly through the smelting zone, thus exposing the silica longer to reducing influence, and also increasing the temperature of the materials in this zone (1) by

<sup>1</sup> The burden is the amount of material that the coke has to melt. We lighten the burden by increasing the amount of coke, and *vice versa*.



causing them to pass through it more slowly and absorb more heat, and (2) by reducing the level of the smelting zone nearer to the tuyeres, which confines the intense temperature to the smaller area, or, in other words, diminishes the passage of heat upward.

Sulphur comes into the furnace chiefly in the coke. It is present as dissolved sulphur and as iron sulphide ( $\text{FeS}$ ),<sup>1</sup> which will dissolve in the iron unless converted into calcium sulphide ( $\text{CaS}$ ). This conversion is brought about, according to the explanation of Howe, by the following reaction:



$\text{CaS}$  passes into the slag, and the odor of sulphur is very strong when the slag is running from the furnace. It is evident from reaction No. 10 that intense reduction, which increases the silicon in the iron, has the contrary effect on the sulphur, and this explains the common observation that iron high in silicon is liable to be low in sulphur. Indeed, this relation is so constant that it is almost a rule. There are two exceptions, however: (1) Increasing the proportion of coke has a doubly strong influence in putting silicon in the iron. As regards sulphur, on the other hand, it has a self-counteracting effect; by increasing the amount of sulphur in the charge it tends to increase it in the iron, which is partly or wholly counteracted by its effect in reaction No. 10. (2) A basic slag may hold silicon from the iron, and it also holds sulphur from the iron by dissolving  $\text{CaS}$  more readily. In other respects the conditions which make for high silicon make also for low sulphur. Particularly is this true of a high temperature in the smelting zone, and the term "hot iron" has come to be synonymous in the minds of blast-furnace foremen with iron high in silicon and low in sulphur.

Manganese is reduced by the following reaction:



The amount of manganese in the iron is dependent, to a certain extent, upon the character of the ores charged, but it may be controlled somewhat by the character of slag made, because an acid slag will carry a large amount of manganese away in the form of silicate of manganese ( $\text{MnSiO}_3$ ).

With a certain unimportant qualification, the amount of phosphorus in the iron is controlled by the character of raw materials charged, and districts or countries having high-phosphorus ores must make high-phosphorus irons. This is not an

<sup>1</sup> A. C. POWELL, *Jour. Am. Chem. Soc.*, Jan., 1923.

TABLE V.—COMPOSITION OF BLAST-FURNACE SLAGS AND EFFECT OF FURNACE TEMPERATURE ON IRON COMPOSITION  
(FROM H. H. CAMPBELL, p. 50 of Ref. 2)


Slag							Iron		Remarks	
SiO <sub>2</sub>	Al <sub>2</sub> O <sub>3</sub>	CaO	MgO	FeO	S	Total not including S	Si	S		
1	33.10	14.92	40.76	9.67	.....	.....	98.45	3.37	tr.	Cuban ore, hot furnace.
2	32.27	14.57	41.02	10.30	.....	.....	98.16	3.18	tr.	Cuban ore, hot furnace.
3	24.26	11.53	40.25	13.28	.....	.....	98.32	4.81	0.01	Cuban ore, hot furnace.
4	32.68	13.50	43.28	9.44	.....	.....	98.90	1.25	0.06	Cuban ore, warm furnace.
5	32.28	9.38	46.95	9.52	.....	.....	98.13	0.70	0.11	Cuban ore, cool furnace.
6	34.50	7.94	46.47	10.47	.....	.....	99.38	0.69	0.05	Cuban ore, cool furnace.
7	34.98	12.05	41.33	9.62	.....	.....	97.98	2.60	0.03	Spanish ore, hot furnace.
8	34.70	11.44	41.27	9.96	.....	.....	97.37	2.32	0.02	Spanish ore, hot furnace.
9	33.68	11.93	45.96	6.69	.....	.....	98.26	1.27	0.02	Spanish ore, hot furnace.
10	29.86	12.04	45.20	11.41	.....	.....	98.51	1.27	0.02	Spanish ore, hot furnace.
11	28.95	12.04	49.30	8.46	.....	.....	98.75	0.57	tr.	Spanish ore, cool furnace.
12	30.62	10.47	49.13	7.49	.....	.....	97.71	0.26	0.02	Spanish ore, cool furnace.
13	32.55	11.13	47.16	6.61	.....	.....	97.45	0.15	0.03	Spanish ore, cool furnace.
14	30.08	11.44	46.36	8.76	.....	.....	96.64	0.58	0.03	Spanish ore, cool furnace.
15	31.46	11.50	44.85	10.41	.....	.....	98.22	0.20	0.07	Spanish ore, cool furnace.
16	36.08	12.85	41.69	7.25	0.54	1.62	98.41	2.15	0.020	Lake ore and part anthracite coal; mostly Connelsville coke Hot furnace Fairly hot Fairly hot Fairly hot Normal Normal Cool Cool Lake ore and Connelsville coke. Av. of 8 wks. Av. of 7 wks. Av. of 7 wks.
17	37.19	12.65	35.47	11.32	0.90	1.70	97.53	1.92	0.029	
18	36.86	10.74	42.46	6.62	0.63	1.54	97.31	1.50	0.028	
19	32.06	11.97	42.46	10.25	0.63	1.76	97.37	1.59	0.032	
20	33.57	10.65	44.11	8.55	0.81	1.74	97.69	0.94	0.017	
21	35.38	11.76	38.19	12.32	0.90	1.60	98.53	1.13	0.040	
22	36.35	10.21	40.10	10.95	0.99	1.28	98.60	0.66	0.095	
23	33.70	12.56	38.12	11.60	0.32	0.96	98.30	0.50	0.101	
24	35.11	14.21	22.48	22.38	.....	.....	100.12	1.37	0.048	
25	35.10	14.75	27.95	22.28	.....	.....	100.08	1.85	0.038	
26	35.84	14.34	32.71	17.46	.....	.....	100.35	1.60	0.034	
Averages for hot furnaces:										
	33.21	13.67	40.68	11.08	.....	.....	98.64	3.79	tr.	Cuban ore.
	34.84	11.75	41.30	9.79	.....	.....	97.68	2.46	0.025	Spanish ore.
	31.77	11.98	45.58	9.05	.....	.....	98.38	1.27	0.020	Spanish ore.
	35.55	12.05	40.52	8.86	0.68	1.66	97.66	1.79	0.027	Lake ore.
Averages for moderate or cool furnace:										
	33.15	10.27	45.57	9.81	.....	.....	98.80	0.88	0.07	Cuban ore.
	30.73	11.32	47.36	8.35	.....	.....	97.75	0.35	0.03	Spanish ore.
	34.75	11.30	40.12	10.86	1.26	1.40	98.29	0.81	0.063	Lake ore.
	35.35	14.43	29.69	20.71	.....	.....	100.18	1.61	0.040	Lake ore.

insuperable objection, because the presence of phosphorus, even up to 1.5 per cent, is desired in certain irons for foundry use, and the basic processes for making steel can remove this element.

The chemical influence of the blast furnace is a strongly reducing one, and this is produced in order, first, to reduce the

iron from the ore; second, to get rid of the sulphur, and third, to saturate the iron with carbon. Many attempts have been made to provide a process wherein the reducing influence was not so strong, and thus to produce a purer material than pig iron, because it is the intensity of the reduction which contaminates the iron with carbon and silicon. The great weakness of all such processes, however, is that they do not get rid of the sulphur, which is the most objectionable impurity that iron is liable to contain and which is not cheaply removed by any process after once it makes its way into the iron. Finally, to saturate the iron with carbon renders the blast-furnace operation very much cheaper, because pure iron melts at a temperature much higher than can readily be obtained in the furnace, and iron is handled much more cheaply molten than in the solid or pasty state. Even the presence of silicon is an advantage, as we shall see in Chapter XIII.

**Drying the Blast.**—The water vapor blown into the furnace (derived from the moisture of the air) is equivalent to from  $\frac{1}{3}$  to 2 gal. of water per 10,000 cu. ft. of blast, or  $1\frac{1}{3}$  to 8 gal. per minute, depending on the humidity of the atmosphere. Though this steam is as hot as the blast, it materially cools the smelting zone of the furnace by dissociating there:



or 1 lb. of steam absorbs 722,500 calories. The hydrogen and oxygen reunite in a cooler part of the furnace and return the same amount of heat, but this does not compensate for that taken away from the smelting zone, where it is most needed. For this reason several American and European plants adopted James Gayley's process of drying the air by refrigeration before it is drawn into the blowing engine. This results in valuable saving in fuel and greater regularity of furnace working. In fact, so great is the improvement shown in this respect that there was a tendency at first to receive the results with skepticism.

The same condition prevailed upon the introduction of the hot blast, early in the last century, for the same reasons: That no explanation was forthcoming of the observation that the fuel saved in practice was so much greater in proportion than the heat saved or restored to the crucible. But it was pointed out by J. E. Johnson, Jr., in the discussion of Mr. Gayley's results, that certain functions of the smelting process can only be carried out above a certain "critical temperature," which was in fact the

free-running temperature of the slag, and that the heat available above this temperature, and not the total heat developed in the furnace, is the measure of the economy that can be attained. Approximately speaking, the interval between the "critical temperature" and the theoretical combustion temperature, is the measure of this available heat, and as the critical temperature is, roughly speaking, four-fifths of the theoretical combustion temperature, any change which increases or decreases the latter by a given proportion, will increase or decrease the available heat by a proportion five times as great. This simple explanation enables us to calculate with accuracy the effect of any given change in known conditions.<sup>1</sup>

Johnson also pointed out that the theoretical combustion temperature might be increased by enriching the air in oxygen, instead of reducing the moisture in it, since this enrichment would increase the calorific efficiency.

**Slag Disposal.**—The slag, on account of its lower specific gravity, floats in the bath of iron in the hearth and accumulates until it reaches nearly to the level of the tuyeres. The cinder-notch is then opened by withdrawing the iron plug and piercing the skull of chilled cinder with a steel bar, and the cinder drawn off down to the level of the notch. This is done three to five times between each iron tap, *i.e.*, each 6 hr. It flows down an inclined iron runner for a distance of 15 to 30 ft. and pours into an iron ladle on a standard-gage railroad track, whence it is drawn away by a locomotive and poured out on the slag dump. Slag varies in composition according to the will of the blast-furnace manager, and some typical analyses are given in Table II. Slags high in lime are sometimes treated with additional lime to make a good grade of Portland cement, known as "Puzzolini." The amount of cinder made will depend on the amount of silica, alumina, etc., in the ore, the amount of coke ash, and the amount of flux, which will also depend on the desired slag analysis. Under favorable circumstances, the slag may weigh slightly less than half the iron; under other conditions it may weigh nearly twice the iron, depending on the amount of impurity in the charge.

<sup>1</sup> If further explanation of this argument is needed, it may be found in the following simile: Water boils at 212°F. If the temperature of a boiler is 262°, there is a certain pressure of steam; if we increase the temperature only 50°, we greatly increase the pressure; yet 50° appears small in comparison to 262°.



**Weight of Slag.**—The amount of slag may be calculated from the amount of lime ( $\text{CaO}$ ) in the furnace, which may be calculated from the percentage of lime in the limestone and other materials charged into the furnace. Since all the lime charged goes into the slag, the amount of the latter will be equal to the weight of lime divided by the percentage of the lime in the slag. Thus, if we use per ton of iron 1,300 lb. of limestone, containing 50 per cent of lime, there will be 650 lb. of lime charged for every ton of



FIG. 16.—Liquid iron running from blast furnace into prepared molding floor.

MG = Mud gun to close tap hole.

S = Support for mud gun. D = Dam or "skimmer."

iron made. If the slag made contains 40 per cent lime, then the weight of slag will be  $\frac{650}{0.40} = 1,625$  lb. per ton of iron made.

**Iron Disposal.**—Immediately after the last "flushing," *i.e.*, removal of cinder, the tap-hole or iron-notch is opened by several men drilling a hole in it with a heavy, pointed steel bar. Oxygen is used to burn a hole through frozen, but red-hot, iron in the notch. Out of this notch flows 100 to 150 tons of liquid pig iron, with which is carried along 30 tons or so of slag. The

"skimmer" is situated about a dozen feet from the front of the furnace. It is an iron plate extending down almost to the bottom of the runner. The slag is deflected by this plate into a runner of its own, which leads it off to a slag ladle such as



(From "*The A.B.C. of Iron and Steel Manufacture*")

FIG. 16A.—Liquid iron running from blast furnaces into ladles.

described before. The heavier pig iron flows under the skimmer and is distributed to six or seven brick-lined ladles on a standard-gage railroad track. It is then drawn away to the steel works, or, if not wanted there, is poured into iron molds at the pig-casting machine.

TABLE VI.A.—U. S. PRODUCTION (1923)<sup>1</sup> AND DISPOSAL OF PIG IRON (1920)<sup>1</sup>

	GROSS TONS	PER CENT. OF TOTAL
Basic pig iron.....	19,795,590	49
Bessemer and low phosphorus pig iron.....	11,677,509	29
Foundry.....	6,470,013	16
Malleable <sup>2</sup> pig iron.....	1,571,064	4
Forge pig iron.....	327,430	1/2
Ferromanganese.....	246,231	1/2
Spiegeleisen.....	130,585	
All other grades.....	519,540	1
<hr/>		
Total production (1923).....	40,361,146	100
<hr/>		
Delivered in molten condition.....	22,293,410	60
Machine cast <sup>3</sup> .....	9,203,174	25
Sand cast at blast furnace.....	4,612,446	13
Chill cast <sup>4</sup> at blast furnace.....	784,480	2
Direct iron castings <sup>5</sup> .....	32,477	
<hr/>		
Total production (1920).....	36,925,987	100

<sup>1</sup> The production of the year 1924 was abnormal, due to industrial conditions.

<sup>2</sup> Malleable pig iron—not malleable cast iron (see p. 37 and Chap. XIV)—this is pig iron manufactured so as to be suitable for making malleable iron castings.

<sup>3</sup> See "Mechanical Pig-molding Machine," below.

<sup>4</sup> "Chill Cast" means cast in permanent steel molds set in the floor of the blast-furnace casting house.

<sup>5</sup> "Direct Iron Castings," *i.e.*, castings made of fluid metal from the blast furnace, see Fig. 20, p. 48, dotted line.

**Mechanical Pig-molding Machine.**—There are several types of molding machine, but a common form is illustrated in Figs. 17 and 18, and consists of a long continuous series of hollow metallic molds carried on an endless chain. D is the pig-iron ladle pouring metal into the spout, from whence it overflows into the molds as they travel slowly past. The pig iron chills quickly against the metallic molds, and by the time it reaches the other end of the machine, it consists of a solid pig iron which drops into the waiting railroad car as the chain passes over the sheave. The pig iron is now in a form convenient for transportation or for storing until needed. The molds travel back toward the spout, underneath the machine and hollow side down. At the point C they are sprayed with whitewash, the water of which is quickly dried off by the heat of the mold, leaving a coating of lime inside to which



TABLE VI.B.—ANALYSES OF SOME COMMON GRADES OF PIG IRON

Trade name	Total carbon, per cent	Silicon, per cent	Sulphur, per cent	Phosphorus, per cent	Manganese, per cent
No. 1 foundry.....	3.00 ±	<b>2.75–3.25</b>	<b>0.05</b> & under	0.30–1.50	0.10–1.00
No. 2 foundry.....	3.25 ±	<b>2.25–2.75</b>	<b>0.05</b> & under	0.30–1.50	0.10–1.00
No. 3 foundry.....	3.50 ±	<b>1.75–2.25</b>	<b>0.06</b> & under	0.30–1.50	0.10–1.00
No. 4 foundry.....	3.75 ±	<b>1.25–1.75</b>	<b>0.065</b> & under	0.30–1.50	0.10–1.00
Gray forge.....	3.50 ±	<b>0.75–1.75</b>	<b>0.07</b> & under	Under 1.00	0.10–1.00
No. 1 soft.....	2.50–3.00	<b>3.00</b> & over	<b>0.05</b> & under	0.50–1.50	0.10–1.00
No. 2 soft.....	3.00	<b>2.50–3.25</b>	<b>0.05</b> & under	0.50–1.50	0.10–1.00
Standard acid } Bessemer pig }	3.50–4.00	<b>1.00–1.50</b>	Under <b>0.08</b>	Under <b>0.09</b>	0.20–1.00
Basic pig.....	3.50–4.00	Under <b>1.00</b>	Under 0.08	<b>0.10–1.50</b>	<b>1.00–2.00</b>
Malleable } Bessemer }	3.50 ±	<b>0.75–2.00</b>	Under <b>0.07</b>	Under <b>0.20</b>	0.50 ±
Ferrosilicon <sup>1</sup> .....	0.50–2.00	<b>10.00–50.00</b>	Under 0.04	Under 0.10	0.20 ±
Silico-spiegel.....	1.00 ±	<b>5.00–15.00</b>	Under 0.02	Under 0.10	<b>15.00–25.00</b>
Ferromanganese.....	6.00–7.00	0.50–1.00	Under 0.03	.....	<b>40.00–80.00</b>
Ferrophosphorus.....	1.00 ±	1.50 ±	Under 0.05	<b>10.00–25.00</b>	.....
Spiegeleisen.....	4.50–6.00	1.00 ±	Under 0.04	.....	<b>15.00–35.00</b>

<sup>1</sup> Ferrosilicon of 10 per cent grade, ferromanganese, silico-spiegel, ferrophosphorus and spiegeleisen are made in blast furnaces, by variations of the usual practice and by using special ores. Ferrosilicon of 20 to 50 per cent grades, and several other so-called "ferro-alloys," are made in electric furnaces. These include, ferrochrome, ferrotungsten, ferromolybdenum, ferrotitanium, ferrovanadium, etc. They are all practically pig irons with large amounts of the alloying metal. When these alloys are free from, or low in, carbon they are made by the thermit and other processes.



FIG. 17.—Heyl and Patterson pig-casting machine.

the melted iron will not stick. This mechanical casting is a great improvement over the former method of cooling iron in front of the blast furnace, because of the severity of the work which the former method involved and which, in hot weather, was well-nigh intolerable to human beings. It also gives pigs which are cleaner, *i.e.*, freer from adhering sand. This silicious sand is objectionable, especially in the basic open-hearth furnace.

**Sand-casting.**—This method is still used at some furnaces, because of the capital needed to install machines and their high cost for repairs. Moreover, foundrymen often prefer the sand-cast pig because they are able to tell by the appearance of its fracture what grade of castings it will make, which they cannot well do with iron cast in metal molds (see p. 354). In the sand method, the cast house extends in front of the furnace and its floor is composed of silica sand, in which the molds or impressions to receive the liquid iron are made. The main runner extends from the tap-hole down the middle of the floor, and the space on either side of it is used alternately for alternate castings. The plan of the arrangement is shown in Fig. 19.



FIG. 18.—Uehling pig-casting machine.

After cooling the iron, the pigs are broken away from the sows, which are also broken into pieces, and then all is carried over and thrown into a railroad car. In making "basic iron"—*i.e.*, iron for the basic open-hearth steel process—the molds for the sows and pigs are permanently made of metal, so that the iron is "chill cast" and will not carry sand into the basic hearth.

**Irregularities in Blast-furnace Working.**—Although the management and control of the operation is in general as I have described it, the blast furnace is by no means a perfect machine, and great difficulties arise in the working of the furnace and in maintaining a uniform grade of product. The chief of these difficulties results from localized chilling of the semi-molten charge. This is most liable to happen in the upper part of the

smelting zone, where a lump of pasty material may attach itself to the walls of the furnace. This has the effect of hindering the




FIG. 19.—Pig beds.

descent of that part of the charge above it and of deflecting the hot gases to other parts of the furnace. The result of the first

action is to disarrange the order and evenness with which originally horizontal rings of stock come down into the hearth. The obstruction is also liable to receive chilled materials from above and to build itself out toward the center. When the furnace is working badly, these scaffolds may occur at two or more places at the same time and cantilever out toward the middle. This will cause a "hanging" of the charge, and may become so bad as to cause a complete arch over the smelting zone, through which it is impossible to drive the blast. Sometimes the scaffold may be broken down by suddenly cutting off the blast pressure and allowing the full weight of material in the furnace to come upon the obstruction; but sometimes it is necessary to cut a hole in the wall of the furnace and melt it out with a blow-pipe burning oil or gas, or with some other form of heat.

The "scaffolding" of a furnace and hanging of the charge is more liable to happen when large percentages of the earthy Mesabi ores are used, and in this type of practice localized hanging and slips are not infrequent. When the slip is extensive in character and a large amount of material is suddenly precipitated into the hearth, the upward rush of gases resembles an explosion inside the furnace and may do damage to the charging apparatus and throw a part of the stock out of the top of the furnace. Some furnaces are provided with explosion doors, which fly open under pressure and relieve the strain; while the practice in other instances is to fasten everything down as tight as possible and prevent the rapid escape of the gases.

There is also a large amount of hanging due to the action of the blast in tending to drive the stock before it up into the stack of the furnace and thus compress it. This action is more liable to take place with fine ores.

Cooling of the charge also results in some cases in the freezing of material over the mouths of the tuyeres. The solid layer may sometimes be broken away with a bar, and the blow thus allowed to continue until more heat can be brought down into the hearth. Sometimes it is necessary to melt out the frozen material with a blow-pipe, and in extreme cases it may even be necessary to break through it with explosives.

Another difficulty sometimes met is the freezing up of the metal in the lower part of the hearth, so that it is impossible to open the tap-hole. Then a new tap-hole must be made by boring through the front of the furnace at a higher level, from which the



iron is drained, and then the heat is gradually worked down until the whole hearth is melted out and normal conditions reestablished. The bad work of a furnace is often cumulative in its effects, because irregularities in the smelting zone have an effect upon the top gases, which, in turn, derange the work of the stoves and hence impair the hot blast.

These irregularities in the smelting have a disturbing effect upon the character of the iron made, and the changes sometimes come suddenly and without warning. For instance, a sudden precipitation of cold material into the hearth will chill the smelting zone and cause the silicon in the iron to be low and the sulphur high. The same effect will be produced by the leakage of several gallons of water into the hearth through the burning out of a tuyere or the cooling-ring of one of the tuyeres.<sup>1</sup>

**Dimensions of Blast Furnace.**—The size of a modern blast furnace is limited by the conditions of its work; the hearth may not be much more than 19 ft. in diameter, else the blast from the tuyeres will not be distributed evenly to the center; the batter of the bosh walls cannot be much more nor less than a certain amount, because they must give support to the charge above them, and yet allow the solid coke to slip down; the height of bosh is limited, because its top must be practically the same as the top of the smelting zone—that is, no solid material except coke should descend into the bosh. These conditions therefore limit the diameter of the top of the bosh to not much more than 25 ft. From the bosh the stack walls must decrease in diameter upward in order that the descending charge, which swells in the reactions that take place from the throat downward, shall not become wedged in the stack; as the throat must have a sufficiently large diameter to charge the materials properly, this limits the height of the stack. Modern furnaces are therefore usually built about 90 ft. in height, and exceeding that limit has resulted in some cases in a decrease rather than an increase of fuel economy. Moreover, increasing the height of the furnace increases the necessary blast pressure much faster than the weight of the charge

<sup>1</sup> In my early days at the blast furnace I was once informed by the assistant manager that, on one occasion, he tapped several tons of water from the tap-hole with the iron. Whether he was himself deceived or whether he was merely trying to test me, I have never been able to decide; but the fact is worthy of mention in an elementary treatise to illustrate the character of the tales to which even the educated men around a plant will treat a novice.

column so the height is soon reached at which the furnace can work only irregularly if at all.

### MAKING CHARCOAL PIG IRON

Charcoal is used as a blast furnace fuel for either of two reasons: (1) Coke is scarce; (2) purer pig iron can be made with charcoal, because of the sulphur contained in coke. In the United States we are chiefly concerned with the latter reason, and it is important that charcoal blast-furnace manufacture is closely allied to chemical manufacture, because the profit in the industry is due almost entirely to the chemical by-products recovered when wood is charred. This puts charcoal furnace practice in a class by itself, especially as it represents but 1 per cent of the production of the country. Because of its purity it usually sells for 25 per cent to 30 per cent higher price than coke pig iron. In Sweden charcoal pig iron is made because of the scarcity of coke as fuel, and there it is the chief product.

Charcoal has several advantages: (1) Its sulphur is only a few hundredths of 1 per cent, as compared with 1 per cent or more in coke. Its ash is only 1 per cent, as compared with 10 per cent or more in coke; (2) what ash there is is basic, instead of acid, and so the amount of flux necessary is greatly reduced. It has two disadvantages: (1) Its strength is low, so that charcoal furnaces must be small, because the fuel bed will not support a tall charge; (2) it contains some 30 per cent of volatile matter, consisting of hydrogen and other gases. The sulphur content of charcoal pig iron runs from 0.01 to 0.02 per cent.

Pig is produced with about 100 bushels (say, 2,000 lb.) of charcoal per gross ton of iron, and about 226 lb. of flux. The slag volume is small, because there is not much impurity to flux off, and the temperature is low, because we do not need to melt a basic (and, therefore, refractory) slag. Almost any slag with a low "free running" temperature can be used in a charcoal furnace, and Johnson says he has used them with anywhere from 40 to 60 per cent of silica.

This possibility of low temperature permits charcoal iron to be made with unheated blast, in little furnaces producing from 5 to 10 tons per day. This "Cold-blast Charcoal Iron" is preferred by many and commands a bonus in price, because of its strength and excellent chilling qualities (see p. 371). "Warm-

blast Charcoal Iron" is made with the air heated to from 500 to 1,000°F. (=260 to 538°C.). Chilled iron rolls are usually made of charcoal iron, because this is almost the only way we can get low-sulphur iron which is also low in silicon, the latter feature being important to insure deep chilling.

### CALCULATING A BLAST-FURNACE CHARGE

This subject is of prime importance to young metallurgists, because the ability to calculate a charge is sometimes a cause of advancement, and the knowledge of the way to do so is not always obtainable from one's superior.

**Assumptions.**—Let us assume that we desire to produce a slag containing 55 per cent lime, 15 per cent alumina, and 30 per cent silica, these proportions being determined by the experience of the manager, and that the materials from which the charge is to be made analyze according to Table VIC. Assume furthermore that the coke ash is equal to 10 per cent of the coke, and that the iron we are going to make will contain about 1 per cent silicon.

TABLE VIC.—ANALYSES OF MATERIALS USED

Material	Per cent CaO	Per cent MgO	Per cent Al <sub>2</sub> O <sub>3</sub>	Per cent SiO <sub>2</sub>	Per cent Fe <sub>2</sub> O <sub>3</sub>	Per cent Fe
Ore A.....	5	4	2	11	..	60
Ore B.....	2	..	12	16	..	50
Coke ash.....	20	..	18	50	..	10
Limestone.....	46	4	2	4	..	2

**Silicon in the Iron.**—This last assumption necessitates our allowing a corresponding amount of silica, because the silica reduced and absorbed by the iron will not be available for slag-making purposes. One per cent of silicon is roughly equal to 2 per cent of silica; we may therefore make the requisite allowance by subtracting from the silica in each material an amount equivalent to 2 per cent of its iron content. Thus we begin to make up Table VII.

**Magnesia.**—In considering slags, magnesia is classified under the head of lime, thus obtaining column 2 in Table VII.



TABLE VII.—ANALYSES AFTER ALLOWING FOR SILICON IN PIG

Material	Per cent CaO	Per cent Al <sub>2</sub> O <sub>3</sub>	Per cent SiO <sub>2</sub>
Ore A.....	9	2	10
Ore B.....	2	12	15
Coke ash.....	20	18	50
Limestone.....	50	2	4

**Self-fluxing of Materials.**—It is evident that in so far as each of the materials in Table VII contains all the components of the slag, they will partially flux themselves. For example, the 2 per cent of alumina in ore A will theoretically combine with 4 per cent of the silica ( $2 \text{ per cent} \times \frac{30}{15} = 4 \text{ per cent}$ ) and 7 per cent of the lime ( $2 \text{ per cent} \times \frac{55}{15} = 7.3 \text{ per cent}$ ) to make a slag of the desired proportions, leaving unfluxed percentages as per the first line of Table VIII. In the same manner we may use up all of the lime in ore B by uniting it with weights of alumina and silica in proportion to the percentages of these components in the slag. Similar simplifications in the analyses of coke ash and limestone may then be calculated, and Table VIII will be completed.

TABLE VIII.—ANALYSES AFTER SELF-FLUXING

Material	Per cent CaO	Per cent Al <sub>2</sub> O <sub>2</sub>	Per cent SiO <sub>2</sub>
Ore A.....	2	....	6
Ore B.....	..	11.5	14
Coke ash.....	..	13.0	39
Limestone.....	43		

**Weight of Charge.**—Let us assume that we are going to make 1 ton of pig iron for every ton of coke used in the charge, and that the coke will be put in in charges weighing 11,000 lb. each. This weight includes about 10 per cent of moisture, dust, etc.,<sup>1</sup>

<sup>1</sup> This assumes that the breeze (or "braize") is removed after weighing the coke. If it is removed before, allow only 3 per cent excess, which makes coke charges = 10,300 lb.

so we calculate with it as if it weighed only 10,000 lb. Now let us determine how much ore will be put in each charge: The ores average 55 per cent of iron; therefore,  $\frac{10,000 \text{ lb.}}{55 \text{ per cent}} = 18,000 \text{ lb.}$ , the amount of ore that must be in each charge, according to the assumption of this paragraph.

**Adjusting the Alumina and Silica.**—Next adjust the different materials so that the weight of alumina shall be  $\frac{15}{30}$  of the weight of silica. In the first rough approximation of this we may neglect the coke ash, because the weight of this ash is so small in relation to the other materials. Therefore only the two ores need be apportioned, and we quickly find by trying a few mixtures at random that 60 per cent of ore A mixed with 40 per cent of ore B will give the desired relation:<sup>1</sup> 60 per cent  $\times 6 + 40 \times 14$  per cent = 920 parts of silica; 60 per cent  $\times 0 + 40$  per cent  $\times 11.5 = 460$  parts alumina;  $\frac{460}{920} = \frac{15}{30}$ . Now draw Table IX, and enter 10,800 lb. of ore A (= 60 per cent of 18,000), 7,200 lb. of ore B, 1,000 lb. of coke ash (= 10 per cent of 10,000), and the percentages from Table VIII. All the weights in this table may then be filled in except those of the limestone and total CaO.

To obtain the total number of pounds of lime:

$$\text{Al}_2\text{O}_3: 958 \times \frac{55}{15} = 3,513 \text{ lb.}$$

$$\text{SiO}_2: 2,046 \times \frac{55}{30} = 3,751 \text{ lb.}$$

Average of 3,515 and 3,751 is 3,632.

TABLE IX.—ESTIMATED WEIGHTS OF MATERIALS USED

Material	CaO			Al <sub>2</sub> O <sub>3</sub>		SiO <sub>2</sub>	
	Weight	Per cent	Pounds	Per cent	Pounds	Per cent	Pounds
Ore A.....	10,800	2	216	....	...	6	648
Ore B.....	7,200	..	.....	11.5	828	14	1,008
Coke ash.....	1,000	..	.....	13.0	130	39	390
	<i>C</i>		<i>B</i>				
Limestone.....	7,940	43	3,416				
			<i>A</i>				
Total, pounds....	.....	..	3,632	....	958	..	2,046

<sup>1</sup>Try first 50 per cent of each, and we see that there is too much alumina; therefore try less than 50 per cent of the ore having the most alumina, and correspondingly more of the other, and we have it.

**Adjusting for Lime.**—It is now only necessary to determine the amount of total lime that shall bear the correct relation to the alumina and silica calculated. This we do by means of the method shown in the figures above Table IX. We enter this in the square *A* of Table IX. The figures at the square *B* are then obtained ( $3,632 - 216 = 3,416$ ), and thence the weight of limestone to be used—( $3,416 \div 43$  per cent = 7,940).<sup>1</sup>

**Checking the Calculations.**—We now check up all the calculations by making up Table X, in which we go back to the original percentages found by chemical analysis and given in Table VI. In making up this final table, however, we use our experience in making slag calculations and estimate slight changes: For example, Table IX shows us that the alumina comes a little low in relation to silica; therefore we increase ore B, say, by 400 lb. and decrease ore A correspondingly. But ore A is high in lime; therefore we use a little more limestone to offset this reduction.

These figures are much closer to those desired than the limit of accuracy in furnace operation. The chief difference is that we

TABLE X.—FINAL ESTIMATE OF CHARGE

Material	CaO + MgO			Al <sub>2</sub> O <sub>3</sub>		SiO <sub>2</sub>		Fe	
	Weight	Per cent	Pounds	Per cent	Pounds	Per cent	Pounds	Per cent	Pounds
Ore A.....	10,400	9	936	2	208	11	1,144	60	6,240
Ore B.....	7,600	2	152	12	912	16	1,216	50	3,800
Coke ash.....	1,000	20	200	18	180	50	500	10	100
Limestone.....	8,200	50	4,100	2	164	4	328	2	164
Total weights.....	..	..	5,388	..	1,464	..	3,188	..	10,304
			= 51.8 per cent		= 14.9 per cent		-206( = 2 per cent $\times$ 10,304)		
							2,982 = 30.3 per cent		

<sup>1</sup> In practice this is often much simplified by taking the Al<sub>2</sub>O<sub>3</sub> simply as fixed, within wide limits, and figuring merely the ratio of CaO and MgO to SiO<sub>2</sub>; disregard Al<sub>2</sub>O<sub>3</sub>, unless it is abnormally high, and therefore bad for physical reasons. If a constant limestone is used all such calculations are much simplified by figuring the net CaO and MgO in the stone after the SiO<sub>2</sub> in the stone is satisfied.

If a given ratio of CaO + MgO to SiO<sub>2</sub> be desired it is only necessary to add up the SiO<sub>2</sub> in ore and fuel, multiply by the desired ratio and divide by the efficiency of the stone. The net SiO<sub>2</sub> in the ores should be taken, that is, the SiO<sub>2</sub> fluxed by the bases in the ore should be deducted.

are making a little more iron with 10,000 lb. of coke than we intended. If any change seems necessary it is then well to reduce the weight of ore A to 10,000, leaving everything else the same. This will lighten the burden and bring the calculated lime, alumina and silica even closer to the desired figures.

**Phosphorus and Manganese.**—No account of the phosphorus has been taken in the calculation above. This is necessary sometimes. For example, if ore A happened to be very high in phosphorus we could not use so large a proportion of it. It would then be necessary either to secure another ore low in both phosphorus and alumina, or else to make a slag with less alumina. The same line of reasoning applies to manganese, but to less extent because the manganese in the iron can be controlled by the work of the furnace to a considerable extent, and in no event does more than two-thirds of that in the charge go into the iron.

#### LABOR AT BLAST FURNACES

At an old-fashioned type of blast furnace, casting in sand, without mechanical devices to carry or break the pigs, as little as 200 to 250 tons of pig iron per 24 hours would require about 15 men in front of the furnace, including a keeper, first helper, 5 assistant helpers, who open and close the tap hole, break the pigs from the sows and do the general cast house work, 5 men to carry iron, a "cinder snapper," a scrap man and a stove man. This labor would be required for each shift. Back of the furnace there must be a scale man to weigh stock, and 18 men on the ground besides 3 "top fillers" to handle material for burden, provided it is done in the old-fashioned manner.

On the other hand, at a furnace with mechanical devices for casting and for handling stock, more than twice as much pig iron can be made with  $4\frac{1}{2}$  to  $6\frac{1}{4}$  men in front of the furnace, per shift, consisting of: 1 "blower" for each 2 to 4 furnaces, 1 keeper, 1 helper, 1 "cinder snapper," 1 "flue dust man," 1 hot blast stove man. Sometimes another man is required, called a "scrap man," or, perhaps, a laborer. With oxygen for burning out the red-hot iron in the tap hole, mud gun, short runners to slag and metal ladles, etc., one furnace is able to get along with 4 men and a fraction of a "blower" per shift. Back of the furnace a scale car man is required, but, with mechanical handling to ore pockets and to the furnace top, about 5 to 6 men per shift per furnace can handle the stock to make 700 long tons of pig iron in 24 hours.

## CHAPTER III

### THE PURIFICATION OF PIG IRON

The large amount of carbon in pig iron makes it both weak and brittle, so that it is unfit for most engineering purposes. It is used for castings that are to be subjected only to compression, or transverse or very slight tensile strains, as, for example, supporting columns, engine bed-plates, railroad car wheels, water mains, etc., but the relatively increasing amount of steel used shows the preference of engineers for the stronger and more ductile material.




FIG. 20.—Skeleton of iron and steel manufacture.

Today three-fourths of the pig iron made in the United States is subsequently purified by the Bessemer, open-hearth or puddling processes. Each of these will reduce the carbon to any desired point, while the silicon and manganese are eliminated as a necessary accompaniment of the reactions—indeed, we might almost say as a condition precedent to carbon reduction. Phosphorus and sulphur are reduced by the puddling process, and by



a special form of open-hearth process known as "the basic open-hearth process."<sup>1</sup> The complete scheme of American iron and steel manufacture is given in Fig. 20.

**Explanation of Fig. 20.**—Practically all the iron ore mined is smelted in blast furnaces to produce pig iron. About 25 per cent of the pig iron is used in the form of castings without purification, and 75 per cent is purified and converted into another form.<sup>2</sup> In all cases of purification the impurities are removed by oxidizing them, and we must again emphasize the rule that unoxidized elements dissolve in the metal, while those in the oxidized condition pass into the slag, or, if there is no slag, form a slag for and of themselves. In considering the Bessemer, open-hearth and puddling processes then, we have to do with oxidizing conditions, whereas the opposite was the case in the blast furnace. The oxidation is effected by means of the oxygen of the air or that of iron ore ( $\text{Fe}_2\text{O}_3$ ), or its equivalent, or of both air and oxide of iron.

There is not an exact relation between the amounts of pig iron used for the different purposes and the amounts of the resulting materials. In 1920 the production shown in Table XI was made.

TABLE XI.—PRODUCTION FOR 1920  
(Long tons)

	Pig iron used	Made
Malleable cast iron <sup>4</sup> .....	1,600,000 <sup>3</sup>	2,000,000 <sup>3</sup>
Gray cast iron.....	7,500,000 <sup>3</sup>	10,000,000 <sup>3</sup>
Acid Bessemer steel <sup>1</sup> .....	9,771,396	8,883,087
Basic open-hearth steel.....	16,737,722	31,375,723
Acid open-hearth steel.....	500,000 <sup>3</sup>	1,296,272
Wrought iron.....	800,000 <sup>3</sup>	1,377,566
Crucible steel.....	.....	72,265
Electric steel and other.....	.....	505,687
Total.....	36,909,118	55,510,600

<sup>1</sup> The basic Bessemer process is not in operation in America.

<sup>2</sup> Only 40 per cent is allowed to become solid (see p. 36).

<sup>3</sup> Estimated.

<sup>4</sup> It is true that the annealing process for malleable cast iron purifies the outer layers of the castings from carbon, and, if the castings are very thin, this purification may extend to the center; but this is not primarily a purification process and will be treated at length in another section.

The reason for this discrepancy is found in the scrap iron or steel mixed with the pig iron in the manufacture of gray-iron

castings and open-hearth steel. Perhaps an average of 25 per cent of old scrap will be mixed with 75 per cent of new pig iron for making iron castings, and 50 per cent or so of steel scrap will be mixed with 50 per cent or so of pig iron in the basic open-hearth process, while wrought iron is often made by the piling and rerolling of old wrought-iron scrap.

**Bessemer Process.**—In the Bessemer process, perhaps 15 tons of melted pig iron is poured into a hollow pear-shaped converter




FIG. 21.—Section through Bessemer converter while blowing.

lined with silicious material. Through the molten material is then forced 30,000 cu. ft. of cold air per minute. In about 4 min. the silicon and manganese are all oxidized by the oxygen of the air and have formed a slag. The carbon then begins to oxidize to carbon monoxide ( $\text{CO}$ ) and this boils up through the metal and pours out of the mouth of the vessel in a long brilliant flame. After another 6 min. the flame shortens or “drops;”

the operator knows that the carbon has been eliminated to the lowest practicable limit (say 0.04 per cent) and the operation is stopped. So great has been the heat evolved by the oxidation of the impurities that the temperature is now higher than it was at the start, and we have a white-hot liquid mass of relatively pure metal. To this is added a carefully calculated amount of carbon to produce the desired degree of strength or hardness, or both; also about 1.0 per cent of manganese and 0.15 per cent of silicon.<sup>1</sup> The manganese is added to remove from the bath the



FIG. 22.—Blowholes or gas-bubbles in steel.

oxygen with which it has become charged during the operation and which would render the steel unfit for use. The silicon is added to get rid of the gases which are contained in the bath. After adding these materials, or "recarburizing" as it is called, the metal is poured into ingots, which are allowed to solidify and then rolled, while hot, into the desired size and form. The characteristics of the Bessemer process are: (a) Great rapidity of purification (say 10 min. per "heat"); (b) no extraneous fuel is used; and (c) the metal is not melted in the furnace where the purification takes place.

**Acid Open-hearth Process.**—The acid open-hearth furnace is heated by burning within it gas and air, each of which has been highly preheated before it enters the combustion chamber. A

<sup>1</sup> In the case of making rail steel.

section of the furnace is shown in Fig. 23. The metal lies in a shallow pool on the long hearth, which is lined with silicious material, and is heated by radiation from the intense flame. The impurities are oxidized by the slag lying on top of the metal. This action is so slow, however, that the carbon in the pig iron takes a long time for combustion. The operation is therefore




FIG. 23.—Diagram of regenerative open-hearth furnace.

The four regenerative chambers below this furnace are filled with checkerwork of brick around which the gas and air may pass. Before the furnace is started these bricks are heated up by means of wood fires. The gas enters the furnace through the inner regenerative chamber on one side and the air enters through the outer one on the same side. They meet and unite, passing through the furnace and thence passing to the chimney through the two regenerative chambers at the opposite end. In this way the brickwork in the outgoing chambers is heated still hotter by the waste heat of the furnace. The current of gas, air, and products of combustion is changed every 15 min., whereby all four regenerators are always kept hot. The gas and air enter the furnace in a highly preheated condition and thus give a greater temperature of combustion, while the products of combustion go out to the chimney at a relatively low heat and thus fuel economy is secured.

hastened in two ways: (a) Iron ore is added to the bath to produce the reaction,



and (b) the carbon is diluted by adding with the furnace charge large proportions of steel scrap, often as much as 75 to 90 per



cent. It takes about 6 to 10 hr. to melt and purify a charge. The manganese and silicon go into the slag first; then the carbon boils off as a gas. When this has proceeded to the desired point we recarburize and cast the metal into ingots. The characteristics of the acid open-hearth process are: (a) A long time occupied in purification; (b) large charges are treated in the furnace (the modern practice is usually 15 to 100 tons to a furnace); (c) at least a part of the charge is melted in the purification furnace; and (d) the furnace is heated with preheated gas and air.

**Basic Open-hearth Process.**—The basic open-hearth process is similar to the acid open-hearth process, with the difference that we add to the bath a sufficient amount of calcined limestone to form a very basic slag. This slag will dissolve all the phosphorus that is oxidized, which an acid slag will not do.<sup>1</sup> The characteristics of the basic open-hearth process are the same as those of the acid open hearth, with the addition of: (e) Lime is added to produce a basic slag; (f) the hearth is lined with basic, instead of silicious material, in order that it may not be eaten away by this slag; and (g) impure iron and scrap may be used, because phosphorus and, to a limited extent, sulphur can be removed in the operation.

**Puddling Process.**—Almost all the wrought iron today is made by the puddling process, invented by Henry Cort about 1780, with certain valuable improvements made by Joseph Hall 50 years later. In this process the pig iron is melted in a reverberatory furnace the hearth of which is lined with oxide of iron. During the melting there is an elimination of silicon and manganese and the formation of a slag which automatically adjusts itself to a very high content of iron oxide by absorption from the lining. After melting, the heat is reduced and a reaction set up between the iron oxide of the slag and the remaining silicon, manganese, carbon, phosphorus and sulphur of the bath, whereby the impurities are oxidized and all removed to a greater or less extent. The slag, because of its basicity (by iron oxide), will retain all the phosphorus oxidized, and therefore the greater part of this element may be removed. The sulphur is the least

<sup>1</sup> We can oxidize the phosphorus in any of these processes, but in the acid Bessemer and the acid open-hearth furnaces the highly silicious slag rejects the phosphorus, and it is immediately deoxidized again and returns to the iron.



removable of the impurities. The oxidation of all the impurities is produced chiefly by the iron oxide in the slag and the lining of the furnace, although it is probable that excess oxygen in the furnace gases assists the slag.



FIG. 24.—500-lb. puddling furnace.

The purification finally reaches that stage at which the utmost heat of the furnace is not sufficient to keep the charge molten, because iron, like almost every other metal, melts at a higher temperature the purer it is. The metal therefore “comes to nature,” as it is called, that is to say, it assumes a pasty state. The iron is rolled up into several balls, weighing 125 to 180 lb.





FIG. 25.—Method of piling muck bar.

apiece, which are removed from the furnace, dripping with slag, and carried over to an apparatus, where they are squeezed into a much smaller size and a large amount of slag ejected from them. The squeezed ball is then rolled between grooved rolls to a bar, whereby the slag is still further reduced, so that the bar contains at the end usually about 1 or 2 per cent. This puddled bar, or

"muck bar," is cut into strips and piled up, as shown in Fig. 25, into a bundle of bars which is bound together by wire, raised to a welding heat, and again rolled into a smaller size. This rolled material is then known as "merchant bar," and all wrought iron, except that which is to be used for manufacture into crucible steel, is treated in this way before sale. The effect of the further



Transvers Section E F

FIG. 26.—Heroult electric refining furnace.

rolling is to eject more slag, and also to make a cross network of fibers, instead of a line of fibers all running in the same direction, *i.e.*, lengthwise of the bar. The fibers are produced by the action in rolling of drawing out the slag into strings as shown in Micrograph, Fig. 35, p. 76.

**Electric Process.**—The electric process has increased much more rapidly than any other during the past decade, due to its power of holding a bath of metal without either oxidizing or

agitating it. The quietness, or lack of agitation, permits the steel to free itself from microscopic particles of slag, oxides, sulphides, etc., which only in part separate by gravity in the ladle of the open hearth or Bessemer processes. The lack of oxidation permits a slag to be maintained practically free from oxide of iron; such a slag will remove both sulphur and oxygen from the bath. Thus the furnace is advantageous for "super-refining" metal from the Bessemer or open-hearth processes. More rarely it is used for refining pig iron, or for melting and refining steel scrap, but these are uses adapted to special conditions in localities removed from iron and steel centers. An illustration of an electric furnace is given in Fig. 26, showing the graphite electrode, which brings the current into the furnace through the roof. The arcs formed between this electrode and the bath are the source of heat, and the temperatures obtainable in this way exceed those obtainable in the Bessemer or open-hearth processes.

#### MISCELLANEOUS PURIFICATION PROCESSES

**Bell-Krupp Process.**—The late Sir I. Lowthian Bell devised a process in which liquid pig iron is violently stirred up with iron oxide, producing a slag which carries away in the course of from 7 to 10 min. more than 90 per cent of the silicon and phosphorus in the metal. As soon as carbon begins to burn the process is stopped, and therefore there is almost no reduction in this element. The operation is conducted on the revolving hearth of a mechanical puddling furnace, into which the melted iron is poured while the hearth is rotating at 11 r.p.m. The temperature is lower than that of the open-hearth process, in order that the elimination of phosphorus may be rapid (see pp. 71 and 118). At low temperatures phosphorus oxidizes ahead of carbon; at higher heats, carbon oxidizes in preference to phosphorus.

The purified metal is used to some extent in the manufacture of crucible steel. During recent years, when the low phosphorus ores of America have become more scarce and the price of Bessemer pig iron is consequently increased, the metal has been bought to a limited extent by foundrymen using the acid open-hearth process or the baby Bessemer process for the production of steel castings.

**Finery Fire.**—This furnace is known under various names, such as "refinery hearth," "running-out fire," "finery fire," etc. It

consists of a shallow, rectangular hearth, surrounded on the sides by water-cooled, hollow blocks of iron about 3 to 3½ ft. long by 2 ft. wide and 24 to 30 in. deep. In and above this hearth is built a fire of coke upon which is placed 500 or 600 lb. of pig iron. The coke is burned by a blast at 2 to 3 lb. pressure from 2 to 3 tuyeres on each side, and the pig iron gradually melts and sinks below it. When this takes place, more coke and pig iron is placed upon the top, and the operation repeated. A bath of pig iron forms in the hearth, and upon this the blast from the tuyeres impinges. This oxidizes the silicon in the metal, and also a large amount of iron, phosphorus, and sulphur. A slag high in iron oxide, and therefore very basic, is formed. As the temperature is low, phosphorus is eliminated without burning much carbon, and the result is the production of a purified iron still high in the latter element.

It takes about 2 hr. to perform this purification, and then the metal is tapped out from the tap-hole in the front. It usually runs into a long, shallow trough, whence the name "running-out fire;" but sometimes the refined metal is not allowed to cool, but is run directly into the furnace in which the purification is to be completed. The consumption of coke in this first furnace is about one-eighth of the metal produced, and the loss from 5 to 20 per cent, depending upon the purity of the iron treated.

The running-out fire is frequently used in connection with the charcoal finery, known as the "knobbling fire," to produce knobbed charcoal-iron, which is employed especially for boiler tubes and to a less extent for boiler plate, wire, rivets, etc. Running-out fires for this purpose are, however, often known as "melting fineries," because in them the pig iron is melted before it goes to the knobbling fire.

**Melting Finery.**—In the melting finery there are usually two tuyeres in the back, and the melted metal, after an operation similar to that described above, is run directly into two charcoal fineries.

**Charcoal Fineries.**—The charcoal fineries, or "knobbling fires," are similar in general to Fig. 27, but have only one tuyere, situated in the back. They take a charge of 250 lb. apiece. During the transfer from the melting finery the slag is separated from the metal as well as possible, but some gets into the charcoal fineries. It is allowed to solidify and then is removed. Upon the metal is now charged some damp charcoal. The cold blast is turned on and the metal constantly agitated and raised



from the bottom so as to bring it in contact with the blast. Charcoal is added from time to time and is kept damp to avoid loss, and the slag is removed at intervals, but there must always be a layer of slag between the metal and charcoal. As the metal comes to nature, it is pressed together with the pointed bar, like a crowbar, which is used for the agitation and raising. At the end of about  $1\frac{1}{2}$  hr., the ball is withdrawn and hammered.




FIG. 27.—Melting finery.


The cinder from the knobbling fire is usually charged into the melting finery.

The great advantages of knobbled iron as compared to puddled iron are its softness and relative freedom from slag. Also it is often lower in phosphorus and sulphur. Tubes made of this material may be flanged out very extensively without showing any cracks, and rivets will flow easily when hammered cold.



**Walloon Process.**—In the Swedish Lancashire or Walloon process, the long pigs of metal are fed slowly down into the fire, so that it is not necessary constantly to pry them up with bars. The charges are smaller and the product is more liable to be heterogeneous, because the first melted metal is decarburized more than the last, and this heterogeneity is not removed by the remelting (see Fig. 28).

The "Walloon process" is used in Sweden for making bar iron from the very pure pig iron reduced from Dannemora iron



(From Howe, "The Metallurgy of Steel")

FIG. 28.—Swedish Walloon charcoal hearth.

ore. This bar iron is used in Sheffield, England, for conversion into blister-steel, and some of the steel-makers pay a large price for it, in the belief that it has a certain intangible "body" not contained in wrought iron from any other process, and which makes a superior quality of steel. It is probable, however, that this body is wholly imaginary.

#### COMPARISON OF PURIFICATION PROCESSES

**Acid with Basic Open Hearth.**—Acid open-hearth steel is believed by engineers to be better than basic, and is usually specified for all important parts of structures although not so rigidly today as a few years ago. This is in spite of the fact that phosphorus and sulphur, two very harmful elements, are lower in the basic steel. The basic process is less expensive than the

acid, because high phosphorus pig iron and scrap are cheap, and the lower cost of materials used more than balances the greater cost of the basic lining and the lime additions. Acid steel is preferred by many, however, because of relative freedom from oxygen and "sonims" (see p. 206) and because:

(a) A basic slag will dissolve silicon from the metal; we therefore recarburize in the basic process by adding the recarburizer to the steel after it has left the furnace, instead of in the furnace, as we do in the acid process. Should any basic slag be carried over with the metal, however, which is liable to happen, there is the danger that the ingots will be too low in silicon. They are then impregnated with gas bubbles, or "blowholes." Indeed the last part of a heat of basic steel teemed from a ladle will be lower in silicon and manganese and higher in phosphorus and sulphur, as later indicated in discussing the basic process. A goodly proportion of the acid open-hearth steel made in America goes into steel castings, which receive no mechanical treatment before going into service. In such products, of course, the presence of blowholes is most harmful; hence, the predominant use of the acid process, although this predominance in point of tonnage is now being lost. Even the acid Bessemer process, modified as explained under the chapter on "Founding," gives a product for castings, which, from the viewpoint of freedom from blowholes, is preferred to the basic open hearth.

(b) Moreover, the recarburizer does not mix with the steel as well if it is not added in the furnace, because of the stirring in pouring, and this sometimes produces irregularities.

(c) A basic slag is more highly oxidized than an acid slag; therefore the metal at the end of the operation is more highly charged with oxygen. For this reason we add a larger amount of manganese in the recarburizer, but the remedy is never quite so good as prevention.

(d) Since we cannot remove the phosphorus from the bath in the acid process, it is necessary to use only picked iron and scrap, whereas, in the basic process, good steel can be made from almost any quality of material. Many engineers believe, however, that a better grade of steel results from using the picked material.

(e) It occasionally happens in the basic process, after the phosphorus has all been oxidized in the slag and the operation is ended, a good deal may get back into the metal again. This is especially liable to happen when basic slag is carried over into the

ladle before the recarburizer is all in. If this occurs, and if the bath is very hot, a reaction may take place between the basic slag and the acid lining of the ladle. In this way the slag will be enriched in silica and phosphorus will be forced out of it into the metal (see p. 149).

**Basic Open Hearth with Bessemer.**—Basic open-hearth steel is better than Bessemer steel. The reasons for this are believed to be:

(a) The open-hearth process being slower, more attention and care can be given to each detail. This is particularly true of the ending of the process, for if the Bessemer process is continued only a second or so too long, the bath is highly charged with oxygen, to its detriment, and even under normal circumstances there is more oxygen in the metal at the end of the Bessemer process than at the end of the basic open hearth, because there has been so intimate a mixture between metal and air.

(b) For the same reason the Bessemer metal is believed to contain more nitrogen and hydrogen,<sup>1</sup> which are thought to be deleterious.

(c) The heat of the Bessemer process is dependent upon the impurities in the pig iron, and especially upon the amount of the silicon, and can be controlled only to a limited extent by methods that are not perfect in their operation. Furthermore, the heat is regulated according to the judgment of the operator and his skill in estimating the temperature of the flame. Irregularities therefore result at times, and these produce an effect on the steel, because the temperature at which the ingots are cast should be neither too high nor too low. It is true that the temperature of the open-hearth steel is also regulated by the judgment of the operator, but more time is afforded for exercising this judgment and for controlling the heat.

(d) In the Bessemer process we get rid of all the carbon first, and then recarburize to the desired point. In the open-hearth process we may stop the operation at any desired amount of carbon, and then recarburize only a small amount. Therefore the open hearth has the advantage of greater homogeneity when making high-carbon steel, since a very large amount of recarburizer may not distribute itself uniformly.

In order to produce the best quality of steel, it must be cast into ingot molds within a certain limited range of temperature,

<sup>1</sup> The hydrogen is said to come from the moisture in the blast.

which varies according to the amount of carbon, etc., that it contains. Therefore, in casting the very large heats of the open hearth process, the ingots must be very large, else the first one will be too hot and the last one too cold for the best results. On the other hand, if the ingots are large, segregation is liable to be excessive (see p. 216).

On account of its ability to make low-carbon steel more readily than the basic open hearth, the Bessemer process has a hold on the wire and welded steel-pipe industry, although even here the open-hearth process has encroached. For rolling very thin plates, for tin plate, etc., we want a metal relatively high in phosphorus, and therefore the Bessemer process is largely used here, although in some cases ferrophosphorus is being added to basic open-hearth metal to accomplish the same result. The reason phosphorus is desired is because the plates are rolled very thin by doubling them up and putting several thicknesses through the rolls at the same time. Low-phosphorus metal welds together too much under these circumstances.

The chief requisites of railroad rails are lack of brittleness and ability to withstand wear. The Bessemer process is able to provide such a material, and it works so well in conjunction with the rapid, continuous operation of the rail rolling-mill that it has a decided advantage. It produces a small tonnage of ingots at frequent intervals (say 15 tons every 7 min.), while the open-hearth process provides a large tonnage of ingots, which may come at irregular intervals and thus alternately delay and overcrowd the rail-mill operations. But notwithstanding these advantages, an increasing tonnage of basic open-hearth rails is made every year in the United States, and now the majority of rails of large sizes are made by the open-hearth process, in which we include the Bessemer open-hearth Duplex process. The lower phosphorus in the basic steel enables us to get a tough rail with higher proportions of carbon, and this higher carbon gives a steel more resistant to wearing down by abrasion.

**Crucible Steel with Others.**—Crucible steel is the most expensive of all and costs at least three times as much as the next in price—acid open-hearth steel. It is also the best quality of steel manufactured,<sup>1</sup> and for very severe service, such as the points and edges of cutting tools, the highest grades of springs, armor-piercing projectiles, etc., it should always be employed. The

<sup>1</sup> Except electrically purified steel, discussed in Chap. VII.



reason for its superiority is believed to be that it is manufactured in a vessel which excludes the air and furnace gases, and is therefore freer from oxygen, hydrogen and nitrogen. When properly "killed" it is also free from "sonims" (see p. 206). Perhaps the fact that the process is in some ways under a little better control than any of the others, and receives more care, on account of being manufactured in small units, assists in raising its grade. Crucible steels are usually higher in carbon than Bessemer and open-hearth steels, because the special service to which the crucible steels are adapted is usually one requiring steel that can be hardened and tempered—for example, cutting tools, springs, etc., and only the high-carbon steels are capable of this hardening and tempering. This is not an essential characteristic of the product, but is most often the case.

**Wrought Iron with Low-carbon Steel.**—Wrought iron costs from 10 to 20 per cent more than the cheapest steel. Its claim to superiority over dead-soft steel consists in its low carbon and the presence in it of slag. Just how much advantage the slag gives has never been proven; it gives the metal a fibrous structure which, perhaps, increases its toughness and its resistance to breaking under bending or under a sudden blow or shock. Some think that the slag also assists in the welding of the material, but this is doubtful, and it is probable that the easy weldability of wrought iron is due alone to its being low in carbon. Some also believe that the slag assists the metal in resisting corrosion; hence one reason for the preference of some engineers for wrought-iron pipe for boilers and other purposes. An advantage of wrought iron in this connection is its rough surface to which paint or other protective coatings will adhere more firmly than to the comparatively smooth surface of steel. Nevertheless the evidence goes to show that *properly made steel* corrodes very little, if any, more than wrought iron, especially in boilers, pipe and other articles which cannot be coated (see p. 454).

The properties of wrought iron are the nearest to those of pure iron of any commercial material, notwithstanding its slag. This is because the slag is mechanically mingled with the metal and does not alter some of its chemical and physical characteristics. Therefore wrought iron is preferred for electrical conductivity purposes and as a metal with high magnetic power, for armatures of electromagnets, etc. When under strain greater than it can withstand wrought iron stretches more uniformly over its entire



length than steel, although the elongation closer to the point of fracture may not be so great. Much wrought iron is made today by the *bundling* and rerolling of wrought iron scrap, as described on p. 78. This makes a much inferior product, the bundles sometimes even containing steel rolled into the pile. The advantages I have mentioned, the conservatism of engineers, and the capital previously invested in puddling furnaces are the chief factors in keeping alive the manufacture of wrought iron. It was freely predicted that the invention of the Bessemer and open-hearth processes would bring about the extinction of the puddling process, but these prophecies have never been fulfilled, although the importance of wrought iron has waned very greatly in 60 years.

**Summary.**—In order of expense and of quality the different steels are arranged as follows: (1) Crucible; (2) acid open-hearth, (3) basic open-hearth, and (4) Bessemer.

#### DISTINGUISHING BETWEEN THE DIFFERENT PRODUCTS

Low-carbon steel pipe, merchant bars, horseshoe blanks, etc., sometimes masquerade under the name of wrought-iron; high-carbon open-hearth and Bessemer steel merchant bars, tool blanks, etc., sometimes masquerade as "crucible steel," or perhaps "cast steel," which is the trade name for crucible steel; other deceptions are not unknown; indeed, even malleable cast iron is sold oftentimes as "steel castings." It is therefore important for engineers to understand the essential differences between these materials, although care in the wording of contracts and specifications should be the important consideration and should precede watchfulness over the products. The definitions of iron and steel materials are in such a confused and unsettled condition that it does not do to rely upon them at all, especially where a lawsuit may be involved; and contracts in clear, simple language, free from legal and metallurgical phraseology, are the best safeguards. But even where it is entirely plain what material is called for, there is always a temptation to substitute steel for wrought iron, Bessemer for open hearth, basic for acid, and Bessemer or open hearth for crucible steel. In case such substitution is suspected, there are means by which the material may be tested, aside from its strength and ductility, which may or may not be in the contract. The tests are some-

what delicate and usually require the judgment and experience of an expert—one who has standard samples of the different grades of material for comparison, because the details of manufacture vary from district to district, and still more so with the purposes for which the products are to be used.

**To Identify Genuine Steel.**—The microscope and the content of manganese and silicon is the surest means of distinguishing genuine steel castings from specially treated malleable-iron castings. The latter are usually much higher in silicon and lower in manganese, and show under the microscope the effects of the carbon which has been extracted from the metal by oxide annealing in the solid state.

**To Identify Wrought Iron.**—Wrought iron usually contains more than 0.50 per cent of slag, while steel should have not more than 0.30 per cent of slag plus other sonims (*i.e.*, solid inclusions). The slag may be determined by ordinary chemical or microscopic means, or it may be disclosed by etching the wrought iron deeply for several hours with dilute hydrochloric acid. The slag will appear in high spots and ridges extending above the surface of the metal which has been eaten away, and from which it is also distinguished by its dark color. Manganese is also low in wrought iron, usually less than 0.10 per cent, and above 0.40 per cent in steel, while phosphorus is normally above 0.10 per cent in wrought iron and below that proportion in steel.

The fibrous fracture disclosed in wrought iron when it is nicked and broken by bending away from the nick, is an uncertain means of identification, and the so-called "threading test" is unreliable.

**To Identify Knobbled Charcoal Wrought Iron.**—Genuine charcoal wrought-iron boiler tubes are lower in all impurities than puddled iron, especially sulphur, phosphorus and slag, as well as (usually) carbon. The carbon is usually lower than that in steel, and the structure as disclosed by the microscope is different.

**To Identify Crucible Steel.**—The sonims in crucible steel should be below 0.10 per cent while open hearth and Bessemer steels will run above 0.20 per cent. (Well-made acid open-hearth steel should, however, be lower than 0.20 per cent sonims.) Crucible steel normally has less than 0.4 per cent manganese and more than 0.2 per cent silicon, while open-hearth and Bessemer steels normally have more than 0.4 per cent manganese and less

than 0.2 per cent silicon. In the case of steel castings, however, this rule for silicon does not apply, as Bessemer and open-hearth steel castings are sometimes as high as 0.6 per cent in silicon. It is possible—but not usual—to make both Bessemer and open-hearth steels low in manganese. Be it noted that when crucible steel is ordered low in carbon, there is a much greater temptation to substitute another steel for it.

**To Identify Electric Steel.**—Electric steel in low-carbon grades runs very low in silicon, while crucible steel is usually 0.20 per cent or over. This, however, does not apply to castings, but the sulphur in electric steel castings is usually under 0.05 per cent, and that in crucible steel is higher. Even in the carbon grades above 0.60 per cent, the silicon of crucible steel will be normally above 0.20 per cent, and that of electric steel not so high.

From open-hearth and Bessemer steels electric steels may easily be distinguished because they should contain practically no sonims, while the others will have more than 0.10 per cent, especially Bessemer and basic open hearth. The manganese of electric steel will be less; the silicon will be less except in castings and steel above structural carbon grades—say, over 0.40 per cent carbon. The sulphur will usually be less—under 0.03 per cent. Finally, for the same tensile strength, electric steel will have higher elongation and reduction of area than any steel except crucible.

**To Distinguish between Acid and Basic Open-hearth Steel.**—Acid open-hearth steel will have less oxygen and sonims than basic. It will also usually have higher silicon and phosphorus and lower manganese. It also has the property of dissolving more slowly in dilute sulphuric or hydrochloric acids.

**To Distinguish between Basic Open-hearth and Bessemer Steels.**—Basic open-hearth steel has lower manganese, silicon, phosphorus and sulphur and higher oxides and “sonims” than Bessemer steel, and dissolves more rapidly in dilute acids.

**To Distinguish between Acid Open-hearth and Bessemer Steels.**—Acid open-hearth steel will have less sonims, oxygen and manganese than Bessemer steel, and less phosphorus than acid Bessemer steel.

**To Distinguish between Acid and Basic Bessemer Steel.**—Acid steel will have less oxygen, sonims and manganese than basic, and higher silicon, phosphorus and sulphur. It will also dissolve more slowly in dilute acids.

## PRICES OF STEEL

We may at this point insert, for the sake of many persons interested in the commercial side of the iron and steel industry, some average prices of a few products, which will give an idea of the representative value of all.

TABLE OF AVERAGE PRICES

1922

Iron ore, Mesabi, non-Bessemer, <sup>1</sup> per gross ton.....	\$ 5.05
Iron ore, Mesabi, Bessemer, <sup>2</sup> per gross ton.....	5.70
Iron ore, Old Range, non-Bessemer, per gross ton.....	5.20
Iron ore, Old Range, Bessemer, per gross ton.....	5.95
Pig iron, Bessemer, per gross ton, at Pittsburgh.....	27.58
Pig iron, No. 2 Foundry, per gross ton at Chicago.....	24.85
Pig iron, Southern Foundry, at Cincinnati, per gross ton.....	23.93
Pig iron, Basic, per gross ton.....	24.20
Ferrosilicon, 50 per cent silicon, <sup>7</sup> per gross ton.....	60.00±
Ferromanganese, 80 per cent manganese, per gross ton.....	74.22
Ferrochrome, high-carbon, 60 per cent Cr., per lb. of contained Cr. ....	0.11
Ferrochrome, low-carbon, 60 per cent Cr., per lb. of contained Cr. ....	0.12
Ferrotitanium, per ton, 15 per cent Ti carbon containing.....	215.00
Ferrovandium, per pound of vanadium contained <sup>6</sup> .....	4.00±
Rails, open-hearth, per gross ton.....	40.75
Structural beams and plates, per 100 lb.....	1.71
Structural shapes, nickel steel, 3.5 per cent, nickel per 100 lb..	3.71
Wrought-iron bars, per 100 lb. at Philadelphia.....	2.00±
Black sheets, No. 28 base, per 100 lb. at Pittsburgh.....	3.25
Wire nails, per 100 lb.....	2.51
Crucible tool steel bars, <sup>4</sup> per 100 lb.....	\$14.00 to \$22.00
Chrome steel, chrome nickel steel, per 100 lb.....	4.25 to 8.25
High-speed tool steels, etc., <sup>5</sup> per 100 lb.....	65.00 to 90.00
Manganese steel castings, <sup>3</sup> per 100 lb.....	25.00 to 35.00
Carbon steel castings, <sup>3</sup> per 100 lb.....	8.00 to 20.00

<sup>1</sup> Base 51.5 per cent iron.

<sup>2</sup> Base 55 per cent iron, under 0.045 per cent phosphorus

<sup>3</sup> The price of all castings largely depends on molding costs.

<sup>4</sup> Price depends on maker, brand, etc.

<sup>5</sup> Price depends on content of tungsten, etc., and on whether heat-treated by maker or not.

<sup>6</sup> The alloy contains about 30 to 40 per cent V.

<sup>7</sup> This is manufactured in electric furnace; the blast-furnace product containing 10 per cent silicon, about \$40 to \$55.



## FIELDS OF USEFULNESS OF VARIOUS CLASSES OF IRON AND STEEL

**Field of Usefulness of Ingot-iron.**—Very pure iron is extra soft and malleable and also less subject to rusting than ordinary iron or steel. It is adapted to pipes and culverts and articles subjected to great distortion during cold forming, such as deep stamping. It is also superior to ordinary steel in its electric and magnetic qualities.

**Fields of Usefulness of Wrought-iron.**—Wrought-iron is much used for boiler tubes, and purposes where ease of welding is a commercial advantage. Its purity commends it for parts of electrical machinery. Many engineers believe that it is superior in non-corrosive or non-rusting properties; this is denied by others, and its inferiority in acid waters is asserted.

**Fields of Usefulness of Cast-iron and Malleable Cast-iron.**—The improvement in the manufacture of steel castings has limited the field of commercial employment of iron and malleable-iron castings, but cast-iron is still employed wherever weight or compressive strength of the casting is the controlling factor, and where as a structural part for a machine or building it does not have to withstand shock, tensile stress or bending. Iron castings have the advantage of being capable of manufacture with simple apparatus right in the field, remote from centers of civilization. Malleable cast-iron was losing some of its trade, but recent great improvements in qualities has enabled it to hold its own and even extend its field for castings of small size, where moderate tensile strength, small ductility and slight bending are required. It has the advantage over steel of better resistance to shocks within the limit of its strength. For pipe fittings, household hardware and many small or thin articles, it can excel steel castings in price, and give all that is necessary in service. (See pp. 374 to 392.) Chilled cast-iron is the cheapest very hard material that is made; for resisting wear and affording a useful amount of strength it is unexcelled, and finds a large field in railroad freight car wheels, rolls with hard surface, parts of crushing machinery, inserts in brake shoes, etc.

**Fields of Usefulness of Crucible Steel and Electric Steel.**—Crucible steel and electric steel excel all others in price and quality. The latter is due to freedom from gases, oxides and defects other than metallic impurities. These steels may be used only for purposes which can afford to pay the high price. As between



crucible and electric steel we cannot yet say which is superior, because electric steel practice has not yet (1923) become sufficiently standardized to serve as a basis of comparison.

**Fields of Usefulness of Basic Open-hearth and Bessemer Steel.**—The Bessemer product is losing ground, not so much on account of the limited field for which it is adapted, but because low-phosphorus pig-iron from which to make it is becoming yearly more rare and costly, due to the exhaustion of low-phosphorus ores. For small railroad rails, small structural shapes (angles, channels, I-beams, etc.), pipe, wire and tin plate, Bessemer steel is as good as any obtainable provided the phosphorus be kept at a moderately low figure. Indeed, the soft and low-carbon steels can be made more easily in the Bessemer converter than in the open-hearth furnace, and this is what is wanted for most wire and for pipe. But for more important structural members, for large railroad rails, which must be relatively high in carbon, and therefore low in phosphorus, to be strong yet not brittle in cold weather, the basic open-hearth furnace is especially appropriate for modern conditions of ore supply, because it can remove phosphorus to any desired extent. The same is true of structural plate, boiler plate, etc. Most modern steel is therefore made by the basic open-hearth process.

**Fields of Usefulness of Basic and Acid Open-hearth Steel.**—It is easier to get low-phosphorus material for melting in the acid open-hearth than for the Bessemer converter, because usually 75 to 90 per cent of this material consists of steel scrap. Therefore, acid open-hearth steel low in phosphorus and in sulphur is obtainable, and is the highest quality of steel in the market, next to crucible and electric. It excels basic open-hearth steel because of its relative freedom from oxygen, and sonims, to which basic steel is liable on account of its highly-oxidized, basic slag. For steel castings this freedom from oxygen is especially valuable, as oxygen and oxides in steel tend to produce blow-holes in castings. The acid open-hearth is not universal, but is generally preferred, for steel casting work. It is also preferred for most important bridges and other structural work requiring high quality, on account of the lesser content of oxides which lower the resistance of the steel to the stresses of service.

## CHAPTER IV

### THE MANUFACTURE OF WROUGHT IRON AND CRUCIBLE STEEL

#### THE MANUFACTURE OF WROUGHT IRON

**Pig Iron Used.**—The pig iron employed is of the grade known as “forge iron” or “mill iron,” (see p. 7). In the United States we prefer to have this contain about 1 per cent of silicon, because the higher the silicon the larger will be the amount of slag made, while if it is too low the iron will be oxidized excessively. Manganese is usually about 0.50 per cent, although it varies anywhere from 0.25 per cent to over 1 per cent, depending on what the blast furnace puts in the pig. Phosphorus is preferred to be less than 1 per cent, and sulphur not more than 0.10 per cent, because neither of these elements is entirely eliminated during the process. A large amount of phosphorus in wrought iron is not, however, as objectionable as it is in steel, because the slag mechanically mingled with the wrought iron hinders it from being brittle under shock, which is the chief damage caused by phosphorus. Pig iron containing 2.50 per cent and even 3 per cent of phosphorus, and as much as 0.35 per cent of sulphur, is sometimes used. The larger the amount of impurities the larger the loss of metal in the process, both because they are oxidized and lost and because, in the case of silicon, the oxidation increases the amount of slag made, which, in turn, increases the amount of iron slagged off. (See p. 78.)

**Puddling Furnaces.**—There are many different varieties of puddling furnace, varying in capacity from 300 to 1,500 lb. and even more, but the commonest is probably the 500-lb. furnace, built either single or in pairs, back to back, the latter arrangement having the advantage of reducing loss of heat by radiation, which is always a very large factor. Puddling furnaces are heated by gas or bituminous coal. The commonest method is a deep bituminous-coal fire, giving a long flame, and with a large area of grate in relation to the area of the hearth in order that a high temperature may be maintained.

**Fettling.**—The hearth is lined or “fettled” with oxide of iron in the form of roll scale, or high-grade iron ore, or “bulldog,” *i.e.*, roasted puddle cinder, and this oxide, together with the metal oxidized during the melting, supplies the base which automatically maintains a very basic slag and also serves as the principal oxidizing agent of the impurities. The fettling is repaired between melts as often as is necessary, and suffers wear with each operation.






FIG. 29.—1,500-lb. puddling furnace. (Two work doors.)

**Puddling.**—Pig iron is usually charged by hand through the working doors of the furnace, and the puddler's assistant fires vigorously in order to melt it down as fast as possible, which usually takes about 30 to 35 min. As soon as melted, there follows a short stage of 7 to 10 min., during which iron oxide in the form of roll scale or very high-grade iron ore is added, in order to make a very basic slag, the charge being thoroughly mixed and cooled, for which purpose the damper is put on and sometimes even water is thrown on to the bath. The object is to reduce the temperature to the point where the slag will commence to oxidize the impurities and especially the phosphorus and sulphur ahead of the carbon. At low temperatures, phosphorus oxidizes ahead of carbon; at higher temperatures, carbon in preference to phosphorus. See Table XII<sup>1</sup> for slow removal of carbon at first. As soon as the carbon reaction is started, light

<sup>1</sup> P. 75.

flames begin to break through the covering of slag, produced by burning carbon monoxide:



The slag must be very basic at this time lest the CO reduce phosphorus and sulphur and cause them to return to the metal.



(Courtesy of Central Iron and Steel Co.)

FIG. 30.—Puddling.

As the carbon monoxide forms more and more abundantly, the charge is more violently agitated by its escape, and the “boil” is in progress. The formation of gas in its interior causes the charge to swell greatly, and it thus rises in the furnace and a large amount of slag pours out of the slag-hole and into a waiting buggy. About one-half of all the slag produced during the process is removed at this time. The boil continues from 20 to 25



min., and during this time the puddler stirs or "rabbles" the charge vigorously with a long iron rabble, shaped like a hoe. Toward the end of the boil the metal begins to come to nature, and points of solid metal project through the cover of slag, while other pasty masses form on the bottom of the furnace. Both of these things must be corrected immediately by the puddler, (1) lest the iron that is exposed to the furnace gases become too much oxidized, (2) lest the iron sticking to the cold bottom become too much chilled, or (3) lest the charge be not uniform



(Courtesy of Youngstown Sheet and Tube Co.)

FIG. 31.—Removing the puddle ball.

in composition. Finally, all the charge comes to nature and the "balling" period begins and occupies about 15 to 20 min. During this period the bath is divided into three or four portions, which are each rolled up into a ball, consisting of a large number of particles partially welded together. The balls are rolled up near the fire-bridge in order, first, to protect them from direct contact with the flame, and second, to keep them as hot as possible until the puddler can draw them, so that the slag may be fluid and thus more easily squeezed out of the metal. The balls are then squeezed in turn, and the furnace hearth repaired



for another charge. The total time between operations is usually from 1 hr. 10 min. to 1 hr. 40 min.

**Squeezers.**—A very common form of squeezer is that shown in Fig. 32, the distance between the inner and outer circle being greater on the entering side than on the outgoing side. As the inner circle revolves, the corrugations on the surface carry the ball around, giving it at the same time a movement of rotation. By the time the ball exists on the opposite side, it has been squeezed and kneaded sufficiently to get rid of a large amount of slag. In European countries the squeezer is rarely used and the ball is “shingled”—reduced under a hammer—to weld its particles together and force out the slag.




FIG. 32.—Rotary squeezer.

**Chemistry of the Process.**—The removal of the impurities during the puddling process is shown in Table XII, which is quoted because it records probably the first successful attempt ever made to study in this way the chemistry of an iron or steel process. A similar study is graphically represented in Fig. 33.

During the melting-down stage, the silicon and manganese in the puddling charge are almost entirely eliminated, and these reactions are as complete as they will be by the end of the “clearing” stage which follows it. Much phosphorus and sulphur are also removed. The boil period is, of course, the period during which the carbon escapes, together with some phosphorus and sulphur which was not removed during the first two periods.

**Fuel.**—The temperature of the puddling process is as high as can be obtained in furnaces of this type without preheating the air.<sup>1</sup> The result is a very large waste of heat up the chimney,

<sup>1</sup> Indeed, in some cases the air is preheated by the regenerative process, although this is not the usual practice.

TABLE XII.—REMOVALS IN HAND PUDDLING  
(By CALVERT and JOHNSON, *Phil. Mag.*, 1857)

	Time after charging		C per cent	Si per cent	S per cent	P per cent
	Hours	Minutes				
Sample No. 1.....	0	0	2.275	2.720	0.301	0.645
Sample No. 2.....	0	40	2.726	0.915		
Sample No. 3.....	1	00	2.905	0.197		
Sample No. 4.....	1	5	2.444	0.194		
Sample No. 5.....	1	20	2.305	0.182		
Sample No. 6.....	1	35	1.647	0.183		
Sample No. 7.....	1	40	1.206	0.163		
Sample No. 8.....	1	45	0.963	0.163		
Sample No. 9.....	1	50	0.772	0.168		
Puddled bar.....	..	..	0.296	0.120	0.134	0.139




FIG. 33.—Removals in hand puddling.

although sometimes economy in this respect is obtained by placing boilers, or else furnaces to heat metal for the rolls, where



FIG. 34.—Squeezing puddle balls and rolling puddle bar.

they will receive the waste heat of the puddling furnaces. The two greatest items of expense in the puddling process are the fuel used and the excessive labor, which, on account of the strength




FIG. 35.—Wrought iron showing strings of slag. Magnified 50 diameters.  
(Unetched.)

and endurance demanded, receives a high price. The amount of fuel burned per ton of iron produced will usually be about 1 ton

of a soft bituminous coal, or a little more, although better figures than this are obtained in some cases.

**Losses.**—The loss in the puddling process usually averages from 4 to 6 per cent of the weight of the metal charged. The following table gives a typical example of loss:

TABLE XIII.—TABLE OF LOSSES IN HAND PUDDLING

	PERCENTAGE OF LOSS
Silicon burned.....	1.00
Carbon burned.....	3.50
Sulphur burned.....	0.20
Phosphorus burned.....	0.50
Manganese burned.....	0.30

Total..... 5.50

Iron reduced from oxide<sup>1</sup> = 1.00 per cent gain.

Net loss..... 4.50

<sup>1</sup> There is much iron oxidized and carried off in the slag, but there is also much reduced by impurities. The figure here given represents the excess of reduction over oxidation; in some cases it runs as high as 6 per cent or more.

**Slag.**—The slag which runs from the tap-hole during the boil is known as “boilings,” while that tapped out at the end of the process is known as “tappings” or “tap-cinder.” The characteristics of the boilings are that they contain a larger amount of phosphorus than the tappings, and also that globules of metallic iron are carried off in the violent agitation of the boil. An analysis of the two varieties, giving a mean composition from seven heats, is as in Table XIV.

TABLE XIV.—SLAG ANALYSES—PUDDLING PROCESS

	Boilings	Tappings
Ferrie oxide ( $\text{Fe}_2\text{O}_3$ ).....	6.94	12.90
Ferrous oxide ( $\text{FeO}$ ).....	62.61	64.62
Silica ( $\text{SiO}_2$ ).....	19.45	15.47
Phosphoric anhydride ( $\text{P}_2\text{O}_5$ ).....	6.32	3.91
Not determined ( $\text{MnO}$ , $\text{S}$ , $\text{CaO}$ , etc.).....	4.68	3.10
	100.00	100.00
Total iron.....	53.55	59.29

The amount of slag will depend chiefly upon the amount of silicon in the pig iron. It will average in weight about one-half the weight of the charge, where the silicon is high, as in English practice (say 1.70 to 2 per cent), and about one-quarter to one-third in American practice, where the silicon is about 1 per cent.

**Mechanical Furnaces.**—The labor in puddling is very severe on the men, and many attempts have been made to remedy this by mechanical furnaces which will work the charge without so much manual labor. Several forms of mechanical appliances and of mechanical furnaces have been invented, and some of them have given some degree of satisfaction. The chief difficulty with

most mechanical puddlers has been inability to reduce the carbon below 0.10 per cent.

**Bundled Scrap.**—In the United States a good deal of wrought iron is made every year by bundling scrap up into a pile roughly resembling Fig. 25.<sup>1</sup> This is then tied up with wire, heated to a welding heat and rerolled into "puddle bar." This is generally an inferior grade of product.




FIG. 36.—Cementation furnace.

#### THE CARBURIZATION OF WROUGHT IRON

Wrought iron is converted into steel by the operation of carburizing, or the adding of carbon to it. This is today accomplished in two ways: (1) By the cementation, or steel conversion, process, in which carbon is allowed to soak into red-hot steel in a manner

similar to the absorption of ink by blotting-paper; and (2) by the crucible process, in which wrought iron is melted in a crucible with carbon, or with iron containing carbon, *e.g.*, cast iron, washed metal, etc.

<sup>1</sup> Page 54.



**Cementation Process.**—We have already said in describing the blast-furnace process that iron at a bright-red heat will absorb carbon very slowly. The action appears to be a traveling of solid carbon into the interior of solid iron, forming with it a chemical solution. When the steel is at a proper heat, the rate of travel is approximately  $\frac{3}{8}$  in. per 24 hr.

**Steel Converting Furnace.**—A section of the type of cementation furnace used in Sheffield, England, is shown in Fig. 36. The superstructure *e* is a mere chimney for the purpose of carrying off the products of combustion from the fire at *c*, and for reducing loss of heat by radiation. The real furnace is the part underneath this superstructure or stack, and it has several small chimneys of its own. The two converting pots are shown underneath the points *a a*. In Sheffield they are built of stone and are  $2\frac{1}{2}$  to 4 ft. wide and deep, and 8 to 15 ft. long. On the bottom of the pot is first placed a layer of charcoal in small pieces freed from dust. On this is laid a layer of the wrought-iron bars to be converted, which are 2 to 5 in. wide,  $\frac{1}{2}$  to  $\frac{3}{4}$  in. thick, and nearly as long as the pot. A little space is left (about  $\frac{1}{2}$  in.) between each pair of bars in order that they may be completely surrounded by the charcoal. On top of the layer of bars is then placed another layer of charcoal, and then a layer of bars, and so on until the pots are filled, each one containing from 10 to 30 tons of iron. The top of the pots is then luted air-tight and the fire is lighted.

In about 2 days the temperature has reached a full red-heat of say 650 to 700°C. (1,200 to 1,300°F.), and this is maintained from 7 to 11 days longer, depending upon the grade of steel to be made. The names of the different grades of steel made in Sheffield are as follows:

No. 1. Spring heat.....	0.50 per cent carbon
No. 2. Country heat.....	0.60 per cent carbon
No. 3. Single-shear heat.....	0.75 per cent carbon
No. 4. Double-shear heat.....	1.00 per cent carbon
No. 5. Steel-through heat.....	1.25 per cent carbon
No. 6. Melting heat.....	1.50 per cent carbon

The product is controlled by a series of trial bars which are so placed that, beginning about 7 days from the full-red heat, they can be withdrawn from the furnace from time to time, broken, and examined. The appearance of the fracture tells the extent of the cementation. When the cementation has proceeded to the desired point, the fire is withdrawn and the furnace is allowed to

cool for about a week, when the pots are opened and the bars withdrawn through the door *b*.

**Blister-steel.**—The product of the cementation process is known as “blister-steel” because its surface is covered with blisters, due to the formation of gas by a reaction between the carbon absorbed and the slag contained in the wrought iron:



The blister-steel has gained about 1 per cent in weight over the wrought iron due to added carbon, and the appearance of the fracture is entirely different, as the broken surface now shows large bright crystals of cementite, *i.e.*, carbide of iron.

**Shear-steel.**—The bars of blister-steel are sometimes forged to a smaller size, piled up, and then the pile forged down again into a bar, which makes what is known as “single shear-steel.” Single shear-steel may be again piled and forged into double shear-steel. It is now more common to melt the blister-steel in crucibles, which separates the metal from the slag it contains.

#### THE MANUFACTURE OF CRUCIBLE STEEL

**Crucible or Cast Steel.**—The cementation process, on account of the length of time and the very large amount of fuel required, has now been largely superseded by the crucible process. In this process the wrought iron is cut up into small pieces and melted in covered crucibles, the desired amount of carbon being placed on top of the charge before the melting, together with any other alloying element desired, such as chromium, tungsten, manganese, etc.

**Furnaces.**—In Sheffield, England, coke furnaces, or melting-holes, containing each two crucibles, are almost universally used, while in America gas furnaces, containing about six crucibles each, are the common type. In the gas furnace it is necessary that the gas and air for combustion shall be preheated, in order that we may (1) obtain fuel economy and (2) reach the desired temperature for melting quickly.

**Regenerative Furnace.**—The construction of the regenerative furnace is shown in Fig. 37.<sup>1</sup>

**Crucibles.**—In England, the crucibles are made of fire-clay. They are usually made by hand at the steel melting plants and are dried for 1 or 2 months, on a shelf next to the chimney of the melting furnace. Before being used they are heated to redness in an annealing furnace and are then ready to receive a charge of 50

<sup>1</sup> For description of the operation see Fig. 23 on p. 52.

lb. of metal. The clay is deeply cut by the slag, and therefore the charge must be reduced to 44 lb. for the second melt and 38 lb. for the third, in order that the slag-line may be lower each time. After the third melt they are thrown away. The advantages of clay crucibles are that the first cost is lower, and that they do not give up any carbon to the metal, so that the




FIG. 37.—Regenerative gas crucible furnace or "melting-hole."

composition of the final product may be regulated with greater exactness and a lower carbon steel may be made, if desired.

In America, the crucibles are usually made of a mixture approximating 50 per cent graphite and 50 per cent fire-clay.

They are made and tempered by factories outside of the steel-works and are received by the latter ready for use. They last about six heats, after which the bottom is sawed off and used for the top of a new crucible. They hold almost 100 lb. of metal, because at high heat, they are stronger than clay and can stand greater strains. Grasping a crucible with the high-leverage tongs and raising it from the furnace puts it under a severe strain.




FIG. 38.—Section through Sheffield melting house.

**Metal Used.**—Although crucible steel is supposed to be made by the melting of pure wrought iron with charcoal, washed metal, ferromanganese and other “physic,” it is not at all uncommon for the wrought iron to be diluted with varying amounts of cheaper scrap steel, which lowers the quality of the product. The pieces of iron are put into the crucible first, and on top of that is placed the charcoal or pig iron, ferromanganese or spiegel-eisen, and various physics, such as salt, potassium ferrocyanide, oxide of manganese, etc. The purpose of these physics is not entirely clear. Probably the salt and oxide of manganese make a more fluid slag; the ferromanganese puts a little manganese in the steel; and the ferrocyanide may, perhaps, favor the absorption of carbon by the steel.



In some cases the material is charged directly into a hot crucible from the previous melt, but when graphite crucibles are used, these are sometimes allowed to cool, in order to be examined for cracks, because the breaking of a crucible in the furnace, allowing the liquid mass to flow out upon the floor, is very objectionable. There is a hole in the middle of the floor of the furnace, so that if such an accident happens the metal may run down into a pit underneath; and the floor is also covered with a few inches of coke dust to absorb the metal in such a contingency.

**Melting.**—In the case of a gas furnace the crucibles are placed in the furnace and the gas and air turned on. In the case of a coke furnace, the crucibles are placed upon their fire-clay stands and the coke packed around them upon the fire left from the last melt. At the end of about 1 hr., the coke fire has burned down so low that it has to be poked down and more coke added. After another hour or so the coke fire requires further attention and at this time, care must be taken that no coke falls into the crucible when the cover is off. The melting takes on the average from 2 to 3 hr. in both cases, and the charge is examined by removing the crucible cover, to make sure that it is entirely molten.

**Killing.**—When the charge is entirely molten, it is kept in the furnace for  $\frac{1}{2}$  to 1 hr. longer in order that it may teem "dead," that is, pour quietly without the evolution of gas, and yield solid ingots. If the "killing" time is too long, the ingots will be solid, but the steel will be hard, brittle and weak, probably as a result of the absorption of too much silicon from the walls of the crucibles. Graphite crucibles probably yield more silicon than clay crucibles. Just what takes place during the killing of steel is not definitely known. Some have suggested that the gas contained in the steel is eliminated from it during this time, but the alternate suggestion that the principal effect of the killing is to cause the steel to absorb silicon, becoming sound on this account, is the more generally accepted one. The quiet "killing" period also permits all solid oxides, slag, and other entangled or occluded particles to float to the surface, even when only microscopic in size. (See Fig. 39.) Without this elimination the steel falls short of the best quality. The amount of silicon in the final steel will vary greatly, but will average perhaps from 0.10 to 0.50 per cent.

**Pulling.**—When, in the judgment of the melter, the steel has



been properly killed, the crucibles are removed from the fire by the puller-out, who straddles the top of the furnace and grasps



(Courtesy, William Campbell)

FIG. 39A.—Sonims in steel. Seven inch motor shaft. Unetched. Magnified 90 diameters.

(Courtesy, William Campbell)

FIG. 39B.—Sonims in steel. Seven inch motor shaft. Etched. Magnified 500 diameters.



FIG. 40.—Pouring.

the crucible with a pair of tongs, his legs and arms being swathed in wet cloths to protect him from the heat, and his eyes frequently


being protected by heavy blue glasses. The puller-out then passes the crucible to the pourer, who pours it as shown in Fig. 40, the slag first being swabbed off with a ball of cold slag on the end of an iron rod. The total time of operations is  $3\frac{1}{2}$  to  $5\frac{1}{2}$  hr. in England, and  $3\frac{1}{2}$  to 4 hr. in America.

**Ingot Molds.**—Ingot molds are shown in Fig. 41, and as a usual thing each mold has a capacity to take the charge from one crucible. The metal must be teemed into this with great care, so that the stream shall not touch the sides during pouring. In case a large ingot is to be poured, several crucibles are poured at once into the same mold, care being taken that the metal shall be liquid as long as the pouring continues, or else a "cold-shut" will result; that is, two parts of the ingot not fully melted together.

**Grading.**—The composition of the final metal is a matter of some uncertainty, especially as regards the carbon and silicon. The former is more easily adjusted when clay crucibles are used, because the amount of carbon dissolved from a graphite crucible will depend to a large extent upon the time and temperature of the operation, etc. The ingots are therefore always graded after they have cooled, by breaking off the upper part of them, which contains the pipe and is therefore useless (except when re-melted), and examining the fracture with the eye. The skilled steel man can thus estimate the carbon within 0.10 per cent, and the ingots are put away in the pile with others of like analysis. At large American works, however, this grading by eye is always supplemented by chemical analysis.

**Chemistry.**—The chemistry of the crucible process is very simple, and consists principally in the elimination of the slag in the wrought iron and the absorption by the metal of carbon, silicon, and manganese. There is also a very slight increase in

sulphur, which perhaps comes from the pyrite in the clay or graphite, or from sulphurous gases which find their way under the cover of the crucible. Phosphorus also increases slightly, perhaps from the slag of the wrought iron.



(From Howe, "The Metallurgy of Steel")

FIG. 41.—Ingot mold for crucible steel.

**Loss.**—The loss is due to the elimination of the slag and to some slight oxidation of metal by oxygen inside the crucible. It is counteracted to some extent by the absorption of carbon, silicon, and manganese, and will average slightly more than 2 per cent in clay crucibles and somewhat less than 2 per cent in graphite crucibles, the difference being doubtless due to less oxidation in the presence of the graphite.

**Fuel.**—In coke fires, the amount of fuel used will be three to four times the weight of steel produced. In gas-fired furnaces the amount of fuel used to make producer gas will be equal to, or slightly less in weight than, the amount of steel produced. The high cost in making crucible steel is due to the cost of crucibles, fuel, labor and raw material.

## CHAPTER V

### THE BESSEMER PROCESS

**Pig Iron Used.**—In the large American works, pig iron for the Bessemer process is preferred to have about 1 per cent of silicon. Silicon is the chief slag producer and also the chief heat producer. To keep it at a low figure limits the amount of slag made, which limits one of the sources of iron loss. Furthermore, the lower the silicon the shorter will be the time of blow; but it is usually risky to allow it to fall below 1 per cent, or the blow will be cold, and it is only by very rapid working and permitting the least possible delay between operations, so that the converter and ladles are kept very hot, that we are able to get along with as little as this. The manganese is below 0.8 per cent. This also furnishes heat;<sup>1</sup>

$\text{Mn} + \text{O} = \text{MnO}$  (generates 90,900 gram calories).

but it is now an expensive ingredient of pig iron, and also has the effect of making very liquid slags, which cause a good deal of slopping or "spitting" from the converter (*i.e.*, ejection of the material by the blast), and also make the steel ingots dirty and spotted with oxide spots, due to slag carried over with the steel. Pig iron containing manganese 1.50 per cent and silicon 1.00 to 0.90 per cent, gives a very "wet" slag, which follows the metal into the ladle and boils up through it, oxidizing the manganese in the steel:

(1)  $\text{FeO} + \text{Mn} = \text{MnO} + \text{Fe}$  (generates . . . . . gram calories).

The phosphorus and sulphur must be below 0.10 and 0.08 per cent, respectively, in order that the steel may be salable, as neither of these elements is reduced in the acid Bessemer process.

**Mixer.**—It takes about two blast furnaces to supply one converter with metal, so that a modern plant of two to four converters will be operated in conjunction with a large blast-furnace plant. The product of each of these furnaces, if not too different

<sup>1</sup> Indeed, formerly, in the Swedish Bessemer practice, the pig iron contained 2 per cent of manganese, and this element was relied upon as the chief source of heat, because silicon was necessarily low in the Swedish charcoal pig iron.



(Courtesy, Lackawanna Steel Co.)

FIG. 42.—A Bessemer blow.



from the desired analysis, will be poured into a huge reservoir, or "mixer," capable of holding 150 to 500 tons, which is then used as a source of supply for the converters.

The mixer serves several very useful purposes: (1) It equalizes the irregularities of pig iron composition by mixing the product of several furnaces, and also brings the composition somewhat under the control of the metallurgist of the Bessemer plant, because he not only can pick and choose from the different furnaces, but he has a few large cupolas under his dominion in which he can melt iron of any desired analysis to pour into the mixer and help regulate its contents.




FIG. 43.—Mixer.

2. Because of its large size, and the fact that it is continually in receipt of new fresh metal, the mixer can keep its contents molten for an indefinite length of time, whereas a ladle containing 15 tons of pig iron would chill in a few hours. Mixers are supplied with oil blow-pipes which can contribute a small amount of heat to the charge, but it is not often necessary to use them. Sometimes they are heated by gas and the regenerative process.

3. The capacity of the mixer is so large that a delay either at the blast furnace or at the steel works will not discommode it greatly, and thus each operation is independent of the other.

4. Pig iron in the mixer suffers a slight loss in sulphur, because manganese sulphide forms and, not being very soluble in iron, slowly rises into the slag.

**Industrial Situation.**—Only the acid Bessemer process is in use in America, because a sufficient supply of pig iron suitable for the basic Bessemer is not available to establish a competitive basis which alone can guarantee success, and because basic Bessemer steel is the poorest in quality and lowest in price. At one time the process was started, but failed through lack of suitable pig



(Courtesy, U. S. Steel Corp.)

FIG. 44.—Pouring pig iron out of 1,300-ton mixer.

iron at a low enough price to make commercial success; a second reason for failure was inability to sell the high-phosphorus slag produced, because American farmers were not familiar with its advantages as a fertilizer, and the necessary educational campaign was not completed in time to save the industry. Unless this slag can be sold as a by-product the returns are not sufficient for commercial success.

For more than 20 years the acid Bessemer process has been fighting a losing battle to maintain its erstwhile supremacy against the inroads of the basic open-hearth process. The struggle between the two processes is one of ores. In order to make acid

Bessemer steel of satisfactory quality we must start with a pig iron below 0.09 per cent, and this entails charging into the blast-furnace ore mixtures averaging 1,000 times as much iron as phosphorus. Such ores have been growing scarcer every year, and consequently the tonnage of Bessemer steel has been decreasing, not only in actual amount, but even more so in relation to the tonnage of basic open-hearth steel, which is now the predominant process, as shown in Table XV.

TABLE XV.—UNITED STATES PRODUCTION OF STEEL, 1920<sup>1</sup>


	Gross tons	Per cent
Basic open-hearth steel.....	28,096,604	66
Acid Bessemer steel.....	8,883,087	21
Basic Bessemer steel.....	0	0
Duplex steel (acid Bessemer in combination with basic O. H.).....	3,279,119	8
Acid open-hearth steel.....	1,296,172	3
Electric steel.....	502,152	1
Crucible steel.....	72,265	
All other processes.....	3,535	
Total.....	42,132,934	100

<sup>1</sup> The year 1920 is chosen because industrial conditions in later years have greatly reduced the production of steel.

It is evident from the table that the question of phosphorus in the ores is not only limiting the Bessemer process, but is transforming it more and more into a source of liquid steel scrap for the basic open hearth, where the phosphorus may easily be removed (Duplex process).

**Construction of the Converter.**—The construction and dimensions of the converter are shown in Figs. 45 and 46. It consists of a steel shell, riveted together and supported by two trunnions upon which it can be made to rotate. One of these trunnions is hollow, and serves as a wind-pipe to connect the blast from the blowing-engine with the wind-box at the bottom of the vessel. On the other trunnion is fastened a pinion, which engages with a rack joined to a hydraulic piston and of such a length that its movement can rotate the converter through an angle of at least 270 deg. The lining of the bottom is pierced with about 250

half-inch holes, which connect the wind-box with the inside of the converter and serve for the passage of the blast. The shape of the converter is such that, when it is lying on its side, the metal will not cover any of these tuyere holes. This is necessary, or the blast could never be turned off without having molten metal run down into the wind-box. The converter may have either an eccentric or a concentric shape. The advantage of the eccentric



(From Howe, "The Metallurgy of Steel.")


FIG. 45.—Fifteen-ton converter shell.

shape is that less heat can escape from the nose; the advantage of the concentric shape is that the vessel may contain its charge when turned on either of the sides, or may receive and pour from either side. (See Figs. 47 and 48.)

**Lining.**—The lining is made of highly refractory acid material composed principally of silica. In England, a ganister rock is used, or sometimes the lining is rammed up around a pattern and is composed of silicious material held together by a small amount



of fire-clay. In America, it consists usually of blocks of ganister or of mica-schist (a silicious rock consisting of pseudostrata, or laminae, formed by tiny plates of mica) laid with a thin layer of refractory fire-clay between, and in such a manner that the edges of the laminae will be exposed to the wear to which it is subjected.<sup>1</sup>



(From Howe, "The Metallurgy of Steel.")


FIG. 46.—Fifteen-ton converter section.

After a new lining is put in, it is carefully dried, and every Sunday afternoon, before the converter begins its operation for the week, a fire is kept in it for several hours in order to heat the lining to a red heat. Between the heats the lining is repaired, if necessary, with balls of silicious material and clay. On Sundays, and with an occasional lay-off for which one extra shell is provided, more extensive repairs are made, and in this way the lining is made to last several months—say 10,000 to 20,000

<sup>1</sup> If we represent the blocks of mica-schist by big books, and lay these books in a horizontal position with the edges of the leaves exposed, it will illustrate the method employed.




heats. The converter slags are always high in silica and corrode the lining only slightly. If, however, any uncombined oxide of iron comes in contact with it, it is attacked very rapidly. For this reason the mouths of the tuyeres are rapidly eaten away, and this part of the converter lasts only about 25 to 30 blows. The bottom is therefore fastened to the body with links and keys, so that it may be readily detached and replaced by a new one. Indeed, in some works bottoms are changed with an average delay to the operation of only about 20 min. for each replacement.



(From Howe, "The Metallurgy of Steel")

FIG. 47.—Concentric converter.



(From Howe, "The Metallurgy of Steel")

FIG. 48.—Eccentric converter.

**Bottoms.**—The lining of the bottom is made by placing the tuyere bricks (see Fig. 46) in position and then filling in around them with refractory material consisting of damp silicious material held together with clay and containing usually some coke breeze, which seems to lessen the chemical activity of the corrosion. The details of lining vary so greatly that no general rules can be given. The number of tuyeres is from 18 to 30, the number of holes in each from 12 to 18, and the size of the holes  $\frac{3}{8}$  in. (England) or  $\frac{3}{8}$  to  $\frac{5}{8}$  in. (America).<sup>1</sup> The correct lining is of the

<sup>1</sup> The acid Bessemer process finds its greatest importance in America, and next to that in England. Before the war Germany was the leader in basic Bessemer practice.

greatest importance and is the most influential factor in determining the life of the bottom, which furthermore depends upon the care in drying, the temperature of blowing, the pressure of blast, and the composition of pig iron. A bottom should dry




FIG. 49.—Corrosion of the bottom lining of Bessemer converter.

36 hr. or more. Its life is shortened by (1) hotter blows, (2) longer blows, (3) lower blast pressure (because the blast holds the metal away from the mouths of the tuyeres), and (4) more manganese in the pig iron (because a wet slag is more corrosive). Between heats, when the vessel is on its side receiving the recarburizer, pouring into a ladle, or receiving a new charge, the lining of the bottom can be repaired. For instance, if one tuyere eats away faster than its fellows, the excessive corrosion can be prevented by stopping it up with mud, because, if no air passes through the holes, no oxide of iron is formed at their mouths. Or a worn tuyere may be replaced by a new one, etc. These repairs are chiefly made through the wind-box, the back plate of which is removable.




FIG. 50.—Converter parts.

When a bottom is worn out, it is taken away and a new one brought on a car and placed under the converter, which is in the vertical position. Around the top is piled a ring of thick wet mud, and, as the bottom is forced up against the body by hydraulic pressure, the mud is squeezed into a firm joint. Lack of space prevents an account of some of the interesting expedients that are resorted to to stop an occasional leak in this joint without delaying the first heat, which must be avoided if possible, as the first heat, on a new bottom is already too liable to be a cold one.

**Operation of the Converter.**—Figures 51 and 52 are sections through a converter plant at different points. In Fig. 51, *A* is




FIG. 51.—Section through mixer and cupola house.

the mixer, capable of containing, say, 300 tons of metal; *B* is the ladle carriage from the blast furnace, from which the ladle *C* has been raised to pour the metal into the mixer. Immediately above *D* is the ladle that is to take the metal from the mixer to the converter, for which it is transferred along a level track until it comes to *E*, Fig. 52, where it is poured into the vessel, now in the horizontal position, as shown by the dotted line. When the metal has been poured in, the wind is turned on and the vessel elevated into the vertical position. The blast now pours through the 18 in. or so of metal in the bottom of the converter in a wide spray of tiny bubbles until the impurities are oxidized, when it is turned again into the horizontal position and the wind cut off. In anticipation of this a predetermined quantity of spiegeleisen has been tapped from the spiegel cupola into the ladle at *H* (Fig. 51). (For soft steel ferromanganese, not spiegeleisen, is used.)

Spiegeleisen is pig iron very high in manganese. Some analyses are given on page 7. It is melted in the spiegel cupola together with a predetermined amount of high-silicon pig iron, and is then used to recarburize the bath in the vessel, for which purpose the ladle is now run into the position *E*, Fig. 52, and its contents poured into the bath.

After the "spiegel reaction" is completed, the steel is poured from the converter into a ladle held at the point *O* by the jibberane *I*, or by one of the traveling cranes *K* or *L*. The ladle is then carried over to a position above the ingot molds into which the steel is to be teemed. In pouring the steel into the ladle, the




FIG. 52.—Section through converter house.

slag is held back in the vessel as much as possible, because this not only furnishes heat for the next operation, but also makes it shorter by as much as 20 or 25 per cent, because the slag, being an oxidized substance, assists in oxidizing the impurities in the next charge.

The turning on and off of the blast and the rotation of the converter is all executed by the blower, who stands upon the pulpit at *W* and operates the various valves, and also judges by eye the progress of the purification from the appearance of the flame which issues from the mouth of the converter.

Every effort is made by him to so arrange the different operations of the converter, cranes, and ladles and to bring in both spiegeleisen and iron, that each step shall fit into the others with-



out delay to the operation in any of the converters. He also has under his control means for lowering the temperature of the bath, if necessary: (a) By ordering an amount of cold steel scrap to be thrown into the mouth of the vessel during the blow<sup>1</sup> and (b) by admitting live steam into the converter with the blast. The decomposition of the steam very quickly reduces the heat of the blow. Attempts have been made to dispense with the blower, who, on account of the long training and experience necessary, is the most highly paid man in the plant next to the foreman, by



Converter.

Cupola.

Ladle.

Runner.

FIG. 53.—Pouring metal into the converter.

judging of the progress of the operation with the spectroscope; but when two or three vessels are blowing at the same time the reflected light from one interferes with the spectroscopic indications of the others. Furthermore, the spectroscope gives no indications of the temperature of the blow, and until the past few years no reliable pyrometer existed suitable for this use.

**Steel Ladles.**—The ladles to receive the steel and teem it into molds are steel shells lined with a cheaper grade of acid refractory material, because the life of these ladles is limited to about six heats by the wearing out of the nozzle, and therefore a more

<sup>1</sup> Scrap is so valuable for use in the open-hearth process that (b) is now used much more than (a).



expensive lining would be wasted. The arrangements of nozzles, stoppers, and handles shown in Fig. 54 are provided in order that a thin stream of steel may be poured into the molds and may be interrupted when a new mold is being brought into place. The slag lies on top of the metal, and when this begins to come out of the nozzle the stopper is let down and the ladle carried over a slag car and turned upside down to dump out the slag. At this time the blower observes the lining of the ladle in order to tell whether




FIG. 54.—Fifteen-ton steel teeming ladle.

the steel was too hot or too cold. If there is a skull of metal frozen inside the ladle, the steel was too cold; if there is no frozen metal, it was too hot; but if there is a spot of metal here and there on the bottom, it was just right.

**Ingot Molds, Stools and Cars.**—The arrangement of the molds into which the ingots are to be cast is shown in Fig. 57, which also gives the size of molds commonly used for railroad rails, wire, and pipe. Molds last about 100 heats, after which

they are so cracked inside that they are with difficulty lifted off the solidified ingot of steel, and are also very liable to tear it, producing cracks which are not easily welded up later because they become oxidized on the interior. A continuous series of mold cars are fed into the steel-mill at one end and drawn out, with the ingot inside, at the other end (see Fig. 57). They should be heated so hot that the palm of the hand will not bear the heat on the outside, and are washed inside with a thin clay



FIG. 55.—Teeming into molds.

wash which prevents the liquid metal sticking to the cast iron. At the pouring platform they are moved forward under the ladle by means of a little finger, which enters a notch in the side of the car and is itself carried on the rod of a hydraulic piston.

**Stripping.**—As soon as they can be run out to the stripping house, the ingots are solidified sufficiently on the outside for the mold to be removed, leaving the ingot standing on the car ready to be drawn to the rolling-mill. In the majority of cases it is only necessary to place the jaws of the stripping machine under the lugs on the mold, raise it up to a sufficient height, and then

transfer it to a stool on a car in the second track of the stripping house. (See Fig. 58.)

Sometimes the ingots do not come out so easily, however, and then the plunger is rested on top of the ingot, which is held down by the hydraulic pressure as the mold is drawn upward. Electrically operated stripping machines are now preferred to the older



(Courtesy, U. S. Steel Corp.)

FIG. 56.—Teeming a 100-ton open hearth heat into molds.

hydraulic type. The empty molds are stored in the yard until they are sufficiently cool to be drawn back to the steel-mill for another charge, and during the wait they are washed inside with clay water, which is quickly dried by the heat of the mold.

**Chemistry of the Acid Bessemer Process.**—If a stream of air be made to impinge upon a melted bath of iron, the metal and impurities will be immediately oxidized, about in proportion to the relative amounts of each present. We may therefore consider



FIG. 57.—Line of cooling ingot molds outside Bessemer mill.



(Courtesy, U. S. Steel Corp.)

FIG. 58.—Electric strippers in operation.






the chemistry of the Bessemer process as a union of the oxygen from the tuyeres with the first element it meets, irrespective of relative affinity, and a subsequent attack upon these oxidized elements by unoxidized ones.

Practically no oxygen of the air escapes from the bath uncombined, even though it has but 18 in. of metal to pass through and amounts to more than 5,000 cu. ft. per minute,<sup>1</sup> because the blast pressure is made high in order that the air may be broken up into



FIG. 59.—Soaking pit heating furnaces at rolling mill which receive the red hot, newly stripped ingot.



a fine spray of bubbles as soon as it strikes the metal and thus offer a large surface of contact for chemical reaction. As iron oxides are easily reduced, and as iron is the predominant element, it especially serves as a carrier of oxygen from the blast to the other elements :



<sup>1</sup> Air is composed of 20.8 parts, by volume, of oxygen and 79.2 parts of nitrogen, and the amount of blast per minute is 15,000 to 30,000 cu. ft. See "Analyses of Gases" in Table XVIII, p. 110.



In the first part of the blow, the oxides of carbon also suffer reduction:



At a later period this condition is reversed as described on pp. 105 to 109.

Equilibrium is therefore established by the elements which have the greatest chemical affinity for oxygen, getting practically all of that agent, either directly or by robbing their neighbors. Some iron oxide survives, however, because it is so predominant in amount that its neighbors cannot quite rob it before a part has united with silica, which is either formed by the oxidation of silicon or else won from the lining:



The ferrous silicate forms a slag with manganese silicate, and this slag will dissolve oxides of iron. Even after the oxide of iron has been so absorbed, it may be reduced by manganese and carbon, although not to the same extent.

**Slag Formation.**—Manganese oxide unites with silica:



and it is perhaps for this reason that manganese, unless very high (say over 2 per cent), is removed early in the blow. The silicates of iron and manganese dissolve in each other and form a slag, and this slag will dissolve large amounts of iron oxide, manganese oxide, silica and alumina, the latter coming from the vessel lining. At all times the bath is so violently agitated that the metal and slag are intimately mixed, and the reducing effect of manganese, silicon and carbon on the iron oxide dissolved in the slag limits it in amount. The slag itself therefore serves as a carrier of oxygen to the impurities.

**Critical Temperature.**—As the temperature rises, chiefly due to the oxidation of silicon, the chemical affinity of carbon for oxygen increases relatively more than that of the other impurities, and reaction No. 4 ceases and then reverses:



What the exact temperature of this reversal in has never been determined, but we may estimate it as being somewhere between 1,450 and 1,550°C. (2,642 to 2,822°F.), and unless the silicon is all oxidized before this temperature is reached, we shall have "residual silicon" in the steel. In English Bessemer practice,




FIG. 60.—Analyses of metal during acid Bessemer blow.




FIG. 61.—Analyses of slag during acid Bessemer blow.

TABLE XVI.—REMOVAL OF IMPURITIES IN THE BESSEMER CONVERTER, WITH ACCOMPANYING SLAG-ANALYSES

Time after commence- ment of blow		Removal of metalloids, per cent					Authority		Analysis of corresponding slags, per cent										
		C	Si	Mn	P	S			SiO	Al <sub>2</sub> O	FeO	Fe <sub>2</sub> O <sub>3</sub>	Iron shots	MnO	CaO	MgO	P	S	Alka- lies
Min.	Sec.																		
Pig iron.....		2.98	0.94	1.43	0.100	0.06			42.40	5.63	40.29	4.36	.....	6.54	1.22	0.36	0.008	0.009	
2	0	2.94	0.63	0.09	0.104	0.06			50.26	5.13	34.24	0.96	.....	7.90	0.91	0.34	0.008	0.009	
3	20	2.71	0.33	0.04	0.106	0.06			62.54	4.06	21.26	1.93	.....	8.79	0.88	0.34	0.010	0.014	
6	3	1.72	0.03	0.03	0.106	0.06			63.56	3.01	21.39	2.63	.....	8.88	0.90	0.36	0.014	0.008	
8	8	0.53	0.03	0.01	0.107	0.06													
9	10	0.04	0.02	0.01	0.108	0.06													
Steel.....									62.20	0.276	17.44	2.90	.....	13.72	0.87	0.29	0.010	0.011	
9	20	0.45	0.038	1.15	0.109	0.059				Al <sub>2</sub> O <sub>3</sub> & P <sub>2</sub> O <sub>5</sub>									
Pig iron.....		3.55	2.39	0.49	0.09				62.65	7.98	1.93	.....	10.52	15.78	0.65	0.52			
8	0	3.21	1.08	0.15	.....				73.24	4.51	0.00	.....	8.72	1.83	1.11	0.64			
15	0	1.25	0.11	0.13	0.09				75.63	5.19	0.00	.....	7.70	10.92	0.96	0.38			
17	0	0.207	0.06	0.13	0.08				61.30	4.24	13.47	.....	9.12	10.82	0.75	0.29			
18	0	0.034	0.04	0.10	.....				64.15	5.71	13.95	.....	2.39	12.81	0.75	0.24			
Steel.....		0.370	0.06	1.17	0.09					Al <sub>2</sub> O <sub>3</sub>									
Pig iron.....		3.93	1.96	3.46	0.040	0.018			40.95	8.70	0.60	.....	.....	2.18	30.35	16.31	0.01	0.34	0.32
After slagging.....		2.465	0.443	1.645	0.040	trace			46.78	4.65	6.78	.....	.....	37.00	2.98	1.53	0.03	0.04	trace
End of boil.....		0.949	0.112	0.429	0.045	trace			51.75	2.98	5.50	.....	.....	37.90	1.76	0.45	0.02	trace	trace
End of blow.....		0.087	0.028	0.113	0.045	trace			46.75	2.80	16.86	.....	.....	32.23	1.19	0.52	0.01	trace	trace
Pig iron.....		4.00	1.02	1.83	.....	.....			50.20	3.86	1.80	.....	.....	5.44	27.22	10.88			
3	0	4.30	0.03	0.22	.....	.....			55.26	2.86	14.20	.....	.....	26.31	0.62	0.22			
4	45	0.90	0.03	0.12	.....	.....			47.20	2.70	18.52	.....	.....	31.01	0.38	0.14			
5	45	0.10	0.03	0.09	.....	.....			40.50	2.24	31.19	.....	.....	25.43	0.32	0.11			




TABLE XVII.—REMOVAL OF IMPURITIES IN THE BESSEMER PROCESS

Time after commence- ment of blow	Removal of metalloids, per cent					References and remarks
	C	Si	Mn	P	S	
Min. Sec.						
Pig iron.....	3.52	3.00	1.25	.....	.....	German method. "Leaving Silicon in the Bath," <i>Stahl und Eisen</i> , vol. iii, pp. 262-264.
5 0	3.6	2.0	0.60	.....	.....	
10 0	3.3	1.25	0.20	.....	.....	
15 0	2.5	0.75	0.10	.....	.....	
20 0	1.0	0.65	trace	.....	.....	
25 0	trace	0.35	....	.....	.....	
Pig iron.....	3.5	3.0	0.75	.....	.....	German method. Same reference.
5 0	3.6	1.75	0.25	.....	.....	
10 0	3.3	1.25	trace	.....	.....	
15 0	2.5	0.9	....	.....	.....	
20 0	1.0	0.7	....	.....	.....	
25 0	trace	0.5	....	.....	.....	
Pig iron.....	3.52	1.85	1.93	.....	.....	German method. Carl Rott.
4 30	2.78	1.21	1.69	.....	.....	
13 0	0.43	0.93	1.00	.....	.....	
16 0	0.05	0.28	0.37	.....	.....	
Steel.....	0.23	0.27	0.62	.....	.....	
Pig iron.....	3.57	2.26	0.04	.....	.....	English method. Carl Rott.
6 0	3.95	0.95	trace	.....	.....	
12 0	1.64	0.47	trace	.....	.....	
18 0	0.19	trace	trace	.....	.....	
Steel.....	0.37	trace	0.54	.....	.....	
Pig iron.....	3.270	1.952	0.086	0.048	0.014	English method. Snelus. See <i>Encyclopædia Bri- tannica</i> , American ed., vol. xiii, p. 334.
6 0	2.170	0.795	trace	0.051	trace	
9 0	1.550	0.635	trace	0.064	trace	
13 0	0.097	0.020	trace	0.067	trace	
Steel.....	0.519	0.033	0.309	0.053	trace	
Pig iron.....	3.5	2.25	1.0	.....	.....	<i>Stahl und Eisen</i> , vol. iii, pp. 262-264.
5 0	3.6	1.0	0.35	.....	.....	
10 0	3.3	0.5	0.2	.....	.....	
15 0	3.25	0.2	trace	.....	.....	
20 0	2.0	0.1	....	.....	.....	
25 0	trace	trace	....	.....	.....	
Pig iron.....	3.50	1.50	0.71	1.57	0.16	"Basic Process," <i>Stahl und Eisen</i> , vol. iii, pp. 262- 264.
5 0	3.55	0.50	0.56	1.60	0.14	
10 0	2.35	0.09	0.27	1.43	0.13	
15 0	0.07	trace	0.12	1.22	0.12	
18 0	trace	....	trace	0.08	0.10	
Pig iron.....	2.97	0.53	0.61	1.22	0.15	"Basic Process," by Müll- er, at Hörde, <i>Encyclo- pædia Britannica</i> , vol. xiii, p. 346.
4 30	2.480	0.009	0.247	1.250	0.206	
9 15	0.811	0.0	0.0	1.320	0.262	
11 15	0.049	0.0	0.0	0.786	0.262	
13 0	0.0	0.0	0.123	0.021	0.206	




where silicon is often above 2 per cent of the pig iron, this is not rare, because the high silicon takes longer to go and also increases the temperature:



There is also a critical temperature for manganese oxidation, above which reaction No. 6 is reversed and residual manganese is left in the steel; but this happens only when the manganese in the pig iron is very high. No warning is given that the temperature is approaching these critical points, because no flame—nothing but sparks—comes from the mouth of the converter until carbon begins to burn, and therefore no indication is given to the operator of the degree of heat until too late.


**Second Period.**—The second period begins when the carbon commences to burn, which happens in America only after the silicon and manganese have been almost eliminated, as shown by Tables XVI and XVII and Figs. 60 and 61. During this period the reactions consist principally of the oxidation of carbon, although a little silicon passes off at the same time. Further details will be learned from the tables and figures. It is interesting to note that the phosphorus and sulphur in the metal are not eliminated, because the acid slag will not dissolve them even if they become oxidized. For this reason the percentage of these impurities increases slightly during the blow, because their actual weight remains the same, while the weight of the bath decreases.

**Gases.**—In connection with Table XIX it is interesting to note what a large proportion of the carbon is oxidized to the monoxide, and this is the more important because this formation generates only 29,160 calories, while the higher oxidation generates more than three times as much:



Thus a large amount of heat is wasted, and is generated only when

<sup>1</sup> It is immaterial from the heat standpoint whether oxidation takes place directly or as a result of two reactions:



the flame passes out of the mouth of the converter and unites with more oxygen. When the heat of a charge is too low, it is customary at some plants to tip the converter forward or backward, so that a few tuyere holes will be above the level of the bath and will blow free air into the interior of the converter. This results in a portion of the carbon monoxide being oxidized to carbon dioxide inside the converter, and is a limited means of making the blow hotter. Oxidation of additional iron by the same means also increases the heat generated.

TABLE XVIII.—ANALYSES OF BOTTOM-BLOWN CONVERTER GASES

Time after starting blow, minutes	Per cent					Reference
	CO	CO <sub>2</sub>	O	H	N	
2	.....	10.71	0.92	.....	88.37	} Sir Loth- ian Bell.
4	3.95	8.59	.....	0.88	86.58	
6	4.52	8.20	.....	2.00	85.28	
10	19.59	3.58	.....	2.00	74.83	
12	29.30	2.30	.....	2.16	66.24	
14	31.11	1.34	.....	2.00	65.55	
18	End of blow.					
3 to 5	.....	9.127	4.762	.....	86.111	
9 to 10	17.555	5.998	1.699	0.908	73.840	
21 to 23	19.322	4.856	0.967	1.120	73.735	
26 to 27	14.311	1.853	0.550	1.699	81.587	
2 to 3	.....	6.608	7.256	.....	86.137	
8 to 10	15.579	5.613	1.296	1.112	76.400	
12 to 15	25.580	4.144	0.980	1.040	68.256	
17 to 19	25.606	2.995	1.318	1.120	68.961	

**Slag.**—In Table XVI the lime and magnesia in the slag come from a small amount of blast-furnace slag which finds its way to the converter through the mixer, in spite of efforts made to hold it back at all points when pouring. Because the blast-furnace slag is basic, it has the effect in the converter of making the slags wet and sloppy, and therefore increasing the loss. Although the iron

as shot is only shown in one case, this is not because it is absent in the other cases, but merely because it was not determined. At all times the slag carries a great many pellets of iron, which should be added to the combined iron, since they represent a loss in the process. It is interesting to note how closely the amount of iron in the slag, after the spiegel addition, approximates 15 per cent,<sup>1</sup> and there seems to be a chemical balance which fixes this amount as a condition of equilibrium. When the silicon in the pig iron is higher, and therefore the amount of slag made is larger, there is a slightly lower percentage of iron oxide in it. The practice of "side blowing for heat," described above has the effect of increasing the amount of iron oxide in the slag by increasing the oxidizing influences in the interior of the converter. The rise in manganous oxide in the slag during recarburizing is, of course, due to the formation of MnO by the action of the manganese on the oxygen of the bath, while the iron oxide in the slag is reduced at the same time by the action of manganese and carbon.

The weight of slag at different periods of the Bessemer process has been calculated by H. H. Campbell<sup>2</sup> from its analyses, with the following average results:

TABLE XIX.—SLAG WEIGHTS IN BESSEMER PROCESS

Percentage of blow finished		Pounds of slag	Percentage of charge
20	Silicon flame	1,035	4.5
36	Brightening	1,146	5.1
66	Carbon flame	1,255	5.5
89	Full carbon flame	1,385	6.1

The final amount of slag made will probably average about 7.5 to 8 per cent of the weight of the metal produced, or, roughly, 7 per cent of the weight of the pig iron charged.

**Flame.**—A flame is the result of burning gas, and as practically the only gas in this process is carbon monoxide, there is no flame except during the period when the carbon is burning. In the first part of the blow a large number of small sparks issue from

<sup>1</sup> Not including pellets, which average 6 to 8 per cent more.

<sup>2</sup> See page 158 of No. 2. Old edition, 1904.



FIG. 62.—Bessemer flames during a blow.

the mouth of the converter, consisting mainly of pellets of iron and slag ejected by the blast. At the end of the first two or three minutes, a small tongue of reddish-yellow flame begins to pour from the mouth, showing that the carbon is beginning to be oxidized. This soon increases in size and brilliancy until a white-hot flame, 30 ft. in height, pours from the vessel with a loud roaring sound caused by the boiling of the bath and the passage of the blast and gas through it. This boil lasts until the end of the operation, and the bath is at all times violently agitated and intimately mixed with the slag, which greatly facilitates the reaction between the two. The process at this period presents a spectacle which is almost unmatched as a pyrotechnic display. Soon the flame begins to flicker or "feather" at the edges, as a warning that the carbon is becoming low, and finally it shortens or drops, whereupon the converter is immediately turned down and the blast stopped. The carbon at this time will be about 0.03 to 0.10 per cent, depending on how "full" or how "young" was the blowing.

At all times there is a varying amount of slag and metal thrown out of the mouth, so that the converter may be likened to a fountain of sparks, the great bulk of which consists of slag. Throughout the blow there is also a constant stream of fume issuing with the flame. It is a brownish-red smoke, which rises to a good height and consists principally of oxide of iron and manganese. Dr. Charles F. Chandler, Professor of Chemistry at Columbia University, while observing this smoke at the Homestead steel-works, suggested to me that it might be due to the formation in the bath of iron carbonyl, a volatile compound of iron, carbon and oxygen ( $\text{Fe}(\text{CO})_5$ ), and perhaps of manganese carbonyl also.

**Loss.**—The difference in weight between the pig iron charged into the converter and the steel ingots made will be 8 per cent in good practice, although running above that (say to 10 per cent) in some mills. This is distributed approximately as follows:

Carbon burned.....	3.5 per cent
Silicon burned.....	1.0 per cent
Manganese burned.....	0.5 per cent
7 per cent slag @ 15 per cent Fe.....	1.0 per cent
7 per cent slag @ 7 per cent iron pellets.....	0.5 per cent
Volatilized and ejected.....	1.5 per cent
	<hr/>
	8.0 per cent






**Recarburizing.**—It might be thought that a more economical method could be found than that of burning up all of the carbon in the pig iron and then adding the desired amount, and in fact such a method was employed in Sweden, where the carbon was burned down to the desired point, as estimated by the appearance of the sparks issuing from the converter, the vessel being then turned down and the charge held until a hammer-test confirms this estimate. Such a complicated procedure, however, requires a hotter bath and very slow working, and it is much cheaper to burn the carbon until the drop of the flame and then add the requisite amount. In making rail steel to contain about 0.50 per cent carbon, we will add to 15 tons of blown metal about 3,000 lb. of melted spiegeleisen, containing roughly 6 per cent of carbon, 12 per cent of manganese, and 1.50 per cent of silicon. The mixture charged into the spiegel cupola for melting must be higher in manganese than this, as there is a loss into the cupola slag by oxidation.

In making dead-soft steel for wire, material to be welded, etc., we add ferromanganese as high in manganese as possible. This material will contain about 7 per cent of carbon, 80 per cent of manganese, and 13 per cent of iron. It is only necessary to add about 500 lb. to a 15-ton bath, and therefore it will dissolve without being melted, although it is customary to heat it to a red heat in order to lessen the chilling of the metal. This dead-soft material will then have the requisite amount of manganese, but will be low in carbon and frequently less than 0.01 per cent in silicon. It is not improbable that pure manganese metal, if it were readily obtainable, would be used in many cases instead of ferromanganese, in order that the carbon might be still lower. Ferromanganese and spiegeleisen are made in blast furnaces by smelting very high manganese ores in a manner somewhat similar to the smelting of pig iron.


The chemistry of the recarburizing operation is important. The recarburizer is added both to give certain elements to the steel and to take certain impurities out of it. The importance of this second function will be appreciated on recalling that the makers of Bessemer steel were not able to produce a marketable product until they learned to take oxygen out of the liquid bath by means of manganese added with the recarburizer. Finally, the chemistry of the recarburizing operation is complicated by the circumstance that some reactions occur between the recarburizer and the slag of the process.

**Deoxidizing the Bath.**—The carbon, manganese and silicon contained in the recarburizer will all deoxidize iron according to the following type reactions:



Of these, manganese is the most powerful deoxidizer and will come nearest to ridding the bath of oxide. The CO has the disadvantage of being somewhat soluble in the molten metal; consequently, although large volumes of CO gas escape from the steel during the "spiegel reaction," there is, under normal conditions, a constant evolution up to the time when the metal becomes solid, and there is probably even a small amount of CO retained by the solid metal. This escaping gas is a cause of blow holes, as described in Chapter VIII. Silicon not only reduces iron oxide, but also is a prime factor in preventing these blow holes, as will also be described in Chapter VIII. The oxides of manganese and silicon tend to separate themselves from the liquid bath and it is thus that they remove the oxygen; whereas, the oxides of iron are much more readily retained by the steel. Nevertheless, the removal of oxygen by manganese and silicon is not complete; because firstly, the deoxidation of the FeO and Fe<sub>2</sub>O<sub>3</sub> is not complete and secondly, the oxides of manganese and silicon do not completely separate from the steel, but, on account of lack of fluidity, remain in tiny particles entangled in the solidified mass. Rail steels will probably contain 0.20 to 0.30 per cent of entangled oxides.<sup>1</sup> Unless there be an excess of manganese and silicon above that necessary to fulfill reactions (a) and (c), their deoxidizing effect is far from complete, and it is partly on this account that the recarburizer is so calculated as to leave about 0.70 to 1.10 per cent of manganese and 0.10 to 0.20 per cent of silicon in rail steel.


**Reactions between Recarburizer and Slag.**—The slag being an oxidized product and the recarburizer being essentially a reducing agent, there is always a certain interchange of elements between the two, the slag giving up some of its oxygen to the carbon and manganese of the recarburizer, and the latter contributing manganese to the slag, both by virtue of reaction (a) and of the following:



It will be observed by the analyses in Table XVI and especially by

<sup>1</sup>In this connection it is interesting to note the effect of vanadium in supplementing the deoxidizing effect of manganese and silicon.

Fig. 61, that the slag is decreased in iron oxides and increased in manganese oxide as a consequence of the recarburizing operation. It will also be observed in the same places that there is more iron oxide reduced than manganese oxide contributed and this effect is produced by direct reduction of iron, by means of CO, in accordance with the following reaction:



**Calorific Equation of the Acid Bessemer Operation.**—The predominant part that silicon plays in furnishing heat for the acid Bessemer process is shown by a calorific calculation. In making this, let us assume that we have a charge of pig iron weighing 30,000 lb., and that we burn: Silicon = 1.00 per cent; manganese = 0.40 per cent; carbon = 3.50 per cent; iron = 2.00 per cent. And let us assume further that the average temperature during the operation will be 1,500°C., and that the atmosphere is at 0°C. Then:

	POUND-CALORIES	SURPLUS POUND-CALORIES
Si + 2O = SiO <sub>2</sub> produces.....	1,900,000	
28.4 2 × 16		
300 lb. <sup>1</sup> + 338 lb. = 638 lb.		
338 lb. of oxygen = 1,470 lb. air.		
Specific heat air = 0.268 calories per pound.		
1,470 lb. × 1,500°C. × 0.268 = .....	591,000	
	<hr/>	1,309,000
Mn + O = MnO produces.....	198,000	
55 16		
120 lb. <sup>2</sup> + 35 lb. = 155 lb.		
35 lb. oxygen = 152 lb. air.		
152 lb. × 1,500°C. × 0.268 = .....	61,000	
	<hr/>	137,000
C + O = CO produces.....	2,552,000	
12 16		
1,050 lb. + 1,400 lb. = 2,450 lb.		
1,400 lb. oxygen = 6,087 lb. air.		
6,087 lb. × 1,500°C. × 0.268 = .....	2,447,000	
	<hr/>	105,000
Fe + O = FeO produces.....	704,000	
56 16		
600 lb. + 171 lb. = 771 lb.		
171 lb. oxygen = 743 lb. air.		
743 lb. × 1,500°C. × 0.268 = .....	299,000	
	<hr/>	405,000
Total net heat from chemical reactions =		1,956,000
<sup>1</sup> 30,000 lb. × 1 per cent = 300 lb.		
<sup>2</sup> 30,000 lb. × 0.40 per cent = 120 lb.		

Now let us suppose that the specific heat of the metal is 0.20 calories per pound, per degree Centigrade; then how many degrees will it be raised by the heat produced in the chemical reactions of the blow?

$$\begin{aligned} 30,000 \text{ lb.} \times 0.20 \text{ calories} &= 6,000 \text{ calories per } 1^{\circ}\text{C.} \\ 1,956,000 \text{ calories} \div 6,000 \text{ calories} &= 326^{\circ}\text{C.} \quad \text{Answer.} \end{aligned}$$

This simple calculation neglects the heat lost by radiation through the vessel lining, and the heat necessary to raise the silicon, manganese and carbon of the bath from their temperature at the beginning of the blow, to  $1,500^{\circ}\text{C.}$ , and also leaves out of account the heat produced by the combination of  $\text{FeO}$  and  $\text{MnO}$  with  $\text{SiO}_2$  to form the slag. All these figures are relatively less important, but those who desire to calculate with greater delicacy should consult J. W. Richards' very thorough little book, No. 6, Part II.

**Basic Bessemer Process.**—The basic vessel is mechanically the same as the concentric acid vessel, but the lining is made of calcined dolomite held together by about 10 per cent of tar and rammed in around a pattern while still warm. In ramming up the bottom wooden pins are rammed in with the lining, and when withdrawn they leave  $\frac{1}{2}$ -in. tuyere holes, through which the blast enters. The object of the basic lining is to resist the chemical action of the basic slag, and it is not desired to have it enter in any way into the chemical reaction. Therefore, before beginning the blowing, lime is added to the bath, equivalent in weight to 14 to 20 per cent of the iron, in order that it may form a basic slag, take up all the silica formed by oxidation, and prevent this silica from corroding the lining. The greater the amount of acid-making elements in the pig iron—*i.e.*, silica and phosphorus—the more lime must be added to flux them.

**Chemistry of the Basic Process.**—There is a degree of similarity between the removal of impurities in the acid blow and in the first part of the basic blow, as will be observed in the analyses in Table XVI, and in Fig. 63. Silicon is removed more rapidly in the basic process, however, both because it is less in amount and because its oxide is greedily absorbed by the basic slag. Manganese, on the contrary, goes more slowly, because its amount is larger and it is not attracted by the slag. Indeed it is not uncommon to find "residual manganese" after a basic blow, and this is considered an advantage because it reduces the amount of manganese necessary to deoxidize the bath. Carbon passes off after the silicon, and the phosphorus does not begin to be sub-



stantially removed until after the carbon is practically eliminated.<sup>1</sup> Consequently the drop of the flame really marks the beginning of phosphorus removal.




FIG. 63.—Analyses of metal during basic Bessemer blow.

**After-blow.**—This final, dephosphorization, period of the basic blow is known as the “after-blow,” because it follows what corresponds roughly to the ordinary blow of the acid process. During this after-blow phosphorus is rapidly eliminated and absorbed by the slag. We have no means of knowing by the appearance of the flame how this chemical reaction proceeds, and therefore the after-blow is continued on the basis of experience, by blowing for a certain number of minutes, or else a certain number of revolutions of the blowing engine. Phosphorus goes into the slag in the form of a lean phosphate of lime perhaps having the formula  $(\text{CaO})_4\text{P}_2\text{O}_5$ , which corresponds to about 60 per cent of lime and 17 per cent of phosphorus. A

<sup>1</sup> In short, we have here a reversal of the action in the Bell-Krupp Process, and for a reason already explained, namely, that carbon has a higher affinity for oxygen at high temperatures, such as prevail in the Bessemer process, but has a lower affinity for oxygen at low temperatures, such as prevail in the Bell-Krupp Process.



variable amount of sulphur is also eliminated during the after-blow and goes into the slag in the form of  $\text{CaS}$ . Some also may be volatilized as oxides of sulphur. A fluid slag and the presence of manganese both assist in the removal of sulphur, sometimes to the extent of 75 per cent of that present. The addition of a certain amount of oxide of iron as a flux with the lime aids in producing a fluid slag and also gives a slightly higher yield of steel.

**Recarburization.**—The bath must not be recarburized in the presence of a basic slag because the latter gives up phosphorus by reduction and the metal is “rephosphorized.” What the chemical action is that produces this “rephosphorization” is not clearly known, but it is probable that manganese is an important factor; hence an additional reason for adding as little manganese after the blow as possible, although this cannot be well controlled as the metal is more oxidized in the basic than in the acid blow, and therefore requires a larger addition of manganese to render it free from “red-shortness” and “rottenness.” The difficulty is avoided in great part by pouring off all the basic slag possible, and then holding more back in the vessel when the metal is poured into a ladle. The recarburization then takes place in the ladle instead of in the vessel. The other chemical reactions of the recarburizing operation are similar to those given under the acid process (see also p. 149).

**Slag.**—The proportion of basic slag made will naturally be greater than that of acid slag, and will usually total about 25 per cent of the weight of the metal. It is important to so control the blow that a slag shall be produced containing 15 per cent or so of phosphoric acid, as this makes it salable as an agricultural fertilizer. The amount of iron in the slag in oxidized form should not be above 10 per cent, although this will be increased by a few per cent of pellets.

**Loss.**—The loss of metal will be much higher than in the acid process, averaging perhaps 13 to 17 per cent, a part of which is due to the fact that the pig iron used contains a larger amount of impurities to be oxidized:

Carbon.....	3.7 per cent
Silicon.....	0.5 per cent
Manganese.....	1.5 per cent
Phosphorus.....	2.5 per cent
25 per cent of slag @ 9 per cent Fe.....	2.3 per cent
Pellets.....	1.0 per cent
Fume and ejected.....	1.5 per cent
	<hr/> 13.0 per cent

**Calorific Equation.**—Phosphorus is the main source of heat in the basic Bessemer process as shown by the following calculation:

TABLE XX.—CALORIFIC EQUATION OF THE BASIC BESSEMER PROCESS

Charge: 30,000 lb.

Analysis:

0.50 per cent silicon burned;	Temperature of atmosphere = 0°C.;
1.60 per cent manganese burned;	Specific heat of air = 0.268 pound-calories per 1°C.;
3.50 per cent carbon burned;	Specific heat of metal = 0.20 pound-calories per 1°C.;
2.50 per cent phosphorus burned;	Average temperature of blow = 1,500°C.

3.00 per cent iron burned:

Principle of calculation same as in "Acid Bessemer Operation," page 116.

REACTIONS	POUND-CALORIES	SURPLUS POUND-CALORIES
2P + 5O = P <sub>2</sub> O <sub>5</sub> produces.....	4,420,000	
62    80		
750 lb. 968 lb.		
4,209 lb. air × 1,500°C. × 0.268 = .....	1,692,000	
		2,728,000
Si + 2O = SiO <sub>2</sub> produces.....	950,000	
28.4 32		
150 lb. 169 lb.		
735 lb. air × 1,500°C. × 0.268 = .....	295,000	
		655,000
Mn + O = MnO produces.....	794,000	
55    16		
480 lb. 140 lb.		
608 lb. air × 1,500°C. × 0.268 = .....	244,000	
		550,000
C + O = CO produces.....	2,552,000	
12    16		
1,050 lb. 1,400 lb.		
6,078 lb. air × 1,500°C. × 0.268 = .....	2,447,000	
		105,000
Fe + O = FeO produces.....	1,056,000	
56    16		
900 lb. 257 lb.		
1,118 lb. air × 1,500°C. × 0.268 = .....	449,000	607,000
Total net heat from chemical reactions =		4,645,000

Thus, much more heat is generated in the basic process, but more is required because a large amount is absorbed by melting the additions of lime to form the basic slag, and also there is greater radiation because the blows are longer and the operation is slower.

**Comparison of Acid and Basic Bessemer.**—The basic Bessemer process finds its chief field in localities where the ores produce a pig iron very high in phosphorus, as, for instance, the Minette ores smelted in Germany and elsewhere. Germany was the great domain of the basic Bessemer process, as shown in Table XXI. The great skill of the Germans enables them to produce by this means a high grade of structural steel by a process which is not intrinsically as well adapted to improve the quality of the metal as any of the others, because of the greater oxidation of the bath, the danger of rephosphorization, and the liabilities to error in the "after-blow." England too is a large user of this process, but it is no longer in use in America because this country does not produce the desired grade of pig iron in sufficiently large quantities. We must have as much as 1.75 per cent of phosphorus in the pig iron or the metal will give a cold blow, and this pig iron must be obtainable at a cheap price or else the process is not commercial. The operating costs are high for several reasons: (1) The blows are long; (2) the basic lining is more costly than silica and wears out faster; (3) fluxes must be added to form the slag; (4) the mechanical handling is more complicated, due to the extra pouring off of slag, etc.

## CHAPTER VI

### THE OPEN-HEARTH OR SIEMENS-MARTIN PROCESS

#### OPEN-HEARTH PLANT

The different open-hearth operations are as follows:

1. Getting the stock to, and in, the furnace.
2. Supplying the furnace with fuel and air and preheating these.
3. Working the charge, repairing the furnace, etc.




FIG. 64.—Horizontal and vertical sections through open-hearth plant.

(In horizontal or vertical section the letters have the same significance): AA, Stock yards. BB, Reversing valves. CC, Charging mechanism on its tracks. DD, 10 O.H. furnaces. EE, Teeming mechanism. The regenerators are located under the charging platform.

4. Recarburizing.
5. Disposing of the steel and slag.
6. Repairing and preparing ladles, ingot molds, etc.

A plan and elevation of a typical open-hearth plant is shown in Figs. 64 and 69 B. It is not to be presumed that all plants are laid out in the same manner, but that shown is a modern type which is much favored in America.

**Arrangement of Plant.**—The principles of ample space in which to perform the operations listed above, minimum handling of materials and “back tracking” in transportation, and avoidance of interference of one operation with another govern the plant layout. It will be noted that there are two lines of track for the charging-box buggies, but these accumulate nevertheless and cause inconvenience, but the arrangement of casting pit avoids congestion in taking care of the finished steel. Where liquid spiegel is used for recarburizing, the melting cupolas are placed beyond the line of furnaces and the molten material brought in on the track used for charging box buggies;<sup>1</sup> the mixer is located similarly and hot pig iron brought in on its track, or else by the crane which spans the melting platform (see Figs. 65 and 76). The stripping machine is placed on the line of track between the casting-pit and the rolling-mill, so that the travel of materials is: Stock yard, melting platform, furnace, casting-pit, stripping machine, rolling-mill heating furnaces.

**Melting Platform.**—On the same level as the hearth, and in front of the furnace, is the melting platform, or working platform. The space above is spanned by one or more electric traveling cranes which assist in repairs to the charging machines, in handling materials on the melting platform, and in pouring molten pig iron into the furnace where such practice prevails. The melting platform has a small extension around the back of the furnace to afford access to the tap-hole and the ladle into which the steel is poured, and for putting the recarburizer into this ladle when necessary. Upon the working platform are the valve handles for regulating the admission of gas and air to the furnace and for reversing the current of these at the proper time.

**Gas Producers.**—The gas producers are situated outside of the furnace house but as near them as possible in order to minimize the loss of sensible heat and deposition of tarry components in the gas. This has the great disadvantage of placing the men on the working platform between the smoke and heat of the gas producers and the heat of the furnace, but there seems to be no good way of avoiding it.

<sup>1</sup> Or by the cranes over the casting pit.



TABLE XXI.—WORLD'S STEEL PRODUCTION 1920

Country	Total	Open hearth		Bessemer		Electric		All other processes
		Basic	Acid	Basic	Acid	Basic and acid	Crucible	
United States.....	42,132,934	31,375,723 <sup>1</sup>	1,296,172	0	8,883,087	502,152	72,265	3,535
Germany.....	19,000,000 <sup>2</sup>	7,592,901 <sup>2</sup>	380,155 <sup>2</sup>	10,629,697 <sup>2</sup>	155,138 <sup>2</sup>	←	200,928 <sup>2</sup>	→
United Kingdom.....	9,202,614	4,592,000	3,296,100	375,500	552,800	52,800	←	→
France.....	2,961,508	1,186,908		1,648,294	51,063	56,305	17,738	
Canada.....	1,126,753							
Japan.....	1,031,550 <sup>3</sup>							
Italy.....	700,000 <sup>3</sup>							
Russia.....	4,500,000 <sup>2</sup>							
Austria-Hungary.....	2,700,000 <sup>2</sup>							
Belgium.....	2,500,000 <sup>2</sup>							
Spain.....	200,000 <sup>3</sup>							
Sweden.....	426,000							
Total.....	80,000,000 <sup>3</sup>							

<sup>1</sup> Including Duplex.<sup>2</sup> 1913 figure. Recent data not available.<sup>3</sup> Estimated.

**Fuels.**—Where natural gas is available it is the best and cheapest fuel to use. Gas from the by-product coke ovens is often used when coke ovens are a part of the plant. This is now a common condition in America, coke being made in the plant itself for the use of the blast furnaces. Tar from by-product ovens is also suitable as an open-hearth fuel, but requires special burners, and the amount is seldom sufficient. Fuel oil and crude petroleum are now very common fuels. Pulverized coal is a good fuel, but requires costly apparatus to powder and handle it.



Charging boxes.

FIG. 65.—Melting platform and “low-type” charging machine. In the background the crane is bringing liquid metal.

Producer gas is the standard. Its manufacture is discussed in Chapter XIX. For open-hearth purpose it is advisable to bear always in mind that sulphur in the fuel may find its way into the steel bath. Producer gas is the only one of the fuels mentioned that is preheated; the others have sufficient calorific power to produce the desired temperature without preheating although the air must always pass through regenerators. Natural gas, by-product gas, oil, and tar would all decompose if heated.

**Stock.**—For its transfer to the furnace, the stock is loaded into steel boxes similar to those in Fig. 66. Three or four boxes are supported on a little car, which is transferred in a train to the melting-floor, passing over a pair of scales on the way, where the

weight is taken. Between the track of the charging machine and the line of furnaces runs the track upon which these cars are transferred, and if a constant supply of boxes is brought to the machine, it can empty them upon the hearth of the furnace at a




Fig. 66.—“High-type” charging machine and position of charging box when ready to dump. This shows also arrangement of tap-hole and spout in stationary furnace.

rate of about 50 boxes (equivalent to about 125 tons) per hour (see Fig. 66).

**Casting-pit.**—This pit is spanned by one or more electric traveling cranes of large capacity, which are used to hold the ladles while the steel is running into them from the tap-hole of the furnace and while it is being teemed into the ingot molds. They are also used to serve the pit for several purposes, such as carrying away the slag, transferring empty ladles to and from the point where they are lined and dried, etc.

### OPEN-HEARTH FURNACE

The form of a modern 100-ton open-hearth furnace is shown in Figs. 67 and 69. It consists of a long shallow hearth suitably enclosed in firebrick and bound together with steel. There are many more stationary than tilting furnaces, but the general principles of the steel-making operation are the same in both.

**Regenerators.**—With the furnace are connected two pair of regenerators which preheat the gas and air for combustion as described in Fig. 23. The internal volume of each of these chambers is equal to  $\frac{3}{5}$  to  $\frac{9}{10}$  of that of the working chamber itself. The larger the regenerators the greater will be the amount of heat intercepted in them, and therefore the lower the temperature of the gases that go to the stack. The amount of space actually

occupied by the bricks, or checkerwork, is the important consideration, however, and this should be from 120 to 350 cu. ft., total, for all four regenerators per ton of furnace capacity, the volume of the two gas regenerators usually being about 30 to 40




FIG. 67.—Longitudinal section of rolling open-hearth furnace.

per cent less than that of the air regenerators, because the volume of gas used is less than that of the air, and also because the gas does not require to be preheated so much, since it is already somewhat warm from the gas producer. During the operation of the




FIG. 68.—Cross section of rolling open-hearth furnace.

furnace more or less slag, dirt, and dust are carried over with the outgoing gases. To intercept this the slag pockets or dirt pockets *AA* are provided; but in spite of them the space between the bricks of the checkerwork become partially choked, and for this reason, as well as because the deposit of dust makes










Fig. 69B.—Cross section of 100-ton basic open-hearth furnace showing refractories used. See Fig. 69A on facing page.

(Both, Courtesy, Illinois Steel Co.)

the surface of the bricks rough, the total area between the bricks must be much larger than the area of the ports, so that the velocity of the gas will not be lessened. The furnace must be laid off for repairs when the passages between the bricks are choked by dirt, but, on the other hand, the interstitial space is limited, because the bricks must be laid in such a way that the maximum amount of surface shall be exposed and the gases forced to the greatest possible contact with them. The modern construction makes the regenerators as tall as possible in order that incoming gas and air may be forced into the furnace by the draught, and also because this chimney effect causes the incoming gas and air naturally to seek the hottest places and the outgoing gas the coolest places, in this way equalizing the temperature in the different parts of the regenerators. They should be not less than 15 to 20 ft. high.

The space underneath the checkerwork should be so large that the incoming gas and air will distribute itself nearly uniformly through the different passages, and the temperature of the fire-bricks at this lower part will be, say,  $400^{\circ}\text{C}$ . ( $752^{\circ}\text{F}$ .), although varying, of course, at different furnaces and at different times. When the regenerator is receiving the waste gas from the furnace, the temperature of these bricks will be that of the gases that go to the chimney, say 400 to  $600^{\circ}\text{C}$ ., and when the air or gas is passing through the regenerator on its way to the furnace, these bricks will be somewhat cooler, depending upon the length of time that the regenerator has been in this phase of the operation. The temperature of the bricks at the top of the regenerator will be about  $1,000^{\circ}\text{C}$ . ( $1,832^{\circ}\text{F}$ .), and therefore the air and gas entering the furnace will be the same.

**Valves.**—The reversing valves of the open-hearth furnace are a cause of large loss in producer gas, and sometimes the leak amounts to 10 or 20 per cent. Ordinary leaks may be prevented by having water-sealed valves, but sometimes the pressure of gas reaches the point where it overcomes the water pressure and escapes, causing a heavy loss. Moreover, water-sealed valves are open to serious objections: (1) The water may freeze, causing an endless amount of annoyance and trouble; (2) some water on the inside of the valve is vaporized and the vapor carried into the regenerator or into the furnace, where it absorbs heat; (3) the hoods are liable to warp with the heat; and (4) valves of this type are so heavy that elaborate mechanism is necessary to reverse

them. The common butterfly valves burn out rapidly and warp badly. If water-sealed, the hoods warp and leak. Lining the hoods with brick makes additional weight for shifting and adds very largely to the repairs. The mushroom type requires eight valves to a furnace and an elaborate arrangement for reversing them properly. They burn out badly unless water-cooled, when difficulty is met from freezing (see pp. 485 and 486).

**Ports.**—The ports are so arranged that the flame shall be deflected away from the roof and yet not impinge upon the bath, or impinge only very slightly, because the bath would thereby be oxidized excessively. The brick space between the gas and air ports is water cooled to promote longer life. The gas should be spread out all over the width of the hearth beneath the air, and the two should be brought together just before they enter the laboratory, or work-chamber. The air especially must be kept away from direct contact with the bath, and for this reason the gas-ports are placed below the air-ports, which arrangement has the further advantage of promoting a better mixing of the two, since the gas is lighter and therefore rises. In America the favorite arrangement is two gas-ports, above which is situated a long slit, extending almost the entire width of the furnace, which serves as an air-port. This is not universal practice, however, for in some cases there are two, or even three, air-ports. Natural gas and by-product gas require a different design of port from producer gas, while oil, tar, and pulverized coal are brought in through pipes. In one case the two gas-ports are built wide and low, so that they will deliver thin streams and get a better mixing of the two materials for combustion. The area of the air-port in a 50-ton furnace should be about 18 sq. ft., and the combined area of all the gas-ports on one end should be from 8 to 10 sq. ft., depending upon the quality of gas used.

The roof must be protected from the direct impact of the flame, because even the most refractory silica bricks would be melted by the intense heat. The chimney effect of the regenerators and uptakes gives the gas and air a velocity which causes them to enter the furnace with some force, and the construction of the ports directs the steam in the desired manner. The mouths of the ports are gradually melted away by the intense heat of combustion of the outgoing gases, until they finally cease to serve this purpose and it is impossible to get the proper mixing and the proper kind of a flame in the laboratory of the furnace. The

ports must then be repaired, else the temperature cannot be maintained.

The ports have to suffer the full temperature of the outgoing furnace gases (flame), and it has recently become more common to equip this part of the furnace with a water circulating system to keep the brickwork cool, which materially increases its life. The floor of the ports of basic furnaces are now commonly covered with a layer of chrome ore—a neutral refractory material which will not be slagged either by acid or basic fluxes. This protects the silicious brickwork of the port from the basic slag which is carried up by the outgoing gases. Occasionally the ports are capable of being removed and replaced bodily when worn out, like the bottom of a Bessemer converter.

**Draught and Chimney.**—The draught must be sufficient to catch the flame about in the middle of the laboratory and drag it out through the ports on the opposite side from which it entered without allowing it either to drop down and touch the bath (as

TABLE XXII.—CALCULATION OF DRAUGHT OF CHIMNEYS

The draught in a chimney is produced by the gases within it being lighter than the air outside, and this lightness is due to their being hotter. In this calculation we assume the following data:

Data assumed	{	Air weighs 1.29 oz. per cubic foot at 0°C. and 760 mm. pressure;
		Chimney gases weigh 1.03 times air at 0°C. and 760 mm. pressure;
		Water weighs 772 times air;
		Mercury weighs 13.6 times water;
		The friction of a chimney absorbs the equivalent of 0.1 in. of water on a water gauge showing draught, for every 100 ft. height of chimney.

As the gases rise in the chimney they cool; therefore their average temperature will be about 50°C. cooler than their temperature at the foot of the chimney. Call this average temperature  $T^{\circ}\text{C}$ . Then:

$$1.29 \text{ oz.} \times 1.03 \times \frac{273^{\circ}\text{C.}}{T^{\circ}\text{C.} + 273^{\circ}\text{C.}} = \text{the weight of 1 cu. ft. of the chimney gases at the temperature } T^{\circ}\text{C.}$$

Subtract this weight from 1.29 oz. and we get the difference in weight of air and the furnace gases at the temperature  $T^{\circ}\text{C}$ . Then:

$$\text{Height of chimney} \times \text{difference in weight} = \text{ounces draught pressure per square foot of chimney area.}$$

$$\frac{\text{Ounces draught} \times 12 \text{ in.}}{1.29 \text{ oz.} \times 772} = \text{equivalent height of water gauge.}$$

From the height of a water gauge so found, we must subtract the amount lost by friction, or 0.1 in.  $\times$  height of chimney  $\div$  100.

For further modifications of this type of calculation see No. 6, Part I.



this is to be heated almost altogether by radiation) or to impinge upon the roof. This draught also has to do the work of overcoming the friction of the outgoing regenerators and flues. Its force will depend upon the height of the chimney and the temperature of the products of combustion after they have left the regenerators, which should be about  $400^{\circ}\text{C}$ . ( $752^{\circ}\text{F}$ .), though even better economy (*i.e.*, a lower temperature) than this is obtained in many cases. All the heat carried away by these flue gases is of course wasted, but the great cost of the refractory bricks in the regenerative chambers makes it unwise to reduce the temperature of the flue gases too much by enlarging the checkerwork. The calculation of the amount of draught produced by any given height of chimney with any given temperature of flue gases, according to the method of Prof. J. W. Richards, is given in Table XXII. A normal chimney is about 150 ft. high and 5 ft. inside diameter.

**Roof.**—The roof is made very thin and of the most refractory bricks that can be obtained, *i.e.*, almost pure silica, with only enough lime to hold it together in a compact mass. The side walls are also thin, and the radiation from the furnace chamber is great, but this has to be endured, as thicker walls and roof produce endless trouble by melting of the brick. The roof is arched and suspended from beams independent of the side walls.

**Life of the Furnace.**—The “life” of an open-hearth furnace means the number of heats that it can make continuously without stopping for any more extensive repairs than can be made without allowing it to cool down. No figure can be given for this except in the most general way. The life of the furnace will be ended usually in one of three ways: (1) The falling in of the roof, (2) the eating way of the ports, so that the flame can no longer be maintained properly, or (3) the giving out of the regenerators, which may occur either through the choking of the checkerwork, or through a crevice formed by the contraction and expansion of the bricks, so that there is a serious leak between the gas-chamber and the air-chamber, and premature combustion takes place. If the roof of a basic furnace lasts 350 heats, it is considered good work. The other parts of water-cooled furnaces, and furnaces having greater length—40 ft. and over—will last nearly twice as long. Three hundred and fifty heats would mean about 18 to 24 weeks’ work in America. An acid furnace will last about



1,000 heats. Foundry furnaces will only last about one-half as many heats as given above in many instances. The reasons for this are the higher temperatures usually attained when making steel for castings, and the longer heats. Another important factor in the life of the furnace is its continuous operation, as contrasted with shutting down each week-end. The continuous operation is now the standard practice, because it saves repairs, heat, and labor charges. Many steel foundries only take two heats per day from their open-hearth furnaces, and most of them shut down for Sunday.

**Construction of Hearth and Bottom.**—The hearth is made with a thickness of 18 to 24 in. inside the furnace shell, in the form of a shallow dish whose sides reach up to the level of the charging doors, and so constructed that the depth of the metal will be from 12 to 24 in.—the former figure in the case of a very small furnace, say 5 to 15 tons, and the latter in the case of one of 100-ton capacity. If the bath is too shallow the oxidation will be excessive and the wear of the lining by oxide of iron, with consequent production of slag, will be great;<sup>1</sup> if the bath is too deep, the melting and oxidation will be slow. In the case of an acid bottom, that portion of the lining next to the shell will be made up of refractory clay brick, and the upper portion will be formed by shoveling in silica sand, spreading it out in a thin layer about  $\frac{1}{2}$  in. thick over the entire hearth, and then allowing it to sinter at the full heat of the furnace for about 10 min., so as to set it firmly in place. Upon this layer will be set another layer in like manner, until the whole hearth is constructed, and then it will be “washed” with a melted bath of old slag to fill up all crevices and give a glazed surface.

In the case of the basic hearth, the bottom is made of calcined magnesite, held together with 10 per cent or less of anhydrous tar. In this case the layer of brick next to the lining is very thin (see. Fig. 70) and the magnesite and tar are set in in layers by the heat of the furnace as in the case of the acid lining. The tar burns to a strong coke, which holds the mass together in a firm hard form. In some cases no tar is used, and the calcined magnesite is fritted slightly to hold it together; in other cases 25 per cent of slag is used as a bond. Pure magnesite gives a more per-

<sup>1</sup>In an open-hearth furnace the lining suffers the greatest wear at the side of the bath where the bath is thin, because the oxidation of the metal is the greatest there.

manent lining than dolomite,<sup>1</sup> and is now much used since its longer life more than compensates for its greater expense. Even when magnesite is used for the bottom, the topmost layer, or working bottom, and the repairs, or "fettling," put in during the intervals of the furnace life, are made of dolomite, because this sets more quickly. As the sides and roof even of the basic furnace are made of silica bricks, it is customary, although not absolutely necessary, to put a layer of neutral material between these bricks and the basic hearth, and also to protect this joint from excessive heat. The neutral material commonly used is chromite bricks, which are made of ground chromite ( $\text{FeO}, \text{Cr}_2\text{O}_3$ ), held together with tar and then burned to form a firm, hard mass.




FIG. 70.—Materials of construction and lining for basic open-hearth furnace.

**Repairing Bottoms.**—Between the heats, bottoms are repaired by filling up holes with acid or basic material, as the case may be. In this way the bottom may be made to last almost indefinitely, unless a part of the charge works its way down a crevice and forces up whole sections of the bottom lining, which not infrequently happens; while sometimes the charge even works its way out through the bottom of the furnace. A sticky or viscous slag is also liable to bring the bottom up by sticking to it. In the tilting furnace, the bottom may be repaired along the point where

<sup>1</sup>Dolomite is a magnesia limestone, and after calcining consists of a mixture of lime and magnesite (CaO, MgO), with a little silica and other impurities.

the worst corrosion usually takes place—*i.e.*, at the edge of slag line—during the operation, by tipping the furnace until this place is uncovered.<sup>1</sup> In a 100-ton basic furnace as much as 1 to 2 tons of dolomite will be shovelled in between each two heats. An appliance is now available for squirting a stream of lining-repair material into the furnace between heats, through a hose which directs it exactly to the point desired, and lessens labor and time in making repairs.

**Tap-hole.**—In the stationary furnace, the tap-hole is made according to the section in Fig. 66. This is closed by material




FIG. 71.—Removable buggies to catch slag in slag pockets.

rammed into it from the door of the furnace. It sets quickly into a solid mass, which is pierced with a pointed bar when it is desired to allow the metal to run out. Recent practice in tapping involves clearing away the clay with an iron bar and then burning a hole through the red-hot, but solid, metal inside with a stream of oxygen. The hole is then often closed with a mud gun, similar to that used in blast-furnace practice. After tapping, the hole must be entirely freed from metal, and then it is made up and filled anew, ready for the next operation. Tap-hole troubles are lessened by keeping the hole clean, which is accomplished occasionally by a blast of compressed air. Otherwise the tap-hole may cause trouble by the charge working through it pre-

<sup>1</sup> See p. 139.

maturely, or, on the other hand, by its becoming so hard that a hole is pierced in it only after a long delay and much difficulty during which the oxidation continues in the charge beyond the desired point. In the tilting furnace there is no tap-hole, strictly speaking, but the opening into the metal spout is closed by loose material, which is scraped away before the furnace is tipped to pour the charge.

**Tilting Compared with Stationary Furnaces.**—Tilting or rolling furnaces are more expensive to install than stationary ones, and



FIG. 72.—Tapping steel into ladle from tilting open-hearth furnace.

require repairs to the machinery and power to operate them. They also require special arrangements of ports and uptakes, to be described later, and means for cooling the junction between the movable and stationary parts of the furnace. Their advantages are that they do away with troubles and delays from the tap-hole, the slag can be poured off at any time, and the charge may be tapped at a moment's notice, which is especially advantageous



when making steels within very narrow limits of composition. One can also tap a part of the charge when using a rolling furnace. Furthermore, the back-wall of the bottom may be repaired more easily between heats when the furnace itself is still white hot. In the stationary furnace the angle of this back-wall will be about 60 or 70 deg. from the horizontal, and loose material thrown in from the front doors will not rest on this angle; but the tilting furnace can be tipped until the back-wall is more nearly horizontal, and then loose material will remain upon it until sintered into place. The tilting type is of more advantage in the basic process than in the acid, because it enables the slag to be poured off at will, which is occasionally advantageous in basic practice. In that special type of practice known as the Talbot process, which will be discussed shortly, a rolling furnace is essential because a part of the charge must be poured out of the furnace without removing all. Except for foundry work, it is now unusual to install tilting or rolling furnaces. Foundry furnaces are generally small in size; 15- to 30-tons capacity is a common limit, and individual furnaces run as low as 5 or even 3 tons. These furnaces are most often charged by hand, and the rolling type facilitates this operation somewhat. The ease of tapping is an especial advantage where castings are being made, because delays may cool the metal to the point where castings will not run readily, or the carbon may be burned out excessively and the metal lack fluidity on this account.

**Tilting Furnaces.**—There are two types of tilting furnaces, known respectively as the Campbell and the Wellman. In the Campbell type the hearth of the furnace is arranged so that the center of tilting is coincident with the center of the ports, and therefore the furnace can be oscillated without shutting off the supply of gas and air. In order to facilitate this, there is a little clearance between the uptake and the furnace proper, and these parts are surrounded by water-cooled castings. In the Wellman type the gas and air supply must be cut off when the furnace is tilted. In tipping the Wellman furnace the ports move with the hearth, and they are therefore seated in a water tank, which makes an air-tight connection with the regenerators when the furnace is in a horizontal position, but breaks it when it is tipped forward.

The Wellman type is not so expensive to build as the Campbell, and probably requires less repairs. The Campbell type has the



advantage that the bottom can be repaired along the slag line without interrupting the operation, and that the lining can be sintered into place by the heat of the flame when the hearth is in any position. This is more important in the acid furnace than in the basic, where the mixture of dolomite and tar can be set by the heat contained in the furnace walls themselves. In the Wellman type, when the furnace is tipped for pouring, cold air can enter it through the port-holes, and may oxidize the manganese in the final product after recarburizing. Finally, a great advantage of the Campbell type is the fact that a great deal of ore can be used during the operation, and although the boiling of the charge is violent on this account, metal does not flow out of the furnace doors, because the hearth can be tipped in the opposite direction. The slag which runs off during this period is allowed to pass through a hole in the bottom of the port-opening, at the joint between the fixed and the rotating portion, where it is continually exposed to the flame and therefore not liable to chill up.

**Temperature.**—There is almost no limit to the temperature attainable in the open-hearth furnace by frequent reversing of the valves, except the danger of melting the roof. The temperature is controlled by the intervals of reversing, and by throttling the amount of gas and air admitted to the furnace. It is the almost universal practice to reverse the valves every 15 to 20 min., in order to maintain a uniform temperature of the regenerators. The melter endeavors to keep the charge always in a very liquid state, and at the same time to have a slight excess of air, in order that the atmosphere of the furnace may be slightly oxidizing to burn the impurities in the metal. Every excess of oxygen, however, causes a loss of heat, because each volume of oxygen in the air is accompanied by four volumes of nitrogen, which carries heat out of the furnace, but does not assist in any way in the reactions. The actual temperature of the furnace will depend upon the length to which the decarburization is carried, because as the metal gets lower and lower in carbon, it requires a higher heat to keep it fluid. It will average about 1,600 to 1,700°C. (2,912 to 3,092°F.).

**Fuel.**—The amount of fuel burned per ton of steel made will depend not only on the quality of fuel, and skill of the operator of the furnace, as well as that of the gas-producer man when this type of fuel is used, but it will also depend on the length of the

heats and the temperature desired for the product. The more impure the metal being converted the longer will be the heats; the greater the degree of purification, the longer the heats. For example, if we purify a charge consisting chiefly of pig iron, and remove all but traces of the phosphorus, and most of the carbon, it will take longer than to melt a charge of 20 per cent pig with 80 per cent of steel scrap and leave 0.70 per cent of carbon in the steel. Furthermore, low-carbon steel must be delivered hotter than high-carbon steel in order to have the necessary fluidity. The more fluxes we have to melt, the greater the amount of heat to be supplied, etc. The average fuel consumption when using producer gas will probably be between 400 and 800 lb. of coal per ton of steel made for ingot steel—and this includes the small amount of gas used for preheating ladles, etc.—and 600 to 1,000 lb. per ton for castings. Natural gas in the Pittsburgh district for ingots will average between 5,000 and 6,000 cu. ft. per ton of steel. The amount of fuel oil used will be within limits of 30 to 50 gal. per ton of steel. Good foundry practice making two heats of steel per day will use not much over 40 gal. per ton.

**Size of Open-hearth Furnace.**—In a 50-ton open-hearth furnace the bath will have a length of about 30 to 35 ft., a width of about 12 to 15 ft., and a maximum depth of about 24 in. In America, however, there is now a tendency to increase the size to a capacity of 80 or even 100 tons. The result is a much better opportunity for complete combustion within the laboratory of the furnace, and therefore less deferred combustion as the gases escape through the ports and downtakes. This lengthens the life of the ports and promotes fuel economy.

The smallest practicable size of an open-hearth furnace is about 5 tons, and this is very expensive to operate. There are furnaces, however, as small as  $\frac{1}{2}$  ton capacity, but this is not good practice, even under the special circumstances which alone justify the use of the 5-ton furnace. The maximum practical size will not be far above 100 tons, and the real governing factor is the ability of the mechanical apparatus to handle the raw material and the product, besides which it is difficult to cast so much metal out of one ladle without having the casting temperature of the first metal too hot, or else that of the last metal too cold. A special process—that of Benj. Talbot—overcomes this objection.

## BASIC OPEN-HEARTH PRACTICE

Formerly, open-hearth practice was divided into two types, known respectively as the "pig-and-ore process" and the "pig-and-scrap process." In the pig-and-ore process the charge consisted entirely of pig iron, and the oxidation was hastened by the addition of as much ore as the charge would stand without boiling over; in the pig-and-scrap process the charge consisted of pig iron with large amounts of steel scrap, the proportion of the latter being so large in some cases that the operation became a mere remelting process, there being only enough pig iron for its silicon, manganese and carbon to protect the metal from excessive oxidation. At the present time normal charges consist of pig iron and steel scrap, in proportions determined by financial considerations, and the operation is hastened by judicious additions of ore. The amount of steel scrap will vary all the way from 0 to 90 per cent, and will average not far from 50 per cent in America. By decreasing the proportion of impurities in the raw material in the charge the scrap enables the process to be completed in less time.

It might seem as if the use of molten pig iron direct from the blast furnace, or through the medium of a mixer, might be as advantageous in open-hearth practice as in Bessemer; but this is not quite so, because the metal in the open-hearth is subjected to oxidation at the same time that it is being melted, so that charging molten material does not shorten the operation as much. The time and labor cost for charging is less, but this advantage is partly neutralized by the scorification and wear of the hearth produced by the inpouring stream of melted metal. About one-half the open-hearth steel of America is made from molten pig. Where it is used the calcined limestone is charged first, on top of that the ore, the steel scrap and any other cold metal, and finally the molten metal is poured in after the solid metal begins to melt. In this way the hearth is protected as much as possible from being cut, and splashing against sides and roof avoided, which would occur if solid pieces were dropped into liquid metal.

**Pig-and-ore Process.**—Where pig iron is cheaper than scrap, the charge may consist entirely of pig and ore and it is then customary to hasten the operations by some of the special processes, such as the Talbot, the Monel, the Hoesch, etc. These conditions prevail in Germany, and there is occasionally practiced

the charging of molten pig iron from the blast furnace together with a fairly large proportion of ore. The working down of such a charge is shown in the Table XXIII.

Such a charge, however, must be under 1 per cent phosphorus at the start, or the carbon will be gone before the phosphorus and the operation be much delayed by "pigging up."<sup>1</sup> The ore should be charged first and the molten metal poured upon it. After approximately half the time of the heat is past, about one-half the slag is removed, carrying with it the bulk of the phosphorus and sulphur. The interposition of a mixer between the blast furnace and the open-hearth furnace gives a greater uniformity in the analysis of pig iron supplied to the open hearth, and also enables some sulphur to be removed in the mixer. In some cases the mixer is used as a preliminary refiner, about 4 to 5 per cent of ore, and 5 to 6 per cent of lime being added to it. In the mixer, manganese, silicon, phosphorus and sulphur are thus removed in amounts worthy of consideration. Purifying in the mixer increases the output of the open-hearth furnace; moreover, the costs for repairs, labor and fluxes in the mixer are comparatively small.

**All-scrap Process.**—In certain localities in America, steel scrap is cheaper than pig iron, but its use is open to the objection that it is severely oxidized and wasted during the melting period unless there be some pig iron with it to give a reducing influence. Instead of using pig iron, however, some plants now replace it with coke, or with a carbonaceous material. The proportions are usually not less than 20 per cent coke and the balance steel scrap.

**Normal Pig-and-scrap Process. Order of Charging.**—In the pig-and-scrap process using about 50 per cent of each, the order of charging for a 75-ton basic furnace is as follows: About 6,000 lb. of small steel scrap is spread evenly over the bottom, preference being given to plate scrap because of its greater covering power. It is placed here for the purpose of protecting the bottom. On top of this is charged from 12,000 to 16,000 lb. of limestone and about 8,000 lb. of ore or scale. Then follows about 70,000 lb. of scrap and 30,000 lb. of pig iron. After about 2 hr. the heat of the furnace has softened this charge so that it has sunk in the furnace and there is room for the final charge consisting of some 12,000 lb. of scrap and 60,000 lb. of pig.

<sup>1</sup>To "pig up" is to increase the carbon by the addition of pig iron to the bath.



TABLE XXIII.—NORMAL PIG AND ORE PROCESS. CHARGE: 49,385 LB. MOLTEN PIG IRON; 12,345 LB. ORE; 3 TO 4 PER CENT LIME BETWEEN 1:45 AND 5:00

Time	Analysis of metal					Analysis of slag				Remarks
	C	Mn	P	Si	S	SiO <sub>2</sub>	FeO	MnO	P <sub>2</sub> O <sub>5</sub>	
12:45	3.610	2.320	0.670	1.890	0.044	.....	.....	.....	.....	Charging finished.
1:45	2.720	0.038	0.005	0.500	0.030	20.99	33.25	10.86	7.33	Warm and boils.
2:15	2.450	0.046	0.035	0.050	0.030	20.98	33.70	11.00	7.30	Begins to foam.
2:45	2.340	0.046	0.027	0.031	0.028	21.15	30.14	11.29	6.96	Warm and foaming.
3:15	1.940	0.054	0.020	0.042	0.026	22.35	24.47	11.68	7.59	Foams and is colder.
3:45	1.760	0.061	0.040	0.065	0.026	23.66	19.02	11.91	7.81	Foams and is colder.
4:15	1.680	0.084	0.044	0.033	0.030	23.83	15.57	12.24	7.95	Foams and is colder.
4:45	1.170	0.154	0.065	0.053	0.026	24.55	11.12	12.19	7.40	Cold.
5:00	1.140	0.199	0.094	0.035	0.034	25.76	9.57	11.80	7.21	Warmer and boils.
5:15	0.820	0.261	0.140	0.017	0.028					
5:45	0.710	0.307	0.138	0.015	0.028	22.67	7.44	10.43	6.41	Warmer and boils, 880 lb. ore.
6:00	0.610	0.192	0.051	0.031	0.040	21.32	11.46	9.67	5.43	Warmer and boils.
6:20	0.375	0.253	0.019	0.015	0.036	22.56	9.90	9.28	6.89	Warmer and boils. 880 lb. ore.
7:00	0.090	0.261	0.059	0.010	0.030	21.87	10.57	8.38	6.30	Carbon low enough.
7:15	0.084	0.269	0.035	0.020	0.038	21.17	10.34	7.95	6.21	353 lb. ferromanganese.
7:30	0.089	0.499	0.067	0.004	0.042	20.29	9.45	9.24	5.73	Steel.




**Rationale of Order of Charging.**—Limestone is charged at the bottom in order to avoid the insulation of heat which would be caused by its intervening between flame and metal; also to protect the basic bottom from scorification; also to keep it down and away from the first slag formed, which would otherwise be too basic, and viscous, and, finally, to defer the "lime boil" to a later period of the operation, as will be described later. The ore is put towards the bottom in order that it may oxidize the pig which melts early and drops down. If cold pig iron is charged it is placed on top, because its impurities protect it from oxidation more than scrap.

**Composition of Pig Iron Used.**—Basic pig should be free from adhering sand, and therefore only machine-cast metal will ordinarily be used, or else that cast in metal molds. Its silicon should be below 1 per cent, and its manganese above 1 per cent, though the price of manganese ore makes this ingredient an expensive luxury. It is desired because it makes the slag more fluid and aids in removing sulphur. The phosphorus will be almost any figure up to 2 per cent, but a regular supply of pig with more phosphorus than that would tempt the manager toward the basic Bessemer process. Silicon and phosphorus increase the amount of slag, lengthen the operation, and require lime to flux them.<sup>1</sup>

**Fluxes.**—The function of the basic lining is to remain inert and serve simply as a container for the bath. In order that the slag may be at all times rich in lime (35 to 45 per cent CaO ordinarily), from 5 to 30 per cent of lime is added with the pig and scrap, the exact amount depending upon the impurities in the metal charged. Especially if the charge is high in sulphur, the slag must be kept as rich in lime as possible without making it too infusible and therefore viscous, the limit being about 55 per cent CaO. The lime is usually added in the form of calcined limestone, and, as already noted, the higher the silicon and phosphorus in the metal the greater must be the amount of lime used. It is also customary to charge ore with the pig and scrap, in order to increase the amount of oxidation that takes place during the melting period. This ore has very little effect on the basic lining, although it would rapidly corrode a silicious one. Further additions of ore are made during the operation if necessary. The average total amount of ore added to a 50-ton charge will be between  $\frac{1}{8}$  and  $2\frac{1}{2}$  tons, equal to 0.25 to 5 per cent.

<sup>1</sup> Analysis of basic pig iron in Table VI, p. 37.

**Chemistry.**—It takes about 4 or 5 hr. for the charge to melt down level, and during that time the silicon is almost entirely eliminated, while the proportion of carbon and manganese is somewhat reduced, as shown by Figs. 73 and 74, which also show the chemical changes that take place during the entire operation. These reactions must be controlled by the melter, because it is necessary that the carbon shall be eliminated last, and therefore it is occasionally necessary to “pig up” the charge, *i.e.*, add pig iron in order to increase the amount of carbon. Pigging up is also resorted to for the purpose of creating a boil (by the escape of CO gas) and thus stirring the metal. This brings up hotter metal from the lower level and increases the heat by the burning of impurities in the pig. The practice of pigging up, except in rare cases, is an indication of previous poor judgment, or poor practice. On the other hand, in case the phosphorus is being eliminated very fast, the oxidation of the carbon may be hastened by “oreing down,” as it is called, *i.e.*, adding ore to produce the reaction.





If the carbon is eliminated before the phosphorus, a great deal of iron will be oxidized, because the phosphorus does not protect it as much as the carbon.

When the charge is entirely melted,<sup>1</sup> and at intervals thereafter, the melter takes a spoon-ladle full of metal and pours it into an iron mold. As soon as this is set hard it is cooled in water, and from the appearance of its fracture the melter can estimate very closely the amount of carbon and phosphorus it contains. In many plants it is customary to tap heats on these estimates alone and astonishing accuracy can be obtained by these methods as to the amount of carbon contained in the bath of steel. In all large plants, however, the laboratory analysis is made for phosphorus and usually for carbon as well, and these determinations may be made in 20 min. or less.

**Functions of the Slag.**—The functions of the slag are: (1) To absorb and retain the impurities in the metal, particularly silicon, manganese and phosphorus, and as much sulphur as possible; (2) to lie upon the top of the bath as a blanket and protect it from excessive oxidation by the furnace gases; and (3) to oxidize the

<sup>1</sup>The charge is not entirely melted until the lime has come up, which takes place about 2 hr. after the charge has melted down level.

impurities of the bath by means of its dissolved iron oxide, which comes chiefly from ore, scale, etc., added by the "melter."



FIGS. 73 and 74.—Chemical changes in bath and slag in basic open-hearth furnace.

For the retention of phosphorus and sulphur, the slag must be rich in bases. For the oxidizing it is necessary that the slag shall be fluid, so that it will mix easily with the bath, and therefore the

content of lime must not be too high. During the boil, when the carbon is passing off, there is an intimate mixture of metal and slag, and there is even such a violent agitation of the bath that the metal itself is frequently uncovered in places and exposed to direct oxidation by the furnace gases.

The removal of sulphur is a variable quantity and cannot be altogether depended upon, but there is usually a large loss of this element during the operation, in spite of slight additions of sulphur from the coal through the gas. This sulphur reduction is greatly assisted if the slag is thinned out (*i.e.*, its melting-point reduced) by the addition of calcium fluoride ( $\text{CaF}_2$ ) just before the end of the operation. The higher the slag is in lime, provided it remains at the same time fluid, the more complete in general will be the sulphur elimination, but over 55 per cent of lime usually makes the slag viscous, unless the calcium be added in the form of fluoride, or of chloride ( $\text{CaCl}_2$ ). The latter agent was added in many cases by the recommendations of E. H. Saniter, but the practice was never general in the United States, and the use of calcium fluoride (known as fluorspar) answers most purposes, unless the sulphur in the charge is excessive. Manganese assists in sulphur removal by forming  $\text{MnS}$ , which floats to the surface. The sulphur in this is slowly oxidized and the manganese returns to the metal.

It is of importance that the final slag in the open-hearth operation shall be a nonoxidizing one, lest the metal itself be full of oxide and very "wild," *i.e.*, give off gas abundantly during solidification. Therefore for the best quality no ore should be added within one hour of the finish of the operation.

**Melting Low-carbon Steel.**—When steel for purposes requiring dead soft metal is made, the charge is calculated so that it will melt practically dephosphorized and of the desired carbon. In other words, very little oxidization goes on after the lime is up. Large amounts of scrap are used, and the necessary amount of ore to take care of the phosphorus, is put in with the charge.

**Slag.**—Final basic slags will contain:

10 to 15 per cent  $\text{SiO}_2$   
 45 to 55 per cent  $\text{CaO} + \text{MgO}$   
 10 to 18 per cent  $\text{FeO}$   
 5 to 15 per cent  $\text{P}_2\text{O}_5$ .

The slag is the crux of the open-hearth operation, and it must be kept slightly oxidizing at all times except just at the end. In



the basic process it must be kept always strongly basic in order to retain phosphorus and sulphur and also spare the lining as much as possible. Sufficient lime must be added when necessary to maintain these conditions, but fluidity must not be destroyed or the slag will lose its power to react well upon the impurities, whose chief means of oxidation it is.

**Weight of Slag.**—The weight of slag will depend upon the silicon, phosphorus and dirt in the metal, and will average from 10 to 30 per cent of the weight of steel. Since the slag takes practically all the lime charged into the furnace, its weight can be calculated with sufficient accuracy by the same formula given for calculating the blast-furnace slag: Divide the total lime (CaO) (plus 30 per cent of itself to allow for wear of the lining) by the percentage of lime in the slag.

**Loss.**—The weight of steel produced will be a variable proportion of the weight of metal charged, depending upon the amount of pig iron in the charge, the amount of ore used, the extent to which the carbon was eliminated before tapping, etc., but it will average perhaps 93 to 96 per cent, the difference being made up in a typical example as shown in Table XXIV.


TABLE XXIV.—ANALYSIS OF CHARGE  
(50 per cent pig; 50 per cent scrap)

	Pig iron, per cent	Scrap, per cent	Average, per cent	Loss, per cent
Carbon.....	3.75	0.25	2.00	2.00
Silicon.....	0.70	0.06	0.38	0.38
Manganese.....	1.50	0.40	0.95	0.95
Phosphorus.....	1.30	0.04	0.67	0.67
Sulphur.....	0.037	0.03	0.02	....
20 per cent. slag @ 15 per cent Fe.....	....	....	....	3.00
				7.00
Iron reduced from ore.....	....	....	....	1.50 gain.
				—
Net loss.....	....	....	....	5.50

When using large proportions of ore which is reduced by the carbon in the bath, the production may exceed 100 per cent.



**Recarburizing.**—Steel must not be recarburized in the presence of a basic slag, lest the carbon, silicon, and manganese of the recarburizer reduce phosphorus from the slag and cause it to pass back into the metal:



Therefore in basic practice the recarburizer is added to the stream of metal while it is pouring from the furnace into the ladle, and special arrangements are made for allowing the slag which floats on top of the metal to overflow at the top of the ladle and thus be largely separated. In careful practice "rephosphorization" need not exceed 0.01 to 0.02 per cent of the steel, although a much larger increase may take place through accident. But, as the steel and slag remain in the acid-lined ladle which is always used for teeming purposes, some silicon in the steel oxidizes and passes into the slag and some ladle lining material is fluxed off by the slag, especially if the temperature is high. Thus, phosphorus and a little sulphur may be reduced out of the slag and absorbed by the metal during teeming, especially if the teeming operation is a long one. The high temperatures and long teeming periods of foundry work tend to produce this rephosphorization.

The recarburizer usually consists of ferromanganese and ferro-silicon together with anthracite coal, charcoal or coke which is broken into small pieces and loaded into paper bags. Anthracite is the commonest. When phosphorus is desired, which it is for tin-plate steel, ferrophosphorus is added in the ladle. In some cases where quality is not desired, stick sulphur is added in the ladle to reduce the "wildness" of the metal. In making high-carbon steel for rails, etc., we may use liquid spiegeleisen, as in the Bessemer process. This requires cupolas to melt the spiegel and a mixer in which it is stored in molten condition until wanted. In rare cases part of the ferromanganese is added in the furnace in order to get a better mixing; this is only when large quantities are used, and it results in some 50 per cent of its manganese being oxidized and lost in the slag. Of the other elements, there is absorbed by the steel: 45 per cent of the carbon in anthracite; 85 per cent of the manganese in ferromanganese; 80 per cent of the manganese in spiegel; 65 per cent of the silicon in ferrosilicon; 75 per cent of the phosphorus in ferrophosphorus; and 67 per cent of the sulphur in stick sulphur. From 67 to 75 per cent of the

carbon in the ferromanganese, spiegel and ferrosilicon is absorbed by the steel.

Recent improvements in recarburizing include an electrical appliance by means of which the heat and labor of adding the recarburizer to the stream of metal is avoided. The ferro, etc., is dumped from a wheelbarrow into a runner, which, at the proper time, is actuated by an electric motor under control and pours the recarburizer at the desired rate into the ladle. The operator stands at some distance from the heat and flame.

**Recarburizing Practice for Low-carbon Steel.**—Reduce the carbon as low as possible without excessive oxidation of the metal and then add manganese by means of ferromanganese. This unavoidably adds some carbon. If silicon is desired, some ferrosilicon must be added.

When making "ingot iron," the carbon is reduced to a very few hundredths of 1 per cent, and then manganese added by means of ferromanganese. The metal is oxidized and it must be deoxidized by aluminum, and perhaps even vanadium, and the "sonims" (see p. 206) removed by titanium. "Ingot iron" made in this way may contain as low as 0.01 per cent carbon.

**Recarburizing Practice for Medium and High-carbon Steel.**—"Catch the carbon on the way down"; that is, tap when carbon is reduced a few hundredths of 1 per cent below the desired figure, and then add ferromanganese and ferrosilicon in the ladle. Or else, reduce carbon to 0.10 per cent; add molten pig iron to the bath in the furnace just before tapping, and then add ferromanganese and ferrosilicon in the ladle. Some operators prefer this because the molten pig rids the bath of oxygen and gives a more uniform mixture. Instead of adding molten pig, we may add molten spiegel to the ladle. Or else, we may add anthracite coal, ferromanganese and ferrosilicon in the ladle.

**Open-hearth Furnace Labor.**—The "first helper" has charge of the operation of each furnace; having received his instructions as to the amounts of various materials to be used, he controls where they shall be placed in the furnace, the heating, the changing of regenerator valves, the addition of ore or pig iron, the tapping of slag, the repairs between heats, and all details of working. He taps the heat, under the direction of the "melter," who has charge only in case of emergency or during tapping. The "second helper" keeps the supply of materials ready, arranges the recarburizers ready for the foreman, performs the

work on the tap-hole, assists in making repairs between heats, and helps work the heats. The "cinder snapper," or "cinder-pit man," cleans up the pit after each heat, assists in making bottom at his own furnace, and others when called upon. The "melter foreman" has several furnaces under his direction; he takes charge of tapping at each one, orders the recarburizer and molds for the kind and size of ingots required, decides when the heat is ready to tap, directs the ladle man when to lift the ladle after the steel is run out of the furnace, and inspects the bottom when the furnace is empty.

**Working a Basic Heat—Flame Control.**—The flame must not reach to the exit ports, lest the bricks be fused, and care must be exercised not to overheat the roof. The temperature must be raised above the melting-point of pig iron before the molten pig, if any, is added. The flame must be an oxidizing one so as to assist the ore in oxidizing the impurities. Such a flame is also hotter than one having an insufficiency of oxygen, but it must not be too oxidizing or much heat will be lost up the stack. Two methods of judging the temperature are employed: One consists in inserting an iron rod in the bath until the end melts off; if the end is pointed, the bath is too cool; if it shows nicks on the sides, it is too hot, but, if just right, the end will be clean and square. Another method is described below. The temperature should rise from the beginning of the heat until tapping time, when it should give fluid steel. If the temperature is not rightly controlled there will be a delay after the desired purification is completed, while temperature is being adjusted.

**Purification.**—During melting much scrap is oxidized and this, with the ore charged, causes a good deal of removal of impurities before all the metal is melted. Every element must be oxidized before it will dissolve in the slag. The silicon and manganese go in the first hour or two, but, in many cases, manganese is rather large in amount and is not all oxidized by the time the temperature reaches the point where carbon comes off so fast as to cause a "boil" or bubbling of the metal. In this case some manganese will be left at the end of the operation, and this protects the iron from oxidation and lessens the amount of manganese necessary to add as recarburizer. Working in this manner, with always a "residual manganese" of 0.10 to 0.20 per cent, is now standard basic practice. The "ore boil," or first bubbling due to carbon, causes the slag to swell before the charge is melted to the bot-

tom, and this first slag is run off to get rid of the bulk of the phosphorus, which will be dissolved in it. There is not very much lime in this slag, because the lime is at the bottom of the charge, but there is much iron oxide, which is lost. After the "ore boil" the charge melts down completely, and the "lime comes up." The "lime boil" is accompanied by a more violent bubbling, due in part to  $\text{CO}_2$  gas from the limestone. The slag is now rich in lime and the temperature should be raised. If the charge has been regulated to this end the carbon will now be of the desired proportions, the phosphorus will be eliminated to 0.04 per cent or lower, and, the temperature being right, the bath is ready to tap. Test bars are poured and tested for carbon. By the way the steel flows out of the test spoon, and the skull left in the spoon, the first helper judges the temperature. This is the second method referred to on page 151. If the phosphorus is not low enough, or the heat is not high enough, "pigging up" is resorted to. On the other hand, if the carbon is still too high, the helper adds ore. If the metal lies dead in the furnace, it must be stirred to bring about a boil or to cause the colder metal at the bottom to rise nearer the flame. In the absence of any of these conditions the order to tap is given. But when the furnace is tapped the slag must not be in a strongly oxidizing condition.

**Repairing the Furnace between Charges.**—The condition of the lining after the steel is run out has an important effect on the life of the furnace. If there are holes in the bottom, they must be carefully filled with dolomite, lest the steel break out during the next heat. Steel or slag in these holes must be well removed with rabbles, before the holes are filled. The damage to the lining along the slag line must be thoroughly repaired.

#### ACID OPEN-HEARTH PRACTICE

Acid open-hearth practice is in many respects similar to basic, but the operations are shorter because: (1) A much larger proportion of steel scrap is commonly used; (2) phosphorus is not removed; and (3) no fluxes are added, except in rare instances, when a little silica is charged at the beginning to prevent iron oxide cutting the lining.


**Order of Charging.**—In the acid furnace it is desirable to charge a goodly proportion of the pig iron on the hearth so as to protect the silicious lining from the action of oxide of iron which trickles down from above. The impurities of the pig iron will



partly deoxidize these drops and, at the same time, become oxidized and eliminated from the metal. On top of this pig will be placed all the scrap, and then the remainder of the pig iron on top of that again; the purpose of this latter is to protect the scrap from too much oxidation by the cutting flame.

**Chemistry.**—The chemistry of the acid process is much simpler, because neither phosphorus nor sulphur is removed; therefore it is necessary to start with pig iron and scrap low in both of these elements. This amount of silicon in the charge will determine the amount of slag made, provided manganese is low; therefore low-silicon pig iron is preferred.<sup>1</sup> The manganese is usually low also because: (1) This element is costly; (2) it increases the amount of slag made; (3) it forms a base which requires silica for fluxing it, thereby cutting the lining; and (4) it increases the waste, since all the manganese burned represents a loss in weight of metal purchased. The manganese, as well as the silicon, in the bath is usually reduced to only a trace by the time the charge is melted. H. H. Campbell has shown that the open-hearth slag at the end of the acid operation automatically adjusts itself to contain about 46 per cent of bases ( $\text{FeO} + \text{MnO}$ ), the remainder being principally silica, and that this ratio remains almost the same even when very varying amounts of iron oxide are added.

**Melting for Mild Steel.**—In America much of the acid open-hearth steel made is used for castings containing most frequently from 0.20 to 0.35 per cent carbon. Structural steel, with about the same analysis in carbon, forms another large fraction of the annual tonnage. In this type of practice, the charge is so constituted of pig, scrap and ore that it will contain when melted, only traces of manganese and silicon, and not much more than 0.35 per cent carbon. Where pig iron is cheaper than scrap, the carbon after melting may be higher than this, but this increases the length of the operation. After melting, the silicon should be all oxidized in order that the slag may be fully formed and cutting of the lining avoided, which would occur if there were insufficient silica in the slag. The analysis of the slag when melted is practically the same as at the end of the operation, provided it is always maintained in a fluid condition so it will react rapidly with the carbon. Ore is added from time to time, but this is almost immediately reduced:



<sup>1</sup> See "Analysis of Pig Iron," pp. 7 and 37.






FIG. 75.

The amount of slag increases all the time, showing that the reduction of iron oxide is not complete, and that silica from the lining is constantly entering the slag to maintain a proportion of about 50 per cent  $\text{SiO}_2$ . The slag also takes some oxygen from the furnace gases and transmits it to the carbon of the bath. At no time, however, when the charge is properly worked, is the slag long in a strongly oxidizing condition, in contra-distinction to the situation in the basic process. Recarburization more usually is affected while the metal is still in the furnace, because the objections to this practice obtaining in the basic process do not apply here, and there are certain advantages such as it being more readily melted; being stirred into the metal better during the transfer into the ladle, etc. On the other hand, a little manganese is thereby oxidized and wasted.

**Melting for High-carbon Steel.**—When making steel for tires, springs, and other objects requiring higher carbon, two general types of practice are followed, depending to some extent upon the relative cost of pig iron and steel scrap. If scrap is cheap, we may regulate the charge so as to melt a low-carbon bath, and then bring this up to the desired point by melting pigs of iron in it just before adding the ferromanganese, etc. This has the advantage of insuring the more thorough removal of dissolved oxygen from the metal, but makes the final analysis a little more uncertain because a variable proportion of carbon is oxidized in the furnace during the melting period. The temperature of the furnace also affects this variable. The second type of practice is to melt to carbon only a little above the desired proportion, and then boil this down in the usual way. In either event the ferromanganese and ferrosilicon are usually added in the furnace. Sometimes, as in the basic process, anthracite coal in bags is used instead of pig iron to bring up the carbon, the bags being thrown into the stream as it runs into the casting ladle from the furnace.

**Special Features of the Acid Open-hearth Process.**—The raw material for the acid process must obviously be lower in phosphorus and sulphur than that for the basic process. It also happens that more acid open-hearth steel is made with cold metal than with molten pig. (Of course, no liquid metal from Bessemer converters is used in the acid open-hearth furnace.) The melting period in the average acid heat is therefore some

hours longer than that in the average basic heat. In order to shorten the melting period, the temperature must be as high as possible, because scrap is oxidized during this time, and the hearth is heavily scorified. The melting takes 5 to 6 hr.

After melting it is customary to thin the acid slag by the addition of a little lime say, 200 lb. of limestone for a 20-ton charge. Sometimes manganese oxide is added, in order to remove a little sulphur. The escape of  $\text{CO}_2$  by the decomposition of this limestone also helps to start a boil of the bath and this boiling action should continue to the end of the operation, in order to keep the bath constantly stirred and therefore uniform in temperature and composition. If it becomes quiet, mechanical stirring or boiling with ore or pig iron should be resorted to.

Within an hour or so, *i.e.* after the temperature is high enough to ensure against stopping the boil by the chilling action of cold ore, we add ore of a very pure variety. It is added as fast as the bath will take it without chilling, and up to a total amount of 28 to 33 lb. per ton of metal. In about 2 hr. the oxidation of the carbon should have proceeded far enough, and a final period of 2 to 3 hr. should follow, during which no ore may be added, but the carbon still remaining in the bath should free the bath of oxygen to a great degree, and, at the same time, be oxidized and removed. It is this long deoxidizing reaction which gives to acid open-hearth steel its reputation for superiority. During this period, test samples will show an increasing freedom from blowholes, indicating lessening of oxide in the steel, and indicating also an increase in silicon in the metal, due to reduction from the slag by carbon at the high temperature which is characteristic of this period of the process. This high temperature is necessary for the deoxidation of the bath by its carbon. The appearance of the slag also acts as a guide in showing the deoxidation of the steel. The slag is collected by causing it to chill around a rod inserted in it. As the iron oxide in the slag decreases its color becomes lighter, from dark-brown to yellow and almost gray. Its interior also assumes an appearance known as "vitreousness" as its content of oxide decreases. By the end of the deoxidizing period the slag color should have become gray and a chemical analysis, if made, should show an iron oxide content of not more than 15 per cent.

If the conduct of the operation has been regulated correctly, the carbon in the bath should now be about that wanted in the

final steel. At once further decarburization is checked, by adding ferrosilicon sufficient for recarburizing purposes and by lowering the temperature. The ferrosilicon should melt promptly and rid the bath of more of its oxide. When this has been acting about 30 min. or so the ferromanganese is charged into the furnace. Sufficient is added to give the desired manganese in the final steel, and, if the process has been conducted properly during the previous stages, the loss of manganese by oxidation into the slag should not exceed 10 per cent, as compared with 50 per cent



FIG. 76.—Runner and ladles for charging liquid metal; charging machine and charging boxes for solid metal.

loss when ferromanganese is added in the basic furnace, or 20 per cent loss when it is added in the ladle after the basic operation.

The steel is now tapped, but (except for steel casting work) its temperature is too high for teeming and it is held until cool enough to avoid deep piping, segregation, external cracks, and columnar crystallization.

The long period of deoxidation by carbon is thought to produce a steel with less oxide content, and also to avoid the solid inclusions which result from silicon and manganese oxidation—known as “sonims.” By deoxidizing first with silicon and then



with manganese we not only save the loss of costly manganese, but we follow the formation of oxide of silicon with that of oxide of manganese, which latter fluxes and retains the silica in the molten condition in which it can most readily separate from the bath by gravity. Oxide of manganese, if formed in excess of that necessary to flux the silica, is itself somewhat fluid, so that it is less liable to be retained as an inclusion or emulsion in the metal. Such inclusions have a weakening and embrittling effect.

**Loss.**—The loss in the acid process will not be as large as in the basic, because the pig iron and scrap charged are not so impure, and because the amount of slag made and the amount of iron oxidized and retained by the slag are not so large. The loss will vary on an average from 3 to 5 per cent, so that the final metal will weigh 95 to 97 per cent of the weight of the charge. The analysis of this difference is shown in Table XXV.

TABLE XXV.—ANALYSIS OF ACID FURNACE CHARGE  
(30 per cent pig; 70 per cent scrap)

	Pig iron per cent	Scrap per cent	Average per cent	Loss per cent
Carbon.....	3.75	0.25	1.30	1.30
Silicon.....	0.90	0.10	0.34	0.34
Manganese.....	0.60	0.40	0.46	0.46
Phosphorus.....	0.035	0.045	0.04	0.00
Sulphur.....	0.03	0.03	0.03	0.00
8 per cent slag @ 15 per cent Fe = .....	.....	.....	.....	1.20
Net loss.....	.....	.....	.....	3.30

**Weight of Slag.**—The weight of slag made in the acid process may be determined, according to the method of H. H. Campbell, from the total amount of manganese in the furnace, which will include that put in with the charge (including any that may have been in the ore) and that added with the recarburizing. First, we subtract from this total the amount of manganese in the metal tapped; the weight of the remainder is then divided by the percentage of the manganese in the slag, which gives the weight of the slag. The amount of acid slag will depend primarily upon the amount of silicon in the charge and will vary on the average



from 6 to 18 per cent of the weight of the metal charged, about three-fourths of which is formed during the melting period.<sup>1</sup>

**Coal Burned.**—The amount of fuel used per ton of steel made in the acid open-hearth furnace will be perhaps 50 to 100 lb. less than in the basic furnace, but will depend again upon many varying conditions, so that figures should be used only with caution (see pp. 140 and 487 *et seq.*).

### SPECIAL OPEN-HEARTH PROCESSES

The original pig-and-ore process is abandoned very largely in America, because of the length of time required to burn off the impurities unless they are diluted by steel, and because steel scrap is more abundant than it is in Europe. It is difficult for a novice to understand why the reactions are not more rapid in the open-hearth furnace, when the entire purification of pig iron in the puddling-furnace is accomplished in an hour and a half, including melting; but the difference is due to the very shallow bath in the puddling operation and its extensive contact with the fettling. If we should attempt to purify under such strong oxidizing conditions in the open-hearth furnace, the molten metal would boil violently, because of the high temperature, and for the same reason would also become so charged with oxygen as to be worthless. Even at the low temperature of the puddling-furnace, the boiling is so violent as to increase the height of the bath, and this action would be proportionately increased at the temperature of the open-hearth furnace, which, at the end of an operation producing dead-soft steel, will be about 1,650 to 1,700° C. (3,002 to 3,092°F.). The increase in volume of the metal when carbon monoxide gas is escaping from it may be likened to that of champagne when the drawing of the cork allows a rapid escape of gas. There is another reason why the boil causes more of an increase in the volume of the bath in the open-hearth furnace than in the puddling-furnace: In the latter, the carbon monoxide has only molten metal and slag to bubble through, but in the open-hearth process, where cold ore is added to the charge, it produces a certain amount of chilling of the metal and slag adjacent to it, and the gas having to bubble through this somewhat pasty material causes a greater increase in its bulk. By the time the puddling charge becomes pasty, the carbon is largely gone and therefore there is not a violent action.

<sup>1</sup> In the case of making structural steel (say 0.18 per cent carbon).

Various attempts have been made by different metallurgists to adapt the open-hearth process to the use of all pig iron rapidly oxidized by iron ore or other agencies, and this has led to the Talbot and the Monell processes, each of which is carried on in a single furnace, molten pig iron being acted upon by a highly oxidized liquid slag. It has also led to the Duplex process, whereby a large proportion of the oxidation is effected in an acid Bessemer converter, the operation being completed on a basic hearth.

**Duplex Process.**—In several large American plants the combined Bessemer and basic open-hearth process is in operation, an



FIG. 77.—Duplex process. Charging liquid blown metal from Bessemer converter into basic open hearth.

acid converter being used to oxidize the silicon, manganese, and most of the carbon, while the phosphorus and the remainder of the carbon is eliminated in a basic open-hearth furnace. In the different localities there are different ways of carrying out this combination, but these divide themselves into two general methods: In one method, the metal is blown in the converter until it is purified to the point where it is practically equivalent to so much high-phosphorus, molten steel scrap, which is then mixed with either liquid or solid pig iron in the open-hearth furnace and worked as any ordinary pig-and-scrap heat after melting. In another, and more common, method, the pig iron is blown in the converter until it contains about 1 per cent or so of

carbon, and this product, with little or no additional pig iron, is then dephosphorized and decarbonized in the open-hearth furnace. The advantages of the combined process are: It shortens the open-hearth purification by sometimes much more than half the usual period; it relieves the basic hearth of the presence of silica which tends to scorify it. Both of these improvements have a secondary advantage in increasing the life of the hearth. An advantage from the Bessemer standpoint is that a poorer grade of iron can be converted and yet a higher grade of steel produced. Open-hearth railroad rails, which are frequently made by the Duplex process in America, brought a higher price than Bessemer rails. Finally, the Duplex process makes the steel-maker independent of the variable price of so-called "melting steel scrap."

In carrying out the process, large mixers with capacities of 250 and even 750 tons each are used as a reservoir for the liquid pig iron: Sometimes a little purification is carried on in these furnaces (see p. 90). They supply pig iron to the converters, and to basic furnaces as well, if desired. The blown metal is also frequently poured into a mixer of its own, which serves as a source of supply to the open-hearth furnaces, and again a little purification may be effected in this mixer. The use of these mixers not only makes each part of the process somewhat independent of delays in the other part, but also corrects slight irregularities in analysis of pig iron or blown metal, thus providing more uniform conditions in each furnace, which greatly facilitates the operation therein. Under proper conditions, an open-hearth furnace with auxiliary converter and mixers, may make as many as 40 to 50 heats per week, as compared with 18 heats by the ordinary method.

The name "Duplex process" is also given to a combination of Bessemer or open-hearth furnaces with electric "super-purifiers," but this practice will be discussed under the head of electric processes.

**Triplex Process.**—The name of "Triplex" is sometimes given to a special form of combination of Bessemer and open-hearth furnaces, in which dephosphorization is performed in open-hearth furnaces in two stages. This process is used in places where the phosphorus in the raw material is very high, nearly 1 per cent, as contrasted with the 0.25 per cent phosphorus in steel centers of the United States outside of Alabama. This very high phos-

phorus results in a first open-hearth slag running up to 17 per cent phosphoric acid and therefore suitable for sale as fertilizer. On the other hand, such a slag would cause serious rephosphorization of the bath during the recarburizing reactions.



Therefore, the purified metal from the Bessemer converters is transferred to tilting open hearth furnaces, where the phosphorus is reduced to about 0.07 per cent. Then the metal is transferred to second open-hearth furnaces, but the slag is separated from it. Further dephosphorization is performed in the second open hearth, but the slag is naturally not so rich in phosphorus, nor in oxide, and the steel is of better quality on this account, besides which it may be recarburized in the ladle in the usual way without danger of rephosphorization.

**Talbot Process.**—The Talbot process has a basic lined furnace and a charge above 200 tons in some cases. As the bath of metal is over 3 ft. deep, however, which is almost twice that of an ordinary bath, the furnace is only as large in other dimensions as a 100-ton furnace. The tilting furnace is commonly used in order that any desired quantity of metal or slag may be poured out at will. The operation is continuous and the furnace is drained of metal only once a week. After the first charge has been worked down to the desired percentage of carbon, the great part of the slag is poured off, and then about one-third of the steel is poured into the ladle, recarburized, and teemed into the ingot molds in the usual way. To the charge of metal left in the bath is now added iron ore and limestone to produce a basic and highly oxidized slag, and through this slag is then poured an amount of pig iron equal to the steel removed. The reaction between the impurities in the pig iron and the iron oxide in the slag is very vigorous, but does not cause a frothing or foaming, because all the materials are in the liquid form and the gas bubbles through them without great difficulty; however, much of the slag runs out of the furnace.

The oxidation is so rapid that the silicon and manganese are said to be oxidized almost immediately, together with most of the phosphorus; then the carbon is worked off in the usual way, using more ore and limestone, if necessary. The temperature is low at first, in order that the phosphorus may be more readily burned. At the end of 3 to 6 hr., the bath has again become purified, and another cast removed, the whole operation being then repeated. The yield of steel is 106 to 108 per cent of the weight of the pig



iron charged, because of the large amount of iron reduced from the ore by the impurities in the pig iron.



The advantages of the process are: We obtain three or four heats of 75 tons each in 24 hr. without the use of steel scrap; the yield is large (though this advantage is somewhat neutralized by the cost of the iron ore used); and the temperature of the final metal can be more easily controlled. The disadvantages of the process are: The very large cost of furnaces and the slightly higher cost for repairs.

**Duplex Talbot.**—Instead of working down the carbon, silicon and manganese in the Talbot furnace, it is now common practice to pour into the bath purified metal from the Bessemer converter. As this passes through the oxidized, basic slag the phosphorus is washed out of it; finally, pig iron is poured into the bath, resulting in a violent boil and evolution of heat, with deoxidization of the metal and slag, after which the steel should be ready to tap, following perhaps a half hour's adjustment and raising of temperature.

**Monell Process.**—Upon a basic hearth limestone and ore, or other form of iron oxide, are heated until they become pasty, and then molten pig iron, equivalent to the capacity of the furnace, poured upon it. When steel scrap is plentiful, a part of the metal charge may be composed of this material, charged with the limestone and ore. Oxide up to 25 per cent of the weight of the pig iron charge is used. The temperature of the bath is necessarily low, since pig iron direct from a blast furnace or from a mixer will not be more than 200 or 300°C. above its melting-point, and therefore the phosphorus will be oxidized very rapidly. The slag foams up and pours out of a special slag-notch; in 1 hr. the bath is free from 90 per cent of the phosphorus, most of the silicon and manganese, and all but about 2 per cent of carbon. The operation is then continued in the usual way to eliminate the carbon, and the metal is tapped when this has been reduced to the desired point. The total time is the same as an ordinary pig-and-scrap process. The apparent disadvantages of the process are excessive cutting of the hearth and a heavy loss of iron in the rich slag which flows off at the beginning of the operation. The Monell process has been used successfully in England, with pig iron containing up to 2 per cent of phosphorus.



**Processes in Two Open-hearth Furnaces.**—At a low temperature phosphorus is very easily oxidized and absorbed by a basic slag, even in the presence of carbon, but when the heat is high the oxidation of phosphorus is hindered by the carbon, for the reason already explained—that the affinity of carbon for oxygen increases more rapidly with the temperature than the affinity of the other elements in the bath. We could obtain the desired conditions in the open-hearth process, but the operation would be extremely slow at this low heat, and the carbon would pass away slowly. These difficulties have been met by the Campbell No. 2 and Bertrand-Thiel processes, the former of which was developed at Steelton, Pa., and the latter at Kladno, Bohemia.

**Campbell No. 1 Process.**—The pig-and-ore process using molten metal has long been in operation in the Campbell tilting furnace, and the frothing of the bath is taken care of by tipping the furnace backward so that no slag or metal will pour out of the door, though a large amount of the former flows from the slag-hole between the ends of the furnace and the ports. The operation is continued in this way for 2 or 3 hr., since, as already noted, the furnace can be tipped without cutting off the supply of gas and air, and the yield of steel is 104 to 106 per cent of the pig iron charged.

**Campbell No. 2 Process.**—At the same plant there is also a combination process in which the charge, consisting of all pig iron, or of pig iron<sup>1</sup> and scrap, is placed in a basic open-hearth furnace and the purification carried on at a low temperature until almost all the silicon and phosphorus and part of the sulphur and carbon are eliminated. The bath is then tapped from the basic furnace and poured into an acid-lined furnace, care being taken that none of the basic slag goes with it. At this period the metal is low in phosphorus and sulphur, and contains about the same amount of carbon that a cold charge would have contained as soon as melted. The conditions are therefore the same as if low-phosphorus low-sulphur material had been charged into an acid furnace and melted there, and the process is now continued at a higher temperature, in the usual way to make acid open-hearth steel. The disadvantage of this process is that the transferring of molten metal from one furnace to another is not an easy matter, nor, in fact, is it possible with the arrangements in many plants.

<sup>1</sup> The pig iron charged may be either in the liquid or solid state.

TABLE XXVI.—WORKING OF A CHARGE BY THE HOESCH PROCESS

Charge: 7,853 lb. ore; 1,697 lb. roll scale; 4,144 lb. lime; 51,323 lb. pig from mixer

Time	Analysis of metal, per cent					Analysis of slag, per cent							
	C	P	Mn	Si	S	FeO	MnO	Al <sub>2</sub> O <sub>3</sub>	CaO	MgO	P <sub>2</sub> O <sub>5</sub>	S	SiO <sub>2</sub>
<i>First period:</i>													
12:15	3.28	1.86	0.96	0.32	0.132								
1:10	2.47	0.59	0.17	trace	0.102								
1:30	1.90	0.47	0.22	trace	0.098	10.25	5.03	1.36	41.56	4.32	22.85	0.069	12.2
1:40	1.65	0.37	0.22	trace	0.098	7.26	4.96	1.38	45.48	4.00	22.26	0.124	11.8
2:05	1.46	0.26	0.34	trace	0.082	4.67	3.93	1.60	48.86	4.00	22.13	0.138	11.4
Charge: 4,806 lb. ore; 2,843 lb. lime; 11,931 lb. scrap													
<i>Second period:</i>													
3:50	0.38	0.090	0.29	trace	0.100	19.64	13.49	3.17	33.64	6.92	6.25	0.110	12.2
4:10	0.20	0.050	0.23	trace	0.089	15.78	12.08	3.00	35.78	6.70	6.70	0.165	15.4 { 231 lb. oxide.
4:30	0.09	0.045	0.26	trace	0.090	15.83	8.88	2.32	43.88	6.00	5.50	0.289	13.2 { 806 lb. lime.
4:45	0.07	0.035	0.26	trace	0.080	14.13	10.19	2.21	43.79	6.10	5.57	0.206	14.2
5:05	0.06	0.035	0.27	trace	0.078	16.23	8.32	2.20	45.30	5.90	5.55	0.275	14.0 { 440 lb. ferro-
5:10	0.04	0.030	0.25	trace	0.077	17.20	7.67	2.00	46.19	6.12	5.15	0.316	13.1 { manganese.
5:15	0.08	0.040	0.47	trace	0.067	17.03	10.25	1.90	46.28	5.92	5.00	0.344	12.4

As an average, 75 per cent of pig and 25 per cent of scrap is used in this process, and the yield is 104.42 per cent.

**Bertrand-Thiel Process. Hoesch Modification.**—The Hoesch process is now in use in some of the German plants, where it is said to give very satisfactory results. Instead of using two furnaces, as in the original Bertrand-Thiel process, and pouring from one to the other, it uses one furnace but pours the bath into a ladle after the first period of purification; the purpose of this is to separate it from the highly phosphorized slag; when this is effected, the metal is poured back into the same furnace and the purification completed. In the first period, all the silicon and manganese, most of the phosphorus and about one-half of the carbon, are removed; in the second period, the remaining phosphorus, carbon and some additional sulphur are eliminated. The slag separated after the first period contains 20 to 25 per cent of  $P_2O_5$ , wherefore it finds a ready sale as agricultural fertilizer. The chemical history of a charge is given on page 165.

## CHAPTER VII

### THE ELECTRO-METALLURGY OF IRON AND STEEL

In the electric smelting and refining of iron and steel, six wholly new modifications in practice are introduced:

1. We may maintain either a reducing or a neutral or an oxidizing atmosphere in the furnace as desired. This is not possible in the open hearth or Bessemer processes.

2. Almost any desired temperature in reason may be maintained. This gives us a much wider latitude in respect of the types of slags which may be used in the furnace. For example, only a very high temperature will maintain slags very high in lime in that liquid condition which is essential for their effective reaction with the metal. A corollary to this is, that a "super-refining" of steel is possible, whereby we may reduce oxygen, sulphur, and segregation to a lower point than may be achieved in the older processes; likewise, dissolved gases, occluded slags, etc., may be eliminated, and are expelled from the liquid metal by means of liquid slags, instead of by means of manganese, silicon, vanadium, titanium, etc. As a result, the strength of basic open-hearth steel may be increased some 10,000 lb. per square inch by a "super-refining" in the electric furnace; its wearing qualities also are improved; and its ductility at low temperatures is increased.

3. The impurities introduced with the usual fuels are avoided.

4. The cost of the process is greater than Bessemer or open hearth.

5. The temperature is regulated with much greater accuracy.

6. Very little, if any, fuel is required, and that only for reduction, since heat is produced by electrical means (with certain qualifications hereafter mentioned).

For many years advantage has been taken of electric smelting in the production of ferro-alloys—*e.g.*, ferrosilicon, ferrotungsten, ferrochrome, ferrovanadium, etc.—that is, alloys of pig iron and some other metal which is used in the manufacture of alloy steels. The high temperature necessary for the production of these alloys gives electric smelting especial advantages while the high price at which they can be sold enables their manufacturers to stand the additional expense with profit. But in the year 1900

a number of important electro-metallurgists in Europe and America began to use electric processes for the production of pig iron and steel on a commercial scale, and from this time the industry dates. As an important industry in America, the year 1913 marks the beginning.

Iron and steel electro-metallurgical processes naturally divide themselves into six classes:


1. Smelting for the production of pig iron from ore;
2. Melting steel scrap and converting it into "synthetic" pig iron by the absorption of carbon, silicon, etc.;
3. Refining of pig iron or scrap steel to produce steel;
4. Super-refining of liquid steels made by other processes;
5. Electrolytic refining of steel or wrought iron to produce almost chemically pure iron;
6. Electrolytic production of iron direct from ores.

The first four classes are electro-thermic; that is to say, they use electricity for conversion into heat; the fifth and sixth classes are electrolytic, that is to say, the electric current serves to produce chemical changes.

#### ELECTRO-THERMIC IRON-ORE SMELTING

Sweden, Norway, Italy, and latterly, Japan, are producing pig iron by the smelting of iron ore by means of electricity, with coke or charcoal, as the chemical reducing agent. The total production of such pig iron in the world for the year 1921 is estimated as close to 300,000 tons.

**Amount of Carbon Used for Reduction.**—Success of smelting depends on the adjustment of carbon exactly to the reduction needs of the process, as we shall see later. This, in turn depends on the ore used—whether  $\text{Fe}_2\text{O}_3$  or  $\text{Fe}_3\text{O}_4$ —and on whether the gas produced is high or low in  $\text{CO}_2$ . We must also allow about 3.5 per cent of carbon to dissolve in the iron. With  $\text{Fe}_3\text{O}_4$  as the ore and a gas containing 30 per cent  $\text{CO}_2$  and 60 per cent  $\text{CO}$ , we shall have the following reaction, roughly:



928 : 144 = 2,240 : 373; then 373 lb. of carbon must be charged per ton of ore.


672 : 144 = 2,240 : 480; and 480 lb. of carbon will be used per ton of iron produced. 480 lb. of carbon = 701 lb. of charcoal.

Both these figures must be increased by the carbon used for dissolving in the pig iron. Also the ore is assumed to be pure.

If  $\text{Fe}_2\text{O}_3$  is used for ore and the gases are the same the amount



of carbon for reduction is increased by 12.5 per cent. If the furnace gas runs lower in  $\text{CO}_2$ , the carbon must be increased. With zero  $\text{CO}_2$  the reaction will be as follows:



160 : 36 = 2,240 : 504; then 504 lb. of carbon will be used for reduction per ton of ore charged;

112 : 36 = 2,240 : 672; and 672 lb. of carbon will be used for reduction per ton of pig produced. 672 lb. of carbon = 981 lb. of charcoal.

For the operating data given by Baron Gerard De Geer, Manager of the Domnarfvet Steel Works, on page 175, the amount of charcoal actually used is 814 lb. per ton of pig produced, including reduction, solution in the iron, loss, etc. This is about one-third the amount of fuel used in ordinary blast-furnace smelting.

**Form of Carbon Used.**—Either charcoal or coke may be used, but coke has a lower electric resistance, which increases the power consumption per ton of product; and decreases the output; coke also tends to graphitize at arc temperatures, when it does not react rapidly with the ore, resulting in "hot runs," as discussed later. Coke is cheaper and higher in ash than charcoal, and the coke type of furnace is often made smaller in size than that for charcoal.

**Power Consumption.**—The power consumption depends on the electric efficiency, which should exceed 75 per cent; then on the  $\text{CO}_2$  in the furnace gases, which may be assumed to be, in good practice, about as per the data for the Domnarfvet plant on p. 175; and, finally, on the richness of the ore smelted and the carbon used for reduction. With 78 per cent efficiency, 65 per cent iron in the charge, 30 per cent  $\text{CO}_2$  in the gases, and coke for reduction, we may produce a long ton of iron with the expenditure of 1,740 kw.-hr., equivalent to 3.75 tons of iron per horsepower-year.<sup>1</sup> With equal efficiency, little  $\text{CO}_2$  in the gases, and

<sup>1</sup> The following data may be of service:

$$1 \text{ e.hp.} = \frac{3}{4} \text{ kw. (roughly);}$$

$$1 \text{ kw.} = 1.34 \text{ hp.}$$

$$1 \text{ kw.-yr.} = 1.34 \text{ hp.-yr.} = 8,760 \text{ kw.-hr.}$$

$$1 \text{ hp.-yr.} = 6,537 \text{ kw.-hr.}$$

$$\text{\$25 per horsepower-year} = 0.38 \text{ cents per kilowatt-hour}$$

$$1 \text{ cent per kilowatt-hour} = \text{\$65.37 per horsepower-year}$$

If 3.75 tons of iron may be produced with 1 hp.-yr. which costs \$25, then the power cost will be \$6.61 per ton of iron.

If only 2.5 tons may be produced with 1 hp.-yr., then the cost per ton will be \$10.

an ore of only 50 per cent iron, the expenditure will be 2,500 kw.-hr., equivalent to 2.5 tons per horsepower-year.




FIG. 78.—Sectional elevation of electric shaft furnace, at Domnarfvet, Sweden.

Baron De Geer gives the power consumption at Domnarfvet as 2,400 kw.-hr. per ton of iron, equivalent to 2.7 tons per horsepower-year. This is an actual figure, including losses through operating difficulties, stoppages, etc. He says that the furnace

will produce 3.6 tons of iron per horsepower-year. Since the Domnarfvet furnace has been operating for over 10 years, it is scarcely wise to expect a new enterprise to produce more than 2.5 tons of pig iron per horsepower-year for the first year or so. This estimate might be used in calculating the chances of a successful industry.

**Electrode Consumption.**—Under good operating conditions,  $17\frac{1}{2}$  lb. of graphite electrode will be consumed per ton of iron produced.

**Industrial and Economic Conditions.**—Only where coke is *very* costly, and electricity and pure ore *very* cheap may electric




FIG. 79.—Domnarfvet ore smelting furnace.

smelting survive as an industry. For each ton of pig iron produced we save over the ordinary iron blast furnace,  $\frac{2}{3}$  ton of coke and  $\frac{3}{4}$  of the flux (when the ore is very pure). To balance this we expend more than \$7 per ton of iron in overhead expense alone, besides which there are costs for electricity, and electrodes which do not enter at all in ordinary blast-furnace costs, and greatly increased costs for labor and repairs. The overhead is often the item which determines the failure of the industry, because the cost of the electric smelting plant is great and its production small. The allowance of \$7 per ton for electric smelting is compared to about one-tenth that sum for a large

blast furnace. In times of poor market, the overhead (except perhaps the royalty) continues undiminished, and this is just the time when the industry is having its hardest fight for life. The accumulated overhead during a period of depression is often sufficient to buy coke for many months of ordinary smelting. Electric power must be figured at  $\frac{1}{2}$  to  $\frac{1}{3}$  hp.-yr. per ton of product, say \$8 to \$12 per ton when electricity is very cheap indeed. Electrodes will be roughly \$5 per ton, depending on supply, and labor plus repairs will be \$4 per ton more than the blast furnace, when skilled labor receives \$6 and unskilled \$4 per day. We can only afford to smelt electrically very rich ores easily available to the furnace, and at a locality where there is an assured market free from long periods of depression, and where  $\frac{2}{3}$  ton of coke costs at least \$20. We may not rely on extra quality to keep the industry alive, because, in times of depression, the consumer may not pay the extra price. More than one failure in America should warn investors against electric-smelting projects which look attractive on paper. In Sweden and Italy electric-power costs are lower than can be thought of in North or South America even under most favorable conditions of hydro-electric development. Where the economic situation warrants it, electric smelting is a great advance in the industry.

**Installation Cost.**—The cost of the electric smelting plant is high, on account of electrical apparatus, instruments, special refractories and electrodes, etc. The two influencing factors are the nearness of the supply of apparatus, and the extent to which labor-saving appliances, such as charging machines, etc., are installed. Roughly, however, a plant capable of producing 20,000 long tons per year will cost from \$600,000 to \$800,000. At 20 per cent per year for interest, depreciation, and amortization, this amounts to \$7 per ton of iron produced, and this is the chief part of the overhead expense. The remainder will include royalty, taxes, selling and general.

**Form of Smelting Furnace.**—Experience with the so-called open-top and the shaft furnace, indicates that the operation of one is about as easy as the other, but the open-top furnace is less economical on account of increased consumption of charcoal and power. An approved type of shaft smelting furnace is shown in Figs. 78 and 79. There are four to eight graphite electrodes to each furnace, which is made in capacities of 10,000 to 20,000 tons per year. This is compared to an ordinary modern coke



blast furnace having a capacity of 175,000 to 200,000 tons per year.

The electrodes in this furnace have a diameter from 600 to 700 mm., and the electrode consumption is approximately  $17\frac{1}{2}$  lb. per ton of iron produced. The furnace uses alternate current of three phases and 25 cycles, capable of adjustment by small intervals from 20 to 80 volts. The fuel mixed with the charge serves as a conducting medium for the current, and by its resistance, transforms the electric into heat energy. By means of the heat so produced the carbon reduces iron from the ore and is itself oxidized to CO and CO<sub>2</sub>. The resulting gases pass upward giving their heat to the charge in the furnace shaft, and also performing some preliminary reduction. Without some means of cooling the refractory lining it deteriorates very fast and therefore a part of the tunnel head cases are cleaned, returned to the crucible, and blown under the roof as shown. The gas is rich enough so that the remainder may be mixed with producer gas and used for firing open-hearth furnaces. The roof of the crucible is the weak point, but by cooling it in this way it will last a year, with the occasional replacement of a few bricks, which can be made in less than 24 hr. The whole roof can be changed in a few days without fully emptying the furnace.

The temperature of the tunnel-head gases is 200 to 300° (392 to 572°F.). The amount is estimated at 400 to 600 cu. m. per ton of pig iron. These gases are much richer than coke blast-furnace gas on account of the absence of nitrogen from the air. A typical analysis is given on p. 175.

The crucible does not support the shaft but the latter rests on six columns, as shown. Shaft and crucible are filled with ore, except where the angle of rest of the charge leaves a space under the roof of the crucible, as indicated by the dotted lines. This space is essential and avoids the contact of electrodes with the charge adjacent to the brickwork, with consequent rapid destruction of the lining. It also gives a space into which the gases are blown for cooling the roof and for better distribution of the heat throughout the charge.

**Operating Difficulties.**—The most important technical consideration in the electric shaft furnace is the correct adjustment of the amount of reducing carbon used to the amount of oxygen in the ore. An excess of carbon over the theoretical amount will accumulate in the hearth and cause "hot runs." This is indi-



cated by an increase in the temperature of the hearth, a decreased rate of melting and an increased ratio of  $\text{CO}_2$  to CO in the tunnel-head gases. The result is that the smelting zone travels into the upper part of the furnace, so that the hearth becomes too cold and the operation of reduction ceases.

On the other hand if there is too little carbon for reduction, the gases will be richer in CO, the rate of reduction will be increased, but there will be insufficient heat to keep the product molten, and the iron lost in the slag will increase due to imperfect reduction of the ore.

Maintaining the correct amount of carbon to oxygen is a very delicate operation and depends on the temperature of the furnace, the pressure of gas, the size of charcoal or coke used, etc.

It is impossible to increase the temperature of the iron by increasing the amperage, because this only alters the rate of melting. The best way to restore equilibrium in carbon for reduction is to omit either the ore or the charcoal from one or two of the furnace charges, but without making any permanent change in the furnace burden.

The production of hot iron is a difficult performance in the electric shaft furnace, because the margin of temperature is not great and, as we have already seen, it is impossible to increase the heat either by means of the electric current or by increasing the amount of carbon. The temperature may be controlled to some extent by varying the voltage of the current.

**Electrodes.**—The electrodes should not be touched any oftener than is necessary, namely, about once or twice a week.

**Controlling of Constituents of Pig Iron.**—No difficulty whatever is found in reducing the sulphur to less than 0.02 per cent. Probably calcium carbide formed by the electric current assists in carrying sulphur into the slag in the form of  $\text{CaS}$ . Silicon is ordinarily less than 1 per cent on account of the lack of temperature and of the basic slag used for sulphur elimination. Phosphorus is not under control, but practically all that present in ores and fuel goes into the metal.

**Operating Data from the Domnarfvet Steel Works.**<sup>1</sup>—The ore and products of the most prominent electric smelting furnace are illustrated below:

<sup>1</sup> Electric smelting of pig iron at Domnarfvet, Sweden: BARON GERARD DE GEER, Manager, *Chem. Met. Eng.*, vol. 24, pp. 429–433, Mar. 9, 1921.

IRON ORE		SLAG
Fe <sub>3</sub> O <sub>4</sub> .....	64.96	} (Fe = 61.49)
Fe <sub>2</sub> O <sub>3</sub> .....	20.64	
FeO.....		0.87 (Fe = 0.68)
MnO.....	0.19	0.96
MgO.....	1.79	12.57
CaO.....	4.00	38.83
Al <sub>2</sub> O <sub>3</sub> .....	2.00	12.06
SiO <sub>2</sub> .....	4.20	32.82
P <sub>2</sub> O <sub>5</sub> .....	2.40 (P = 1.05)	0.64
PIG IRON, PER CENT		GAS, PER CENT
C.....	3.6 -4.0	CO <sub>2</sub> ..... 25.0
Si.....	0.5	CO..... 65.0
Mn.....	0.75	H..... 8 5
S.....	0.02-0.015	M..... 1.5
P.....	1.8 -2.15	

### MELTING STEEL SCRAP TO PRODUCE "SYNTHETIC" PIG IRON

Synthetic cast iron was made somewhat extensively during the war of 1914 to 1918 by France, Canada, northwestern United States, and Germany. Two methods were used, both of which have decreased greatly with resumption of normal conditions: The more economical was to melt scrap borings or turnings (usually steel, or mixed steel and cast iron) in the ordinary cupola, adding ferrosilicon to give the desired silicon. The melted metal contained from 1.90 to 3.30 per cent of carbon, and was high in sulphur, because coke was used to the extent of one-fourth to one-fifth of the scrap. The liquid product was tapped into a basic electric furnace, where it was superheated to the point where it would dissolve carbon from carbonaceous materials added until the carbon content reached 3.50 to 4.00 per cent. Sulphur was then reduced by means of a limey slag, and the bath tapped and cast direct into molds. Rarely it was cast into pigs for sale to other foundries. This process prevailed only where scrap was cheap and pig iron costly, because of lack of a nearby supply. It was replaced by the following process where coke was very costly.

Scrap borings or turnings were melted in a basic electric arc furnace and heated to 1,350 to 1,450°C. (2,462 to 2,642°F.). At this temperature the bath could be carburized to the desired extent (3.50 per cent) by adding petroleum coke, coal-tar coke, charcoal, bituminous-coal coke of low ash, etc. Ferro-alloys were added to supply the necessary silicon, manganese, etc., and then the metal was cast into molds, or into pigs for sale.

## SUPER-REFINING LIQUID STEEL IN BASIC ELECTRIC FURNACES

Sulphur, occluded oxides (sonims), and dissolved gases are not completely eliminated by the Bessemer or open-hearth processes. The crucible process has long produced a steel excelling these in quality, but its operation is costly and the product is made in small units, so that large ingots are made by pouring several crucibles into one mold and the analysis is subject to non-uniformity. The electric furnace, when expertly operated, will produce a steel equal in properties to crucible steel, and freed to



(Courtesy, James H. Gray, U. S. Steel Corp.)

FIG. 80.—Super-refining liquid steel. Pouring basic open-hearth steel into a 40-ton basic electric arc furnace.

any desired extent from impurities and occluded particles or gases. That it has not always accomplished this result, is due to lack of care or expertness, and has delayed its more general adoption. It is also more costly than the older "tonnage" processes, because of the greater cost of electric heat than of that obtained from fuel. Therefore, the cheapest way to make steel of this high quality is to perform all the purification possible in the open-hearth furnace, and then pour the liquid steel into the electric furnace, where the sulphur is reduced to a harmless point and the sonims and gases eliminated. The first essential is

that only moderately impure metal shall reach the electric furnace, because sulphur above about 0.08 per cent is reduced with much expense and waste of time, and highly oxidized steel is never restored to high quality. For this reason Bessemer steel is no longer super-refined. Phosphorus may be eliminated in the basic electric furnace, but this is uneconomical, because the basic open-hearth elimination is cheaper; hence has arisen the so-called "Triplex" process, in which the liquid metal goes from the Bessemer to the open-hearth and thence to the electric furnace.

**Furnaces Used.**—Probably more than 300,000 tons of steel were super-refined in electric furnaces in the United States in 1922, of which the greater part was treated in arc furnaces of the Heroult type. In Italy the Fiat arc furnace is extensively used. The induction type has its advantages also, and other makes are preferred by some manufacturers.

**Heroult Furnace.**—As shown in Figs. 26<sup>1</sup> and 81, the arc electric furnace is similar to the open-hearth furnace in general form and design. The essential difference is that electrodes above the bath bring in electricity, which travels in a series of arcs to the bath and thus produces the heat for the refining operation. The Heroult furnaces combine simplicity with adaptability and economy of operation. The electrodes are suspended about 1 in. above the bath, and may be automatically controlled so as to continuously give arcs of varying and predetermined intensity, depending on whether the temperature is to be increased, diminished or held constant. The regulation is automatic electrical and may be set by the operator and allowed to take care of itself. The current is alternating, three-phase and 25 to 60 cycles; the voltage is up to 100 according to the desired length of arc; the kilowatt capacity of a furnace of 40-ton size will be 3000. In the Heroult type the current is both brought and carried away by electrodes above the bath, as distinguished from the Girod type, in which electrodes are suspended above and also set in the hearth, so that the current passes through the bath. This method has its advantages, but complicates the already serious troubles of all high-temperature furnace hearths (see Figs. 81 and 88).

**Induction Principle.**—The simple induction furnace is based upon the principle of the ordinary static transformer, whereby alternating electric current is transformed to lower voltage. It was independently developed by E. A. Colby, of the United

<sup>1</sup> Page 55.







States, and F. A. Kjellin, of Sweden, whose American rights have been joined under one management. A sectional elevation of the furnace is shown in Fig. 83, in which *CCCC* is the core of an electromagnet, around one leg of which a coil of wire *AA* passes. When an alternating current goes through the coil *AA* it sets up an alternating magnetic field in the core *CCCC* and this in turn sets up a secondary current in the circle *BB* parallel




FIG. 82.—Girod type of electric furnace.

to the coil *AA*. In other words, an alternating current passing through the coil *AA* induces an alternating current in the coil *BB* without there being any metallic connection between the two. This is a well-recognized phenomenon in electrical engineering and requires no further comment here. In the furnace operation, the circle *BB* is a hollow ring in the brickwork into which melted metal is poured. The resistance offered by this melted metal to the passage of the induced current generates heat which will

maintain the temperature or raise it to any desired point. The slot *BB* is really an annular crucible into which pig iron, steel scrap, iron ore and flux may be charged as if it were an open-hearth furnace, and the operation of steel making is practically the same in principle except that electric heat is employed instead of regenerated gas and air. We may charge solid metal if desired, but, in such a case, it is well to leave a shallow circle of metal in




FIG. 83.—Vertical section of Kjellin induction furnace.

the bottom of the slot *BB* after each operation is ended, to serve to carry the induced current during the beginning of the next operation, until the solid charge is melted.

**Roechling-Rodenhauser Furnace.**—The combination induction furnace is shown in Fig. 84. This is in effect a combination of three simple induction furnaces, the coils of the metallic baths joining in a central pool. By means of this pool, a more effective refining may be employed, for the pool serves the purpose of a

bath upon which slags may be charged, etc. It has also several steel terminal plates inbedded in the lining, which are connected to a few heavy turns of copper placed outside the primary coils, which collect and feed to the terminal plates the induced current in these turns, thus suppressing magnetic leakage.




FIG. 84.—Horizontal section of Roebling-Rodenhauer furnace.

**Operation of Super-refining.**—Liquid steel from the open-hearth furnace is poured into the electric furnace, great care being taken that no open-hearth slag gets into the electric furnace. The steel should have been carefully analyzed and should contain less than 0.08 per cent sulphur; manganese of 0.15 to 0.40 per cent; phosphorus of 0.02 per cent or less; and carbon 0.10 to 0.25 per cent (10 to 25 points) lower than that desired in the finished steel, in order to allow leeway for carbon to be increased by coke added for deoxidizing purposes, plus a little which goes in with the final additions of manganese, silicon, etc. The amount of steel poured into the furnace must be carefully estimated, in order that the additions can be adjusted correctly. While the steel is pouring in through one door, sufficient lime to make a slag covering for it is shovelled through another, mixed with about 20 per cent of its weight of fluorspar and 15 to 20 per cent of sand, to make a fluid slag. The slag will not exceed 2 per

cent of the weight of the bath. If the carbon in the open-hearth metal is too low, some anthracite may be dissolved in it during the transfer, or may be shovelled into the electric furnace while the steel is pouring in. Sometimes part or all of the slag is not introduced until the steel has been for some time in the furnace, and sometimes two slags are used.

The open-hearth steel usually chills over the top when it gets into the furnace, and the furnace is first set for high temperature,




(Courtesy, James H. Gray, U. S. Steel Corp.)

FIG. 85.—Three-ton Heroult electric furnace at Johnstown plant of the Lorain Steel Co.


which should result in the charge being melted in 30 min. to 1 hr. Cold metal at this point is, however, one of the difficulties and costly features of the process. When the metal and slag are melted, a sample is taken for analysis. The sample of slag will show a brown color, indicating that the steel is still oxidized. To a 20- or 25-ton heat about 100 lb. of coke dust are now added and the temperature kept up. In 15 to 30 min. the slag should begin to lighten in color, and, within 1 hr. after adding the coke, it should be light-gray or white, and should smell of acetylene when dipped in water. If necessary, more coke dust and, possibly, more slag



mixture will have been added in the meantime. From now until the end of the heat a slag should be maintained that contains some acetylene, the purpose being to desulphurize and deoxidize the steel.



The carbide is formed by the action of lime and carbon at the electric arc:



In the case of large baths, the metal must be stirred frequently, because carbide may not be found near the doors.

The carbide slag is the best means of degasifying the steel, and steel that is degasified is assuredly desulphurized. It requires  $\frac{1}{2}$  to 3 hr. to degasify under a carbide slag, and it must be maintained strongly basic and reducing, and fluid at all times. Coke must be added when necessary, and the doors must be kept closed and luted tight with clay as much of the time as possible. Dripping of the acid roof, or scorifying the lining may spoil the slag and the operation.

After the steel is deoxidized, the ferrosilicon, ferromanganese, ferrochrome, ferrovanadium, etc., may be added. They should be added in small doses so not to chill the metal, and all additions should be complete 45 min. before the heat is tapped, during which the bath should lie as quietly as possible in the furnace, to allow all sonims to escape. This corresponds to the "killing" period of the crucible process. Ferrosilicon should be added first; then ferromanganese and ferrochrome, and lastly ferrovanadium, for the reasons given under acid hearth, namely, to avoid sonims.<sup>1</sup> The bath must be kept liquid and as quiet as possible at all times, and lies dead for the last 45 min. for the same reason. If the color of the slag shows that any of the elements, as manganese and chromium, are being oxidized, coke should be added and the conditions investigated. Elements, like nickel, which do not oxidize, should have been added as soon as the bath was melted, in order to avoid chilling it during the latter part. It must never be allowed to become viscous, lest it entangle solid particles, while an excessively high temperature must also be avoided.

<sup>1</sup> See p. 157.



The heat should be tapped at a temperature 200 to 250°C. above its melting-point; held in the ladle while the temperature drops about 100°, and poured 100 to 125° above its melting-point, which will, of course, depend on its analysis. The reasons for hot working and cool pouring are the same as those given under the acid open-hearth process.<sup>1</sup> It is of paramount importance that the steel be tapped from underneath the slag. All the care, skill and expense expended to eliminate "sonims" may be thrown



(Courtesy, James H. Gray, U. S. Steel Corp.)

FIG. 86.—Seven-ton Heroult electric furnace pouring out the slag after tapping the steel.

(For the prevention of "Sonims" it is imperative that all the slag be retained in the furnace when the steel is tapped into the ladle.)

away if any slag or dirt is poured or tapped with the steel and mixed with it to again produce sonims. The total time of a heat, from charging liquid metal to tapping, will be roughly 4 to 5 hr. and the power used equals 100 to 200 kw.-hr. per ton of product.

After the steel is tapped, the bottom is repaired with dolomite, about 500 lb. of dolomite being used for a 25-ton furnace. The roof and walls are carefully examined and precautions taken to avoid trouble in the next operation. As in the open-hearth process, the worst cutting is at the slag line. The bottom lasts

<sup>1</sup> See pp. 156 to 158.

2,000 to 3,000 heats and the roof from 50 to 200 heats, depending on care and the make of furnace.

The final slags will contain about 20 per cent silica, 70 per cent lime plus magnesia, 0.30 to 1 per cent calcium carbide, about 1 per cent sulphur, and less than 1 per cent of iron.

**Time of Adding Ferrosilicon.**—Differences of opinion exist as to the advisability of adding ferrosilicon either immediately after deoxidization of the bath is complete, or adding it toward the end of the operation. The purpose of early addition is the same as that mentioned under the acid open-hearth process, namely, there is the least likelihood of sonims in the finished steel. On the other hand, some costly silicon is wasted by absorption in the basic slag. This, however, should not be of real moment, provided oxidizing conditions are prevented, and provided the temperature is kept low enough to prevent a reaction of unoxidized silicon, with manganese or iron in the slag. Even if such a reaction should occur, it would necessarily be very small in amount, because a good slag will contain less than 1.5 per cent of manganese plus iron. If silicon is added toward the end of the process there must be at least 30 min. of quiet lying in the furnace thereafter, in order to free the metal from any particles of silica formed. The heat should also lie quietly in the ladle for 15 to 30 min. and even then it is somewhat doubtful whether the steel is clear.


#### MELTING PURE STEEL SCRAP TO PRODUCE ELECTRIC STEEL (BASIC OR ACID FURNACES)

Where liquid steel is not available, the electric furnace may be used to melt scrap steel and refine it. This is naturally more costly than treating liquid steel, on account of expenditure of time, which means labor and electricity, corrosion of lining, etc. The melting period is also costly, on account of the "jumping" of the arc and irregularity of the power input. There are two distinct types of practice in melting scrap:

First is the melting and super-refining of pure scrap, which necessitates using only selected stock below 0.02 per cent phosphorus and 0.08 per cent sulphur. Stock of this kind is melted under reducing, instead of oxidizing conditions, and the process, after melting is complete, is very similar to the super-refining of liquid steel. This type of practice makes steel whose quality is as high as any, and better than that made by the refining and

super-refining of less pure material, because the latter requires a period of oxidation previous to the period of deoxidation, desulphurization, and degasification. This period of oxidation leaves the metal with impurities which are never perfectly removed.

**Operation of Melting Pure Stock in Basic Furnaces.**—The care of the furnace between heats is similar to the practice described under the super-refining of liquid steel, but the magnesite hearth is protected by charging some lime upon it before the stock is inserted. The melting period is one of great difficulty, because



(Courtesy, James H. Gray, U. S. Steel Corp.)

FIG. 87.—Forty-ton Heroult electric furnace in operation at the Naval Ordnance plant at South Charleston, West Virginia.

the scrap is of loose texture which melts away from the arc, causing the greatest difficulty in regulation of length of arc and irregularity in power input. Usually hand regulation and feeding of the electrodes is employed until the one or two electrodes have melted a hole for themselves in the stock and are partly buried so as to maintain a fairly constant length of arc. It is common practice to use a relatively high voltage during melting, with low voltage during the refining stage. Especially during the melting period it is of great importance to employ a rapid adjustment of the electrode, but with slow speed as the arc approaches its normal length, so to avoid what is known as

"hunting," that is, "overrunning" the point of correct adjustment, first on one side and then on the other. The automatic regulator of J. A. Seede, and the peak-load regulator of E. T. Moore are great improvements in this connection. As soon as a pool of liquid metal is formed in the bottom of the furnace, some coke dust is shoveled in to keep the slag in a deoxidized condition and to the lime is added one-fourth of its weight of fluorspar. The purpose of this is to liquify the slag. Occasionally sand is used in place of fluorspar, or in addition to it. The slag should always contain more than 55 per cent of lime and be so reducing at all times that none of the metalloids in the steel will be oxidized and removed. It is desirable to form a carbide slag as soon as possible and to maintain it with a content of 0.50 to 3 per cent of  $\text{CaC}_2$ .

The practice from this point is very similar to that described under super-refining of liquid steel. There is a difference in this respect: That this type of melting and refining is commonly used for producing tool steels, and magnet steel, containing tungsten, chromium, vanadium, etc. It is important not to oxidize any of these costly metalloids. There is now a regular market supply of scrap from alloy-steel manufacture, containing the costly metalloids, but in a less expensive form than if they are added in ferro-alloys. Each electric steel manufacturer also has scrap from previous operations which serve the same purpose. It is also of the utmost importance to know the exact weight of material in the furnace and to prepare the initial charge so as to get the desired final analysis in the costly elements (tungsten especially, as being most costly), so as to use the minimum of ferro-alloys.

Some carbon is dissolved in the bath from the calcium carbide in the slag, and, if careless practice results in oxidizing tungsten, it may be reduced back into the metal by means of a carbide slag and high temperature. Even greater precaution against oxidation must be taken than in the super-refining of liquid steel, such as putting coke dust upon the top of the slag every time the doors are opened, and keeping the furnace tightly closed as much as possible.

A skilful melter may melt and super-refine pure stock with minimum addition of extra alloying elements in  $4\frac{1}{2}$  to 5 hr. Six hours is the longest time for good practice, but delays due to poor heat adjustment and laboratory methods will sometimes run heats to 8 hr. in length. The power consumption in good practice will be 600 to 800 kw.-hr. per ton product.



It is important that the metal should be thoroughly degasified. If degasified, it will be desulphurized, but the converse is not true: Reduction to a low content in sulphur is not proof of degasification. The use of ferrosilicon, in small doses so as to avoid chilling, at an early period of the operation is a great assistance to degasification, as well as making steel denser and smoother.

In case a large amount of sulphur has to be removed we may have to skim off one white slag and add a second. This is rare practice, however, but it is often necessary to add more slag after the charge is melted. The lime and coke should be thoroughly mixed before adding. The amount of white slag will be from 3 to 7 per cent of the weight of the bath.

The temperature should be high during the deoxidation period, but the steel is teemed cool and must, therefore, be allowed to stand in the ladle for some time after tapping. The slag should be held back in the furnace when tapping the metal. Furnaces are built with this object in view.

**Use of Fluorspar or Sand for Thinning.**—Sand is cheaper than fluorspar and it avoids corrosion of the side walls and roof caused by the volatility of the fluorspar. It thins the slag effectively, but decreases its basicity, and interferes with the permanency of the carbide in the slag. It also increases the danger of adding ferrosilicon early in the process, by decreasing the excess of bases. The commonest practice is to use part fluorspar and part sand, keeping the slag fluid, but never allowing the silica content to exceed 18 to 20 per cent.

**Acid vs. Basic.**—Every acid furnace is cheaper to operate than the corresponding basic furnace. This applies to Bessemer, open-hearth and electric processes. The raw material, however, is cheaper for the basic process. The product of the acid process excels in quality, due to conditions already discussed, including more oxidizing slag in the basic process, more difficult recarburizing (with consequent trouble from sonims), and a great amount of impurities to be removed in the slag, with resulting hazard of reversion of impurities to the steel. The relative economy of the acid operation is due to its being shorter, requiring less repairs to lining, less fluxes and less metalloids added in recarburizing.

When we come to melting pure stock in the electric furnace, it is evident that the basic process loses its chief advantage, *viz.*,


the lower price of raw material. True, we may remove sulphur, but the cost of otherwise pure stock containing up to 0.08 per cent of sulphur is not much less than the cost of raw material which will make low-sulphur steel even in the acid electric furnace. It is claimed that a little sulphur is removed in the acid furnace, using slags similar to those cited in Table XXVII, provided manganese is used freely. A slag containing  $\text{CaC}_2$  is the most efficient desulphurizer known, and this cannot be used in an acid furnace, but many believe that manganese and low-sulphur stock is cheaper than the combined additional costs of the basic operation.

The relative brevity of the acid operation is due to:

1. The comparative ease with which acid slags may be maintained in a deoxidizing condition;
2. The briefer deoxidizing and degasifying period, because the steel itself is less oxidized, and is normally free from gases (see below);
3. The freedom from melting of such large proportions of fluxes;
4. Less recarburizer additions to be melted.

These circumstances require for the acid process, less current, less labor and less cost for overhead per ton of product.

Acid steel requires less manganese, and usually no ferrosilicon need be added, because it is reduced from the acid slag and acid lining:



This decreases the cost of additions. The lining is less corroded, and acid refractories cost less than magnesite, besides being more durable. Acid side walls and roof are normally used even in basic furnaces, on account of their strength and high melting point; if the acid roof drips, it does not damage an acid slag. Acid fluxes are also less costly than basic fluxes, and the slag does not accumulate impurities, so that the acid slags may be used several times.

Finally, well-made acid steel is uniformly of high quality, and not subject to the dangers from which basic steel suffers. For example:

1. After the melting stage is complete, acid steel is less oxidized than is basic steel at the same period;
2. It normally contains less dissolved or occluded gases, because silicon is maintained in it almost automatically;

TABLE XXVII.—ACID ELECTRIC STEEL PRACTICE

Practice	Analyses of steel baths							Analyses of corresponding slags								
	Test No.	C	Mn	P	S	Si	SiO <sub>2</sub>	CaO	MgO	Al <sub>2</sub> O <sub>3</sub>	Fe <sub>2</sub> O <sub>3</sub>	FeO	MnO	S		P <sub>2</sub> O <sub>5</sub>
Open-hearth metal 324	1	0.12	0.60	0.020	0.040	trace	51.50	15.30	3.80	2.60	....	6.95	18.85	0.25	0.01	1
40 lb. petrol coke	2	0.42	0.52	0.020	0.045	0.20	58.80	11.40	4.30	2.14	....	6.85	16.30	0.27	0.03	2
22.4 lb. ferro-manganese	3	0.47	0.64	0.020	0.045	0.24	58.80	11.40	4.30	2.14	....	6.85	16.30	0.27	0.03	2
26.9 lb. ferro-manganese	4	0.47	0.75	0.025	0.046	0.28	58.80	11.40	4.30	2.14	....	6.85	16.30	0.27	0.03	2
Final analysis of heat 24	5	0.47	0.78	0.025	0.046	0.31	54.00	11.50	5.20	1.72	....	3.35	23.55	0.29	0.03	5
Open-hearth metal 330	..	0.11	0.66	0.025	0.044	0.18	39.02	5.80	1.50	1.92	2.15	23.80	25.41	0.15	0.20	oxidizing slag
44.8 lb. ore, slagged off	1	0.13	0.28	0.025	0.034	0.07	54.84	14.50	....	....	....	3.85	12.66	0.20	....	3
44.8 lb. petrol coke and electrodes	2	0.42	0.28	0.020	0.033	0.10	54.84	14.50	....	....	....	3.85	12.66	0.20	....	3
22.4 lb. ferro-manganese	3	0.48	0.40	0.030	0.053	0.09	54.84	14.50	....	....	....	3.85	12.66	0.20	....	3
22.4 lb. ferro-manganese	4	0.50	0.64	0.025	0.038	0.18	52.70	15.80	....	....	....	3.60	20.15	0.12	0.12	5
6.7 lb. ferro-manganese	5	0.52	0.68	0.025	0.037	0.21	52.70	15.80	....	....	....	3.60	20.15	0.12	0.12	5
Final analysis of heat 25	7	0.56	0.70	0.025	0.040	0.25	52.60	13.70	3.20	1.52	....	3.85	23.70	0.13	0.12	7
Open-hearth metal 360	..	0.09	0.46	0.015	0.030	trace	52.50	18.75	2.90	1.36	....	5.80	16.70	0.11	0.05	1
62.7 lb. petrol coke	1	0.62	0.30	0.015	0.026	0.09	52.50	18.75	2.90	1.36	....	5.80	16.70	0.11	0.05	1
3 shovels of sand	2	0.60	0.28	0.013	0.026	0.12	52.50	18.75	2.90	1.36	....	5.80	16.70	0.11	0.05	1
Petrol coke to reduce	3	0.69	0.28	0.010	0.018	0.16	55.80	19.60	4.02	2.02	....	3.55	13.85	0.03	0.03	5
MnO in slag	4	0.70	0.28	0.015	0.020	0.23	55.80	19.60	4.02	2.02	....	3.55	13.85	0.03	0.03	5
Final analysis of heat 29	5	0.74	0.30	0.015	0.020	0.23	55.80	19.60	4.02	2.02	....	3.55	13.85	0.03	0.03	5
Open-hearth metal 383	..	0.10	0.45	0.015	0.034	trace	45.10	5.35	2.10	1.75	2.30	23.65	19.30	0.40	trace	oxidizing slag
134 lb. ore, slagged off	1	0.12	0.17	0.020	0.032	0.04	53.50	29.60	3.10	1.49	0.43	3.60	4.95	0.37	trace	3
49 lb. petrol coke and electrodes	2	0.51	0.18	0.020	0.039	0.07	53.50	29.60	3.10	1.49	0.43	3.60	4.95	0.37	trace	3
Test red short	3	0.56	0.18	0.025	0.042	0.10	53.20	not det.	....	....	....	4.35	5.70	....	....	4
Test red short	4	0.58	0.18	0.025	0.057	0.08	53.20	not det.	....	....	....	4.25	8.35	....	....	5
44.8 lb. ferro-manganese	5	0.56	0.54	0.025	0.048	0.16	54.20	not det.	....	....	....	4.05	11.15	0.40	trace	6
Final analysis of heat 31	6	0.56	0.44	0.022	0.035	0.19	54.20	23.20	3.05	1.86	0.35	4.05	11.15	0.40	trace	6
Open-hearth metal ?	..	0.09	0.40	0.015	0.036	0.10	58.83	24.29	2.40	1.75	0.29	3.07	8.93	0.39	trace	1
54 lb. petrol coke	1	0.61	0.44	0.018	0.037	0.13	58.54	not det.	....	....	....	2.96	9.59	....	....	2
22.4 lb. ferro-manganese	2	0.63	0.60	0.021	0.043	0.17	58.54	not det.	....	....	....	2.96	9.59	....	....	3
33.6 lb. ferro-manganese—3 shovels sand	3	0.63	0.74	0.023	0.039	0.23	59.78	not det.	....	....	....	3.08	11.45	....	....	4
4 shovels sand	4	0.62	0.78	0.023	0.038	0.26	57.92	not det.	....	....	....	2.58	13.79	....	....	5
Final analysis of heat 39	5	0.60	0.78	0.020	0.037	0.25	66.27	15.26	2.03	0.15	....	2.81	11.68	0.51	0.51	5

(This Table quoted from R. J. WEITLANER, *Blast Furnace and Steel Plant*, January, 1922, p. 45.)

3. The danger from silicious sonims is absent, because silicon is being reduced into the steel and it cannot be both reduced and oxidized at the same time;

4. Other sonims are avoided during the heat, because even manganese is not oxidized when added to the bath;

5. The slag is pure, which avoids danger of reversions to the metal either in the furnace or the ladle.

The basic furnace has the great advantage that we may, when market conditions make it desirable, melt and refine impure stock. And a very serious special hazard in the acid electric process is the tendency of the slag to become infusible and viscous, with consequent danger of sonim formation which sometimes overbalances all the advantages mentioned above.

**Acid or Basic Process for Steel Castings.**—The uniform freedom of acid electric steel from gases and sonims, and the ease and economy with which it may be charged with silicon up to 0.3 to 0.4 per cent would admirably adapt it to the manufacture of castings from the quality standpoint. But competition drives the price of castings down below the point where pure stock can be melted with profit. Moreover the consumer is not yet educated to the point where there is a large tonnage demand for steel castings of high quality at high prices.

**Acid Electric Process.**—We may consider the acid furnace as a huge crucible in which pure stock is melted, "killed," as in the crucible process, brought to the desired temperature and poured into molds. The essential difference is that electric energy is used instead of fuel to produce heat. The character of the slags is shown by the analyses in Table XXVII. Coke is added to maintain a slag of reducing character, but, of course,  $\text{CaC}_2$  cannot be held in an acid slag. The details of the process are similar to, but much simpler than, those of the basic operation, but the acid process is not as much used for the reasons already given.

#### MELTING IMPURE SCRAP TO PRODUCE ELECTRIC STEEL (BASIC FURNACE ONLY)

Scrap containing more than 0.08 per cent sulphur or (and) 0.02 per cent phosphorus, must pass through an oxidizing period before it can be deoxidized. This lengthens the process and lowers the quality, because oxidized steel is not always perfectly deoxidized—some say it never is. The raw material is cheaper, and is easier to secure. In practice the operation differs in that,



besides putting limestone (instead of lime) on the hearth, we use enough iron ore with the scrap to oxidize all the silicon and phosphorus, but not any of the other elements. This requires low temperature until the oxidizing (black) slag is removed. If the temperature is too high, some manganese, chromium (if present) and carbon will be removed. Sometimes scrap pig or new pig iron is charged with the stock to melt down hard and allow more ore to be used. It is most desirable that the charge, when melted, shall be reduced to less than 0.02 per cent phosphorus, except in the case of steel for castings, which may be higher. On account of the basic slag, the silicon goes before the phosphorus.

**Charging.**—Pig iron, if used, is put next the limestone on the hearth, in order to protect the latter from iron oxide. On top of this is put the large scrap, and then the interstices filled with small scrap as well as possible, to lessen "jumping" of the arc. Hand charging is used to avoid damage to the electrodes, except recent installations which permit raising the electrodes out of the danger zone. In this case, charging machines save much labor. Unoxidized scrap is used, as rusty steel adds an uncertain oxidizing influence. Scrap containing nickel must be avoided, as the nickel will not be removed.

**Black Slag.**—When the charge is melted and the "lime comes up," a sample of the bath is taken and analyzed. If phosphorus is removed, the black slag is poured off, with the aid of rabbling. It must be completely removed, including any that adheres to the sides. If too thin to follow the rabble, it must be thickened with lime. If the phosphorus in the initial charge was above 0.07 to 0.09 per cent we may require a second black slag for removing it. This is costly and usually uneconomical, because purer stock is normally less expense than a longer operation and additional fluxes.

**White Slag.**—When melted and purified, with the black slag removed, the bath is ready for the white slag. This is made up of lime, thinned with  $\text{CaF}_2$  or sand or both. It is mixed before charging, and about one shovel of coke also is used for each three shovels of lime.

**Recarburizing and Refining.**—The temperature is raised as rapidly as possible and the analysis adjusted to give the steel about 10 to 25 points less carbon than is desired in the final analysis; manganese 0.15 to 0.40 per cent, and silicon 0.10 to

0.20 per cent. There will be no waste of metalloids later in the operation, because no subsequent oxidation of the bath. Carbon is added in the form of coke, charcoal or ground electrode stumps. Sometimes pure pig iron is used, depending on market conditions, and sometimes, washed metal, as in the crucible process. Carbon in coke enters the metal to the extent of about 60 per cent of its weight, and usually causes a boiling of the bath, due to escape of CO gas. If the bath is very wild, ferrosilicon may be added with carbon, but usually the order of charging is like that in the acid open-hearth recarburizing, so that carbon (the cheapest deoxidizer) will remove all the oxygen it can, then silicon and then manganese. Some operators omit the ferromanganese, but others use it to deoxidize more thoroughly and remove any silica sonims present. The need of manganese is greater the more extensive has been the oxidizing action previously. If impure stock was used, it is doubtful whether the white slag and  $\text{CaC}_2$  will deoxidize the bath sufficiently.

When the white slag and recarburizers are charged, the doors are closed tightly and the heat increased and atmospheric oxidizing conditions decreased as much as possible. The amount of white slag is 3 to 7 per cent of the weight of the bath. It should be melted and have lost its brown color in about an hour after charging. If the color does not begin to go in 30 to 40 min., more coke should be added to it; its fluidity should be kept right by additions of lime,  $\text{CaF}_2$  or sand as needed. Upon reaching this point we come to a condition similar to the super-refining operations already twice described. If ferromanganese was not added with the other recarburizers, it is added when the slag is white. This saves a little manganese. Some operators add ferrosilicon in small doses towards the end of the heat, but this is dangerous practice. Tungsten, if used, may be added any time after the slag is white, and this is added in small doses so not to chill the bath.

**Super-refining.**—We are now ready for the super-refining (*i.e.* carbide) slag: Coke dust is mixed with about twice its volume of lime and thrown in near the arcs, where the carbide reaction will take place. More coke dust is also scattered over the slag. The practice is essentially the same as that described on p. 183. The operation lasts about 2 to 3 hr. after the black slag is removed, and the total time will be  $5\frac{1}{2}$  to 7 hr. or longer, depending on the degree of purification and skill of the operator.

On the other hand, too much hurry during the deoxidation and degasification period results in inferior steel.

The making of low-carbon steel in electric furnaces is more difficult, because over-oxidized baths are almost impossible to deoxidize.

### MELTING AND REFINING PIG IRON

In the case of melting pig iron instead of steel scrap we have the condition of oxidizing melting, during which the silicon, phosphorus, and a part of the carbon will be removed, followed by a long boiling with black slags and additions of ore to remove the remainder of the carbon. The process is necessarily very costly, and finds no application except where scrap is scarcer and much costlier than pig iron, and where a very high price may be had for the product. The method is very little used. In case of melting pig iron low in phosphorus, we may use an acid furnace.

### ELECTRIC MELTING IN GRAY AND MALLEABLE CAST-IRON FOUNDRIES

Freedom from sulphur and a very high temperature is advantageous in all foundries, but especially in malleable-iron foundries. For this reason the electric furnace has evidently come to stay in some malleable cast-iron plants, where it gives great satisfaction, but at a somewhat high cost for operation. It is claimed that the saving in decreased defective castings, and the extra quality produced, in some examples, at least, more than make up for the higher cost of melting. The most economical way in which such a process may be practiced is to melt the iron in cupolas and then desulphurize, deoxidize and degasify in a basic electric furnace. Obviously the conditions must always be so reducing as to leave the silicon and carbon untouched, but the practice is normal for the usual white slag and carbide slag stages already described, except that the temperatures are much lower on account of the low melting-point of cast iron. Sometimes acid electric furnaces are used, with much excess of manganese for the purpose of cutting down sulphur. When sulphur is rather high for cast iron, say, 0.10 to 0.20 per cent, it may be reduced to 0.07 to 0.15 per cent by long treating in an acid furnace, but the operation is slow, and, moreover, silicon is liable to increase greatly in the acid furnace, as already mentioned, with bad

results to the metal. In gray cast-iron foundries the advantages are not so powerful, but the high temperature possible in cast iron from the electric furnace is valued in almost any foundry.

## TYPES AND DETAILS OF HIGH TEMPERATURE ELECTRIC FURNACES

(NOT INCLUDING ORE SMELTING FURNACES)

There are nearly 400 electric furnaces in America, of which nearly one-half are of the Heroult type. About 20 other inventors have contributed new types or modifications and given their names to furnaces which are sold or operated on royalty. The principles on which the different varieties are based fall into a few classes, which we may discuss briefly, without attempting to describe the several types as such, but quoting in Table XXVIII the names of those most used.

**Method of Heating. Note A. Direct Resistance.**—Pure iron has a resistance to the electric current six to seven times that of pure copper (the basis); cold steel has a resistance about eight times copper, and molten steel about 110 times that of copper. The passage of an electric current through a bath of molten steel therefore generates large volumes of heat, and this method of heating the charge would be ideal except that a bath convenient and economical to handle is not the right shape to offer a uniform and small cross-section to the passage of current. The Roechling-Rodenhauser furnace offers a means of overcoming this objection, and the so-called "pinch effect," discovered by Dr. Carl Hering, keeps the steel in motion, so that the metal heated to a high temperature in the part of the bath where the cross-section is small circulates into the other parts and distributes its heat. An objection to resistance heating, from the metallurgical standpoint, is that there is no arc to form  $\text{CaC}_2$ . An advantage is the economy of its use (although not necessarily of its application. For example, when applied by the induction system, the loss of energy through induction more than offsets the economy of its use. Good means for applying it, other than by induction, have failed so far). Another good point is the uniformity obtainable by the rotation of the metal through the "pinch effect" principle; another is the possibility of heating the metal hotter than the lining, and the ease and economy of temperature control. The difficulty of starting a cold charge by the resistance-



TABLE XXVIII.—CLASSIFICATION OF HIGH TEMPERATURE ELECTRIC FURNACES, EXCEPT ORE-SMELTING FURNACES

Method of making electrical connection		Method of heating charge	Name of furnace
Is hearth used as one electrical connection (Note D, p. 198)	Method of getting electricity into furnace		
No Electricity does not pass through furnace hearth	Induction principle (see p. 177)	Direct resistance (Note A, p. 195)	Kjellin Roechling-Rodenhauser
	By means of carbon or graphite electrodes (Note C, p. 197)	Indirect arc (Note B, p. 195)	Stassano Rennerfelt
		Direct arc to metal or slag from electrodes	Heroult vom Baur Ludlum Volta
Yes Hearth serves as conductor of electricity			Snyder Greaves-Etchell Girod Fiat Grönwall Booth Stobie Nathusius Moore Greene Keller

heating method is as great, but perhaps not as wasteful as the corresponding difficulties in the arc furnace.

**Note B. Indirect Arc.**—Figure 88 illustrates the principles of indirect and direct arc heating. The indirect arc heats by radiation; is not so economical of heat as the direct; does not form

$\text{CaC}_2$  easily, and is harder on the furnace walls and roof. It is not much used in America.

**Note C. Direct Arc.**—The direct-arc system of heating (see *B* and *C*, Fig. 88) applies the heat right at the surface of the bath, but does not distribute it uniformly over the area. The electrodes usually dip into the slag, but the slag does not “wet” the slippery carbon surface, and a myriad of tiny arcs pass from electrode to slag or metal.




FIG. 88.—Types of electric arc furnace heating.

A, Indirect arc; Stassano type. Heat radiates to bath. B, Direct arc; electricity does not intentionally traverse hearth. C, Direct arc; hearth serves as conductor of electricity.

**Method of Making Electrical Connection.**—Little thought is needed to convince anyone of the difficulty of connecting an electric current to a bath of molten metal. No substance has been found which will not either melt or chill the bath, or dissolve in the steel, if in contact with it. But the carbon (graphite) electrode suspended above the bath and transmitting the electricity through a series of arcs performs the double function of making the connection and converting the electric energy into heat energy. Obviously it requires good automatic means of controlling the length of arc and therefore the intensity of heat input.

**Note C. Electrodes.**—Amorphous carbon electrodes are made from anthracite coal and petroleum coke, agglomerated with tar, pressed in a mold, baked to remove volatile compounds, and then annealed for 10 to 15 days. They are threaded at both ends, so that, when burned down to a stump, a new electrode may be added on by means of a threaded nipple and paste to make a tight joint and avoid heating by electric resistance of the joint. The length of electrode is 5 ft. and the diameter depends on the amperage to be carried, which, in turn, depends on the size of furnace. Table XXIX gives diameters of carbon and of graphite electrodes for different sizes of furnace.

TABLE XXIX.—DIAMETERS OF ELECTRODES

Size of furnace, capacity in tons	Diameters of electrodes, inches	
	Graphite	Carbon
1 to 2	5 to 7	8 to 10
3	8 to 10	14
6	9 to 12	17
25	12	24
30	14	
40		
80		

Graphite electrodes are made of carbon heated to the point of graphitization. They are fastened together by means of a threaded joint and nipple, but their conductivity is so much better that they require no paste to avoid heating at the joint.

**Carbon Vs. Graphite Electrodes.**—Graphite electrodes cost about twice as much as carbon per pound, but have 3 to 3½ times the conductivity, so weigh less than one-half per unit of current carried. They are used in more than half the electric furnaces of the country. Their disadvantages are: Lower strength per unit of cross-section; lessened area of bath surface in which the arcs are active; higher heat conductivity, which means greater radiation loss through electrodes, but also better cooling of the electrode in the holder. The advantages of their smaller size are: The holes through the roof are smaller, which is of much importance on account of its strength; the control mechanism is lighter; broken stumps are easier to remove from bath; the smaller electrodes are handled easier, in general; and the smaller surface area radiates less heat from that part outside of the furnace. The graphite electrode oxidizes less easily in the furnace.

**Note D. Conducting or Non-conducting Hearth.**—In *B* and *C*, Fig. 88, is illustrated the difference in course of current in non-conducting and conducting hearths. It is claimed that the conducting hearth enables electricity to be converted into heat by resistance of the bath, as well as arcing, but this is evidently a small feature. The conducting hearth is said to simplify the problem

of melting a cold charge, but it also increases the already serious hearth difficulties.

**Tilting Furnaces.**—All the furnaces used for steel refining and super-heating for foundries are arranged to tilt, especially for the removal of slag. Most of them also have tap-holes, so that the furnace may be tipped and the steel tapped from under the slag, thus getting it into the ladle without slag.

**Power Charges.**—The only economical manner in which to operate an electric furnace is to regularly use "off peak load" power, or else to maintain an almost uniform load. "Standby" charges from the power producer, when the furnaces are idle, quickly run into heavy expense, and it is often customary to base charges per unit of electricity on the maximum amperage used, so that short-circuits during the melting period are very costly.

**Thermal Efficiency.**—The thermal efficiency of the direct-arc furnace is very high, as compared to other metallurgical furnaces. This balances in part the high cost of heat obtained from electrical energy. Thus, Lyon, Keeney and Cullen (U. S. Bureau of Mines, *Bull.* 77, 1916) give the thermal efficiency of the Heroult furnace as 70 per cent as compared with:

	PER CENT
Iron blast furnace.....	60
Acid open-hearth.....	12
Basic open-hearth.....	10
Crucible furnace.....	4

More recently (1922) the thermal efficiency of the basic open-hearth has been determined as 13 to 17 per cent. The 30 per cent lost thermal efficiency of the Heroult furnace consisted chiefly of losses through electrodes, by conduction through roof and to the cooling water, by bad joints, and by electrode oxidation, as well as radiation losses through doors and a little through the lining and roof.

#### ELECTROLYTIC REFINING OF CAST IRON OR STEEL SCRAP

For more than 50 years attempts have been made to produce pure iron on an industrial scale by means of electrolysis, which modern metallurgy recognizes as the "tonnage production" method for metals in a pure form, and which is the established process since a number of years for pure copper, gold, silver, aluminum, lead, zinc, etc. The combination of unexcelled cheap-



ness with unexcelled utility for many purposes, possessed by *impure* iron, has diverted attention from the superior utility of the *pure* metal over pure copper, aluminum, etc., at a fraction of the price. We now know that pure iron is at least as soft and has better cold-working or drawing qualities than either pure copper or aluminum, besides having great advantages for household and machine purposes in respect of price, durability, maintenance of a bright surface, resistance to corrosion or tarnishing, to heat, etc.

Speculations as to the properties of pure iron—that is, iron of at least 99.99 per cent Fe.—which have been based upon researches carried out on metal having 99.50 per cent purity, are now known to be well below the actual quality of the metal in such properties as softness, malleability when cold, ductility, magnetic qualities and, probably, resistance to corrosion.

An industrial plant is now using the electrolytic process to refine cast-iron scrap and produce iron 99.97 per cent pure. The electrolyte is ferrous chloride; the anode is cast iron; the cathode is a revolving mandrel upon which the pure iron is deposited in the form of a tube, which is annealed to remove the embrittling hydrogen which is deposited with the metal, stripped and used as a boiler tube, either with or without drawing through a die.

The research departments of the American Telephone & Telegraph Co. and the Western Electric Co., in seeking a commercial process for the manufacture of pure iron in a pulverized form, employed the very ingenious expedient of utilizing the hardness and brittleness of electrolytic iron from which the hydrogen had not been eliminated, in order to get the material into a finely powdered form and compress it into magnet cores which would have high electrical resistance because the particles were not soft enough to crush together into a unit mass. When these operations were concluded, the compressed cores were baked to remove the hydrogen, leaving pure iron particles.

This process proved cheaper and better than reducing the iron powder by hydrogen from the oxide. A commercial electrolytic iron plant was therefore equipped at Hawthorne, Ill., with a capacity of about 2 tons of iron per day. This method of securing pure iron proved to be relatively inexpensive and to afford a ready means of controlling the quality of the material.

The cores of the loading coils which are introduced at regular intervals to increase the inductance of a telephone circuit are now made of this material. The electrolyte is of ferrous sulphate

and chloride and ammonium sulphate; the anode is mild steel; the cathode polished sheets of steel, from which the deposited metal is stripped when it has reached a thickness of  $\frac{1}{8}$  to  $\frac{1}{4}$  in., the current density is about 12 amp. per square foot.

### ELECTROLYTIC IRON DIRECT FROM ORE

The deposition of iron by electrolysis is from the electrolyte directly on to the cathode. The use of a soluble anode is only a means of keeping the electrolyte supplied with iron. Any other means of accomplishing the same result would give the same deposition, electrical efficiency, etc. For example, the circulation of the electrolyte, always maintaining it up to the desired standard of iron content, would effect the electrolytic action and avoid some disadvantageous features, such as the economic waste due to the loss in slimes with the soluble anode, the migration of impurities from anode to cathode, etc.

This is the novelty introduced by Frederick A. Eustis and Charles P. Perin in patents issued the former and developed jointly by them. This process has passed through the laboratory stage and commercial installation is under way. The solution of iron ore is the means of keeping the electrolyte enriched in iron in proportion as it is impoverished by the electrolytic deposition. The electrolyte is ferrous chloride; the anode is of some insoluble material such as graphite; the current density is 50 amp. per square foot. The cathode may be a revolving mandrel on which the iron is deposited in the form of a tube, or it may be in the form of a sheet, or a traveling belt from which the crumbs are removed continuously by mechanical means.

Obviously, the process can be applied to any iron ore capable of solution, but its cheapest raw material is the abundant sulphide ores which occur in many parts of the world and which sell at a low price, because, first, of their abundance, and second, their inapplicability to blast-furnace smelting until after a process of complete roasting. Such ores also yield their sulphur content as a by-product, at a price which more than covers both the cost of sulphur production and the total cost of the ore itself.

### INDIRECT HEATING FURNACES FOR TEMPERATURES UP TO 1,100°C.

For very accurate heating, electric furnaces of the indirect resistance type are used, in which resistance wire or tape of nickel steel, or even, sometimes, of platinum tape, is wound around a

refractory muffle inside which are placed the articles to be heated. For laboratory purposes, for heat treatment of fine tool steels, for heating baths of molten barium chloride (or similar salts) in which small articles are to be heated for tempering, and even for delicate heating of large I-bars, furnaces of this type are used. They are costly to install and operate, but give the best control of temperature of any furnace available for such work.

## CHAPTER VIII

### THE INGOT-MAKING STAGE OF MANUFACTURE

By whatever process steel is manufactured it leaves the steel mill in the form of an ingot or casting.

It might be thought that this stage of manufacture was of lesser importance and that if we could so control the steel-making process as to avoid excessive amounts of impurities, then the quality of the resulting ingots or castings would almost necessarily take care of itself. It is now well recognized that this is by no means true, and that many injurious defects may appear during the ingot-making stage, although some of these




FIG. 89.—Locations of blowholes in steel ingots.

A, Deep-seated and skin blowholes. B, Deep-seated blowholes only. C, Skin blowholes only. (See also Fig. 22, p. 51.)

may be caused by improper methods of manufacture, such as: Too high or too low temperature on leaving the furnace, or insufficient deoxidizing of the bath. Other defects may originate during the ingot-making stage itself, such as: Teeming too soon after adding the recarburizer, casting too hot or too cold, improper shape or proportions of ingots, or the addition of too much aluminum or other deoxidizer to the metal in the ingot mold.

The defects which may appear during the ingot-making stage are:

1. The inclusion or entanglement in the solid steel of minute particles of slag or other oxidized substances. These occur



often in so fine a form as to be like an emulsion, and it has been suggested that we might almost consider them as colloids. They separate from the steel very slowly and their presence in the solid metal is a source of weakness or brittleness or both. Their source is largely the oxidation of silicon, manganese, aluminum and other metals added to deoxidize the steel; also minute particles of slag, dirt from the ladle lining, manganese sulphide, etc. The general name of "sonims" has been given to these solid non-metallic impurities.

2. Blowholes or gas bubbles entangled in the metal (see Fig. 89).




FIG. 90.—Stages in the formation of a pipe.

3. A pipe or shrinkage cavity extending so far down into the ingot that it is not removed when the ingot top is cut off during the rolling operation (see Figs. 90, 91, 92).

4. Internal checks, or "flakes," that is, minute cracks in the interior of the steel which weaken the structure.

5. External cracks due to straining the surface of the steel during solidification or when the ingot mold is removed in the stripping process.

6. Scabs on the outside surface of the ingot, caused by particles of slag or oxide of manganese.

7. A weak crystalline structure formed during the solidification of the steel and having such forms as: Very large crystals, or "ingotism;" fir-tree crystals or dendrites; columnar crystallization.

8. Segregation or the concentration of impurities in localities, thus forming points of weakness. This is almost invariably the result of oxidized or dirty steel, excessive impurities left from the

furnace stage, or excessively slow cooling of the ingot allowing the liquation of more fusible compounds to the late-freezing portions of the ingot or casting.

**Occluded Oxidized Substances.** "Sonims."—When large in size, these enclosures are commonly the result of accident, negligence or ignorance, and therefore could usually have been avoided by the exercise of due care, but, in microscopic particles, aggregating as much as 0.25 to 0.30 per cent of the weight of the metal, they are often found in Bessemer and open-hearth steels, not as a result of chance, but as a regular occurrence. Oxides and sulphides of iron and manganese, oxide of silicon or aluminum and tiny particles of slag are the commoner examples of these enclosures. Entangled particles of slag seem to be due to their having become caught in the solidifying metal before they had an opportunity to rise to the surface. No doubt the bulk of the oxides of manganese and silicon originate through the recarburizing reactions in the bath, and the tiny particles thereof are retained because they cannot separate immediately. Like the cream in milk, time must be allowed for them to rise to the surface. The same necessity is felt to an even greater degree in the case of sulphide of manganese, which separates from a molten bath of iron or steel only upon long standing. The sulphide of iron appears to be actually soluble in the molten metal and not to separate until after solidification.

All these occluded oxidized particles are harmful to the metal. It is now commonly believed that many previously unexplained failures of steel are due, in part at least, to such defects, and the "shelling" off of the surface of railroad rails and locomotive tires is often directly traceable to this cause. Sometimes the sonims appear like a cloud or mist in the form of a plane within the body of the steel, forming a definite plane of weakness.

The proportion of sonims in the ingot will depend largely on the precautions taken during the final stages of the steel-making process (see pp. 157 and 184), the opportunity allowed for sonims to separate before and during teeming, and the care with which deoxidizers, such as aluminum, are added in the ingots to quiet the steel. Investigations are now being made regarding the addition of metals, such as calcium, magnesium, boron, whose oxides will flux the other sonims present, and so enable them to separate very easily, because it is known that the particles rise to the surface better when they are in the liquid condition.

Titanium has long been used for this purpose, because it has a strong affinity for oxygen and not only assists in the deoxidation of the steel, but its oxide also helps to flux and tends to coalesce and cause to rise to the surface oxides of some of the other metals. The titanium must be added after all the other oxidizers and must be kept out of contact with the slag.

Vanadium is a powerful deoxidizer and it has the effect, when added after all the other deoxidizers, of robbing the oxides of manganese, iron, etc., of their oxygen and so causing them to dissolve in the steel. In this way vanadium is one of the best scavengers that can be used, and is a powerful deoxidizer, but must not be left in the steel to the extent of over 0.30 per cent (see p. 449).

**Blowholes.**—Blowholes are especially liable to occur in low-carbon steel. When the metal is in a molten state, it readily dissolves certain gases, such as hydrogen, nitrogen, oxygen. Upon solidification these gases come out of their state of solution, but may become entangled in the steel and cause a gas bubble or cavity varying all the way in size from microscopic proportions up to 1 in. or more in length. The formation of these blowholes is precisely similar to the formation of air bubbles in ice; water dissolves a good deal of air while in the liquid state and, as we all know, it is well-nigh impossible to freeze the water without obtaining a great many air bubbles in the ice, due to the separation of this air during freezing. The occurrence in the case of steel is not so prevalent as in the case of ice, and it is by no means impossible to obtain steel absolutely free from this defect. Apparently the reason for this is that the gas separates from steel a short time before solidification is complete, and thus the bubbles have *some* opportunity to escape before they are enclosed in the solid.

Another cause of blowholes in steel is the presence of oxide of iron in the metal. This oxide of iron reacts with the carbon added in the recarburizer and forms carbon monoxide gas (CO), which may be produced during the entire solidification period and thus cause many blowholes. That oxide of iron is one of the chief causes of blowholes is shown by many things, for instance: (1) Steel known to be highly oxidized is very liable to blowholes; (2) cast iron, which from its chemical composition can never be much oxidized, is not so subject to blowholes; and (3) the addition to steel of deoxidizers prevents the formation of blowholes.

**Prevention of Blowholes.**—Chief among the deoxidizing elements which are added for this purpose are manganese, silicon, and aluminum. These elements seem to act partly by deoxidizing the iron and carbon, in both ways reducing the formation of carbon monoxide, and partly by increasing the solvent power of the solid metal for gases, so that a less amount separates. The amount of these deoxidizing substances necessary to be added will depend largely upon the extent to which we desire to prevent the formation of blowholes. In the case of steel castings it is often necessary that blowholes be entirely prevented, but in the case of ingots which are to be subsequently forged or rolled it is not necessary that blowholes should be absent altogether, because they will be closed up under the pressure of the mechanical work and their sides welded together. Indeed, their presence is sometimes desired, because when they separate from the steel they occupy space, thereby counteracting to a certain extent the shrinkage of the metal during solidification and tending to reduce the volume of the shrinkage cavity, or pipe. For this reason a small number in some harmless locality is often intentionally allowed to form in steel ingots. Mr. Brinell found in his steel works that if the percentage of manganese plus 5.2 times the percentage of silicon is equal to 2.05, or more, the steel will be entirely free from blowholes. In this case, however, the pipe will be large. If this sum is equal to 1.66, the steel will contain a harmless number of minute blowholes, but the pipe will be small. This figure is therefore about the correct amount for ingots under conditions similar to those of Mr. Brinell's experiments, and not far different in any event. Mr. Brinell also found that the addition to the steel of 0.0184 per cent of aluminum will give approximately the same result as that given by the amount of manganese and silicon last mentioned, 1.66.

**Location of Blowholes.**—The number and size of blowholes is no more important than the position they occupy in ingots in relation to the external surface. Even in castings, blowholes, if present, should be deep-seated, as they are then less liable to be exposed by machine work performed on the surface. In the case of ingots the deep-seating is of still greater importance, because then the blowholes may be closed up before they have an opportunity to break through to the surface and thus become oxidized on their interior. The normal gases in blowholes are reducing in effect, and thus the interior surfaces of the holes



are bright and silvery in appearance and readily weld together; but if they become oxidized they will never adhere firmly. For instance, a blowhole near the surface, as in Figs. 89, *A*, *C*, is liable to break through to the exterior when the ingot is put under pressure. This not only causes a crack in the steel, but allows the air to oxidize the interior of the hole and thus prevent the crack being welded up by the rolling. It is not at all uncommon to see a number of these openings form during rolling.

As the percentage of manganese plus 5.2 times the percentage of silicon decreases from 1.66, the blowholes become correspondingly deeper-seated. Finally, when this sum becomes as low as 0.28, the blowholes are harmlessly located in the interior. It is usually impracticable, however, to get the manganese and silicon as low as this in steel, because manganese is needed to counteract the bad effect of sulphur and oxygen.

The location of the blowholes is also very largely dependent upon the fluidity of the metal when first cast into the molds. The more fluid it is, other things being equal, the nearer will the blowholes be to the surface of the solid ingot. On the other hand, if the casting temperature is too low there will be a dangerously large number of blowholes in the steel (see Fig. 89, *A*), because it solidifies so quickly that very little opportunity is afforded for any part of the dissolved gases to escape. The fluidity of the steel depends partly upon its temperature and partly upon the amount of impurities in it. For instance, pig iron is fluid at a temperature at which steel is solid; high-carbon steel is fluid at a lower temperature than low-carbon steel. Therefore every different kind of steel has a different correct casting temperature; but we have already learned (p. 99) how to determine this by means of the skull left in the casting ladle, and it is evident that this test applies equally well to all grades of steel. It is to be observed that low-carbon steel suffers greatly from blowholes, because the less the carbon the greater the liability to oxidation of the steel.

**Pipes.**—When steel is poured into a mold, it forms almost immediately a thin skin of frozen metal against the cold surface of the sand or iron. The radiation of heat thereafter necessarily takes place through these surfaces, and therefore a casting will usually complete its solidification by the formation of thicker and thicker layers of solid metal around all the sides. The top surface, however, will usually remain molten longer than the rest because the hottest metal is usually at this point, having been



(From Jas. M. Camp's "*The Making, Shaping and Treating of Steel*," 2nd Ed.)

FIG. 91.—Pipes in steel ingots.



(From Jas. M. Camp's "*The Making, Shaping and Treating of Steel*," 2nd Ed.)

FIG. 92.—Pipes in steel ingots.

the last to leave the ladle, and also because the heat is not conducted away by the air as fast as by the walls of the mold. This is especially true where the casting is poured into an iron mold, for example, in the case of ingots (see Fig. 90). But it is evident that at some period a stage will be reached when all the outside of the ingot, or casting, will be covered by a skin of solid metal while the interior will still be liquid. The liquid interior will continue to freeze and will, at the same time, contract. The result will be the shrinking of the molten mass away from the solid walls and consequently the formation of a cavity, known as a "pipe," in the interior. This pipe will be filled with the gases evolved by the steel during solidification. Professor Howe has shown that the volume of the pipe is too large to be accounted for altogether by the shrinkage of the steel during solidification, and has shown that the rate of contraction of the inner walls of the ingot being greater than the rate of contraction of the outer walls, a virtual expansion of the outer walls is caused and a consequent enlargement of the pipe.

The portion of the steel containing the pipe is of course defective and should be discarded at some time subsequent to casting. In the casting of ingots the upper part, which contains the pipe, is cut off during the rolling or forging and goes back to the furnace to be remelted as scrap. In the casting of steel castings there is a large adjunct to the castings situated above it, and so regulated in size and otherwise that it freezes after the casting itself, and thus always contains a supply of molten metal which runs down and fills any cavity that forms in the casting. This adjunct is cut off when the casting has cooled. In other words, the "riser" or "feeder," as this extra part is called, serves the same purpose for a steel casting as the upper part of an ingot does for the ingot (see Fig. 140, p. 267).

Cast-iron castings do not form a pipe under ordinary circumstances, because cast iron expands during solidification on account of the separation of graphite, as we shall learn later. Under certain circumstances, however, there may be enough difference in expansion between the inside and outside of cast-iron castings to produce a porous spot which, while not exactly a pipe, is due to similar causes. We shall discuss this matter further in Chapter XIII.

**Lessening the Volume of the Pipe.**—If the steel were poured into the mold so extremely slowly that it would solidify in layers

from the bottom upward there would be no pipe. Therefore one method of lessening the volume of the pipe is by slow teeming. Another is to have the metal near its point of solidification when teemed. We have already noted another method, namely, permitting a small number of blowholes to form, which causes a certain amount of expansion to the steel during solidification and thus diminishes its shrinkage. Another way is to use wide ingots because this reduces the difference in contraction between the inner and outer layers of the ingot. Casting in sand molds has the same effect because radiation is not so rapid through sand as through metal. Still another method is to prevent the steel forming a solid skin over the top by constantly stirring and breaking it up with an iron rod. This method is often resorted to with the risers of steel castings, with very beneficial results. Still another method is to have the walls of the ingot molds much thicker at the bottom than at the top. This causes a more rapid radiation of heat from the bottom and concentrates the pipe at the upper end. In some cases a sand lining is placed in the mold at the top to insulate heat radiation, and keep the top warm.

**Bottom Casting.**—In the case of steel castings, and less frequently in the case of ingots, the metal is poured from the ladle into a runner which delivers it at the bottom of the casting (see Fig. 140, p. 267). With steel castings this is often necessary, in order to prevent dirt getting into the casting. It also has a similar effect on ingots, because it prevents slag getting into the molds and also prevents metal from spattering up on the side of the mold and forming what is known as a "cold-shut," that is, a part of the metal which is not melted in with the rest. In both cases, however, this bottom casting has the effect of increasing the volume of the pipe and also of making the pipe extend deeper, because at the end of casting the hottest metal is at the bottom instead of at the top.

**Casting with the Large End Up.**—Risers on castings are almost always made with the top end larger than the bottom, in order that the pipe may be less in volume and shorter in depth. At steel works, however, the ingot molds are usually tapered slightly with the large end at the bottom, in order that the mold may be easily drawn off the top (see p. 102). This results in the large end of the ingot being down, and consequently in the pipe being larger in volume and very much greater in depth. In making



the highest quality of steel for cannon, etc., ingots are cast with the large end upward.

**Liquid Compression of Ingots.**—If the pipe is caused by the difference in expansion between the inside and the outside of an ingot, it is evident that putting sufficient pressure upon the outside when the walls are solid but the interior is still liquid will prevent the formation of a pipe. Numerous processes have been devised for effecting this liquid “compression,” some of which are in operation at steel works and produce ingots that are entirely free from pipes. In Whitworth’s system the ingot is raised and compressed lengthwise against a solid ram situated above it, during and shortly after solidification. In Harmet’s method the ingot is forced upward during solidification into a tapered mold. This causes a large radial pressure on its sides.

**Internal Checks, or “Flakes.”**—These may have their origin in stresses in the ingot during the solidification period, and immediately thereafter. This is especially hazardous when making large and wide ingots or castings, which sometimes must be cooled with extreme slowness, even resorting to the expedient of removing them from the mold and burying them in ashes at the earliest possible moment. Sonims, by forming points of weakness, form loci of possible internal cracks.

Stresses produced during heating the ingot for rolling may also be a source of internal cracks, and this heating should be very slow, especially with large ingots. The less the number of ingots in the furnace, the shorter the time in which they may be heated from the cold state. Thus, with wide spaces between the ingots in the furnace and ingots of 2-ton size, they may be heated from the cold in 4 to 6 hr.; on the other hand, very large ingots require heating for 36 hr. or more. Even when hot ingots are charged into the heating furnaces as rapidly as they can be stripped and transferred, there must not be too high a temperature of the furnace as related to that of the ingot.

Still another cause of internal cracks is breaking a part of the crystals by mechanical work in rolling or forging. This is most likely to occur in the case of ingotism, dendritic or columnar crystallization, which see below.

**External Cracks.**—Bad pouring which splashes steel on the sides of the molds, where it solidifies, produces scabs on the surface of the ingot, which persist and appear in the final product as marks, slivers or seams. These splashes may also hinder the

free movement of the metal along the sides of the mold, and thus give rise to strains which tear the outer surface either during the weak and brittle period when the steel is not quite solid, or during the second weak period known as the "blue heat" ( $300$  to  $375^{\circ}\text{C.} = 572$  to  $707^{\circ}\text{F.}$ , see p. 257). Rough molds, and those which have cavities burned in the sides, produce the same effect. Finally, "stickers" which have to be removed from the molds by main strength in the stripping machine will naturally be liable to emerge with cracked surfaces. The remedy for this is not to use molds that are too old or rough, and to have a good taper on the mold, so that the ingot will free itself easily during the contraction period of solidification. Cracks are also liable to occur on the corners of ingots, due to the junctions of crystals,



FIG. 93.—Horizontal sections of ingots to show different forms. Steel crystals grow from the cooling surface inwards. The relation between the size of crystals and the radius of curvature of cooling surface will determine the extent of weakness due to crystal junctions.

as indicated for fluted ingots in Fig. 93. In the case of square ingots the weak line of junction is even more marked than is here indicated, since the crystals normally grow perpendicularly from the surface inwards. Pouring at a low temperature and slowly tends to restrain external cracks by giving the walls time to grow in thickness before the ingot gets long and assumes much longitudinal contraction, as well as by decreasing the tendency to form large crystals. The tendency to crack is increased by the expansion of the hotter internal layers of steel at the temperature of about  $700^{\circ}\text{C.}^1$  ( $1,472^{\circ}\text{F.}$ ) when the colder exterior is shrinking. This effect is intensified in the case of very large ingots, which are therefore cast in a fluted form (see Figs. 93

<sup>1</sup> At the critical temperature,  $700^{\circ}\text{C.}$ , cooling steel passes through a period of inward reheating, or recalcence, during which it grows warmer for a few minutes and expands slightly, see p. 416. This action is followed by cooling and contracting.

and 104) so that the outer surface can stretch without cracking. Steel of 0.17 to 0.24 per cent carbon is specially liable to external cracks.

**Scabs.**—During teeming particles of pasty slag or oxide of manganese, floating on top of the liquid steel in the mold as it fills, may adhere to the side of the mold and appear later as a scab. The plates of oxide of manganese so common on rail-steel ingots do not cause any damage usually, but slag or dirt may produce a permanent defect in the rolled material.

**Ingotism.**—When iron and steel freeze they crystallize, and these crystals grow with great rapidity, so that if their passage through the solidification period is slow they will attain a very



FIG. 94.—Ingotism. Showing how the junctions of crystals form planes of weakness.

large size. This formation of large crystals is known as “ingotism.” It is especially liable to occur if the metal is cast at too high a temperature or is allowed to cool through the solidification period at too slow a rate. In the case of steel, ingotism may be detected by breaking the casting; the large size of the crystal faces or facets will then be observed.

**Damage Due to Ingotism.**—Large crystals always produce weakness and loss of ductility, for the large crystals do not adhere to one another as firmly as when there is a more intimate association; consequently steel that shows ingotism will be tender. In the case of steel castings, they will not give as good a result in

the testing machine; in the case of ingots they will be liable to tear during rolling or under the hammer.

**Remedy for Ingotism.**—Ingots in which large crystals have formed during solidification may be brought to a high degree of strength and ductility by forging or rolling, because the mechanical work crushes the crystals and reduces them to a smaller size. The work must be done very carefully at first, however, or cracks will be formed that are not afterward welded up. Ingotism in steel castings is not so easy to cure; indeed, it is maintained by some authorities that its bad effects are never entirely obliterated. I am inclined to agree with this opinion, although annealing the steel at a proper temperature will produce a very beneficial effect (see Chapter XV).

**Dendrites.**—As the cooling of ingots proceeds from the surface inwards, the crystals join one another and grow somewhat like a fir-tree structure. When the individual crystals forming this structure are large, we often have a coarsely crystalline steel which breaks easily at the crystal joints. Very large ingots which cool slowly are in danger of this form of weakness which, however, can be eliminated by proper “saddening.” Saddening consists in treating the steel with light blows of the hammer or light drafts in the rolling mill when it first comes from the heating furnace, in order to break up the large crystals before the steel cracks due to heavy pressure put upon it.

**Shape of Ingots.**—The tendency of a cooling ingot to tear the outer surface in cooling is greatest in round ingots, medium in square ones and least in fluted shapes like those shown in Figs. 93 and 104. In each case the tearing depends on the inability of the outer surface to stretch without cracking. The larger the ingot the greater the tendency to tear the surface, and therefore very large ingots are always cast in fluted form. Ingot corners are always made round, because square corners concentrate the cooling at the edges and also result in lines of weakness along the junctions of crystals, as indicated in the paragraph on External Cracks, p. 213.

**Segregation.**—When either iron or steel is molten, the various impurities are dissolved in it, and some of them, especially carbon, phosphorus, and sulphur, make the metal more fusible, that is, they lower its melting-point. But the impurities are not as soluble in the solid metal, and therefore tend to separate on solidification; so it can readily be conceived how each layer



that freezes, beginning at the outside, rejects some of its impurities to be dissolved by the still liquid mass in the interior. When the next layer freezes that too will tend to reject a part of its impurities into the contiguous molten layer, and thus the concentration will proceed so that as a general thing the portion of the metal richest in impurities, especially in carbon, phosphorus, and sulphur, will be that which freezes last. With ingots, this will evidently be at a point just below the bottom of the pipe (see Fig. 96) and it is found to be so in the great majority of cases; but the location of the richest segregate is very liable to vary, and rules can only be used for general guidance. For example, in Fig. 95, the most impure metal is found at a point higher than the bottom of the pipe, and other unexpected exceptions occur. In the case of iron and steel castings, the most impure point will generally be near the top of the thickest section of metal. The riser is calculated to be the last portion to freeze and the richest segregate should be located in it.

In iron castings which contained on an average less than 1 per cent phosphorus and 0.1 per cent sulphur, I found on one occasion a segregated portion containing 1.856 per cent phosphorus and 0.144 per cent sulphur; and on another occasion I found one containing 2.43 per cent phosphorus and 0.236 per cent sulphur. An extreme case of segregation in steel is shown in the following analyses:

	Carbon, per cent	Silicon, per cent	Manganese, per cent	Phosphorus, per cent	Sulphur, per cent
Average.....	0.24	0.336	0.97	0.089	0.07
Richest segregate.....	1.27	0.41	1.08	0.753	0.418

**Treatment of Segregated Steel.**—Segregation cannot be prevented, although, of course, it seldom takes place to the degree shown in the extreme cases that I have cited above. Nevertheless, there are always certain portions of the ingot or casting which are richer in impurities than others. An attempt is made to get this richer portion into the upper part of an ingot, or into the riser of a casting, and then it is cut off when the ingot is rolled, or when the riser of the casting is removed. It is therefore advantageous to cause the segregate to go as high up in the ingot or casting as possible. Whatever tends to raise the pipe higher

up in the casting would, in general, tend to raise the segregate also; but wide ingots, or ingots cast in walls with low conducting power, though they tend to decrease the volume of the pipe, would not necessarily raise the segregate to a higher point.

Furthermore, wide ingots will probably have a much greater degree of segregation than narrow ingots, other things being equal, because the wider the ingot the greater will be the number of layers of solidification, and consequently the greater concentration of impurities in the center.




FIG. 95.—Lines of equal carbon-percentage in a steel ingot.




FIG. 96.—Carbon-percentage at different parts of a steel ingot.

**Lessening Segregation.**—Benjamin Talbot has shown that quieting the steel by adding aluminum to it will lessen the segregation. J. E. Stead argues that this result is due to the branches of crystals (commonly called “fir-tree crystals”)

which grow perpendicularly to the cooling surfaces when steel solidifies mechanically entangle some of the impure metal, thus preventing it from traveling inward. Professor Howe calls this type of freezing the "land-locking type." When the steel is violently agitated by the escape of gas its rapid movement washes off the fir-tree crystals and prevents them from growing out into the liquid mass and entangling the impure metal. The quietness produced by aluminum, however, makes this growth possible.

Another important means of lessening the segregation is by making ingots narrow, that is, by reducing the area of the horizontal cross-section; but this is often difficult of accomplishment. For example, if we cast 50 tons of open-hearth steel out of one ladle, it will take a very long time to cast all of this into small ingots, and therefore the first ingots cast will be too hot or else the last ingots will be too cold. There is a difference of opinion as to whether or not rapid cooling decreases or increases the degree of segregation, and it seems probable that it acts in both directions, sometimes prevailing one way and sometimes in the opposite. On first thought it would seem that slow cooling must necessarily increase segregation, because it would allow more time for the impurities to separate from one layer of metal and dissolve in the next. On the other hand, slow cooling also favors the growth of the fir-tree crystals, and therefore opposes segregation. It does not seem possible, at the present time, to tell under what conditions we should have the one influence prevailing or the other.

It seems to be pretty well established that the greater the percentage of impurities present the greater will be the extent of the segregation. Therefore high-carbon steel should be cast with due care and narrow ingots used wherever possible. Generally when the phosphorus and sulphur are low (say, not more than 0.05 per cent each), much segregation is not liable to occur, especially in low-carbon steels. One of the most active causes of segregation is oxidization of the steel as it comes from the furnace. This appears to be the most potent influence next to excessive phosphorus and sulphur.

**Pouring.**—The preceding paragraphs indicate how important is each detail of the ingot-making stage of steel manufacture, since good steel may be made bad and bad steel may be made worse. Thus, hot pouring decreases the amount of sonims, but

increases the external cracks, size of crystals and segregation. Pouring steel that has cooled too much increases sonims, blow-holes, and scabs, and may cause a cold shut, that is, freezing over of the steel before the ingot mold or casting is filled, with insufficient heat in the subsequent metal to melt the crust and form a perfect union. Fast pouring increases sonims and size of pipe. The rate of pouring is determined largely by the size of the ladle nozzle through which the steel is teemed.

**Top and Bottom Pouring.**—Teeming the steel into the top of the ingot mold is usual for most rolling-mill ingots, because it decreases the pipe, and segregation, and requires less costly apparatus. Pouring into the bottom of the casting or ingot is common for very large ingots and those whose quality enables them to stand the added cost. It has the advantage of keeping dirt and slag out of the metal, thus reducing scabs or large entangled particles. It also avoids cutting the bottom of the mold, and agitating the upper surface of the ingot during teeming, but increases the amount of scrap produced, because of the runner which leads to the bottom of the casting, increases the danger of run-outs by keeping the metal in the runners molten. It has the merit that one runner may lead to many ingots, thus giving all a uniform composition. In general, for high-quality steel, small ingots are top poured, large ones are bottom poured, and very large ones are poured from the bottom until a pool is formed which will take the splash, after which they are poured from the top.

**Size of Ingots.**—Ingots must be large enough to require sufficient reduction in rolling to ensure a thorough kneading of the crystals of steel. Up to a limit of 2 or 3 diameters the more work put upon steel the better will be its strength and ductility, assuming, of course, that it is finished at a temperature just above the critical range. Therefore, ingots must be at least two or three times the dimensions of the finished material. Sizes larger than that represent a loss of power, because the greater the size of the mill in which the ingots are rolled, the greater the cost of the rolling-mill, both initially and in respect of cost of operation. On the other hand, to teem an open-hearth heat of 100 tons into ingots of a few tons each requires time, which represents labor cost and loss of heat through radiation. The smaller ingots are also more costly to handle in the stripping and heating departments. In one respect ingots may be increased



in size without increasing the cost of the mill in which they are rolled, that is, in length. Therefore, ingots are customarily long and as heavy as the balance of opposing interests mentioned above indicates in each case. Rails ingots usually weigh about 3 tons each, when made in the Bessemer mill from heats of 15 to 20 tons each. Open-hearth ingots from furnaces of 50 to 100 tons capacity weigh from 3 to 10 tons each for rolling purposes. Of course ingots to be forged or hot pressed into armor plate or cannon tubes must be large enough to serve the purpose; they may weigh 100 tons and upwards. They are cast in special molds, and often in molds built up of sand and baked into a strong, hard mass.

**Taper of Ingots.**—The taper of molds must be such that the ingot will free itself easily, and that it will strip without tearing even when the mold is somewhat rough from service. The longer the ingot the greater must be the taper, because the greater the total contraction between top and bottom, and the greater the amount of surface for sticking. Most molds have a taper of about  $\frac{1}{2}$  in. per foot of length, but the importance of each decimal of a fraction requires special investigation for every type of practice.

## CHAPTER IX

### THE MECHANICAL TREATMENT OF STEEL

Metals may be shaped either by pouring them while molten into a mold, as described in the following chapter, or by mechanical pressure. The choice of the casting or the mechanical method of shaping will depend on the cost of production, the size and form of the finished product and the purpose for which it is intended. Some shapes must be produced by casting, because they are either too intricate or too large to be shaped by pressure; others must be produced by pressure, because the service in which they are to be used demands the higher strength and ductility which mechanical work produces. Between these two classes, however, is a large number of forms, each of which is a study by itself. Financial considerations will govern in some cases, and the importance of quality in others. The advantage of quality is usually with the pressed material. Cost is usually in favor of castings except where many pieces are to be produced alike in shape and size.


**Effect of Work.**—Mechanical work will multiply the strength of steel from two to five times. In order to accomplish as much as this latter, however, it is necessary (1) to reduce the material to very small sizes, in order that the beneficial effect of the kneading action may extend throughout the mass, and (2) to finish the work cold, in order that the metal may have no opportunity to recrystallize. The ductility also will be increased at first by working, but again decreases if the metal is worked cold. The increase in strength and ductility is due (1) to decreasing the size of the crystals and closing the grain of the steel; (2) to the closing up of blowholes, both large and small, which are almost all welded together under pressure at high temperatures, unless they are near enough to the surface to become oxidized inside, and (3) to increasing the cohesion and adhesion of the crystals. All these effects increase the specific gravity and hardness of the metal, and are more effective in these respects, as well as in increasing strength, if hot work is followed by cold work.

**Crystallization of Steel.**—Metals are crystalline substances, the individual components arranging themselves in regular



(Courtesy, Jas. M. Camp.)

FIG. 97.—Crystals of cast steel, magnified 100 diameters, showing large size.




(Courtesy, Jas. M. Camp.)

FIG. 98.—Crystals of steel like that in Fig. 97, but showing small size due to mechanical work in the cold. Magnified 100 diameters.

forms unless opposed by the rigidity of the mass in which they form. Indeed, the metallic crystals grow with astonishing

rapidity when the metal crystallizes from the molten state (*i.e.*, solidifies), or even when it is in a mobile condition (*i.e.*, at temperatures near or above a red heat). Once crystals have formed they cannot be reduced in size except by annealing (see Chapter XIV), or by breaking them up by mechanical crushing. These facts are important, because large crystals do not adhere to each other firmly, and thus they cause a weak and brittle mass. Iron and steel follow the same laws as other metals in these respects.



(Courtesy, William Campbell)

FIG. 99A.—Straight slip bands in wrought iron magnified 60 diameters.



(Courtesy, William Campbell)

FIG. 99B.—Neumann's lines. Cleavages produced by forging at too low a temperature.

**Effect of Strain.**—When a metal is strained, the crystals first stretch, and the amount of this stretching is directly proportional to the strain; when the strain is relieved, the crystals and the mass as a whole return to the original dimensions. If the strain is greater than the “elastic limit,” however, the crystals yield, and the particles composing them slip along the cleavage planes, so that a permanent deformation or extension occurs in the direction of the strain. This “elongation” is accompanied by a “reduction in cross-sectional area,” and gives warning that the material is suffering from excessive strain. The extent to which these two forms of distortion precede rupture is usually taken as the measure of the “ductility” of the metal.

**Rationale of the Effect of Work.**—Mechanical pressure upon a metal crushes the crystals, mixes them intimately together, and breaks up the cleavage planes along which they would yield. If the work is finished above a red heat where the mass is still mobile,



the crystals reform to a certain extent, decreasing the strength. The elastic limit of a structural steel rolled in this way will be a little more than one-half its ultimate strength. If the work continues while the metal is cold, there is no opportunity for the reformation of the crystals, and the strength, hardness, and brittleness are much increased.

**Methods of Applying Pressure.**—Aside from the differences of hot and cold working, the mechanical pressure may be exerted in one of three ways: (1) Instantaneously, by a blow, in which method the pressure is relieved before the metal has fully yielded to it; (2) more slowly, by rolling or wire-drawing, in which the pressure is relieved almost as soon as the metal has yielded to it; and (3) slowest, by presses, in which the pressure remains for a second or so after the metal has yielded (see p. 257 to compare).

### THE FORGING OF METALS

The instantaneous application of pressure is man's first method of shaping metals and is accomplished by a blow from a falling weight, frequently aided by some other force. Examples of the first practice are found at the present time in the helve hammer used at many small forges and steel works. After the introduction of steam, however, this was used to raise the weight, and very soon steam-power was employed not only to raise the weight but also to force it downward for the blow, whose momentum was thus greatly increased. Hammers of this type, which is now the most prevalent, have been built capable of delivering a blow estimated as equivalent to 150 tons weight. Such large sizes are not now approved of, however, because of the inordinate expense for foundations, which must be deep and powerful in order to take up the force of the blow, while the constant jarring disturbs the foundations and alinement of machinery, even at distant parts of the plant. For very heavy forging work, such as armor plate, etc., the hydraulic press is therefore preferred, and hammers are not often built in sizes above 30 or 50 tons.

**Effect of Hammering.**—A blow creates in a metal practically nothing but compressive strains, which act chiefly in the vertical direction, and, by transmission, in the two horizontal directions. Because the pressure is relieved almost as soon as felt, the elasticity of the metal causes it to recover somewhat from the effect. This makes the effect of hammering superficial. Also the amount of yield to it is not great in proportion to its force, and

therefore it takes more pressure to accomplish a result than would be the case if the application were slower. This makes hammering a slow process of reduction, but results in a better and more uniform working of the crystals on the surface at least, which is one of the chief reasons for the superiority of hammered



FIG. 100.—Steam hammer.

over rolled material. Another and, perhaps, even more potent reason is the exact control of the operation which can be exercised by the expert forger, and more especially his control over the temperature at which the work is finished, and over the varying force of pressure applied at different stages and temperatures. On the other hand, the effect of forging extends only skin-deep from the upper and lower surfaces.

**Finishing Temperatures for Forging.**—Forging seldom continues after the red heat is lost, but the exact temperature will

depend upon the article and the properties which it is desired to have. The colder it is finished the closer to the exact size required it can be made, because it has less shrinkage to undergo; but it will also be harder, less ductile and stronger. The relation between the finishing temperature of mechanical work and the critical points of steel will be discussed in Chapter XV.



FIG. 100A.—Forging a small billet under a steam hammer.

**Drop-forging.**—There is a large variety of articles, such as parts of machinery, hammer-heads and similar tools, which are formed by the process known as “drop-forging.” In this operation a piece of metal of the desired size is forged by repeated blows between a lower die, upon which it rests, and an upper die attached to the head of the hammer. These two dies are made in the desired form of the finished article, and the metal is squeezed into them until it has assumed the proper shape. Sometimes several pairs of dies are necessary to complete the finished shape. Drop-forgings are directly comparable with steel castings, to which they are superior in quality on account of the beneficial effect of the working. To be economically made, they must be ordered in large quantities, so that it will pay to make the costly dies of hardened steel—often an alloy. Even then, castings are

sometimes cheaper, though forgings are still preferred on account of their quality. There are cases, however, in which drop-forgings may be made more cheaply, either because the shape




FIG. 101.—Stages in making a drop forged crankshaft from a flat bar.

is one that lends itself to rapid production in this way, or because it is one liable to checking, or requiring a large riser, if cast.


**Forging Bars.**—Crucible-steel ingots are often forged instead of rolled, because the material will bring a price high enough to pay for the superior method of working it. The ingot, after the





(Courtesy, Jas. M. Camp.)

FIG. 102.—Effect of finishing temperature. Crystals of steel, magnified 100 diameters. Finishing temperature high. The grain is smaller than that of Fig. 97, but coarser than that of the steel in Fig. 103.



(Courtesy, Jas. M. Camp.)

FIG. 103.—Effect of finishing temperature. Crystals of steel magnified 100 diameters. The steel, like that in Fig. 102, was subjected to mechanical working while hot, but the finishing temperature was low.

top third has been broken off to remove the pipe and segregate, is heated to a bright-red heat, out of contact with the flame and fuel, and then tilted down under a hammer of about 10 to 15 tons size until it is about one-half as large on the sides and four times as long. One end is then reheated and drawn down to a bar of the desired size, under the same hammer, or under one of less weight, and the long bar is then used as a handle while the other end undergoes heating and reduction. The finished size is produced by light taps of the hammer just before the blue heat appears, and often a piece of cold steel is laid beside it on the anvil to more correctly arrest the downward blow. The finished bar will be so straight and true as to lead one to believe that it was produced by drawing through a die, or rolling in grooved rolls.

**Forging Razors.**—Flat bars for razor stock, made of cemented steel melted in crucibles without additional carbon, are produced in a manner similar to that outlined above, and then forged down by hand to the rough size of a razor. They are then stamped with the appropriate name and mark, drilled with a hole, heated to the correct temperature and hardened in water, after which the temper is drawn to the light or medium straw color (see p. 419). The exact shape is then produced by grinding, care being taken not to heat the razor during this operation, lest it be tempered thereby, and the blade polished and fitted with a handle.

**Forging Cannon.**—Large cannon tubes are made from open-hearth steel ingots weighing perhaps 65 tons or so, more than one-half of which is discarded or "scrapped" during the process. In France and Germany, cannon-tube ingots have been made of crucible steel by pouring many crucibles into one mold, but the expense and the liability to heterogeneity because of the many small units is believed to outweigh the advantages due to the quality of crucible steel. The heating of the ingots must be done with great care, lest a crack or hollow be formed by too rapid expansion or by the expansion of the outside away from the interior, and for the same reason ingots of the form shown in Fig. 104 are usually employed, and those cast in sand molds are preferred



FIG. 104.—Fluted ingot for making cannon tube.

This form allows what Howe calls "the virtual expansion of the outer walls" (see page 210), without cracking those walls. It also allows the interior to expand without cracking the exterior (see page 213). Finally, it avoids weakness due to crystal junctions (see Fig. 93).

because they are not liable to contain surface cracks produced by tearing the steel when the iron mold is withdrawn. Moreover, as reducing a flame as possible must be maintained, lest the carbon be oxidized in the outer layers of steel during the many hours required to attain the bright-red heat necessary.

During the long forging process reheatings of about an hour or so are necessary at intervals. Not more than the lower two-thirds of the original ingot is allowed to be present in the tube at the finish of the forging operation in order that the segregated and piped portion may be avoided. The blows are delivered on all sides of the ingot in order that the center of the tube shall be the same as the center of the original ingot, for this center portion is to be drilled out in the subsequent operations, and, as we have already seen, the center of the ingot is of looser texture and contains more of the segregate.

After the inner tube is forged, an outer tube is produced in a similar manner, but of larger size, so that it may be bored out to fit over the carefully turned inner tube. After the boring the outer tube is too small to pass over the inner one, and it is therefore heated to a temperature of about  $280^{\circ}\text{C}$ . ( $550^{\circ}\text{F}$ ). in a tall vertical furnace, which expands it so that it may be passed over the inner tube and "shrunk" upon it, greatly increasing its compactness and reinforcing it against the tremendous strains it is subjected to in service. Cannons are now forged under presses instead of under hammers. J. W. Hall (see Reference 31, p. 855) says that the difference in strength and ductility of metal cut from the outer and inner portions of cannon tubes forged under a hammer was so greatly in favor of the outer portion that all the best makers of heavy forgings in England have installed presses in place of, or in addition to, their hammers.

### THE REDUCTION OF METALS IN ROLLS

If two rolls rotating as shown in section in Fig. 105 be made to grip a piece of metal, *A*, they will drag it between them and force it out on the other side reduced in thickness. The metal between the points *OO* and *NN* is being compressed vertically, while its outer layers are suffering tension. In the case of a deep section, the unequal strain produced by unequal speed of travel is liable to tear the steel (see Fig. 125). The mechanical pressure is therefore not as uniform as in hammering, and acts for a longer period

of time. Reduction can only take place vertically, as in forging, there being always a certain amount of expansion sidewise, and a large amount of extension in length. The metal at the points *NN* being forced backward, and that at the points *OO* being forced forward, the ends of the rolled section assume a shape somewhat




FIG. 105.—The reduction of metals in rolls.

like that shown in Figs. 106 and 107. The reduction in area at each “pass” will vary between 5 and 50 per cent of the original, and the work is very rapid. For example, a railroad rail may be produced, from an ingot having a section 18 in. square, in 22 passes, varying in amount of vertical squeeze from 8 to 50 per cent, only about 5 min. being required for the whole opera-



FIG. 106.—Shape of ends of rolled metal when the inside is the hotter.



FIG. 107.—Shape of ends of rolled metal when the outside is the hotter.

tion, the piece traveling through some of the passes at a rate of 10 miles per hour, and in some mills not being reheated after the ingot comes to the first pair of rolls. Some American rolling-mills produce over a mile of single rail per hour for 24 hr. a day, and 26 days per month. The temperature at which the rolled



material is finished is gaged with much less accuracy than in forging operations, and is always too high for the best quality of the steel, because economy of power urges the manufacturer to work the metal hot.

**Pull-over Mill.**—In a single pair of rolls, such as shown in Fig. 108, the metal, after passing between them once, must be handed or pulled over the top of the mill, to be fed in for a second pass. This type of train is known as a “pull-over” or “pass-



FIG. 108 —Rolling “black plate” which is coated with tin to make “tin plate.”  
This is an example of a pull-over mill.

over” mill. It can be used only for shapes small in size and that can be handled readily, and the action is slower than in a continuous operation, such as in a “three-high mill.” The pull-over mill is simple and cheap to construct and operate, and is used especially for the rolling of plates and shapes from crucible steel, whose high price renders it less important to seek rapid output. It is also used very largely for the rolling of steel to be used for tin plate. The upper roll is adjustable, so that any thickness may be produced.

**Multiple-ply Plate, etc.**—Three-ply plates for plowshares, and five-ply plates or bars for burglar-proof safes and jail bars, are often made in this type of mill. We first roll independently thin plates of high-carbon, crucible, chrome steel (or an equivalent alloy steel capable of becoming very hard upon quenching in water from a red heat), and thicker plates of wrought iron. For a plowshare, a plate of wrought iron will then be sandwiched between two plates of chrome steel, tied into a bundle with wire, and raised to a welding heat. The wire burns off in the furnace, but the bundle is grasped with a pair of tongs and fed into a pair of plain rolls, where it is welded into a plate of three-ply steel which is reduced to a thickness of a little over a quarter of an inch. This plate is trimmed and then hardened and used for a plow, the hard outer layers resisting the attrition and wear of service, and the ductile core resisting the shocks. For safes and jail bars we have an inner layer of wrought iron, then two layers of chrome steel, and then two layers of wrought iron, welded together and then hardened. A prisoner can neither file this, on account of the hardened chrome steel, nor break it with a sledge, on account of the soft iron, which is not hardened by quenching.

**Three-high Mills.**—When a piece is passed over a two-high mill, it is often rested upon the top of the upper roll, whose travel assists somewhat in the transfer. While watching this operation at the Cambria Iron Company's mill in 1857, John Fritz conceived the idea of the three-high mill, which is shown in section in Fig. 109. It will be seen that the piece receives work in both directions. At the present time the great bulk of the tonnage of steel and wrought iron produced, consisting of structural shapes, railroad rails, plates, wire rods, billets and bars, is finished in this type of mill. The output is large, because the rolls can be run very fast indeed (rod mills running 600 to 1,200 r.p.m. and sometimes passing the rod through at the rate of  $\frac{1}{2}$  mile a minute in American practice<sup>1</sup>), and two or more pieces may be passing through at the same time. The disadvantage of the three-high mill is the power necessary to raise large weights

<sup>1</sup> The reason for this rapid rolling is not only large product, but that the thin rods may not radiate their heat during the operation and thus be finished too cold. This rapid work actually raises the heat of the metal faster than it can be radiated, and rods are hotter at the end than at the beginning of the rolling.




FIG. 109.—Action of three-high rolling mills.




FIG. 110.—Three-high mill.

up to pass over the middle roll. Most Bessemer ingots are cast 2 tons or more in weight, and most open-hearth ingots from 3 tons to 10 or more tons.

**Reversing Mills.**—Therefore ingots are often “cogged” in two-high reversing mills to avoid this consumption of power. Moreover, the two-high mills, which have an adjustable upper roll,



(Courtesy, U. S. Steel Corp.)

FIG. 111.—Two-high reversing blooming mill. S = screw-down mechanism (see p. 244). H-H. = Roll housings.

have the advantage of being able to work an ingot gently at first, in case it shows a tendency to be “tender,” that is, to crack in spots when the pressure is applied. The disadvantages of the two-high reversing mill are its slowness and the severe strain on the engines, which are often reversed while running full speed.

**Comparison of Three-high with Reversing Blooming Mills.**—The loss of power necessary to raise pieces to pass above the middle roll of a three-high mill is more than counteracted by the loss of



power due to overcoming inertia and reversing the two-high blooming, or cogging, mill. In the reversing mill 30 per cent of the power transmitted to the rolls is used in deforming the metal, and 60 per cent in the three-high mill. The work of the continuous three-high mill is also faster, turning out about twice as much rolled steel per day. On the other hand, the reversing mill is more flexible both as to the reduction given per pass and the size of products rolled. When we desire to make a different size or




FIG. 112.—Reversing plate mill showing the dial which indicates the adjustable distance between the rolls.

shape in a three-high mill the rolls must be changed. Pieces which become very long during the rolling process can be handled more easily in reversing mills.

**Universal Mill.**—During the rolling of metal there is a certain amount of expansion sidewise, which gives the piece a cross-section somewhat bulging on the sides, and makes the edges uneven, unless the rolls have collars which form a groove through which the metal passes. In 1855 R. M. Daelen, at Hoerde, Germany, devised a mill in which even edges could be produced at any width by having an auxiliary pair of vertical rolls, between which the piece passes immediately after it emerges from the

horizontal rolls. These vertical rolls are adjustable to any width up to the capacity of the mill, and give only enough pressure to keep the edges even without producing any reduction. They are usually made to rotate with a surface velocity greater than that of the horizontal rolls, so as to prevent the serious buckling that would take place if the conditions were reversed. As this tension is not good for the edges of the metal and wears out the vertical rolls, some mills have independent control of drive for




FIG. 113.— Universal mill.

each pair of rolls, and others have friction-clutches connected with the vertical rolls, which allow them to run faster if pushed by the metal, but ordinarily run them at a slower speed. Universal mills are made two-high or three-high, and with vertical rolls on one or on both sides of the horizontal rolls. In England, the Universal mill is not as much in favor as grooved rolls because rolling-mill managers believe that the faster work of the latter more than makes up for the necessity for changing rolls whenever a new width is to be produced.

## PARTS OF ROLLING-MILLS

**Rolls.**—Rolls may be plain cylinders, by which plates and rectangular shapes are produced, or they may be cylinders with “collars” at intervals, as shown in Fig. 115, in which large rectangulars with even edges may be produced; and the collars may be on both rolls, giving an “open pass,” or may be on only one roll and extend into grooves on the other roll, as shown in Fig. 115, giving a “closed pass.” With open passes, the collars



FIG. 114.—Two pair of plain cylindrical rolls for rolling plate. Plates to a limit of 90-in. wide, and 132-in. wide, respectively may be rolled in these mills. The rolls are of chilled cast iron (see Fig. 191, page 371).

cannot be made to quite touch, hence the name; and the pressure may squeeze some metal between them, forming a “fin” along the side of the piece. This results from “overfilling the pass.” The closed pass makes the upper roll weaker, and there is also a liability of the metal becoming wedged tightly between the collars and thus drawn all the way around the roll, with the result that something will be broken. Wedge-shaped grooves may be cut in the rolls, producing the “diamond” pass, in which small squares are made (see Fig. 115); or oval grooves make nearly round bars which are finished round in the last pass with

almost no draft. Other forms of passes are shown in Figs. 110 and 124. In case rolls are weakened by deep cutting, as shown in Fig. 115, they may be strengthened by stiffeners *D* while long rolls for producing wide plates are sometimes stiffened by an idle roll running on top, lest the springing of the roll make the plate thicker in the middle than at the edges.

**Cast-iron vs. Steel Rolls.**—Cast-iron rolls are chilled upon the outside so as to produce a surface layer of white iron (see Fig. 191),<sup>1</sup> which, after turning in a lathe, makes a very smooth sur-




FIG. 115.—Rolls for shaping steel.

face for rolling and is especially advantageous for finishing-mills. They are not so good for the mills which do preparatory work, however, because they are not so strong, and because in preparatory work we want a rough surface to assist in gripping the metal and drawing it through. Furthermore, they cost more to turn to the desired shape, and they cannot be turned down many times (see p. 242), lest we get below the "chill." The greater cheapness of cast iron over steel, however, counteracts these factors of higher cost. Where the rolls must be very strong and yet not too large in diameter, and for sharp corners, which would crumble if made of cast iron, steel rolls are often used. The steel employed should be high in carbon—say 0.50 to 0.75 per cent; but any case-hardening of steel is useless here, because the

<sup>1</sup> See p. 371.



heating of the roll by the material passing through will soon draw their temper. This heating cannot be prevented altogether, though it is customary to have a stream of water flowing over the rolls. Sometimes nickel-steel rolls are used for strength. An analysis of roll metal of a very large American company is: 0.40 to 0.50 per cent carbon, 0.65 per cent manganese, 3.25 per cent nickel, and 0.15 to 0.20 per cent silicon. In an attempt to combine the strength of steel rolls with the hardness of chilled cast iron, an alloy known as "adamite" is much used. It consists of cast iron containing nickel and chromium, mixed with steel.

**Diameter of Rolls.**—With smaller rolls, the amount of power consumed is less because the area of metal under vertical pressure is less. There is a limit below which the diameter cannot go, however, either because the rolls will not be strong enough to give the desired pressure, or they will not grip the bar. In order to be gripped the upper and lower edge of a piece must touch the rolls at a point not more than 30 deg. from the center line of the two rolls (see Fig. 116). Every effort is made to use smaller rolls, because the size of all the mills is regulated by them. The surfaces of all but the finishing-mill are usually "ragged" (*i.e.*, made rough), to make the rolls give a better grip. Those to receive the ingots are ragged the most, with deep indentations somewhat like the cogs of cog-wheels, whence the name of "cogging rolls" for this mill.<sup>1</sup> The next trains, known as the "roughing rolls," are also deeply marked, but even then the piece must come within the 30-deg. line, or time is lost in trying to make them bite the piece.

**Speed of Rolls.**—The more work the rolls do, the slower must they revolve, because the piece entering the train gives a shock to the mechanism that is dependent upon the power exerted and the momentum of the moving parts. Thus (1) the larger the pieces treated (2) the colder they are, and (3) the larger the rolls, the slower must be the speed. Pieces of irregular shape must also be rolled at lower speeds because the faster the metal is deformed the less time it has to yield to the pressure. Take, for example, a railroad rail: At the finishing pass the part

<sup>1</sup> In America, the train that produces blooms (*i.e.*, pieces of steel usually about 6 to 8½ in. square) from ingots is sometimes, but not always, known as "bloom rolls," or "blooming rolls," instead of cogging rolls; and the train that produces "slabs" (*i.e.*, thick, wide, rectangular pieces that are to be rolled into plates) from ingots is known as the "slabbing-mill."

of the roll which forms the web and base of the flange (see Figs. 124 and 125) has a peripheral speed 24 per cent faster than that part which forms the edge of the flange. This indicates the extent of the plastic flow which must occur in the metal. In America, speeds are at the high limit. Reversing slab-mills may do the work at 20 or 30 r.p.m.; three-high blooming rolls may run over 50 r.p.m.; mills for finishing rails, 100 r.p.m.; and rod mills from 550 to 1,200 r.p.m.

**Making of Rolls.**—Cast-iron or steel rolls are cast in approximately the desired shape and then turned accurately in a lathe, being fitted exactly to a templet when completed. After rolling some thousand tons of material, they become worn and produce too large a size of finished shapes. They may then be used for a larger size of the same kind of article by putting them back in the lathe and turning to another templet. For example, a roll for a 20-in. I-beam, with a certain thickness and width of flange, may be converted to one for a 20-in. I-beam with thicker web and longer flange.

**The Mill.**—The different parts of a rolling-mill may be seen in Fig. 119. The *chocks* are the bearings which support the end of the roll in the *housing*. The *wobblers* (Fig. 118) are made of the same cross-section as the spindle, some examples being shown in Fig. 111. The *coupling boxes* (Fig. 119) fit over the spindle and wobblers, so that neither can turn without the other. In some mills the coupling boxes are made of cast iron in order that, if any shock comes upon the driving mechanism, the boxes shall give way and relieve the strain. In other mills the boxes are made of cast steel, as it is thought that the constant delays due to broken couplings are more costly than breakages in other parts of the mill. The *spindles* (Fig. 119) are at least twice as long as the coupling boxes, in order that they may carry both of them at




FIG. 116.—Limit of gripping power of rolls.

once when the train is uncoupled. Both boxes slip back upon the spindle.

**Pinions** (Fig. 118) are now usually made of steel for the sake of strength. *Housings* (Fig. 119) are made of either steel or of



(Courtesy, U. S. Steel Corp.)

FIG. 117.—Trains of rolls for rolling billets into wire rods.

cast iron, depending on the strains to which they are subjected and the opinion of the manager. In America, they are usually made so that the top can be removed and the whole train of rolls removed at once, together with the chocks, and several mills



FIG. 118.—A pinion. W = wobbler.

have spare sets of rolls all made up ready and carried in a sling, so that a new set may be dropped into place with a crane with the least possible delay to the mill. Delays in rolling-mills are




Fig. 119.—Parts of rolling mills.

H. Housing of Rolls.  
 HC. Housing Cap.  
 PH. Pinon Housing.  
 L. Electric Roller Table Motor.

GI. Guide.  
 GA. Guard.  
 TT. Transfer Table.

S. Spindles.  
 C. Chocks.  
 CB. Coupling Box.



very costly, because of the idle labor and capital, and because other parts of the plant may be delayed thereby.

The *screw-down mechanism* (Figs. 111, 112) which adjusts the distance between the rolls is operated by hydraulic pressure or by electric motors. It is connected with a telltale gage which advises the roller exactly as to the distance separating the rolls.

**Guards** (Fig. 120) are of steel and serve to peel the piece off the roll and prevent it encircling the roll (called "collaring") in case it becomes wedged between the collars. They may be upon the lower roll, as shown in Fig. 120, or upon the upper roll, and counterbalanced to hold them in position, when they are called "hanging guards." *Guides* (Fig. 119) are on the opposite side of the train, and assist in conducting the piece straight into the groove.





FIG. 120.—Section of rolls showing guard.

**Roll Tables.**—Heavy pieces are handled at the rolls by supporting them upon a series of rollers, situated in front of and behind the roll train, and known as the "tables" (Fig. 121). At

two-high mills the tables are stationary; at three-high mills the front and back tables are sometimes raised and lowered together by hydraulic or electric mechanism, and sometimes they are pivoted near the middle, so that the end next the rolls can be tilted upward in order to bring the piece between the guides which direct it into the groove. The rollers to handle large pieces are "live," that is, they are made to revolve by electric motors and thus move the piece back and forth. "Dead" rollers are used where pieces are to be moved by hand.

**Transfer Tables.**—Roller tables are sometimes made so that they may be moved from one roll train to another, carrying the piece of metal with them, and so connected electrically that the roller can be caused to revolve when the table is in any location. (See Fig. 119.)

**Manipulators.**—If two or more posts, supported on a carriage which can be moved laterally, project between the rollers of a table, their sidewise motion will transfer the piece



(Courtesy, U. S. Steel Corp.)

FIG. 121.—Table between two trains of plate rolls.



(Courtesy, U. S. Steel Corp.)

FIG. 122.—Table with live rollers. R R R live rollers.

from one pass to another. If the table is of the lifting type, the posts, or "horns," or "fingers" can be brought to such a position that the lowering of the table will bring the edge of the piece upon the horns and thus tip it on to the other side. This form of manipulator is much used at three-high blooming rolls, and is very efficient and rapid in its work. The same type is used at reversing blooming rolls, but the piece is more usually tipped over by the roller with a tool.

**Roll Engines.**—The service on rolling-mill engines is very severe, because the full load comes upon it when the piece enters the rolls, and then leaves it as suddenly again. To equalize these sudden variations of power, all but the reversing engines are built with very large and heavy flywheels and run at a high rate of speed (from 30 to 250 r.p.m.), with governors of a quick-acting type. The Allen engine with the Porter governor serves these purposes, and the Porter-Allen type is much used. The ordinary slide-valve is used on the smaller engines. Corliss valves are commoner in America for engines doing heavy work (1,000 to 3,500 hp.), while piston-valves are favored in England. The flywheel is placed upon the crankshaft, to which the roll train is directly coupled. The flywheels very exceptionally weigh as much as 75 and 100 tons or more.

Piston-valves are used almost always for reversing engines which are compounded, so they may never come to rest at a dead point. There is, of course, no flywheel, and the engine is directly coupled from the crankshaft to the roll train in the large American mills, but is geared down so that the engine can develop a higher speed than is desired for the rolls, thus requiring less power. Reversing slabbing-mill engines have capacities up to 25,000 hp. each.

**Electric-motor Drive.**—In many mills in America and Europe electricity has replaced steam for all power purposes. The advantages of electricity over steam are a lower operative cost, greater security of operation, fewer breakdowns, and a more flexible relation between the prime mover and the load, the result of the electric motors receiving a sudden shock more elastically. On the other hand, the advantage of steam, is that, although it receives the load less elastically, it adjusts itself quicker and better to the extreme variations in load that always occur in rolling-mills. This is especially true of reversing mills.

As already noted, the smaller the mill the less will be the load, and therefore the variation in load. Consequently, in England, Sweden and Germany there are many motor-driven roll trains of the smaller size, and a few up to several hundred horse-power, including one reversing motor of 1,200 hp. Even large mills are now most commonly operated by electric power, if of recent installation, and this applies even to reversing mills. One reason for the extent of this change is of course the cheapening of the cost of electricity due to the better utilization of the waste power of blast furnaces at large plants by the installation of gas engines. (See motor drive for rolls, Fig. 119.)

**Size of Rolling-mills.**—As related to blooming-mills the size indicates roughly the diameter of the rolls. But this dimension is only indirectly used; thus, the term "40-in. blooming-mill" refers to a mill which is 40 in. center to center of pinions. Obviously this is approximately the distance from center to center of rolls when one roll rests upon the other, and also the diameter of the rolls when new and unworn. The larger the roll the stronger it is and the more power required to drive the mill; also the larger piece it will grip (see Fig. 116). Blooming-mills are used in sizes varying from about 28 to 50 in.

The size of plate-mills, on the other hand, indicates the width of plate that can be rolled by them. Thus, the "140-in. sheared plate-mill" describes a mill which can roll plates 140 in. wide. (The term "sheared mill" indicates a mill producing plates which must be sheared to give straight edges, as contrasted with a "universal mill" (see Fig. 113) which rolls them straight.)

### ROLLING-MILL PRACTICE

**Troubles in Rolling.**—There are more difficulties met with in rolling-mill practice than we can discuss here, but it may be said that the seriousness of the difficulty is estimated almost altogether in proportion to the delay it causes in the operation of the mill, rather than in the loss of a small amount of material or of a part of the mill itself. For example, the breaking of a table engine, roller, or even a roll, is regretted more because of the time necessary to put in a new one than because of the loss of the part. This is one reason why electric motors to operate the tables have, in many cases, replaced small steam engines. The same conditions have also resulted in different parts of the mill being made



interchangeable. In many mills it is customary to have spare table engines, or motors, etc., always ready, and the least accident to one of these machines would result in its being immediately replaced by a whole new one.

The most important common troubles in rolling-mill operations, probably, are: (1) Bending and breaking of the rolls, due to their being placed under too severe a strain, either because the draft is too heavy or because the piece is cooled too much; (2) fins caused by metal being squeezed out between the collars of the rolls, as shown in Fig. 123; these fins, besides spoiling the material, are liable to break the rolls; (3) collaring.



FIG. 123.—Fin.

**Rolling Plates.**—In the rolling of plates an ingot, usually of open-hearth steel and weighing 2 to 10 tons, is first clogged down in the slabbing-mill, producing a long, flat piece of metal. The slabbing-mills are frequently of the two-high, reversing, universal type. The front end of the piece is cut off in a huge hydraulic or electric shear to remove the pipe and then it is cut up into slabs of the desired size or into slabs of a size such that each one will make one plate. The slabs are then transferred to the heating furnace, heated to about  $1,300^{\circ}\text{C}.$ , and rolled in a three-high or, more rarely, a two-high reversing plate-mill, in some cases there being a pair of vertical rolls to keep the edges straight. During the rolling a shovelful of salt is occasionally thrown upon the surface of the plate, which carries in between the rolls some of the water which is always trickling over them to keep them cool. Sand may be used for the same purpose, and in England heather is sometimes used. As soon as this water is pressed against the hot plate it is converted into steam, causing a rapid series of explosions which blow the scale off the upper surface of the plate and give it a smoother finish. As the process continues, the operator tests the thickness of the plate with a gage, and when it is of the desired thickness, it is passed up to the straightening rolls and then to a cooling table, being marked with a distinguishing mark on the way to indicate the heat of steel from which it was manufactured. When cooled it is sheared to the desired size and shape. The weight of finished plate will probably be not more than 80 per cent of the weight of the steel sent to the rolling-mill in the form of ingots.

**Rolling Rails.**—An ingot of about 3 tons in weight is sent to the rolling-mill, where it is kept in the heating furnace for




FIG. 124.—Trains of rolls showing passes from bloom to rail.




FIG. 125.—Sections of successive shapes and sizes of "pieces" from bloom to finished rail.

50 min. or more until the interior is entirely solid and it is of a uniform temperature throughout. It is then rolled into blooms, either in a three-high mill, such as shown in Fig. 122, or in a



FIG. 126.—Cross section of skelp when rolled up preparatory to rolling into lap-welded pipe.

two-high reversing mill. In the three-high mill, an ingot  $18\frac{1}{2}$  in. square at the middle (tapering about  $\frac{1}{8}$  to  $\frac{1}{4}$  in. to 1 ft. in order that the mold may be more easily removed) will be reduced




FIG. 127.—Pipe welding rolls with mandril in position.

to a bloom of about 8 in. square in nine passes, the amount of reduction in each pass being about 12 to 18 per cent of the original area. The top end is then cut off to remove the pipe, the bottom

end to remove the irregularity due to the rolling, and the piece cut in two to make two blooms. The blooms are then generally reheated in a heating furnace and passed through the series of changes shown in Fig. 125, until they have assumed the proper size and form, the greatest amount of draft being usually not more than 22 per cent, except upon the middle portion of the web. In some cases the blooms are not reheated, but go directly from the bloom rolls to the first roughing train. This makes the metal crack more in rolling, however, and these cracks will ultimately show as a mark on the finished product, which causes the rails to be classified by the inspector in the second or third class. Rail-




FIG. 128.—Mandril. This sets on the end of the rod and lies between the rolls shown in Fig. 130 to support the inner diameter of the pipe as it is being welded.



FIG. 129.—Section of bell through which small sized skelp is drawn in order to curl it up and butt-weld the edges together.

roads will accept only 5 or 10 per cent of their order in second-class rails, while third-class rails are not acceptable and must go into the tracks of the steel company itself or else be reheated and rolled into smaller sizes, whereby the marks will often be eliminated. If the blooms are reheated before going to the roughing train, many of the cracks formed during blooming will be seemingly closed up, or in any event will not show. Furthermore, if this reheating is to take place, the ingots need not be heated so hot in the first instance, and therefore will not be so tender and so liable to crack.

**Making Lap-welded Tubing.**—The wrought iron or steel low in carbon is first rolled out into skelp about 20 to 25 ft. long, and of a width a little more than three times the intended diameter of the tube. The skelp if large is then rolled up into a rough form of a pipe, as shown in Fig. 126, by passing it sideways through rolls, which bend it roughly to the shape of a pipe, with edges overlapping. The same is done in the case of small 2 to 8-in. tubes, by drawing them through a die. It is then passed at a



welding heat through a pair of rolls, with the seam that is to be welded upward. Between the rolls is a mandril on the end of a long rod and of the size of the inner diameter of the tube (Fig. 128). The rolls press the two parts of the weld together over the mandril, and the pipe, after another rolling to give true size and after straightening and testing, is ready for service.



FIG. 130.—Pipe rolls showing the welded pipe coming towards the observer over the mandril and rod.

**Making Seamless Tubes.**—Seamless or weldless tubes are made either by distorting a steel plate between dies, as shown in Fig. 131, or else by piercing a hole through the center of a hot steel billet and then rolling it successively between rolls over a mandril. The hole is sometimes first of small size and then expanded by pressing larger and larger expanders through it. The pierced billet is then rolled over mandrils constantly decreasing in size until the inner and outer diameters are brought to the desired size.

**Butt-welded Tubes.**—Butt-welded tubes are made by heating the skelp to a welding temperature and then drawing it out of the furnace through a bell, as shown in Fig. 129, which curls it up and

welds the edges together, without lapping. Butt-welded tubes are not so strong as lap-welded tubes, and are not usually used for boilers or high pressures, or where they will be expanded much by heat during service. They are mostly made in the small sizes.




FIG. 131.—Steps in making a seamless tube.

### WIRE DRAWING

Wire is a product formed by being drawn cold through a die. The commonest shapes are “rounds,” and the next, hollow tubes, but a great variety of forms may be produced at will.

**Effect of Drawing.**—The effect of the drawing is to produce a very exact size of material and to increase the strength, hardness, and brittleness of the metal. In the drawing of steel, the crystals of the metal are actually pulled apart and flow by each other, the outer layers of the metal being dragged back over the central core, there being at the same time a pressure exerted in all directions toward the center, which results in a certain amount of backward

flowing even there. Because the crystals are so broken up during the operation, and because the metal is never heated above its critical temperature during annealing, the grain of the steel is very fine and the crystals are intimately mixed, which is probably the cause of the great strength of wire.

**Annealing.**—With each draft the wire becomes harder and more difficult to draw. As it is pulled through the die by a force equal to 40 to 80 per cent of its tensile strength, it is necessary to soften it at intervals by annealing, lest it break. The annealing is accomplished by enclosing the wire in some receptacle that pro-




FIG. 132.—Section of wire die.

protects it from oxidation and then heating to a low-red heat. In the case of steel, it is required after every eight to three passes, depending upon the amount of carbon in the metal and the amount of "draft;" *i.e.*, proportionate reduction in size.

**Dies.**—Wire dies are usually made of high-carbon steel (1.25 to 2.00 per cent), through which a tapered hole is made, as shown in Fig. 132. The object of using this material is that, as it becomes worn in service, it can be reformed and used for larger sizes, which could not be done with white cast iron.

**Bench.**—A "bench" on which wire is drawn consists of a reel which holds the coil of undrawn wire, a die support, and a second reel which draws the wire through the die and coils it up and which is driven by bevel gears. The die rests against the support, and the wire, having a tapered point, is thrust through the hole and grasped by a pair of tongs, which pulls it out until it can be attached to the reel. This is then set in motion and draws the wire through. The die-holder is heaped up with lubricant of some kind, in order that the metal may pass more easily through the hole. The speed at which wire is drawn will vary from 75 to 750 ft. per minute, depending upon the size and hardness of the material drawn and the amount of reduction during each draft. In many cases there is more than one die, and the wire passes successively through two, three or more, being constantly reduced in each one. Between each pair of

dies is a reel, around which the wire passes two or three times, since the strength of the wire emerging from the last die would not be sufficient to draw it through all of the holes.

**Draft.**—The heavier the draft the greater is the hardness produced in the wire and the greater the wear of the dies. The average amount of draft will probably be from 20 to 25 per cent.

**Drawing Tubes.**—Hollow wire or small tubes are drawn sometimes over a mandril. This mandril may be a wire of about the size of the inner diameter of the finished tube. After several drafts, the tube is wedged so tightly on the mandril that it cannot be separated. It is then given an unbalanced squeeze between a pair of rolls, so that the tube is reduced in thickness, whereby its diameter is increased and the mandril may easily be withdrawn.

### PRESSING

Steel may be pressed either hot or cold, the latter method being used chiefly for thin and soft steel, and the former for very large work, such as armor plate, cannon, etc., for which hydraulic presses have now largely replaced the heaviest steam hammers.

**Effect of Pressing.**—The effect of pressing upon the metal differs from hammering, in that its action extends deeper into the material, thus giving a somewhat superior texture to the interior. Tests cut from the center of large pieces forged under the press are very much superior to those cut from the same place in pieces forged under the hammer.

**Hot-pressing.**—Presses vary in size usually from 600 to 14,000 tons. They may be either of the continuous or of the intermittent type. In the latter, the amount of pressure exerted increases step by step as the work progresses. The amount of work that can be done by the press in large-sized pieces is greater than that done by hammers for the same amount of power used. This results in a double saving of fuel, since more work can be accomplished with one heating. By means of the 10,000-ton press at the Homestead Steel Works, a 50-ton armor plate has been reduced 2 in. in thickness and moved forward 6 in. for each squeeze, while a 3,000-ton press at the Firths Works in England has reduced a 30-ton ingot from 49 to 28 in. diameter in 30 min., and from 51 to 26 in. diameter in 65 min. Small pieces can, however, be turned out a little faster under the hammer.



**Cold-pressing.**—Thin plate for steel railroad-car construction, and many other purposes, is often formed by pressing it cold between dies under hydraulic presses of from 30 to 800-tons capacity. In this way bolsters, braces, and many other parts are formed with great economy. Sometimes two or three presses



FIG. 133.—Fourteen-thousand-ton armor-plate press.

are required with different dies to complete the shaping, and occasionally it is necessary to press some of the work hot, because the distortion is so great that the steel would otherwise be torn. Cold-pressing is also known as “flanging.” It has one great difference from hot-pressing, in that there is no reduction in the sizes of pieces treated.

## COMPARISON OF MECHANICAL METHODS

**Hot-working with Cold-working.**—Cold-working gives greater strength, a harder material and more accurate finish as to size than any form of hot-working. Furthermore, it produces a finer grain on the surface of the metal. If the cold-working is followed by annealing at a temperature below the critical range of the steel (see pp. 325 to 330), the material retains its fine grain, and is stronger and more ductile in proportion than metal that has been worked hot. Before cold-working the metal is pickled in dilute sulphuric acid to remove the scale, and is therefore produced with a bright surface which is suitable, without machining, for use as shafting, for nickel-plating, etc. The annealing is usually effected inside closed vessels, in a reducing atmosphere of illuminating gas or some similar medium, which prevents the formation of scale. Cold-rolled steel is used for shafting and for articles that are to be drawn or stamped to shape—watch and clock springs, hack-saw blades, corset steels, etc. Cold rolling, wire-drawing and “flanging” are the commonest forms of cold-working.

The plastic deformation of wrought iron or steel under pressure is different in nature above than it is below the so-called “critical range” (see p. 325), that is, above the range from 700 to 900°C. (1,292 to 1,652°F.). At the high heats the steel crystals break up and reform in smaller size; below the range, they are distorted and broken (see the slip bands in Fig. 99*B*), but do not reform. The making of smaller crystals improves all the qualities of the metal, but we never can get very great strength by mechanical working above the critical range. Deformation below the critical range greatly increases the strength, elastic limit and hardness, but at the expense of the ductility. Working near the temperature of 700°C. (1,292°F.), where the metal is somewhat mobile and plastic, has a less drastic effect than working at atmospheric temperatures, where repeated deformations destroy ductility and malleability altogether.

**Working Steel at the “Blue Heat.”**—At the temperature at which steel assumes a blue color due to formation of oxide coating it is very sensitive to deformation, and mechanical work in this range has a damaging and embrittling effect. This temperature is from about 300 to 375°C. (572 to 707°F.).

**Hammering, Rolling and Pressing Compared.**—Of all the mechanical methods, rolling gives by far the largest output per

day, per unit of power, and usually per unit of fuel for heating. It is therefore the cheapest method, especially for labor. It does not work the metal as well as either hammering or pressing, both of which produce a much better crystalline structure, beside affording a better control of the temperature at which the operation is ended. Pressing works the metal at greater depths than hammering, and is therefore especially advantageous for producing large pieces. In such large pieces the size of the hammer which would be sufficiently heavy to forge the piece all the way into the center of the section becomes so large that it is unwieldy. The press turns out a much larger production of large pieces than would a hammer suitable for the same work, and is less destructive on the dies and other equipment. The press is also used on special forging work, such as drawing, special punching and closed die forging, where it is almost impossible to use a hammer. Where a shape is intricate, rolling is more liable to tear the metal than hammering or pressing because, at the point where the roll is deeply cut, its surface velocity is much less than where the diameter is greater, and thus it tends to drag the metal through at different speeds.

### HEATING FURNACES

Heating furnaces are usually of the reverberatory type, burning soft coal or gas. The flame produced must be as reducing as possible in order to produce a small amount of scale. Much better control is obtained if the ash-pit is enclosed and forced draft is used to burn the fuel. In this way about half a ton of fuel will be required to heat a ton of steel from the atmospheric temperature to that necessary for mechanical work, with a loss of about 4 to 5 per cent of the metal as scale. The gases must necessarily leave the furnace at a high temperature, and therefore it is not uncommon to have boilers situated over the heating furnace, in which steam is raised by means of the waste heat. With this economy the amount of fuel chargeable against heating the steel will be from 350 to 450 lb. per short ton of steel heated.


**Regenerative Furnace.**—If the heating furnaces are fired with producer gas and the regenerative method is employed, we get a far better control of the temperature and of the reducing influence of the furnace gases. By this means a short ton of steel may be heated with from 150 to 200 lb. of fuel and with a loss of metal of from 1 to 5 per cent by oxidation.

**Continuous Furnaces.**—Billets and other small pieces may be heated in furnaces whose action is continuous. Such a one as this is shown in section in Fig. 134. Along the hearth stretch two lines of pipe, which are kept cool by a stream of water inside. Upon the pipes is laid a long series of billets, which are gradually moved forward toward the end at which the gas and air enter. In this way the flame is always met by colder material and finally leaves the furnace at a relatively low temperature. As the gases pass out, they go through a series of pipes *BB* around which circulates the air that is afterward led to the fire and used for combustion. As soon as the billet nearest the fire end is heated to the desired temperature, a new one is pushed in at the bottom, causing the hot billet to be shoved onto the inclined plane, whence it rolls out of the furnace to the point *A*, whence it is transferred to the rolling-mill. In this type of furnace a short ton of steel may be heated with from 120 to 145 lb. of fuel, with a loss in weight of less than 1 per cent by oxidation.

**Soaking-pits.**—Ingots with molten interiors must be put in some form of the furnace in which they will stand upright until they have solidified throughout and are ready to roll, in order that the pipe may form in the upper portion. The type of furnace used for this is known as a soaking-pit and is shown in Fig. 135. The original intention of soaking-pits was to have the heat in the ingot itself bring the interior of the furnace and the mass of metal to the desired temperature; but this is not found practicable in the United States, and soaking-pits are usually heated by regenerated gas and air. The ingots must be kept in these soaking-pits long enough to be entirely solid in the interior, and for this purpose at least 55 min. are required for 3-ton ingots when stripped and charged as soon as possible after teeming, and more for ones of larger size. Cold ingots must be brought up to rolling temperature very slowly, lest they crack because of too rapid expansion. It requires about 8 hr. When low-carbon steel has been heated in soaking-pits the temperature must be reduced before cold, high-carbon steel is introduced into them.

**Furnace Bottoms.**—Heating-furnace bottoms must be of some material not readily corroded by oxide of iron scale, and basic bottoms are very commonly employed with success. Heating furnaces are also frequently supplied with a tap-hole, from which the slag, composed chiefly of oxide of iron, can be tapped at





BB  
(Courtesy, Morgan Construction Company)  
Fig. 134.—Continuous recuperative billet heating furnace.

intervals. Soaking-pit bottoms are frequently covered with a layer of coke breeze to absorb the slag and prevent corrosion of the furnace bottom. This is shoveled out when an opportunity is afforded, and new breeze substituted, or is knocked out through a hole in the bottom, for which see Fig. 135.

**Heating Practice.**—In heating steel for rolling, the lower the temperature the better will be the quality of the product. On the other hand, if the metal is to undergo many passes before it receives another heat, it must be correspondingly hot, in order




FIG. 135.—Brickwork of regenerative gas soaking-pit.

that the finishing temperature may be high enough to avoid excessive power for reduction. There is no doubt that rolling temperatures at the present time are higher than they should be, for the metal when finished should be only just above the critical temperature of the steel. Until within recent years no suitable pyrometers for measuring the temperature have been available, and the temperature for drawing the material from the heating furnace is judged by eye, so that no figures can be given. More careful attention to this point will result in less waste in rolling (on account of the production of cracked or second-class material because of too hot steel at the starting) and in the production of a higher quality of steel.

It must be remembered, however, that the steel must be hot enough to cause it to weld together wherever it has become cracked. This is especially to be observed in low-carbon steel whose welding, as well as its melting-point, is higher than that of high-carbon steel. The teeming temperature and the absence of ingotism which the author has discussed elsewhere is probably more important than any other factor in preventing cracking during rolling, as properly made steel can stand without injury



(Courtesy, U. S. Steel Corp.)

FIG. 136.—Charging bloom into heating furnace.

a high temperature which would be very harmful otherwise. High-carbon steel is very delicate to roll especially when the silicon also is high.

**Temperatures of Rolling.**—The higher the carbon in the steel, the lower will be the temperature of rolling, and the higher the sulphur the higher must be the temperature, in order that greater plasticity may counteract the tendency to crack during deformation. Rolling temperatures at the beginning of the operation vary from 1,250 to 1,050°C. (2,282 to 1,922°F.). The finishing temperature should be as near above the critical range (see Fig. 172, p. 329) as possible—that is, 900°C. (1,652°F.) for soft steel and 700°C. (1,292°F.) for steel of 0.85 per cent of carbon and over.

## CHAPTER X

### IRON AND STEEL FOUNDING

Founding is a mechanical art, and consists in pouring melted metal into a mold of any desired size and form, which the metal assumes and retains when cold. The mold is made of some kind of sand, with rare exceptions to be mentioned hereafter. The art is a very complex one, added to which it is now passing through an important transition period in which science is very rapidly taking the place of rule-of-thumb. It is impossible to treat the subject adequately in a single chapter, but several books are now available, to which foundrymen, metallurgists and chemists are referred, and which are also recommended to all engineers, to whom a knowledge of the art is of prime importance.

#### THE MAKING OF MOLDS

There are various kinds of sand molds made for foundry work, but the three principal kinds are *loam molds*, *dry-sand molds*, and *green-sand molds*.

**Loam Molding.**—In molding with loam, sand is usually built up into the required shape by hand, aided by machines. Fig. 137 shows the molding of a gear in which the parts are built up of brick and sand and then formed into the desired shape by means of a machine. Large wheels and gears are often swept up, the teeth being formed subsequently by means of a small pattern that is moved around as the molder progresses, or by means of a machine, as shown in Fig. 137. In the case of a gear, the arms are usually formed by placing within the swept-up mold forms of sand known as “cores,” as shown in Fig. 138. Loam molding is common in iron foundries, but less often used for steel castings.

**Pattern Molding.**—To only a limited class of work is loam molding applicable, and the commonest manner of making a mold is to press or ram sand around a pattern, which is subsequently removed, leaving the desired cavity. Usually the pattern is enclosed by a “flask” much larger than itself, between which and



the pattern the damp sand is rammed. The pattern (sometimes) is split into halves, one-half being in the lower part, or "drag," of the flask, and the other half being in the upper part, or "cope."<sup>1</sup> The cope is now taken off and turned upside down, after which a lifting-screw is inserted into each half of the pattern in turn, by means of which it is drawn from the sand; and when a "grate" is




FIG. 137—Machine for forming the teeth of a bevel-gear.

cut through the cope, the flask is again fastened together, and a receptacle is formed of the shape of the pattern into which the metal may be poured.

The art does not consist of these simple operations alone, however, for in drawing the pattern from the sand, even though the lifting-screw be lightly tapped with a hammer in four horizontal directions to loosen the pattern, the slightest tremble of the

<sup>1</sup> The old English word "cope," meaning a covering for the head, which has now largely been replaced by the name "cap." (See Fig. 139.)

molder's hand, or of the crane used for lifting, may cause the sand to be broken in places, and the chief skill of the molder as well as a large share of his time is employed in repairing the damage thus produced. Furthermore, the mold may be "washed," that is, painted inside; the proper cores must be put in place; parts of the sand liable to drop off must be nailed in place with thin, large-headed wire nails thrust in with the thumb; before the pattern is taken from the sand the cope must be "vented," that is, made



FIG. 138.—Placing cores in a mold.

porous, by jamming a wire into it many times and pulling it out again, so that the air and gases will escape when the metal is poured in; and so on.

Furthermore, it may readily be imagined that parts of the pattern as shown in Fig. 139 might be of such a shape, with flanges on the bottom, or something of that kind, that they could not be drawn without breaking the sand. In the case of such a design the pattern and flask must be split into three or more parts,<sup>1</sup> or else a core must be put in to make an offset. It will be evident to

<sup>1</sup> The bottom and top parts being still known as the "drag" and "cope," respectively, while the intermediate parts are known as "cheeks." (See Fig. 140.)

every engineer that he will have to pay more for making a casting so designed (see Fig. 140).

**Ramming.**—In pattern molding, it is essential that the pressure of the sand around the pattern shall be nearly uniform in all places; because (1) when the metal is poured into the mold, it drives out the air already there by forcing it through the interstices between the particles of sand, and if the sand is too hard in any place, the pressure of air collected there is liable to form a




FIG. 139.—Pattern in sand.

depression in the casting; and because (2), if the sand is too loose in any place, the pressure of the metal upon it is liable to “swell” it outward and thus cause an enlargement of the casting at that point. To obtain uniformity it is necessary that the sand be packed around the pattern, and not the pattern pushed into the sand. This packing is accomplished by the hands for the sand immediately adjacent to the pattern, and by rammers for the layers farther distant. In the case of bench molding hand rammers are used, and for making larger molds on the floor long iron rammers are employed. The molder’s skill is

shown in applying the proper amount of power in ramming each different kind or part of pattern.

**Dry-sand Molds.**—After ramming up the mold, drawing the pattern and applying the “wash,” the mold may be used green (when it is called a “green-sand mold”), or it may be put in the ovens and dried (when it is called a “dry-sand mold”). The drying has the effect of driving off the moisture and leaving a




FIG. 140.—Section of flask and pattern.

firm, hard mass, semi-baked into a sort of brick. Sand for these molds should have slightly more clay than for green-sand molds; otherwise, instead of baking into a hard mass, they would be liable to crumble with the heat. The temperature of drying-ovens should be about 350 to 400°F. (170 to 200°C.), and they are heated by coke, coal, gas or oil. If the temperature is too high, the mold will be burned, that is, it will crumble under the fingers after drying; if not hot enough, the mold will not be baked hard. The length of time in the oven will depend upon






FIG. 141.—Tools used in molding.

the size of the mold, and will vary from an hour or so to a day or so. During the drying the molds are liable to shrink somewhat, due to the action of the clay in binding together.

**Green-sand Molds.**—Green sand requires less clay than dry sand, because it has a certain coherence due to its dampness. Many natural sands are found suitable for both the green-sand mold and the dry-sand mold, or they can be made up as desired by mixing a good clay with a sand rich in silica. Green-sand molds must not be rammed as hard as dry sand, so the moisture may more readily evaporate.

**Washes.**—For iron castings the common wash is graphite dust, which is made up into a paint with water and applied with a brush or dauber to the inside of a dry-sand mold before it goes to the oven. In the case of a green-sand mold, pulverized coal is dusted onto the surface through a piece of cloth, and then spread uniformly with the "slicker." In the case of a dry-sand steel casting, the wash is composed of pulverized silica rock, running from 98 to 99 per cent silica, which is made up into a thick paint with water, thickened with molasses, and applied to the inside of the mold with a brush or dauber before the mold is dried. Green-sand molds for steel castings cannot ordinarily be washed. Graphite washes cannot be used for steel molds, because the hot metal attacks the graphite and becomes rough upon its surface.

The functions of washes are: (1) To make a very smooth face on the sand, so that the surface of the casting shall be smooth (this they accomplish by the very fine size of their particles); (2) to give a surface that shall resist the melting and chemical action of hot metal, so the castings may be easily cleaned of sand.

**Skin-dried Molds.**—The inside surface of green-sand molds is occasionally dried by painting or spraying it with some inflammable liquid, such as gasoline, and then applying a match. This is more common in steel-foundry than in iron-foundry practice, and produces a little better surface to the casting. Herbert B. Atha patented a mold wash for green-sand steel castings which would enable them to be skin dried.<sup>1</sup> The formula for this wash was devised by me with the aid of Parker C. McIlhiney. It consists of ordinary gasoline in which is dissolved as much rosin as it will take up without warming. The rosin increases the specific gravity of the gasoline so that it forms a paint with the silica wash, which would otherwise sink to the bottom and not adhere

<sup>1</sup> United States Letters Patent No. 686189.



FIG. 142.—View in a foundry.

to the brush. After the wash is applied, it is touched with a match, the burning resulting in giving a dry skin to the mold and leaving it coated with the silica. The rosin does not completely burn off, but binds the sand together and gives a tough skin, so that the sand is not so liable to drop when the cope is turned over to place it upon the drag.

**Dry- vs. Green-sand Molds: For Iron Castings.**—Dry-sand molds are often cheaper to make and require less molding skill, because (1) the sand does not have to be tempered so carefully, that is, brought to the proper condition of dampness, since the moisture is eventually to be driven off by the drying. In green-sand molds, if the sand is too wet, it is liable to “cut” (be eroded by the stream of metal) and get dirt into the casting, and also to be impervious to the gases. (2) The sand requires less care in ramming, because, whether too hard or too soft, the expansion and contraction in drying will adjust its firmness and porosity. (3) Furthermore, the dry sand is stronger, which is an advantage, when the sand is liable to be under pressure from the metal, or to have the metal fall upon it from a height. (4) Dry-sand castings are also more liable to be sound, because there is less gas in the pores of the sand.

The disadvantages of dry-sand castings are: (1) The mold is liable to shrink during drying and therefore be less true to the pattern; (2) the castings are more liable to “check” (that is, crack in cooling), because the mold is firmer and so does not give way so easily to the crushing action when the casting contracts; (3) molds exposed to the direct action of the flame during drying, or heated too hot, are liable to be burnt and therefore rendered useless, causing a loss; (4) in handling, the molds are liable to be damaged; and, furthermore, it is more costly to repair a dry mold than a damp one, because the adjacent sand must first be damped, the damage repaired, and then a flame applied to dry the wound; (5) it takes longer to complete an order. The actual cost of heat is not very great, and usually is less of an item than the extra labor of handling for drying.

**For Steel Castings.**—Dry-sand steel castings have a surface much superior to those made in green sand.<sup>1</sup> They are also

<sup>1</sup> One reason that dry-sand steel castings have a better surface is because they can be washed. In practice, however, the drying and washing is often improperly performed; therefore green-sand castings often have the better surface.



stronger and more liable to be sound. Soundness is much more difficult to obtain in steel castings than in iron castings. Green-sand molds, however, have the great advantage of allowing their sand to crush more easily when between two parts of the casting that are being drawn together by the shrinking of the metal. This is doubly advantageous in steel work, because steel shrinks twice as much as cast iron and is therefore more liable to checking. Special means may be employed for making the sand easily collapsible after the metal is poured, such as mixing with it an inflammable substance like flour, chopped hay, hay-rope, sawdust, coke, etc., which burns away after the hot metal is poured in.

**Cores.**—The function of cores has already been referred to: They are set inside the mold proper to assist in forming the metal.



FIG. 143.—Core.

The commonest use for them is to extend through a casting in some place to make a hole, as, for instance, the inside of a cylinder, the bore of a pulley, etc. In this position they are subjected to great crushing strain when the metal shrinks, and therefore the bond which keeps the sand together, consisting of linseed-oil, or flour paste, a patented core compound, etc., must be of such a nature that when subjected to the heat of the liquid metal it will burn away and allow the sand to disintegrate, which both prevents it bursting the shrinking casting and permits of its being more easily cleaned out. Cores are often built up around an iron pipe riddled with holes, so that the gases formed may readily escape through this "vent." In the case of large cores, the pipe

is frequently wound with hay-rope, or some similar material that will burn away and make the sand more collapsible. Some cores have coke breeze or spongy cinder in the center to make them light as well as porous.

Cores are supported sometimes by being set in the drag, sometimes by being hung in the cope (see Fig. 145); but it is more common to have a hollow adjunct to the mold, known as a "core-print," into which an extension of the core fits. Sometimes both ends of the core are so supported, and sometimes only one end is thus supported, while the other end rests upon a metal chaplet that is absorbed in the casting when the metal is



FIG. 144.—Core.

poured. Cores are often dried, lest their gases make the casting unsound or cause it to blow, that is, boil with the rapid escape of gas through the metal.

**Chill Molds.**—It is often desired to chill certain parts of a mold, or cool them more rapidly than the remainder, in order either to make a thick part of a casting solidify as soon, or sooner, than the thinner portions, or else to produce white cast iron at that point. The former may be desirable in the case of either an iron or steel casting, because the shrinkage cavity occurs in the last portion to freeze, and therefore hastening local freezing may be necessary to bring the pipe into the riser or feeder. The latter applies only in iron-casting work in which it is desired to make the outside of a casting very hard. The chilling is usually accomplished by embedding pieces of metal in the sand, against the face of which the casting is poured. This

metal is oiled, blackened or "washed," so that it does not stick to the casting.




FIG. 145.—Cores hung from the cope.




FIG. 146.—Chaplets.

**Permanent Molds.**—A great deal of expense in foundry work is due to the fact that a sand mold must be made anew for every

casting, and the subject of permanent molds has occupied the attention of foundrymen for a great many years without the problem being completely solved. When a casting is knocked out of the mold, the sand is usually knocked out also and its form destroyed. In the rare case of a smooth cylinder, or something of that kind, the casting may be withdrawn without damage except to the face of the sand, and this can sometimes be repaired and swept up anew without reforming the entire mold. Again, molds for railroad car wheels, which have a metal "chill" all the way round the tread and flange, in order that the cast iron may be white at that point to withstand the grinding action on the rails, have a certain amount of permanency. Finally, molds carved out of carbon which has been preheated to a very high temperature are said to withstand the action of the melted metal and to last for a large number of castings.

**Gating of Patterns.**—The gate of a mold is the place into which the liquid metal is poured (see Fig. 140) while the sprue extends from the gate to the casting proper. The placing of gate and sprue is governed by certain principles whose best application can only be learned generally by experience. Referring especially to Fig. 140, we see for example that if the metal were poured into the riser of the casting it would drop upon the core and knock this to pieces. Even if this core were absent, the metal in dropping from such a height on to the sand bottom of the mold would wash sand from it and make a defective casting because of the cutting of the mold at this point as well as the probable inclusion of some of the sand in the solid metal. Furthermore, the metal would spatter on the sides of the mold and frozen drops might accumulate which would afterward form a "cold shut" on the side of the casting. It is rarely good practice to pour a casting through a riser, and whenever the metal is poured from a height, it is well to insert a refractory firebrick upon which the stream shall strike. Steel castings are almost always poured from the bottom in a manner in general similar to Fig. 140, and this method is often followed in case of gray iron as well. The general principles of gating may be very briefly summarized as follows:

1. The metal must be forced into the mold fast enough to prevent its chilling at any point, so that sprue and gates must be amply large; in the case of a thin casting, for example, this may necessitate having the metal enter at a number of different points at the side of the mold.



2. On the other hand, unnecessary amplitude is to be avoided since the sprues have only the value of scrap.

3. The stream of metal must not wash against the sand in such a way as to cut it. We may exemplify this by an example in steel castings where the stream of metal is usually brought in at the bottom and with a certain tangential direction so that it shall rise in the mold with a rotary motion.



FIG. 147.—Molding machine.

4. The metal must not have too far to run. In large or long castings this may necessitate gating at several different points.

5. As far as possible we must arrange to pour into a reservoir and to have the rate of pouring such that this reservoir shall be kept as nearly full as possible in order that any slag or dirt accidentally getting in at this point may tend to float to the top of the metal and not be carried into the casting proper.

6. The point at which the metal enters is the hottest part of the casting, and this must be borne in mind when considering

the question of feeding, to avoid shrinkage cavities. Sometimes it is desirable to chill this location in order to artificially oppose these conditions.

7. In placing a gate we must remember that as the metal shrinks, it will draw the sprue towards the casting. The sprue being the hottest part, there may be a tendency for this contraction to tear the metal in two and especially to tear the sprue off at the point where it joins the casting proper, thus making an unsightly defect.




FIG. 148.—Molding machine.

**Molding Machines.**—At the present time various types of molding machines are being extensively introduced into foundries, in order to save some of the labor or skill required in molding, or both. The simplest form of machine is the “squeezer,” which may be described as follows: The correct amount of sand is poured into the flask and by means of a long lever the “presser board” is forced down on top of this sand, squeezing it around the pattern and producing a half mold. In taking the flask off the pattern by hand, damage may be done the sand, and the molder’s skill is still required to repair it.



FIG. 149.—Molding machine.




FIG. 150.—Molding machine.

The stripping-plate machine obviates part of this difficulty, however. In this type the half pattern may be pushed up or down through a close-fitting hole in a plate known as the "stripping-plate." After the sand has been rammed around the pattern, a lever draws the pattern down through the stripping-plate. As this drawing is mathematically exact, no damage results to the sand and no repairs to the mold are necessary, so that unskilled laborers may be employed for the work.



FIGS. 151 and 152.—Multiple mold and casting.

A still further extension in the line of machines is the "vibrator," whereby the pattern is vibrated an extremely small amount, some 5,000 to 30,000 times per minute, during the drawing of the pattern. No stripping-plate is necessary to separate it from the sand, since the vibrator frees it perfectly and without damage.

In all these molding machines the operation may be conducted either by means of levers, or by a mechanism operated by hydraulic or pneumatic power, and several hundred patterns may be made per day by one man who is very little, if any, more skilled than a common laborer; and machines are made in which castings weighing from a couple of ounces to several hundred pounds may be molded with great economy.

**Gated Patterns.**—Where the castings are very small, a large number of them will be made into one pattern, fastened onto a common "gate" through which they are poured, which produces very great economy in molding (see Fig. 151).



**Core Machines.**—There are also on the market several machines for making cores.

**Multiple Molds.**—During the past few years a new type of molding, known as “multiple molding,” has come into use, in which several flasks are placed in a pile and poured through a common gate of sprue, as shown in Fig. 151. This type of molding saves mold costs, flasks, sand, floor space, and the weight of metal wasted in sprues, and many difficulties have been overcome, so that the castings are now made accurately to size and good in all respects.

**Contraction.**—A bar of cast iron 12 in. long will contract about 0.125 in. during solidification and cooling (*i.e.*, it will be about  $11\frac{7}{8}$  in. long when cold. See page 365 for further details), while a bar of steel will contract about twice as much. In both cases the contraction in sectional dimensions will not be as great as in length.

#### DESIGN OF PATTERNS

The foregoing description will show what a great financial advantage it is to a purchaser if he designs castings that can be easily molded, and if he can order a large number of castings of exactly the same design. It is certain that a hundred castings of one design can be made with very much greater cheapness than the same number all of different designs, and of this economy the purchaser obtains his full share, because the foundry is glad to encourage such a customer and to make concessions in order to do his work. I cannot recommend too strongly to engineers the practice of making the castings in all similar machines interchangeable, both for the sake of economy and of avoiding some delay and expense in replacement after a breakdown. The correct design of castings is furthermore one of the most important branches of engineering work, since the number of castings used is almost one-half of the total number of pieces used in engineering work, while their weight is equal to about one-sixth of the weight of all the iron and steel employed. The following general hints are therefore offered to assist in this design; but each casting is a study in itself, in order that the various desiderata referred to may be obtained.

**To Avoid Checks.**—The commonest error in engineering designs of castings is to make the corners too sharp, which makes them very liable to check, because of the crystalline character of

iron and steel. This is the more important, because the greatest leverage comes at the corners, which therefore should be made as strong as possible. Metals are crystalline substances and the crystals grow during solidification. As solidification usually extends from the surface inward, the crystals grow in a direction perpendicular to the cooling surfaces. As shown in Fig. 93,<sup>1</sup> this results in a line extending inward from all corners, marking the junction of many crystals. As the junction lines of crystals are not as strong as the crystals themselves, this makes a line of weakness on corners, which is the more marked the sharper the corner is. In case a casting is to be machined, it is much better to put a large fillet in all the corners, even if the rounded metal must be cut away later, as greater strength is obtained in this way.

The checking of castings comes from the strain produced by the contraction of the metal tending to crush the sand. This is the more intense the greater the distance between the two crushing parts, because they must approach each other by an amount exactly proportional to the length of metal between them. It is therefore wise, wherever possible, to avoid long lengths of metal connecting two parts which project into the sand.

Unequal cooling strains will also cause a check. This may be illustrated by a pulley with thick arms and a thin face. The face will solidify first and therefore yield very little to the subsequent contraction of the arms. Moreover, the face, being cooler, will then be stronger and the tendency will be for the arms to tear themselves in two. To avoid this it is common practice to chill the arms either by setting metallic pieces in the mold, or by means of a "water gate." A water gate is a loose column of coke molded into the sand of the cope, down which water may be poured.

**To Avoid Shrinkage Cavities.**—The formation of a "pipe" or shrinkage cavity has already been explained. Such a defect in a casting would be intolerable, and is commonly avoided by having a reservoir of metal situated above the casting proper and large enough to keep it supplied with molten metal until it has completely solidified. This reservoir is known as the "riser," or "header" (sometimes merely "head"), or "feeder." The riser is included as a part of the mold when it is made, but is cut off the finished casting and used over again as scrap. Sometimes

<sup>1</sup> Page 213.

castings are so designed by engineers that a heavy section of metal must be molded underneath a thinner section. As the thinner section will solidify first, it cannot "feed" this lower, heavy section; and therefore a special form of riser is required, or else the heavier section must be artificially cooled. Iron castings usually do not form shrinkage cavities, but steel castings must be fed carefully to all parts.

### CUPOLA MELTING OF IRON FOR CASTINGS

Iron for castings is melted either in the cupola or the air furnace,<sup>1</sup> although "direct castings," *i.e.*, castings made from the metal just as it comes out of the blast furnace, are used in many cases, and especially for cast-iron ingot molds at steel works. For this practice it is necessary to employ men with sufficient expertness to be able to judge by eye the character and the analysis of the liquid iron as it flows from the furnace, because the metal may vary greatly and without warning from one cast to another. Sometimes, also, metal mixers are used, similar to those at steel works. Ford makes automobile engine castings by mixing in a ladle iron taken liquid from his blast furnaces with iron from cupolas.

In the cupola (see Fig. 153), a layer of iron rests on top of a bed of white-hot solid fuel. Air is blown against this fuel; the oxygen unites with carbon, and the resulting hot gases, as they pass upward, melt the iron. The layer of iron is not deep; it should therefore all be melted in less than 5 to 10 min. During this interval the fuel is being consumed also. Now a new layer of fuel rests on the bed to replace what has been burned, and a new layer of iron on top of that. By correct proportioning of the alternate layers of fuel and iron, the new layer of iron will occupy exactly the position of its predecessor, this location being the "melting zone" of the furnace.

**Cupola Zones.**—The cupola should be so operated that certain well-defined zones of action will be maintained, in order that rapid, hot and economical melting will result and that loss by oxidation be small. If proper conditions prevail all of these desiderata may be obtained together, while, if otherwise, wasteful methods may be accompanied by slow, irregular melting and "dull iron," *i.e.*, iron not sufficiently hot.

<sup>1</sup>The air furnace is used in gray cast iron, chilled iron and malleable cast-iron foundries and will be discussed in Chapter XIV.




FIG. 153.—Iron cupola.




**Crucible Zone.**—The crucible extends from the bottom of the cupola to the level of the tuyeres. The object of this part is to form a place in which the iron and slag may collect after they have melted and trickled down. If the tap-hole is kept open all the time and the metal allowed to flow out of the cupola and collect in an outside ladle as fast as it melts, the crucible zone will be very shallow, and the tuyeres will be situated not more than 2 to 5 in. above the bottom. If, on the other hand, the crucible is used as a reservoir for a large amount of metal, the tuyeres are placed correspondingly high. Hotter metal may be obtained by collecting the iron in an outside ladle, because it is not blown upon by the cold blast, and using the cupola as a reservoir is not considered good practice except for short intervals.

**Tuyere Zone.**—The tuyere zone is the place in which the blast comes in contact with, and burns, the red-hot coke. It is the zone of combustion, and all the heat of the operation should be produced in this place. It is of course situated near the tuyeres and wherever the raw blast may come in contact with coke. As there is always a column of coke extending to the very bottom of the cupola, combustion will begin immediately above the reservoir of melted metal. Its upper limit will depend upon the pressure of blast, because the greater the blast pressure, everything else being the same, the higher will it extend its zone of combustion. The blast pressure should be such, however, that the top of the tuyere zone, or zone of combustion, should never be more than 15 to 24 in. above the uppermost tuyeres.<sup>1</sup>

**Melting Zone.**—The melting zone is the space in which all the melting of iron takes place; it is situated immediately above the tuyere zone. During the melting, the iron is supported on a column of coke, which is the only solid material below the melting zone. When each layer or charge of iron enters the melting zone it should be about 15 to 24 in. above the uppermost tuyeres. As fast as it melts it trickles down over the column of coke to the bottom. It takes about 5 to 10 min. for each layer of iron to melt, however, and during this time the column of coke is burning and sinking. Therefore, the last of the iron will melt at a point about 7 in. lower than the first. Consequently, the melting zone overlaps the upper limit of the zone of combustion. If the layers of iron and coke are properly proportioned to the

<sup>1</sup> There are sometimes two rows of tuyeres in cupolas (see Fig. 155).



(Courtesy, The Paxson Co.)  
 FIG. 154.—Foundry ladles.

pressure of blast, each charge of iron will enter the top of the melting zone just before the next previous charge is completely melted at the bottom, and thus a continuous stream of iron will




FIG. 155.—Section of cupola showing almost continuous slot for lower tuyeres. The best practice would have even less space between.




FIG. 156.—Section of cupola of 60 in inside diameter.

collect in the crucible or run from the tap-hole. Also, the coke burned from the column will be exactly replenished each time by the layer of coke coming down, and the position of the melting

zone, which is the important consideration, will be maintained within constant limits.

The actual position of the melting zone may always be learned when the cupola is emptied, because the iron oxide formed there will corrode the acid lining, which will therefore be cut away somewhat at this point. Corrections may then be made, if necessary, in the next charge of the cupola. For example, the




FIG. 157.—Section of positive pressure blower of the two-impellor type, capable of producing pressures up to 5 lbs. or so. The arrows show the direction of rotation and intake of air at bottom; exit at top.

bed should be so proportioned that it will extend, after the coke is well heated up, to a point about 7 in. above the bottom of the combustion zone. The melting zone itself, as indicated by the cutting of the lining, should not be more than 8 to 12 in. deep.

**Stack.**—The stack extends above the melting zone to the level of the charging door. The function of this part of the furnace is to contain material that will absorb heat and thus prepare itself for the actions at lower levels, and that will also keep the heat down to the melting zone as well as possible.



**Tuyeres.**—The blast enters the cupola through the tuyeres, of which there is usually one or two rows. The lower tuyeres are made of iron castings. The opening they make into the inside of the cupola should form a practically continuous slot around the inner diameter of the furnace. The position of the upper row of tuyeres determines the position of the melting zone in the cupola. Two rows of tuyeres give faster melting in the cupola than one row, but cause greater oxidation and the consumption of more fuel on the bed, because the melting zone being higher in the cupola, requires a larger bed to start with.

**Blast.**—The blast pressure will depend somewhat upon the size of the cupola, but the present prevailing opinion is in favor of pressure not exceeding 1 lb., even for the very largest cupolas, and diminishing to  $\frac{1}{2}$  lb. or so for the smaller sizes. Fan-blowers, although cheaper, are giving place to pressure blowers, because if the former are opposed by pressure in the cupola stack, they revolve without blowing any wind. The common type of blower used in America is of the two-impellor type, an example of which is shown in Fig. 157. It takes about 60 cu. ft. of air to burn a pound of coke,<sup>1</sup> from which may be calculated the size of blower necessary for each cupola, allowing about 50 to 100 per cent excess for leaks and incomplete combustion.

Makers of cupolas and blowers give all the necessary data in their catalogues, but advocate too high blast pressures and volumes. If the blast volume is too large, or the pressure is too great, the position of the melting zone will be too high. This means that the bed of coke must be larger to reach to the upper level of the melting zone, which is wasteful. It also means that the melted iron will have a greater height to drop through. It therefore oxidizes more, corrodes the cupola lining more, and consequently causes more waste of iron and more slag. The volume of blast is the most important consideration, but this is difficult to measure, so the pressure is the substitute.

**Loss.**—The loss in melting will average about 2 to 4 per cent. It is made up of the silicon burned and the iron oxidized and carried away in the slag. There are other sources of loss in the

<sup>1</sup>  $\text{C} + \text{O} = \text{CO}$ . Then 1 lb. carbon requires 1.33 lb. oxygen;  $= 1.33 \times \frac{12}{16}$   
 $11.209 = 15$  cu. ft. oxygen; 1 lb. coke requires  $15 \times 90$  per cent  $= 13.5$  cu. ft. oxygen;  $= 13.5 \div 20$  per cent  $= 57.5$  cu. ft. air at 32°F. and 14.7 lb. per sq. in. atmospheric pressure.

foundry, such as a second loss of metal remelted—the sprues, risers, etc., which go back to the cupola in the form of scrap; metal spilled during pouring (which may amount to as much as 5 or 6 per cent more), etc. In some foundries it is customary to pass the used floor sand through a magnetic concentrator, in order to recover the pellets of iron spilled during pouring, and important economy is sometimes obtained in this way. The total loss, that is, the difference in weight between pig iron bought and castings made, will probably be about 7 to 8 per cent of the weight of the iron bought.

**Scrap Used.**—Scrap pig iron is often mixed with new pig iron for the manufacture of castings, both for the sake of economy and because the scrap iron has a somewhat closer grain or texture, which increases the strength of the mixture. The amount of scrap used will depend upon the materials to be manufactured. Cast-iron pipe is usually made without scrap, this industry amounting to between 500,000 and 800,000 tons per year in the United States alone. Stove foundries, on the other hand, use a very large amount of scrap as a rule, and jobbing foundries, in general, would probably use an average of 30 to 40 per cent of outside scrap, besides the gates, sprues, bad castings, etc., made in their own foundries. The total production of gray-iron castings in the United States will represent about 75 per cent pig iron and 25 per cent bought scrap.

**Cupola Run.**—The campaign of an ordinary foundry cupola is only 3 or 4 hr. long. As a general thing, the kindling is started about noon and allowed to burn with a natural draft until shortly after one o'clock, when the breast is closed and the blast put on. Metal is then received until 4 or 5 in the afternoon, when the last charge is melted. The supports are then pulled out from underneath the door closing the bottom of the cupola, and the sand bottom, slag, coke, etc., left in the cupola is allowed to drop and is quenched with water. In order to allow plenty of room for the “drop” to fall, the cupola is usually elevated above the foundry floor.




FIG. 158.—Magnetic concentrator.

**Fuel.**—The cupola is the cheapest furnace for melting because it affords direct contact between metal and fuel. The amount of fuel will be from one-fourth to one-twelfth of the weight of the iron melted, the former figure prevailing where very much steel scrap is mixed with the charge and where exceedingly hot metal is desired—as, for example, for very small castings for malleable cast-iron work—and the latter figure where the melting is continued for several hours and the metal is not made very hot but is to be poured into large castings. Coke is the commonest fuel, with sometimes a mixture of coke and anthracite for the bed.

**Cupola Charge.**—In the cupola is first placed shavings and wood, on top of which is placed the bed of coke, which should be large enough to reach 15 to 24 in. above the uppermost tuyeres after the kindling is burned off. On top of this is placed a layer of pig iron about 6 in. thick, then another layer of coke about 7 in. thick, another layer of iron, and so on. The actual weight of the coke for the bed and of coke and iron for each charge will therefore depend directly upon the diameter of the cupola inside the brick lining, which varies from about 32 to 120 in., or even more in some cases. The weight of the coke in each layer will be about one-sixth to one-twelfth of the weight of iron in each layer. The tuyeres and front of the cupola around the tap-hole, known as the “breast,” are left open for an hour or so after the kindling is lighted, in order that the draft may draw air in at that point for combustion. When the kindling is thus burned off and the bottom coke well lighted; the breast is closed and the wind turned on. It is very necessary that the bed should be well lighted and level. More recently it has become common practice to light the coke bed with a specially designed oil burner, instead of kindlings, which saves time and labor.

**Cupola Melting.**—The heat now generated by the combustion of coke begins to melt the iron, and in less than 15 min. after the wind is put on the metal should begin to run from the open tap-hole. If it takes longer, then the coke bed was too high and wasteful. In 8 to 10 min. thereafter the first layer of iron should be all melted. Now the second layer of iron lies upon the column of coke, whose top should again be 15 to 24 in. above the uppermost tuyeres. If the layers of coke are too thick there will be a delay in the iron entering the melting zone and the extra coke burned will not have been used to the best account. If the layers of iron are too thick, the last of the layer will melt too near the

tuyeres, which will oxidize it excessively and make it cold. This can be observed during the run by noting if the iron runs first hot and then cold. It is very important to watch the flame that comes off the top of the stack in the cupola. When the blast volume is too large this flame will be "cutting," *i.e.*, oxidizing in character. Too great oxidation may also be observed if sparks of burning iron are projected from the slag-hole. If the layers of iron and coke are both too thick, there may be a correct relation between the weights of the two, but both of the irregularities mentioned above will be observed. It is probably not possible to have the alternate layers of fuel and iron too thin if the correct relation between them is maintained. Of course, if very hot iron is required it will be necessary to have thicker layers of coke, and slower melting must be expected.

**Chemical Changes.**—As the iron drops down over the coke, it absorbs sulphur, the exact proportion depending chiefly upon the relative amount of coke and iron used and the per cent of sulphur in the coke. It will vary from 0.02 to 0.055 per cent of the iron; that is to say, if the pig iron charged contained 0.08 per cent sulphur, there will be from 0.1 to 0.135 per cent in the castings. The sulphur in the first iron will be higher than in that of the middle of the run, because of the extra amount of coke burned before the iron begins to come from the tap-hole. The last iron will also be somewhat higher in sulphur, because there is a larger loss of metal during the last of the run, when the oxidizing conditions are more intense, and therefore a concentration of sulphur. The best practice is to cut the blast off progressively as there is less stock in the cupola.

In many foundries it is customary to charge limestone, in the form of oyster shells, marble chippings, or crude limestone, and sometimes with it a little fluorspar ( $\text{CaF}_2$ ), into the cupola. The amount of limestone varies greatly, but will average perhaps  $\frac{1}{2}$  to  $1\frac{1}{2}$  per cent of the weight of the metal. This limestone fluxes the dirt on the metal and the ash of the coke and carries off some sulphur in the slag. Fluorspar makes a somewhat more liquid slag than limestone alone and the more liquid slag is believed to absorb a little more sulphur, and also to make the cupola "drop" more easily, *i.e.*, dump its contents when the campaign is ended, and the bottom is allowed to fall. It also cuts the lining more.



As the metal melts and falls from the melting zone down in front of the tuyeres, it suffers oxidation, which carries iron oxide into the slag and also burns up silicon. The melted metal therefore contains from 0.25 to 0.4 per cent less silicon than the original pig.<sup>1</sup> In other words, if the mixture charged contains 2.25 per cent of silicon, the castings will contain 1.85 to 2 per cent silicon.

**Cupola Gases.**—The gases coming out of the top of the cupola charge consist principally of nitrogen from the air, while the remainder is carbon dioxide ( $\text{CO}_2$ ) and carbon monoxide ( $\text{CO}$ ) with sometimes a little free oxygen. Free oxygen is evidence of a "cutting flame" and shows too great oxidation in the melting zone. Such a flame may be recognized without the aid of chemical analysis after a little practice by means of the eye. It is "sharper" looking than a richer flame and burns close to the top of the stock. One can identify it definitely by holding an iron rod in it for a while; after the iron becomes red hot it will oxidize much more rapidly in a cutting flame than in a reducing flame. Again, a reducing flame will usually not burn until it becomes mixed with the air sucked in at the charging door. All the carbon monoxide that goes out of the charge represents incomplete combustion and a waste of heat. It seems to be impossible to prevent this here, however, just as in the blast furnace, whose operations cupola melting resembles in some general respects. Several analyses of cupola gases are given in Table XXX.

<sup>1</sup> With good practice it should be no more than 0.30 per cent less.

TABLE XXX.—ANALYSIS OF CUPOLA GASES  
(Collected about 3 or 4 ft. below the Charging Door)

Time elapsed since blast was put on		Analysis by volume				
Hours	Minutes	Oxygen O	Carbon dioxide CO <sub>2</sub>	Carbonic oxide CO	Nitrogen (by differ- ence) N	Ratio CO <sub>2</sub> is to CO as 1 is to:
	10	0.0	13.8	9.9	76.3	0.717
1	13	0.0	9.5	16.9	73.6	1.780
2	17	0.4	9.2	16.6	73.8	1.804
3	13	0.0	6.7	21.7	71.6	3.239
4	15	0.1	7.8	22.3	69.8	2.859
	38	1.8	7.6	15.5	75.1	2.04
1	42	2.8	7.5	13.3	76.4	1.77
2	50	1.9	7.1	15.8	75.2	2.225
3	40	0.1	7.2	19.0	73.7	2.64
	38	0.0	10.2	14.6	75.2	1.431
3	..	2.9	5.4	14.3	77.4	2.65
	10	0.2	13.1	7.7	79.0	0.588
3	10	0.3	10.3	11.7	77.7	1.136
	50	0.0	7.1	15.4	77.5	2.17
1	40	0.0	8.3	13.5	78.2	1.626
2	40	0.0	8.2	12.1	79.7	1.475
3	40	0.0	6.0	15.0	79.0	2.50
	45	0.0	13.0	12.6	74.4	0.97
1	40	0.0	13.0	11.2	75.8	0.862
2	40	0.0	8.2	20.0	71.8	2.44
3	50	0.4	6.0	22.1	71.5	3.683
4	43	1.2	5.1	21.2	72.5	4.157
1	..	0.0	9.8	15.4	74.8	1.571
1	53	0.0	9.1	16.8	74.1	1.846
2	45	0.0	8.8	16.8	74.4	1.91
3	45	0.0	7.5	19.7	72.8	2.627
4	45	0.0	7.5	18.7	73.8	2.500

## ANOTHER CUPOLA

	30	0.1	16.7	7.3	75.9	0.437
1	30	0.1	13.1	10.7	76.1	0.817
2	38	0.4	11.8	11.0	76.8	0.932
3	20	0.0	12.8	7.7	79.5	0.602

**Burdening the Cupola.**—It should be the duty of the foundry metallurgist or chemist to learn from his records, or other approximations, the amount and analysis of all the metal in the yard. The following table will, for example, show a convenient form of this record.

TABLE XXXI.—SAMPLE FOUNDRY RECORD OF IRON IN STOCK

Kind	Weight, tons	Si	S	P	Mn	Price
High Sulphur, Southern..	500	0.70	0.100	1.50	0.30	\$18.00
High Silicon, Bessemer....	60	2.50	0.025	0.07	0.60	25.00
X No. 1.....	100	3.00	0.030	0.80	1.25	24.00
No. 3 Foundry.....	150	1.75	0.070	0.30	0.60	22.50
Ferrosilicon A.....	30	10.00	0.040	0.50	0.10	35.00
Ferrosilicon B.....	30	50.00	0.003	0.04	....	105.00
Machinery scrap.....	100	1.70?	0.100?	1.00?	0.60?	19.00
Miscellaneous scrap.....	300	1.50?	0.20?	1.40?	0.60?	15.00
Cast-iron borings.....	100	1.50?	0.20?	1.40?	0.60?	11.00
Steel scrap.....	100	0.10	0.07	0.10	0.60	13.00

The price should always be in evidence. It should not be the price at which the material was purchased but the market price at the time the iron is to be used. For instance, if a large amount of high grade pig iron had been contracted for a year previously and if meanwhile the price of pig iron had been rising, the purchase price of that pig iron would not represent its present value. From the current numbers of such trade periodicals as the *Iron Age* and the *Iron Trade Review*, one can always obtain the prevailing prices for the different grades of iron.

Suppose now with these irons it is desired to burden a 72-in. cupola with a mixture for making heavy hydraulic pumps for which a satisfactory analysis might be 1.60 per cent silicon, 0.70 per cent phosphorus, less than 0.10 per cent sulphur and about 0.50 per cent manganese. The first step is to calculate the cupola charges, and the chemist knows by experience with this particular cupola that it will lose 0.25 per cent silicon and 0.10 per cent manganese and it will gain 0.03 per cent sulphur. The average analysis of the mixture put into the cupola must then be 1.85 per cent silicon, 0.70 per cent phosphorus, less than

0.07 per cent sulphur and about 0.60 per cent manganese. The chemist also knows by calculation that about 5,200 lb. of iron will give a layer of the proper thickness in a 72-in. cupola. His problem now is to make such a mixture of the available pig irons that their collective weight will be 5,200 lb. and their average analysis as given above. Moreover if he is a good metallurgist he must aim at using as large an amount as possible of the cheapest materials.

He first considers the steel scrap, but knows he cannot use very much of this because too much coke would be required for getting iron of the requisite fluidity, but he estimates that 5 per cent (say 200 lb.) will not increase harmfully the fuel necessary. This figure therefore comes at the top of his list (see Table XXXII).

Next he considers the use of machinery scrap, because he knows that his miscellaneous scrap and borings are too uncertain in analysis to be used in a mixture which must give pretty strong and non-porous castings. One thousand pounds of machinery scrap would be about 20 per cent of his mixture, and he knows from experience that this is a fairly satisfactory proportion for scrap, so that figure goes down second in Table XXXII. The low price of the High Sulphur Southern Pig tempts him, but he realizes that he must offset the use of this material by some high-silicon low-sulphur iron. And in casting about for such a one he naturally considers first the X No. 1. He cannot use much of this either because of its high manganese and it seems reasonable to mix an equal amount of these two; the only question is, How much of this mixture will the cupola stand? To get an idea of this, he first calculates their average analysis and finds it to be 1.85 per cent silicon, 0.065 per cent sulphur, 1.15 per cent phosphorus, and 0.78 per cent manganese. Evidently the phosphorus is the only element in this mixture that gives him difficulty. Indeed, if that were not high he could make almost his whole charge up of these two irons and the scrap. The phosphorus in this mixture is 0.45 per cent higher than that of his desired mixture. Therefore he knows that he must use a good deal of No. 3 Foundry iron to bring this element down. The phosphorus in the No. 3 Foundry iron is about as much below the desired phosphorus as that in the mixture of the High Sulphur Southern and the X No. 1 is above it. He must not forget, however, that he has already used 1,000 lb. of machinery scrap



containing probably 1 per cent of phosphorus. Therefore he must use a correspondingly larger amount of No. 3 iron to offset this also. As a first estimate he therefore considers using 800 lb. of High Sulphur Southern, 800 lb. of X No. 1, and 2,400 lb. of No. 3 Foundry—that is, once and a half as much No. 3 as the mixture of the other two. But a little reflection tells him that this mixture is going to be too low in silicon, because the mixture of High Sulphur Southern and X No. 1 only gave us 1.85 per cent silicon, while the No. 3 Foundry and the machinery scrap are both below that. There are then three ways open to him. He may use a little Ferrosilicon A or he may pound up a little Ferrosilicon B and dissolve it in the ladle of iron or he may use a little High Silicon Bessemer iron. Either of these methods would do, but the writer would prefer to use the High Silicon Bessemer because this will have the effect of cutting the sulphur and phosphorus down and the expense is practically the same. (It requires such a small amount of ferrosilicon to give the desired silicon in the mixture that the expense of using it is very small, in spite of its price.) Consequently we put down the weights shown in the second column of Table XXXII, and we now figure out the weight of silicon, sulphur, phosphorus, and manganese in the mixture by the methods indicated there, and the average percentage of each element. The latter figures show us that the silicon is too low, and a simple calculation shows us that we need 5 lb. more in the total weight of silicon. We can get this by increasing the amount of either High Silicon Bessemer or of X No. 1, and correspondingly decreasing the No. 3 Foundry. The High Silicon Bessemer has 0.75 per cent more silicon than the No. 3, so it would take ( $5 \text{ lb.} \div 0.75 \text{ per cent} =$ ) about 650 lb. change to make up the difference in this way. The X No. 1 has 1.25 per cent more silicon than the No. 3, so it would take ( $5 \text{ lb.} \div 1.25 =$ ) 400 lb. change to make up the difference in this way. We naturally would prefer to use the latter, being cheaper, and if we think we can stand all that extra manganese in our castings we probably will do so; if not, we will have to use altogether 1,000 lb. of High Silicon Bessemer and only 1,400 lb. of No. 3 Foundry. We then make up a new table similar to Table XXXII and figure out the average analysis as before. It should now come about right.

TABLE XXXII.—CALCULATION OF CUPOLA BURDEN

Kind	Weight, pounds	Analysis				Weight of <sup>1</sup>		
		Silicon, per cent	Sulphur, per cent	Phos- phorus, per cent	Man- ganese, per cent	Silicon	Sulphur	Phos- phorus
Steel scrap.....	200	0.10	0.07	0.10	0.60	0.2	0.14	0.2
Machinery scrap.....	1,000	1.70?	0.100?	1.00?	0.60?	17.0	1.00	10.0
High Sulphur Southern.....	800	0.70	0.100	1.50	0.30	5.6	0.80	12.0
X No. 1.....	800	3.00	0.030	0.80	1.25	24.0	0.24	6.4
No. 3 Foundry.....	2,000	1.75	0.070	0.30	0.60	35.0	1.40	6.0
High Silicon Bessemer.....	400	2.50	0.025	0.07	0.60	10.0	0.10	0.3
Total weights.....	5,200	....	.....	....	....	91.8	3.68	34.9
Average percentage <sup>2</sup> .....	.....	....	.....	....	....	1.77% <sup>2</sup>	0.071 <sup>2</sup>	0.67 <sup>2</sup>

<sup>1</sup> Multiply the weight of each kind of material by the percentage of the elements in it.<sup>2</sup> Divide each total weight of element by 5,200 lb.

## COMPARATIVE CUPOLA PRACTICE

In Table XXXIII are shown some figures on "Comparative Cupola Practice" which confirm in a striking way the rules laid down above, and add new light on the subject.

**Fuel.**—The first lesson we learn from the table is that a mixture of coal and coke and inferior coke give slow melting and a poor fuel ratio. Indeed, the work of the cupola using these grades of fuel is so far inferior to the others that I have separated them in Table XXXIII and omitted them from all my calculations. After a careful study of the figures, we are strengthened in the opinion that a mixture of coal and coke has nothing to recommend it except a deceptive first cost.

**Tuyere Ratio.**—The next most striking evidence produced by the figures is the relation between the tuyere area and the speed of melting: If we average up the iron melted per minute in the cupolas whose area is less than 6.56 times the tuyere area we obtain a figure of 22.56 lb.; if we get the corresponding figure for the cupolas with lesser proportionate tuyere area, we obtain 18.57 lb. Indeed so striking is the relation that there is only one exception, namely, cupola No. 8, and we need not look far for a reason for the slow melting in this cupola. It is evidently due to the short height of stack which causes the iron to reach the melting zone before it has been sufficiently preheated. A large proportionate tuyere area evidently means that the wind will pass through the tuyeres with less resistance and a lower velocity. That is to say, we will get more wind and it will not be driven so much to the center of the cupola. It may be said to be established for the types of practice here exhibited that the collective area of the tuyeres should not be less than one-sixth, and preferably not less than one-quarter, of the horizontal area of section of the cupola.

**Height of Stack.**—There is also an important relation between the speed of melting and the height of the charging door above the tuyeres divided by the diameter of the cupola. The average speed of melting of the cupolas, where this ratio is greater than 2.5, is 24.12 lb. per minute, while the average speed of melting of those whose ratio is less than 2.5 is only 19.15 lb. per minute. There are only two exceptions to this rule: (1) Cupola No. 6 is a fast melter, but this is doubtless due to the large proportionate tuyere area. (2) Cupola No. 3 is a slow melter, but this is



(Courtesy Whiting Corporation.)

FIG. 158A.—Mechanical charging machine for cupola.



TABLE XXXIII.—COMPARATIVE CUPOLA PRACTICE

	1	2	3	4	5
Diameter of cupola, inches.....	27	35	42	44	54
Height of tuyeres from sand bottom, inches.....	12	7	11	12	7.5
Height of charging door above tuyeres, inches.....	106	120	139	109	103.5
Height of charging door above tuyeres divided by diameter.....	4.0	3.4	3.3	2.5	1.9
Number of tuyeres.....	6	6	6	.....	6
Size of tuyeres, inches, vertical × horizontal.....	4 × 6	5 × 5	4 × 6	.....	4½ × 13
Area of tuyeres, square inches.....	144	170	144	336	348
Cupola area is how many times tuyere area.....	3.97	5.66 <sup>1</sup>	9.62	4.53	6.58
Diameter of blast pipe, inches.....	8	16	14	15	17
Blast pressure, ounces, 20 min. after start.....	9	16	8	9½	13
Class of work made..... {	Job	Plate	Light job	Boiler and plate	Stove plate
Lined up how often? Months.....	.....	6	6	6	6
Weight of fuel on bed, pounds.....	350	650	650	1,300	1,400
Weight of iron on bed, pounds.....	700	1,300	1,400	3,000	3,000
Weight of fuel in charges subsequent to the bed, pounds.....	90	125	100	175	300
Weight of iron in charges subsequent to the bed, pounds.....	400	1,300	1,000	2,000	3,000
Total weight of fuel, pounds.....	2,000	1,850	2,150	3,075	4,800
Total weight of iron, pounds.....	8,000	14,000	16,000	27,000	33,000
Ratio of fuel on bed, above tuyeres, to iron on bed, 1 is to.....	3.2	2.8	3.5	3.2	3.7
Ratio of fuel to iron, later charges..	4.4	10.4	10.0	11.4	10.0
One pound fuel melts how many pounds iron.....	4.0	7.5	7.6	8.8	6.9
Kind of fuel used..... {	Coke	Coke	Coke	Coke	Coke
Fuel weighed or measured..... {	W	W	M	W	W
Height of fuel bed above tuyeres, inches.....	20	21 <sup>1</sup>	33	33	24
Thickness of fuel, charges after the bed, inches.....	8.4	7.0	3.8	6.1	6.9
Thickness of iron charges after the bed, inches.....	3.3	6.5	3.5	6.3	6.3
Time before iron comes after blast is on, minutes.....	7	15	5	15	10
Time to melt each iron charge after the bed, minutes.....	3.25	8.5	5.7	9	10
Total iron melted per minute, pounds	123	155	175	225	300
Total iron melted per minute, per square foot cupola area.....	30.98	23.20	18.19	21.30	18.87

<sup>1</sup> Two rows of tuyeres.

TABLE XXXIII.—COMPARATIVE CUPOLA PRACTICE

	6	7	8	9	10	11
Diameter of cupola, inches.....	54	56	58	60	60	72
Height of tuyeres from sand bottom, inches.....	14	25	16	2	12	24
Height of charging door above tuyers, inches.....	113	141	92	112	114	142
Height of charging door above tuyeres divided by diameter.....	2.1	2.5	1.6	1.9	1.9	2.0
Number of tuyeres.....	6	12	6	8	6	
Size of tuyeres, inches, vertical $\times$ horizontal.....	10 $\times$ 7	6 $\times$ 12	7 $\times$ 12	4½ $\times$ 7½	7 $\times$ 10	
Area of tuyeres, square inches.....	420	864	546	270	420	708
Cupola area is how many times tuyere area.....	5.45	2.85	4.83 <sup>1</sup>	10.47	6.73	5.76
Diameter of blast pipe, inches.....	18	24	20	18	18	24
Blast pressure, ounces, 20 min. after start.....	14	16	16	8	8	13½
Class of work made.....	Boiler & radiator	Rolls	Pipe ft'g & job	Plate	Sanitary & plate	Electrical
Lined up how often? Months.....	10	8 to 10	7	6	12	6
Weight of fuel on bed, pounds.....	2,000	3,000	2,000	1,700	1,800	2,500
Weight of iron on bed, pounds.....	6,000	9,000	6,000	6,000	5,000	7,000
Weight of fuel in charges subsequent to the bed, pounds.....	450	450	400	200	350	600
Weight of iron in charges subsequent to the bed, pounds.....	4,000	4,500	4,000	2,000	4,000	7,600
Total weight of fuel, pounds.....	8,500	12,000	4,400	6,600	6,600	12,700
Total weight of iron, pounds.....	64,800	100,000	30,000	49,500	50,000	127,500
Ratio of fuel on bed, above tuyeres, to iron on bed, 1 is to.....	4.3	5.0	5.0	3.8	4.7	5.4
Ratio of fuel to iron, later charges...	8.8	10.0	4.1	10.0	11.4	11.7
One pound fuel melts how many pounds iron.....	7.5	8.3	6.8	7.5	7.6	10.0
Kind of fuel used.....	Coke	Coke	Coke	Coke	Coke	Solvay coke
Fuel weighed or measured.....	M	W	W	M	W	W
Height of fuel bed above tuyeres, inches.....	32	40	14 <sup>1</sup>	30	22	6
Thickness of fuel, charges after the bed, inches.....	10.4	9.6	8.0	3.8	6.5	7.8
Thickness of iron charges after the bed, inches.....	8.4	8.8	7.3	3.4	6.8	9
Time before iron comes after blast is on, minutes.....	20	5	15	1	15	15
Time to melt each iron charge after the bed, minutes.....	11	12	12	5.5	11	13.5
Total iron melted per minute, pounds.....	360	370	333	367	360	567
Total iron melted per minute, per square foot cupola area.....	22.64	21.60	18.14	18.80	18.40	20.06

<sup>1</sup> Two rows of tuyeres.

TABLE XXXIII.—COMPARATIVE CUPOLA PRACTICE (*Continued*)

	A1	A2	A3	A4	Averages
Diameter of cupola, inches.....	32	42	44	48	.....
Height of tuyeres from sand bottom, inches.....	11	12	9.5	14	12.6 <sup>1</sup>
Height of charging door above tuyeres, inches.....	133	132	84.5	103	116
Height of charging door above tuyeres divided by diameter.....	4.1	3.1	1.9	2.1	2.5 <sup>2</sup>
Number of tuyeres.....	6	6	8	6	
Size of tuyeres, inches, vertical × horizontal.....	4½ × 6	4 × 10	2¼ × 11	4 × 6	.....
Area of tuyeres, square inches.....	162	240	198	144	.....
Cupola area is how many times tuyere area.....	4.96	5.77	7.68	12.56	6.56 <sup>1</sup>
Diameter of blast pipe, inches.....	12	14	12	16	
Blast pressure, ounces, 20 min. after start.....	16	12	13	8	12 <sup>1</sup>
Class of work made .....	Gas engine	Job	Pumps & job	Medium light	
Lined up how often? Months.....	6	.....	3	6	
Weight of fuel on bed, pounds.....	450	1,000	1,000	1,300	
Weight of iron on bed, pounds.....	1,000	4,500	1,000	4,000	
Weight of fuel in charges subsequent to the bed, pounds.....	110	250	110	200	
Weight of iron in charges subsequent to the bed, pounds.....	1,000	2,000	1,500	2,000	
Total weight of fuel, pounds.....	1,250	1,935	2,040	4,100	
Total weight of iron, pounds.....	8,000	12,000	14,800	32,000	
Ratio of fuel on bed, above tuyeres, to iron on bed, 1 is to.....	3.5	8.6	1.6	5.0	4.2
Ratio of fuel to iron, later charges.....	8.7	8.0	13.6	10.0	9.5
One pound fuel melts how many pounds iron?.....	6.4	6.2	7.2	7.8	7.3 <sup>1</sup>
Kind of fuel used .....	Light coke	Coal & coke	Coal & coke	Coal & coal	
Fuel weighed or measured .....	M	M	W	M	.....
Height of fuel bed above tuyeres, inches...	21	11	25	22.5	22.5 <sup>1</sup>
Thickness of fuel, charges after the bed, inches.....	7.3	9.5	3.9	5.8	7.0 <sup>1</sup>
Thickness of iron charges after the bed, inches.....	6	7	4.7	5.3	6.4 <sup>1</sup>
Time before iron comes after blast is on, minutes.....	10	15	15	7	11.3 <sup>1</sup>
Time to melt each iron charge after the bed, minutes.....	7.7	.....	9.5	13.8	9.46 <sup>1</sup>
Total iron melted per minute, pounds.....	57	.....	164	145	
Total iron melted per minute, per square foot cupola area.....	10.2	.....	15.53	11.54	21.11 <sup>1</sup>

<sup>1</sup> Including A1, A2, A3, A4.<sup>2</sup> Excluding A1, A2, A3, A4.

doubtless due to the very small proportionate tuyere area. With these exceptions the rule is universal and a comparison of different cupolas one with another only strengthens it; for example, 4 with 8, the proportionate tuyere area being nearly the same; also 2 with 6, etc. A comparison of 3 with 9 is an apparent exception which is perhaps explained by the low tuyeres in No. 9.

**Blast Pressure.**—The average speed of melting of the cupolas with more than 12-oz. blast pressure is only 20.75 lb. per minute, while that with less than 12 oz. is 21.53. This relation is not so striking as to establish a rule, especially as a single cupola (No. 1) throws such a large influence into the low-blast column. Nevertheless, the evidence is sufficiently striking to discredit the theory that higher blast pressure necessarily gives faster melting. Indeed, if cupolas 3, 9, and 10 had a larger tuyere area, we should expect an average result very favorable to low blast pressure.

**Height of Fuel Bed.**—The original height of fuel bed is no criterion with which to figure as it in many cases is raised or lowered during the first few minutes of melting, and thereafter occupies some other position. It is the thickness of the fuel and iron charges after the bed which is the important consideration and, as already observed, these should be regulated to about 6 to 8 in. for fuel and 6 in. for iron irrespective of the diameter of the cupola. In case hot iron is desired the layer of fuel should be at the upper limit of thickness and *vice versa*.

**Speed of Melting.**—The speed of melting is very important, because everything else being equal the faster the melting per square foot of cupola area the greater will be the efficiency of operation of the cupola, and therefore of economy under the given conditions.

### MELTING STEEL FOR CASTINGS

Steel castings are made in (1) acid open-hearth furnaces, (2) basic open-hearth furnaces, (3) small Bessemer converters of special design, (4) crucibles, and (5) electric furnaces. The castings are made from the metal just as it comes from the steel furnace.

**Open-hearth Furnaces.**—The making of steel for castings is practically the same as making steel for ingots, except that foundry furnaces are of smaller size, varying on the average from 5 to 30 tons. In some cases furnaces smaller than this are used, but it is generally believed that circumstances rarely



warrant this, since the expense of running the small furnaces is large in proportion. The chief difference in practice is that the temperature for steel-casting work is hotter than when ingots are made. Therefore furnace repairs are higher and the life shorter. In ordinary open-hearth foundry work the purification is continued to the point where the steel contains about 0.18 to 0.28 per cent carbon after recarburizing, while the silicon will be usually 0.20 to 0.30 per cent.



**Acid vs. Basic Open-hearth Steel.**—In steel castings it is necessary to have somewhat lower phosphorus and sulphur than in ingots, because the metal is not to receive the beneficial effect of mechanical work, and therefore must be purer in order to have a good degree of strength and ductility. Consequently, if we use an acid steel-making process, we must start with very low phosphorus and low sulphur pig iron, which is costly and becomes more so each year in America. For this reason the Bessemer and the acid open-hearth steel-making processes are more expensive for casting work than the basic open-hearth. The result is a present rapid increase in the use of basic open-hearth steel in America as well as in Germany, with a probability that in a few years it will be the predominant process for this purpose. This is in spite of the fact that basic steel has very serious disadvantages, chief among which are the amount of oxygen contained in it at the end of the process and the difficulty of keeping the desired amount of silicon in it during teeming, both of which conditions increase the liability to blowholes, which are especially objectionable in castings, as there is no opportunity of their being welded up and as castings may have to be discarded on this account after a good deal of expensive machine work has been done. On this account the acid open-hearth process has long held the predominant position in the steel-casting industry. In fact, this is the only place where the acid open-hearth process now finds important employment on a large scale in this country.

**Bessemer vs. Open Hearth.**—The open-hearth furnace gives a large amount of steel at long intervals, which is very inconvenient for foundry work, because the molds necessary to take all the metal must be stored upon the foundry floor until the heat is ready to pour, and then those who are to do the teeming must interrupt their other work  $\frac{1}{2}$  hr. or more for this purpose. Even where the foundry is large enough to have many furnaces, there is no surety that they will come out at regular and short

intervals, because the operation in one may be delayed. Another disadvantage of the open-hearth process is that, in order to be economical, it must be operated continuously day and night, which also is inconvenient for foundry work. Further, it is not possible to get the metal as hot as desired without great damage to the furnace, which is subjected to a higher temperature than the metal. Lastly, since hot metal is desirable for all castings except those of very large size, it is usually necessary to tap all the metal from the furnace at once, and recarburize it at once, which prevents castings of special analysis being made, unless ordered in very large quantities. Nowadays, a great many nickel-steel castings are made in open-hearth furnaces, but this requires nice calculations, so that the castings molded shall be just equal to the capacity of the heat, and usually results in a certain amount of scrapping of high-class metal.

All these objections are avoided in making castings in Bessemer converters, but they too have their great disadvantages, chief among which is greater cost. The latter is due principally to the amount of waste in the side-blown converters used for this purpose, and the greater cost of the pig iron used, which must be low in phosphorus and sulphur. Small converter plants are so very cheap—costing less than \$20,000 for apparatus—that many iron foundries in the United States are putting them in as an adjunct to their cupola process, in order that they may be able to make steel castings at will. The amount of capital tied up is so small, and there being no important expense in starting and stopping the converter as often as desired, they can do this economically.

**Tropenas Converter.**—The largest number of converters for steel-casting work are of the Tropenas type, in which the wind enters the vessel from seven tuyeres on the side, and the converter is tipped in such a manner that the streams of air are deflected onto the top of the bath. The impurities are oxidized as in the regular Bessemer process, except that the action is not quite so rapid, and the carbon is burned to carbon dioxide instead of carbon monoxide, which generates a much larger amount of heat:



The pig iron used for these converters runs frequently above 2 per cent of silicon, and this, together with the formation of

carbon dioxide, results in very hot and fluid steel, which can be poured into castings of almost any small size. The blows usually last about 15 to 20 min., and the loss is from 15 to 18 per cent of the weight of pig iron charged into the cupola in which it is melted. The vessel can be started up and stopped with very little expense, and this advantage over the open hearth, together with the small amount of capital necessary to build the converter plant and the other conditions already mentioned, has caused many of these converters to be installed in America, and several in France, England, and other countries.

The great disadvantages of the Tropenas converter are the waste and the cost for making repairs. Slight patching can be done through the mouth, but there is a hole in the front of the converter shell, closed by a movable steel plate, through which the operator can dig his way into the interior to perform the necessary repairs. As the lining in the neighborhood of the tuyeres is usually worn out in less than 20 blows, this costly method of lining is a serious drawback.




FIG. 159.—Sections of long-tuyere converter.

**Long-tuyere Converter.**—Next to the Tropenas, the greater number of converters at work in America are of the long-tuyere, or Stoughton, type, devised by the writer. The bottom part of this vessel is attached to the trunnion-ring by a method similar to that used for regular Bessemer bottoms, and may be removed with great ease, thus cheapening and facilitating repairs. Moreover, the chief repairs are in the bottom part at the mouths of the tuyeres, and therefore the lining of the

upper part does not have to be relined completely for several months, although slight patching is necessary every 25 to 30 blows, when the bottom is changed. This converter is arranged to have but one row of tuyeres, discharging the blast immediately at the surface of the metal, and the lining on the tuyere side is thicker in order that the tuyeres may be increased in length, which decreases the loss of metal during the process. The excessive loss

in the side-blown converters is due chiefly to the spitting, which is very large, especially when the tuyeres have become worn away to a short length and the streams of air are badly directed and set up interfering currents.

Another cause of the excessive loss is the large amount of slag formed, because more iron is oxidized, and this corrodes the lining very rapidly. Part of the iron is oxidized at the mouths of the tuyeres, and another part is oxidized when the violent agitation of the bath, which occurs in all of these converters, especially during the boil, throws the metal up into the stack, where it meets free oxygen. The loss in the long-tuyere modification is 14 to 16 per cent, including cupola loss.

**Sizes Used.**—Most of the small converters have a capacity of about 2 tons, because this is economical and well proportioned to the capacity of an ordinary foundry. There are some 4 and 5-ton converters, however, and some of less than 1 ton capacity. Sizes less than 2 tons are costly to operate in proportion to their output. The blast pressure usually employed is 3 to 5 lb., with an average of about  $3\frac{3}{4}$  lb.

TABLE XXXIV.—ANALYSES OF SIDE-BLOWN CONVERTER GASES

Sample No.	Time after beginning of blow	Analyses, per cent				Calculations from analyses, per cent			
		CO	CO <sub>2</sub>	O	N and H	Total O	N <sup>1</sup>	O entering	O burning Si and Fe and Mn
1	4 min., flame starts...	0.0	8.2	1.1	90.7	7.1	88.7	23.6	16.5
2	10 min., boiling.....	0.3	24.3	0.4	75.0	18.3	73.0	19.4	1.1
3	12 min., shortening <sup>2</sup> ...	0.4	8.8	0.2	90.6	6.8	88.6	23.5	16.7
4	17 min., after first drop	10.7	13.0	0.2	76.1	15.8	74.1	19.7	3.9
...	21 min., end of blow...								

<sup>1</sup> By difference, H being estimated as 2 per cent.

<sup>2</sup> *i.e.*, just before the first drop. There are two drops to the flame in this operation, the second marking the end.



## CHAPTER XI

### THE SOLUTION THEORY OF IRON AND STEEL

Scientifically considered, all of the members of the iron and steel series are alloys of iron and carbon. Therefore a study of the general theory of alloys leads to important information upon iron and steel. According to the authoritative definition, "a metallic alloy is a substance possessing the general physical properties of a metal, but consisting of two or more metals, or of metals with non-metallie bodies, in intimate mixture, solution, or combination with one another, forming, when melted, a homogeneous fluid." It will be seen from this that the essential feature of an alloy is that, when melted, it shall form a homogeneous fluid. In plain language, this means that, when melted, the different components are dissolved in one another. Melted alloys, therefore, come under the general head of solutions. In fact, the great bulk of our alloys, and especially of iron and steel, are produced by first dissolving the melted components and then allowing them to freeze. The laws governing this freezing, or solidification, have been known only a few years, and if this new knowledge has made great revolutions in physical chemistry, it has led to no less important discoveries in regard to the nature of iron and steel.

**Solid Solution.**—Suppose first we have two metals that are soluble in each other when liquid, and also when solid. In other words, the metals of the alloy will be just as completely dissolved in each other after solidification as before. They will then form a "solid solution," and a solid solution bears practically the same relation to a liquid solution as a solid pure metal does to the same metal when liquid. For example, gold and silver dissolve in each other when liquid, and also when solid, in any proportion. Consequently any solution of these metals will cool to the freezing-point and then solidify without there being any important change (from the metallurgical or practical standpoint) in the relations of the two metals after the freezing. The reason that these solid solutions form in any proportion is that the two metals crystallize

alike. It is, perhaps, a new thought to the reader, but it is nevertheless true, that a metal forms a crystal whenever it solidifies. Furthermore, each metal has a particular, general shape which its crystals assume, and there is almost no force powerful enough to prevent them from taking that shape in preference to any other.

Tiny as the crystals sometimes are—often requiring the highest powers of the microscope to reveal them—their crystalline forces are very powerful. If, therefore, two metals do not form like crystals, they cannot solidify in solution, *i.e.*, in the same crystal, but freezing must be accompanied by separation.

By European metallurgists solid solutions are often called “mixed crystals,” or “isomorphous mixtures,” but this terminology is objected to because the relation of two substances when dissolved is far more intimate than any mixture possibly could be. In a mixture, the microscope will always be powerful enough to distinguish the different components, but a solution always appears like a simple uniform body. Furthermore, the properties of a mixture are intermediate between the properties of its components, but a solution—either liquid or solid—has some properties which are different from any of the properties of either of its components. Again, the components of a solution are held together by chemical forces, while the components of a mixture are either not held together at all, or only because of close mechanical association. In brief, a solution has some of the characteristics of a chemical compound, and differs from such a compound chiefly because the latter must be composed of definite amounts of each component, and in some multiple of their atomic weights, while a solution may contain widely varying amounts of each component.

**Freezing of Solid Solutions.**—When metals form solid solutions, the solutions freeze more or less like pure metals. In Fig. 160, I have shown graphically the freezing of all the alloys of gold and silver, extending from no silver (*i.e.*, 100 per cent gold) to no gold (100 per cent silver). This figure has been drawn from results obtained by experiment. The proportion of silver is shown by the abscissas, or the horizontal distance away from the axis *OC*, and the temperature is shown by the ordinates, or the vertical distance away from the axis *OO*. In other words, any point between these two axes represents by one axis distance the composition of the alloy in silver and gold, and by the other, the temperature at which the alloy is at the moment. For

example, the point marked *a* is a certain distance from the axis *OC*, which shows that the alloy in question contains 50 per cent of silver; it is also a certain distance above the axis *OO*, which shows that the alloy is now at a temperature of 1,100°C. (2,012°F.).

Since there is nothing in the alloys but silver and gold, the percentage of gold in each is 100 minus the percentage of silver. The horizontal distances therefore show the percentage of gold as well as of silver, and this is given in the second line of figures under the table.

Suppose we have a solution of 50 per cent of silver and 50 per cent gold at a temperature of 1,100°C. It is represented at the point *a*, and is now liquid. When it cools to about 1,035°C. it begins to freeze. It does not all freeze at the same time, but first




FIG. 160.—Freezing curve of the gold-silver alloys.

some solid crystals freeze out and we have a mixture of solid crystals with liquid solution. The more the mass cools the more solid crystals there will be, each crystal being a solid solution of gold and silver. It is not until we reach a temperature of 985°C., however, that the last liquid freezes, and then we have a solid solution of gold and silver, the two solid metals now bearing practically the same relation to each other chemically that they did when liquid.

It will be noticed that when this alloy cooled from the point *a* to 1,035°, it met the line *AEB*. This is the line that represents the beginning of freezing for all the gold-silver alloys. It has been drawn after many experiments have been made to show where it lies in the diagram. It will furthermore be noticed that when this alloy cooled to 985°, it met the line *ADB*. This is the line that represents the completion of freezing for all the gold-silver alloys, and its position has been learned from many experiments.

Take now the alloy containing 60 per cent silver and 40 per cent gold, at a temperature of  $1,150^{\circ}\text{C}$ .—the point *b*. As this cools to a temperature of  $1,025^{\circ}\text{C}$ ., it meets the line *AEB* and freezing begins in the same way as before. Solid crystals form more and more as the alloy cools further, until we meet the line *ADB* at a temperature of  $980^{\circ}\text{C}$ . At this point the last liquid freezes.

### THE FREEZING OF ALLOYS OF LEAD AND TIN

1. Suppose now, on the other hand, we have two metals which are soluble in each other when melted, but not when solid. Evidently there cannot be the same results as those described in the case of the gold-silver alloys. Such a series is found in the alloys of lead and tin, whose freezing is shown in a simplified form in




FIG. 161.—The freezing of alloys of lead and tin.

Fig. 161. Here again I have shown the percentage of lead and tin by the abscissas and the temperature by the ordinates. And, again, the diagram has been drawn from results obtained by experiment. The following facts are not based upon reasoning or logic, but are to be accepted because it is known that the different actions described actually took place upon trial.

2. Consider first a solution containing 83 per cent of lead and at a temperature of  $300^{\circ}\text{C}$ . This will be represented by the point *a* in Fig. 161, and will be a solution of lead in tin, still liquid,



although about  $26^{\circ}$  below the melting-point of lead itself. If cooled, the solution will remain liquid until it reaches a temperature of about  $275^{\circ}$ , which brings it, we see, to the line  $AB$ . This is the lowest temperature to which it will go and retain that much lead in solution. If cooled any more, the lead will begin to precipitate and of course as much as is precipitated will immediately solidify, being already well below its melting-point. The lead comes out as crystals of solid lead, which remain mixed with the mass of the molten solution, but form no longer a part of it chemically.<sup>1</sup> The solution, *i.e.*, the part still liquid, becomes enriched in tin in proportion as the lead precipitates. Leaving this alloy here for the moment, let us next consider one with less lead.

3. Now take an alloy with 67 per cent of lead and 33 per cent of tin at a temperature of  $250^{\circ}\text{C}$ . This will be represented by the point  $b$  in Fig. 161. We have again liquid lead dissolved in liquid tin, although the alloy is  $76^{\circ}$  below the melting-point of pure lead. Suppose this alloy cools until it reaches a temperature of about  $240^{\circ}\text{C}$ ., where it meets the line  $AB$ . It will not cool below that temperature and retain all the lead in solution. If we cool it a few degrees, lead separates out and becomes mechanically mixed with the liquid solution.

4. Consider next an alloy of 55 per cent lead dissolved in 45 per cent of tin at a temperature of  $250^{\circ}\text{C}$ . As this cools to a temperature slightly below  $225^{\circ}$ , it again meets the line  $AB$  and crystals of lead separate out and solidify. And so on: Any solution, when it cools to a temperature where it meets the line  $AB$ , reaches its limit of solubility; it cannot cool more and retain all of the lead in solution; but if it does cool, then some of the lead must be precipitated.<sup>2</sup>

5. To sum up the preceding paragraphs, we may then say that the less lead we have in solution (within limits to be afterward defined) the lower the temperature can go without any of it being precipitated. Or, in other words, the less the lead in solution the

<sup>1</sup> It is a fact that when the lead is precipitated from the solution, it carries with it a few traces of dissolved tin, but for the present we neglect this slight impurity for the sake of simplicity, and consider that pure lead separates.

<sup>2</sup> Any lead that is precipitated must of course freeze, because the temperature is already below the freezing-point of lead. Conversely, any lead that freezes must be precipitated from the alloy, because we know as a matter of experiment that frozen lead will not retain tin in solution (omitting, of course, the few traces of tin retained by the lead and which, for the sake of simplicity, we omit in the discussion).

lower the temperature will go before any freezing begins. This knowledge is the result of experiment, and it has been shown that the line *AB* in Fig. 161 represents the equilibrium between the amounts of lead in the different solutions and the temperature to which each will cool before any lead is precipitated, or, in other words, the amount of lead that saturates the solution at each temperature.

6. With this knowledge let us consider again the first solution—containing 83 per cent of lead. We have said that when this solution was cooled below  $275^{\circ}\text{C}.$ , some lead was precipitated. Have we any evidence now as to how much lead would be precipitated with each unit drop in temperature? Evidently we have, for we know how much lead is normally in the saturated solution at each temperature; this evidence is given to us by the line *AB*. For example, assume that the solution containing 83 per cent of lead is cooled to  $240^{\circ}\text{C}.$ ; how much lead will be left in solution, and therefore how much will have been precipitated? From paragraph 3 we know that 67 per cent of lead remained in solution down to a temperature of  $240^{\circ}\text{C}.$  and that there was an equilibrium between the amount of lead and this temperature, or, in other words, the solution is saturated with lead at this point. Therefore it would be reasonable to suppose that the solution which started with 83 per cent of lead would retain exactly 67 per cent of lead by the time the temperature of  $240^{\circ}$  is reached. That this reasoning is correct is proved by experimental evidence.

7. Now let us cool the same alloy to a temperature of  $225^{\circ}$ ; how much lead will this retain in solution and how much would be in a precipitated form? We have already seen (Par. 4) that an alloy containing 55 per cent of lead will retain all of that lead in solution until it falls to a temperature of  $225^{\circ}$ . Therefore, it is reasonable to suppose that the cooling alloy we are considering will retain just 55 per cent of lead and no more by the time its temperature has fallen to  $225^{\circ}$ , and this is in fact the case. In short, each solution will always retain enough lead to keep it in a saturated state after it once becomes saturated.

8. We have learned above that every point on the line *AB* represents the maximum amount of lead that can be retained in one of these solutions at that temperature. Therefore as soon as any solution meets the line *AB*, it follows along this line as it cools and lead precipitates in amounts proportional to the

temperature, so that the solutions will always be saturated with lead.

9. It is therefore evident that if we start with any of these liquid alloys containing an amount of lead represented on the diagram to the left of the point *B*, lead will precipitate from it during cooling and the amount of lead in solution will continually decrease, so that the composition of the alloy at the different temperatures will be represented by a point traveling down the line *AB*. Therefore, in every such case we shall reach finally a solution with 31 per cent of lead and 69 per cent of tin (the proportions represented by the abscissa of the point *B*) when the temperature has fallen to 180°C. (the ordinate of the point *B*). Mixed with the solution at this temperature will be the amount of lead which has separated during cooling and which will depend upon the percentage in the original solution. (If this is not clear on the first reading, a little thought will make it so, especially if the reader follows in Fig. 161 each action I have described, step by step.)

10. We have considered up to now only the solutions containing large amounts of lead and from which lead is precipitated on cooling. Let us now consider a solution containing 90 per cent of tin at a temperature of 225°C. (point *d*, Fig. 161). It is still liquid, although below the normal melting temperature of both lead and tin. This will cool until a temperature of about 210° is reached and it meets the line *CB*. If it cools any more, tin will be precipitated and will of course freeze, because it is already below its normal freezing-point (231°C.).

11. Consider next an alloy containing 85 per cent of tin at a temperature of 225° (point *e* in Fig. 161). This will cool to about 200°C., where it meets the line *CB*, but if it cools any further, tin will be precipitated and will freeze.

12. In other words, the line *CB* represents the conditions of equilibrium between the temperature and the amount of tin that will be retained in solution, just as the line *AB* represented the equilibrium between the temperature and the amount of lead that would be retained in solution. That is to say, every point on the line *CB* represents the amount of tin that will saturate a solution at that temperature.

13. Returning then again to the alloy containing 90 per cent of tin, how much tin will have been precipitated by the time the alloy cools to, let us say, 200°C.? Obviously 5 per cent of tin

would have been precipitated, leaving a solution containing 85 per cent of tin, because we have already seen that 85 per cent of tin will saturate a solution at  $200^{\circ}\text{C}$ .

14. Whatever solution we may have had to start with, provided there was always more than 69 per cent of tin, as soon as that solution met the line  $CB$  it would travel down this line, precipitating tin progressively in proportionate amounts such that the tin left in the solution at the varying temperatures would correspond to the ordinates of the line  $CB$ . In other words, this solution follows the line  $CB$ . Therefore, in all such alloys we shall finally arrive at a solution having 31 per cent of lead and 69 per cent of tin (the abscissa of the point  $B$ ) when the temperature has fallen to  $180^{\circ}\text{C}$ . This solution is known as the "eutectic" solution, and with it will be mixed precipitated tin in amount depending upon the amount of tin in the original solution.

15. We may now sum up paragraphs 9 and 14 by saying that whatever solution of lead and tin we have to start with, we will always have one containing 31 per cent of lead and 69 per cent of tin by the time the temperature has fallen to  $180^{\circ}$ , and with this solution will be mixed some precipitated tin or precipitated lead, as the case may be (unless, of course, we started with exactly 31 per cent of lead and 69 per cent of tin).

Now let us consider the further cooling of these alloys. What will happen, however, to the solution containing 31 per cent of lead and 69 per cent of tin, which we have called the "eutectic" solution? It is evident that when this solution cools below  $180^{\circ}$ , it must cross the point  $B$ , and therefore both the lines  $AB$  and  $BC$  at once. Obviously, it cannot cross either of these lines without precipitating lead or tin. In point of fact, on crossing both of the lines at the same time, it precipitates at once all the remaining lead and all the remaining tin, and therefore completes the decomposition of the solution and the solidification.

The lead and tin separate in tiny solid crystals or flakelets, which arrange themselves in a parallel banded structure similar to that shown in Fig. 166, page 327. This structure is known as the "eutectic" structure. The term "eutectic alloy" means etymologically "well-melting alloy," because it remains melted longer than any other alloy of the same metals, and every solution, the components of which are soluble in each other in the liquid state and insoluble in the solid state, will form a eutectic solution in the way I have described. This applies not only to



solutions of metals in each other, but to solutions of metals in liquids which are afterward frozen, and even of salts in water, etc.

**Freezing-point Curves.**—The lines *AB* and *CB* are often spoken of as the “upper freezing-point curves” of the alloys, because any alloy which cools to this line will then commence to freeze. The line *DE* is often called the “lower freezing-point curve,” because this line represents the temperature of freezing of the eutectic of the series, and we have already shown that every alloy in the series automatically forms a eutectic by “selective” precipitation; therefore every alloy in the series will not be entirely solid until it reaches the temperature at which the eutectic solidifies,<sup>1</sup> which is always the same.

**Cooling Curves.**—There are certain thermal changes which accompany the chemical changes I have outlined in the preceding paragraphs. These thermal changes are of importance, because it is by means of them that we are usually able to obtain the first evidence of the precipitation of excess metal, the formation and solidification of a eutectic, etc. Consider the alloy containing 83 per cent of lead and 17 per cent of tin, at 300°C., and let us observe by means of a thermometer or pyrometer the rate of cooling. At first the thermometer will fall pretty fast, but when we reach 275°, where the line *AB* is met, the rate of fall is suddenly retarded. It thus becomes evident to us that some event counteracts the fall in temperature. What this event is we learn from microscopic evidence, and, as has already been explained, it is the precipitation of lead. This explanation might have been expected, because the precipitation of lead at a temperature below its normal freezing-point would of course be accompanied by freezing and, during the freezing, the metal would liberate its latent heat of fusion and thus oppose the cooling of the mass as a whole. The rate of fall of temperature is, moreover, retarded all the way down to 180°, because lead is being continuously precipitated as the solution travels down the line *AB*. When we reach 180°, the fall of temperature is not only retarded, but actually ceases; in some cases the temperature may rise slightly. This change is due to the large amount of latent heat of fusion liberated by the rapid freezing of the eutectic at one temperature. This arrest continues until the eutectic is entirely solid, after which the rate of fall becomes rapid again and proceeds without impor-

<sup>1</sup> Some metallurgists prefer not to draw the line *DE*, but to represent the freezing of the eutectic merely by the point *B*.

tant change until the atmospheric temperature is reached, because now we have merely the cooling of a solid alloy.

These changes are represented diagrammatically in Fig. 162, in which the abscissas show the time, in minutes, from the beginning of the cooling, and the ordinates show temperatures. The change in direction at the point *a* shows the retardation due to the precipitation of the lead, while the long horizontal part at *b* shows that for several minutes the temperature was not falling at all, because the eutectic was freezing.




FIG. 162.—Freezing curve of an alloy containing 83 per cent of lead and 17 per cent of tin.

Next, experimenting upon the alloy with 67 per cent of lead, we find that it cools rapidly until it meets the line *AB*, when the rate of fall is retarded continuously until we reach 180°, where again an arrest (or perhaps an actual rise) of the temperature is observed, after the completion of which the fall in temperature becomes rapid again and proceeds normally.

Similar thermal changes are observed in the alloy containing 55 per cent of lead, but at temperatures of 225 and 180°. Now, by plotting the upper changes in the several solutions (*i.e.*, at 275°C., at 240°C., and at 225°C.), the position of the line *AB* is determined, and by plotting the lower changes (*i.e.*, at 180°C. in each case) the line *DE* is determined.

In studying the solutions of the series rich in tin, similar thermal changes are observed. Consider the alloy containing 90 per cent of tin and 10 per cent of lead; this will cool rapidly until a temperature of 210°C. is reached, when a retardation will

occur and will persist until the temperature  $180^{\circ}$  is reached. By this time the excess tin will all have been precipitated and the residual solution<sup>1</sup> will have travelled down the line  $CB$  to the point  $B$ . Thereupon an arrest (or an actual reversal) in the rate of cooling will occur until the eutectic has solidified, after which




FIG. 163.—Freezing-point and strength curve of the lead-tin alloys.

the cooling will proceed at a rapid rate. In the case of the alloy containing 85 per cent of tin, the first retardation will begin at  $200^{\circ}$ , and then an arrest at  $180^{\circ}$ . By plotting the points at  $210^{\circ}$  and  $200^{\circ}$ , we obtain the position of the line  $CB$ ,<sup>2</sup> and by plotting the two points at  $180^{\circ}$  we obtain further points to determine the line  $DE$ .

**Properties of Eutectics.**—As already said, not only the lead-tin alloys, but every alloy of which the components are soluble when

<sup>1</sup> These residual solutions are technically known as “mother liquors” or “mother metals,” because it is out of them that the solid metal is being “born.”

<sup>2</sup> It should be understood that in actual experimental determination of lines corresponding to  $AB$ ,  $CB$  and  $DE$ , in any series of alloys, not a few but a large number of different solutions are studied, and a great many retardation points are found before the lines are drawn.

liquid, and insoluble (or nearly so) when solid, will form eutectics, and it happens that this is the case with the great majority of our metallic alloys. For this reason the properties of the eutectic are very important in all metallurgical work. It will be seen that a eutectic is not a chemical compound in atomic proportions. For example, in the case of the lead-tin alloy, the point *B* comes at 31 per cent of lead and 69 per cent of tin merely because the line *AB* crosses the line *CB* at this ordinate, and this has no relation to atomic ratios. If the melting-point of tin happened to be higher, or if it did not precipitate from lead so fast upon cooling, the line *CB* would cut the line *AB* at a different point, and therefore the composition of the eutectic would be different.

The structure of the eutectic is also very important. The majority of eutectics have a structure similar to the banded form shown in Fig. 166. The tiny crystals in this structure are intermingled very intimately, and this close association has a beneficial effect on the strength of the mixture. In Fig. 163 we may see how the curve showing tensile strength rises to a maximum at the point corresponding to the eutectic of the series of lead-tin alloys.

#### THE FREEZING OF IRON AND STEEL

1. When the iron and steel alloys are liquid, they are composed of liquid carbon dissolved in liquid iron, and their freezing-point curves are shown in Fig. 164, page 320. It will be noticed that the lines in this figure bear a close similarity to those in Fig. 161. This similarity is real, and the laws governing the freezing of this series of alloys are very similar to those governing the freezing of the lead-tin alloys. There is a eutectic of this series when the line *AB* crosses the line *DB*, and the components of this eutectic are 95.8 per cent iron and 4.2 per cent carbon. In the study of the iron-carbon alloys, however, we have to take into account a solid solution which forms. That is to say, we must remember that iron, if it contains as much as 1.7 per cent of carbon, never separates from the liquid state without carrying 1.7 per cent of carbon with it in solid solution.<sup>1</sup> It will be remembered that when lead separated from the liquid solution, it carried

<sup>1</sup> This solid solution may consist of carbon dissolved in the iron, or of iron carbide dissolved in the iron. We do not know definitely which, but it is not necessary to discuss this question just yet. If it contains less than 1.7 per cent carbon, it retains all of it in solid solution.



with it a small amount of tin as an impurity, and that when tin separated, it carried with it a small amount of lead as an impurity; but we disregarded these traces of impurity for the sake of simplicity in outlining the laws of solutions. In the case of iron-carbon alloys, however, the carbon carried out with the iron in solid solution, substantially as an impurity, is too important in its effect upon the material to permit us to neglect it.

2. The line  $XY$  therefore divides the diagram in Fig. 164 into two parts. Everything to the left of this line freezes as a solid solution and the laws are similar to the freezing laws of the gold-silver alloys. Everything to the right of the line  $XY$  freezes selectively, according to the same laws as those given in the case of the lead-tin alloys.




FIG. 164.—Freezing of the alloys of iron and carbon.

**3. Freezing of Steel.**—All the steels freeze as solid solutions. Let us consider a solution of 99.5 per cent iron and 0.5 per cent carbon at  $1,650^{\circ}\text{C}$ . This cools until it meets the line  $AB$ , and now it commences to solidify. For a few degrees of temperature it is part liquid and part solid, but by the time it has fallen to a temperature where it meets the line  $Aa$ , it has become entirely solid, and it is now a solution of 0.5 per cent of carbon in iron. Consider next a solution containing 99 per cent iron and 1 per cent of carbon. When this cools to the temperature where it crosses the line  $AB$  it commences to solidify and it is in a partly liquid and partly solid condition until it crosses the line  $Aa$ , upon which solidification is completed and it now becomes a solution of 1 per cent carbon in iron. The same actions take place with an alloy containing 98.3 per cent iron and 1.7 per

cent carbon. In all these alloys we finally arrive at a solid solution of carbon in iron.<sup>1</sup> To this solid solution the name of "austenite" is given, and this name applies no matter how much or how little carbon is in solid solution. In other words, all steels are in the condition of austenite as soon as their solidification is complete.

**4. Freezing of Cast Iron.**—The freezing of cast iron is shown by the diagram to the right of the line of 1.7 per cent carbon, and if we should consider this part as a separate diagram, then it would be similar to Fig. 161, the freezing of the lead-tin alloys. There is one difference to be borne in mind, however: Along the line *AB* in Fig. 161 we had a selective precipitation of lead; along the line *AB* in Fig. 164 we have a selective precipitation, not of pure iron, but of iron containing carbon. In other words, this entity, consisting of a solid solution of iron with a small per cent of carbon, behaves almost as if it were an elemental substance. It is sometimes called "austenite." Suppose we have, for example, a liquid solution of 2.5 per cent of carbon in iron at a temperature of 1,400°C. The liquid solution will cool until it reaches a temperature of about 1,320°C. At this point there will begin to precipitate the entity of which I have spoken, namely, iron containing a small per cent carbon in solution. This precipitation will cause the liquid solution to be impoverished in iron, and it will therefore move to the right in the diagram as the temperature falls; or, in other words, it will travel down the line *AB*. By the time the temperature of 1,135°C. is reached, a large amount of austenite will have precipitated, and the small amount of liquid solution left will be at the point *B*, that is, the eutectic point, where there is 4.3 per cent carbon. With further cooling the eutectic will cross the point *B*, and therefore will complete its precipitation and its freezing. It decomposes into crystals, a part of which are of tiny flakelets of the austenite before mentioned and the other part, crystals of carbide of iron—*i.e.*,  $\text{Fe}_3\text{C}$ .

5. A similar result will be obtained in the case of a 3 per cent liquid solution of carbon in iron. This will cool until it reaches

<sup>1</sup> The formation of the solid solution from the liquid solution is discussed in detail in Professor Howe's "Iron, Steel and Other Alloys," but it requires too much space to be discussed here. For our purpose it is sufficient to know that when freezing is completed, we have a solid solution of all the carbon in all of the iron.

1,280°C., where the austenite will precipitate, decreasing the residual solution in iron so that it travels down the line *AB* and finally reaches the point *B*, after which this eutectic solution at the point *B* will precipitate as before.

6. We may sum up paragraphs 4 and 5 by saying that any solution of iron containing more than 1.7 per cent and less than 4.3 per cent of carbon will consist, after freezing, of a eutectic together with a certain amount of previously precipitated austenite (consisting of iron with 1.7 per cent of carbon in solid solution).

7. What will occur in case the solution contains more than 4.3 per cent of carbon?<sup>1</sup> Take, for example, a liquid solution containing 4.7 per cent of carbon at a temperature of 1,200°C. This will cool until a temperature of about 1,170° is reached and the line *DB* is met. As cooling proceeds to lower temperatures, carbide (*i.e.*,  $\text{Fe}_3\text{C}$ ) precipitates out and the liquid solution remaining moves to the left in the diagram. That is to say, it travels down the line *DB*. When the temperature, 1,135° is reached, so much  $\text{Fe}_3\text{C}$  is precipitated that the residual solution is now of the eutectic proportions. With further cooling, this eutectic breaks up as before, consisting thereafter of crystals of  $\text{Fe}_3\text{C}$  and of austenite with 1.7 per cent of carbon.

8. **Summary.**—To sum up, then, all the solutions of iron and carbon containing less than 1.7 per cent of carbon will consist, after solidification, of a solid solution of iron and carbon having the same chemical composition as the original liquid solution, and being a solution of one in the other. There can be no eutectic form if there is not more than 1.7 per cent carbon. All the solutions with more than 1.7 per cent of carbon will consist, after solidification, of a eutectic together with a certain amount of previously-precipitated  $\text{Fe}_3\text{C}$  or of the previously-precipitated 1.7 per cent austenite mentioned.

9. **Metastable Freezing of Cast Iron.**—The reactions described above will yield in each case a cast iron containing  $\text{Fe}_3\text{C}$ , that is, white cast iron. It would seem then that gray cast iron is an anomaly, and this is indeed the case: Pure iron and pure carbon, slowly cooled, will never yield a gray cast iron, that is, a cast iron with 2 or 3 per cent of carbon in the graphite form. To secure such a product we must add other elements to the mixture,

<sup>1</sup> It is very seldom that solutions contain more than 4.3 per cent carbon, because this much carbon does not readily dissolve in iron.

such as silicon, for example. Since commercial cast irons always contain graphite when slowly cooled, and tend to contain combined or dissolved carbon when rapidly cooled, it has been maintained that austenite-graphite is the normal eutectic, and that austenite- $\text{Fe}_3\text{C}$  is the metastable condition. But recent researches indicate that austenite- $\text{Fe}_3\text{C}$  always forms in alloys of pure iron and pure carbon, and that graphite can be obtained only by means of the presence of some other element, such as silicon. We may then summarize this part of the subject by saying that purity of the iron-carbon alloy secures the carbon in combined form and rapid cooling keeps the carbon in dissolved form. Rapid cooling keeps the carbon in dissolved form even in the presence of small amounts of silicon. This is illustrated in the "chilling" of cast iron, for which see pages 354 and 371. But silicon of more than 1 per cent will usually bring out some graphite, even with a moderately rapid rate of cooling. We must always bear in mind that carbon is all in solution in iron in the liquid state: normal freezing of a pure alloy brings it out of solution as  $\text{Fe}_3\text{C}$ ; rapid cooling may hold some of it in solution in the solid (frozen) state; but silicon tends to bring it out of solution as graphite—to make gray cast iron, in other words. To make malleable cast iron (see page 375) we have enough silicon in the iron to cause precipitation of graphite, but this precipitation is first suppressed by rapid cooling. Later we "anneal" the castings and graphite is precipitated in the frozen mass. Without the presence of some silicon, iron castings would not "anneal" to bring out graphite.

**10. Effect of Silicon on Freezing.**—Silicon tends chemically to precipitate graphite. Also it pushes the point *B* in Fig. 164 to the left, so that we would have to draw a new diagram to represent the reactions when iron contains silicon. When blast furnaces are making iron with 1 to 3 per cent of silicon and only 3.50 to 4 per cent of carbon, the point *B* is situated well to the left of 3.50 per cent carbon and graphite separates from the iron as it runs molten out of the furnace. This graphite, or "kish," blows in flakes and settles over the sand and parts of the furnace. This represents carbon separating on cooling of the iron below the line *BD*, and above the line *BC* where the iron becomes entirely solid. Strangely enough, more than 3 per cent of silicon has the contrary effect and causes carbon to separate as cementite, instead of graphite, so that gray iron is not produced by silicon above 3 per cent.



**11. Effect of Sulphur on Freezing.**—Sulphur has the opposite effect from that of silicon: It tends to hold carbon in the combined form, or, if not that completely, to increase the amount of carbon in solution and to cause cementite, instead of graphite, to precipitate. It pushes the point *B* in Fig. 164 to the right, and its effect is 15 times as strong as that of silicon, so that sulphur of 0.06 per cent will counteract the effect on carbon of silicon of 0.90 per cent.

**12. Gray Cast Iron vs. White Cast Iron.**—It is now easy to comprehend why silicon and sulphur and the rate of cooling give the metallurgist control over the production of gray or white iron at will.

#### THE SOLID SOLUTION OF IRON AND CARBON

We have seen that every alloy of iron and carbon contains, after solidification, a varying amount of the solid solution of iron and carbon. For example, if we started with 0.5 per cent of carbon, then, immediately after solidification, we would have a solid solution of 0.5 per cent carbon in iron; if we started with 1 per cent of carbon, we would have a solid solution containing 1 per cent; if we started with 1.4 per cent of carbon, then we would have a solid solution of 1.4 per cent carbon. Even if we start with more than 1.4 per cent carbon, then the alloy, after solidification, will consist partly of a solid solution containing 1.4 per cent of carbon and partly of graphite.

Now, what becomes of these solid solutions which make up a part or a whole of the cast iron and steel alloys when they freeze? Does the carbon remain in solid solution down to the atmospheric temperature, or does it precipitate, or does it undergo some other change? We find by experiment that the solid solutions do not survive, but precipitate at a lower temperature, and the laws governing the decomposition of these solid solutions are similar to the laws governing the decomposition of liquid solutions—for example, the lead-tin solutions. In short, we have another series of curves showing the selective precipitation of the constituents of these solid solutions, and the only difference between the nature of these curves and the lead-tin curves is that these represent changes taking place in the solid state, while the lead-tin curves represent changes taking place in the liquid state.

**Nature of the Solid Solution.**—In the footnote on page 319 I called attention to the fact that the solid solution of iron and

carbon might be a solution of pure carbon in iron, or a solution of a carbide of iron in iron, for example, of  $\text{Fe}_3\text{C}$  in iron. Several authorities hold this view,<sup>1</sup> while others maintain that the solution is of elemental carbon in iron. The question is of more academic than practical interest. The important thing is that, when the solution decomposes, it is carbide of iron which precipitates. Those who believe that the solid solution is composed of elemental carbon and iron explain the precipitation of the carbide by maintaining that when the carbon separates from solution, it immediately unites with iron and forms a carbide, usually  $\text{Fe}_3\text{C}$ . With this explanation I shall hereafter, for simplicity's sake, discuss the solid solutions as if they were  $\text{Fe}_3\text{C}$  in iron.


**The Decomposition of the Solid Solutions.**—The curves of decomposition of the solid solutions are shown in Fig. 165. The line *GOS* is the line upon which there is selective precipitation of pure iron. To this pure iron the name of "ferrite" has been given by Professor Howe, and this name meets with universal acceptance.

Consider first a solid solution containing 0.55 per cent of carbon at a temperature of  $850^\circ\text{C}$ . This will be at the point *o* in Fig. 165. It will cool until it reaches a temperature of about  $800^\circ\text{C}$ . upon which ferrite will begin to precipitate. As the temperature continues to fall more and more ferrite precipitates, which impoverishes the solid solution in iron and causes it to travel down the line *OS*. By the time the temperature has reached  $690^\circ$ , the solid solution has reached the point *S*, corresponding to 0.85 per cent carbon.

Consider next an alloy containing 1.50 per cent carbon at  $1,100^\circ\text{C}$ .: This will be above *E*. It will cool until it reaches a temperature of about  $975^\circ$ , at which carbide of iron ( $\text{Fe}_3\text{C}$ ) will begin to precipitate. This precipitation continues as the temperature falls, constantly decreasing the amount of carbon in the solid solution, which therefore travels down the line *ES* until, at  $690^\circ$ , it reaches the point *S*, where there is 0.85 per cent carbon.

A similar precipitation will take place with all of the solid solutions of iron and carbon: If they contain less than 0.85 per cent carbon, they will begin to precipitate out ferrite when they fall to the line *GOS*. If they contain more than 0.85 per cent

<sup>1</sup> Indeed, one authority believes that there are probably several different carbides ( $\text{Fe}_3\text{C}$ ,  $\text{Fe}_2\text{C}$ ,  $\text{FeC}$ ) dissolved in the iron.



- indicates the crystallization of the Solid Solution (Austenite) from the Liquid Solution.
- indicates the crystallization of Fe<sub>3</sub>C from the Liquid Solution.
- indicates the separation of Ferrite crystals from the Solid Solution.
- indicates the separation of Fe<sub>3</sub>C from the Solid Solution.


\* In commercial cast irons containing from 1 to 3 per cent of silicon, there will be a crystallization here of graphite instead of Fe<sub>3</sub>C.

FIG. 165.—The equilibrium diagram of iron and carbon.



(Courtesy, William Campbell.)

FIG. 166.—Eutectic of copper and silver.



(F. Osmond.)

FIG. 167.—Pearlite eutectoid of iron and carbon.




FIG. 168.—Pearlite and ferrite  
250 diameters.




FIG. 169.—Pearlite and cementite.  
250 diameters.



FIG. 170.—Pearlite.

By a student of H. B. Pulsifer in the  
Metallographic Laboratory of Lehigh  
University.



FIG. 171.—Pearlite.  
1,000 diameters.

Large crystallization due to long overheating. Polished in Relief.



carbon, they will begin to precipitate carbide of iron when they meet the line *ES*. In either case the residual solid solution will travel down the line *GOS*, or else *ES*, until it reaches the point *S* when the temperature has fallen to  $690^{\circ}\text{C}.$ ; we will then have some solid solution left containing 0.85 per cent carbon, and mixed with this some previously precipitated ferrite or cementite, as the case may be.

**Eutectoid.**—The alloy containing 0.85 per cent carbon is known as the “eutectoid alloy,” a name invented by Professor Howe to indicate that the formation of this alloy, which results by selective precipitation of the solid solution, is similar to the formation of the well-known eutectics of liquid solutions. When this eutectoid solid solution cools below  $690^{\circ}\text{C}.$ , it is completely decomposed into its constituents, ferrite and cementite. These constituents precipitate in tiny flakelets, which arrange themselves in the banded structure already familiar to us as the structure of eutectics. A magnified view of the structure is shown in Fig. 167, while Fig. 168 shows the magnified structure of a piece of steel composed of a eutectoid together with previously precipitated ferrite; and Fig. 169 shows the structure of a steel consisting of the eutectoid with previously precipitated cementite.

It will be evident that there will be some of the eutectoid in every piece of iron or steel, for even the cast irons contain, after solidification, a certain amount of solid solution which precipitated either while the liquid alloy was traveling down the line *AB*, or during the freezing of the liquid eutectic (containing 4.3 per cent of carbon), or both. The formation and characteristic of this eutectoid are therefore of very great importance. Its presence in iron and steel was known long before the theories that I have outlined in this chapter had begun to be understood, and the name of “pearlite” was given to it because, under certain circumstances, it has the appearance of mother-of-pearl. The name pearlite is only used to designate the eutectoid after its complete decomposition and the separation of the ferrite and cementite into the banded structure shown in Fig. 167.

**Changes on Heating.**—As in the case of the liquid solutions, the changes already described above in connection with the cooling of the solid solutions are reversed on heating. The temperatures at which the reverse changes occur on heating,

however, are somewhat higher than the corresponding change on cooling, unless both cooling and heating be very slow. In other words, the chemical changes seem to lag behind the temperature changes. With extremely slow heating and cooling, the lag is but slightly perceptible, and the various changes and reversals take place at almost the same temperature, but with the rates of cooling usually employed in research laboratories at steel works, there is a difference of about  $20^{\circ}$  between the temperatures of the changes in the different directions. It is customary to plot the curves as in Figs. 161 and 165, showing temperatures on cooling, and that method has been adopted here.

**Roberts-Austen.**—The diagram of Fig. 165 is often known as the Roberts-Austen diagram, after Sir William Roberts-Austen, because the cooling curves that located the lines were first determined in his laboratory. However, the diagram in Fig. 165 is very greatly altered from the original graphs offered by Roberts-Austen. We also have reason to believe that even this does not represent all the changes which occur in the iron-carbon alloys at different temperatures. Furthermore, there is a controversy as to whether it is  $\text{Fe}_3\text{C}$  or graphite which precipitates under stable conditions of slow cooling when the eutectic freezes, and also along the line *BD*. This discussion belongs to a more advanced treatment of the subject than is possible in the space afforded in this book. There are also points of controversy concerning the amount of carbon which will be retained in solid solution by iron at various temperatures. We have assumed here that the limit of solid solution is 1.7 per cent at  $1,135^{\circ}\text{C}$ . Other authorities give this figure as 1.4 per cent. It is also claimed that iron will retain as much as 0.03 per cent carbon in solid solution at atmospheric temperatures. While this might seem so small as to be negligible, it has a very important effect upon the magnetic permeability.




FIG. 173.—Effect of mechanical working at atmospheric temperature on the properties of electrolytic iron of 99.99 per cent purity.




FIG. 174.—Effect of mechanical working at atmospheric temperature on the properties of electrolytic copper. (Compare with Iron, Fig. 173.)

## CHAPTER XII

### THE CONSTITUTION OF STEEL

The properties of steel depend upon the chemical composition of its constituents as well as upon their size and relation to one another. Enough has been said to show that steel is not a simple homogeneous union of iron with varying proportions of carbon, silicon, manganese, etc., but is built up of individual crystals somewhat in the same way as crystalline rocks are formed—granite, for example. But while the crystals of granite are generally visible to the naked eye, and its structure may therefore be determined by a more or less cursory examination, the structure of steel is visible only by means of the microscope and after careful polishing, sometimes followed by chemical treatment to differentiate between the various grains. Nevertheless, the structure of steel is of great importance, and in some cases, perhaps, is even more so than the chemical composition.

#### THE MICRO-CONSTITUENTS OF STEEL

In this chapter I shall speak only of slowly cooled steel except where I have indicated the contrary. We have already learned that slowly cooled steel must necessarily contain ferrite and cementite, resulting from the decomposition of the solid solution of iron and carbon. There are also other constituents which are found under the microscope, or separated by chemical analysis, or in both ways. These latter constituents are compounds of iron with various other impurities, such as iron sulphide, iron phosphide, and iron silicide; or of two impurities with each other, such as manganese sulphide.

**Ferrite.**—Ferrite is theoretically pure iron, and especially iron free from carbon. It is weak as compared with several of the other constituents, having a tensile strength of 38,000 to 90,000 lb. per square inch, depending on heat treatment and extent of working in the cold. It is very soft, ductile, and malleable. The effect of cold work on hot-rolled iron of 99.99 per cent purity, which is almost pure ferrite, is shown in Fig. 173. It is



especially to be noted that the softness and ductility fall off rapidly at first, and then remain almost constant with added cold treatment. This characteristic is true also of the reduction of area, not shown in the figure, which starts with about 60 to 70 per cent, falls to 30 to 40 per cent and then decreases only very slowly with further cold work. On account of this behavior, pure iron may be rolled or drawn cold to small sizes without intermediate annealings. Ferrite has an elongation of 40 to 50 per cent in 2 in. when in its softest condition. It has a very high electrical conductivity as compared with the other constituents of iron and steel, and about one-sixth the conductivity of copper and silver, the best conductors known. (Copper and silver are of nearly the same conductivity.) Its magnetic force is the highest of any known substance; its magnetic permeability is high, and its hysteresis low. It crystallizes in the isometric system.

Ferrite is an important constituent of all steels and the predominant one in all the low-carbon steels. The larger industrial product approaching ferrite is wrought iron, if we disregard the slag, which, being mechanically mixed with the mass, does not appreciably alter its chemical and physical behavior. It is for this reason that wrought iron is so useful where a soft and ductile material is necessary, as in boilers for instance; or where high electrical conductivity is demanded, as in telegraph wire; or a high degree of magnetism, as in the cores of electromagnets. The wrought iron made in Sweden, and known as "Norway iron," is greatly preferred for this latter purpose, on account of its purity.

Under the microscope ferrite may be distinguished from cementite by its softness. If steel containing these two constituents be polished on damp, rough parchment, or on chamois skin stretched over a soft background (as wood), the ferrite will wear away below the carbide and appear in intaglio. The same effect will be obtained by Osmond's "polish attack."<sup>1</sup> Ferrite is also distinguished from carbide of iron by the fact that, after being subjected to the brief action of certain reagents, such as 2 per cent nitric acid, or ordinary commercial tincture of iodine, the ferrite is seen in darker grains and the carbide in bright thin plates, unattacked by the reagent. When the two are intimately associated in minute grains, as in pearlite, the carbide appears bright and the ferrite dark, because eaten away below the surface by the reagent.

<sup>1</sup> See page 469.

**Allotropic Modifications.**—There is one peculiarity of pure iron, or ferrite, which deserves special attention, namely, its ability to assume different allotropic modifications at different temperatures. To the allotropic modifications of iron the names of "alpha," "beta," and "gamma" have been assigned. The alpha modification is the one existing at atmospheric temperatures, and it is familiar to all who make or use iron. If this be heated, however, it undergoes a sudden change at about  $760^{\circ}\text{C}$ . ( $1,390^{\circ}\text{F}$ .). This change is evidenced by an absorption of heat and the circumstance that the iron loses almost entirely its power to attract a magnet; that is to say, it becomes about as non-magnetic as lead, copper, etc. The change in magnetism is accompanied by a change in electrical conductivity, in specific heat, and in other properties. In short, the iron has changed in many of its properties without undergoing any alteration in chemical composition. This new allotropic modification of iron is known as beta iron.

If, now, beta iron be further heated to a temperature of about  $890^{\circ}\text{C}$ . ( $1,634^{\circ}\text{F}$ .), it again changes several of its properties and becomes what is known as gamma iron. Gamma iron differs from beta iron, especially in electrical conductivity and in crystalline form. Ferrite crystallizes always in the cubic system, and Osmond and Stead have studied the variations of form assumed by it and by its alloys with carbon. Osmond especially has studied the crystallography of the gamma, beta, and alpha modifications of the pure metal. Gamma iron does not crystallize isomorphously with either beta or alpha iron, which crystallize identically in cubes; but it assumes all the combinations of the cube and octahedron, and in the latter form would be isomorphous with carbon in the diamond form. Therefore, in the isomorphous mixtures (*i.e.*, solid solutions) of iron and carbon one would expect to find some carbon in the diamond form, which has indeed been accomplished by Osmond. This is used as an argument in favor of the belief that the solid solution is with carbon, not with cementite; for Osmond has shown that cementite does not assume any crystalline form which would be isomorphous with ferrite. Beta and alpha iron do not crystallize isomorphously with either carbon or cementite, which accords with the observed tendency of ferrite to begin to separate from the solid solution at the same temperature at which it changes from gamma to beta.

If ferrite is in the gamma form, and say at  $1,000^{\circ}\text{C}$ . ( $1,832^{\circ}\text{F}$ .), it will undergo upon cooling the reverse of the changes which have already been described. That is to say, at about  $890^{\circ}\text{C}$ . ( $1,634^{\circ}\text{F}$ .) it will change from gamma to beta iron; at  $760^{\circ}\text{C}$ . ( $1,390^{\circ}\text{F}$ .) it will change from beta to alpha iron, in each case

receiving again the properties which it had before heating. In other words, the change from one allotropic form to another is a reversible change, taking place in one direction on cooling and in the opposite direction on heating. The change on cooling takes place at a slightly lower temperature than on heating. This is not because it is other than a true reverse action, but because the change in either direction is necessarily slow and lags a little behind the temperature. The amount of this lag will vary directly with the speed of heating and cooling.

We never get pure gamma iron at any temperature unless we start with iron free from carbon, because gamma ferrite never separates from the solid solution. If, however, we have a solid solution of iron with, let us say, 0.2 per cent of carbon, then this solid solution will begin to precipitate ferrite at a temperature of about  $830^{\circ}\text{C}$ . ( $1,524^{\circ}\text{F}$ .). This ferrite will be, of course, in the beta form and will be non-magnetic until the mass cools below  $760^{\circ}\text{C}$ . ( $1,390^{\circ}\text{F}$ .), when the previously precipitated ferrite will change from the beta to the alpha form. Any ferrite which separates from solid solution after that

temperature is reached will separate in the first instance in the alpha form. For example, if we have a solid solution, containing, say, 0.7 per cent carbon, this will commence to precipitate ferrite below  $760^{\circ}\text{C}$ . (about  $720^{\circ}$ ), and the ferrite will be in the alpha form.<sup>1</sup>

<sup>1</sup> Some maintain that the ferrite always precipitates as gamma ferrite, then immediately changes to beta and next to alpha ferrite. Others maintain that when the solid solution is cooled near the line GOS, it changes from a solid solution of gamma iron into a solid solution of beta iron, and then into a solid solution of alpha iron, from which alpha iron then precipitates.




FIG. 175.—Cooling curve of pure iron.

**Cementite.**—The carbide of iron is, next to ferrite, the most important constituent of steel, and practically all of the carbon is present in this form.<sup>1</sup> Cementite is very hard and brittle, scratching glass with ease and flying into pieces under a blow. It crystallizes usually in thin flat plates, which are large in size (sometimes up to  $\frac{1}{8}$  in. in diameter) when there is much cementite present. It is less attacked by reagents than most of the other constituents and is in this way distinguished under the microscope. It is a little difficult to distinguish, by microscopic evidence alone, between steel consisting of pearlite with a slight excess of cementite and steel consisting of pearlite with a slight excess of ferrite. The practiced eye can usually tell; but a chemical analysis readily distinguishes, since steel with less than 0.8 per cent carbon will have excess ferrite over pearlite, and that with more than 0.9 per cent will have excess cementite.

Cementite contains 6.6 per cent of carbon, or roughly, is one-fifteenth carbon. We may therefore tell the amount of cementite in any steel by multiplying the amount of carbon by fifteen.<sup>2</sup> Cementite may be separated from steel by electrolysis. It is magnetic at ordinary temperatures, but not above 700°C. (1,292°F.).

The carbon united with iron in cementite has been given various names, such as "cement carbon," or "carbon of cementation" (because of its prominent appearance in cemented steels), and "carbon of the normal carbide," "annealing carbon" (because all the carbon of well-annealed steels will usually be present as cementite).

**Manganiferous Cementite.**—Manganese forms a carbide having the formula  $Mn_3C$ . This is isomorphous with  $Fe_3C$ , and we often find the two carbides together in one crystal. The name cementite is still applied to this crystal, although it must be recognized that a part of the iron has been replaced by manganese. The formula for the compound is usually written  $(FeMn)_3C$ . The amount of manganese in these crystals is very variable, running almost all the way from nothing to 90 per cent. As manganese has an atomic weight almost the same as that of iron ( $Mn_{55}$ ,  $Fe_{56}$ ), one weight of manganese will replace

<sup>1</sup> There is not wanting evidence in favor of several carbides being present, such as  $FeC$ ,  $Fe_2C$ ,  $Fe_3C$ ,  $Fe_4C$ , etc., but  $Fe_3C$  is the one usually considered.

<sup>2</sup> In other words, steel containing 0.5 per cent of carbon will contain 7.5 per cent cementite; steel containing 1 per cent carbon will contain 15 per cent cementite; etc.






FIG. 176.—Ferrite, pure iron (electrolytic). 1,000 diameters. Etched with picric acid.




FIG. 177.—Pearlite crystals. Surrounded by ferrite. 250 diameters. Etched with  $\text{HNO}_3$ .




FIG. 178.—Big cementite crystal in pearlite. 250 diameters. Polished in relief.



FIG. 179.—Crystals of manganiferous cementite. 50 diameters. Etched with nitric acid.



FIG. 180.—Elongated bubble of manganese sulphide. 250 diameters. Unetched.




FIG. 181.—Eutectic of  $\text{Fe}_3\text{P}$  and iron. 1,000 diameters. Etched with picric acid.

almost exactly an equal weight of iron in the crystal. The peculiarity of the manganiferous cementite is that the crystals of free cementite are liable to be larger, especially when the proportion of manganese is large, and are seemingly harder and more difficult to machine.

**Manganese Sulphide.**—Manganese and sulphur unite to form manganese sulphide, having the formula  $MnS$ , and this compound is found in all steels. Indeed, all of the sulphur will be found in this combination, provided there is enough manganese in the steel to unite with it. It is necessary to have more than the theoretical amount of manganese for this purpose, however, because unless there is a surplus present, the manganese does not seem to catch it all. Steel should therefore always contain about four times as much manganese as sulphur, because it is advantageous to have the sulphur all in the form of manganese sulphide.

Manganese sulphide is seen under the microscope as a dove-gray substance before the polished material is etched with any reagents. It is usually segregated in round drops, which are sometimes, if large in size, seen to be elongated by the rolling or hammering of the material (see Fig. 180).

Manganese tends to make the crystals of steel smaller, which is advantageous, but makes the metal more liable to crack in heating, and still more so in cooling suddenly from a red heat.

**Iron Sulphide.**—The bulk of the sulphur not united with the manganese will be found in the form of iron sulphide ( $FeS$ ). This iron sulphide is more brittle than manganese sulphide, and instead of coalescing in drops, it spreads out in webs or sheets. It is therefore very weakening to the steel, because the area of weakness is more extensive than the tiny spots of manganese sulphide. Steel containing iron sulphide is liable to show poor tensile test and low ductility. It is at the rolling temperature, however, that iron sulphide produces the greatest weakness, because at this point it is in a liquid form and therefore has practically no adhesion to the crystals of steel, which are liable to break along the planes or meshes of sulphide. Manganese sulphide, on the contrary, does not melt at forging temperatures but occurs as drops instead of membranes between the crystals. The damage which its presence does to the strength and ductility of steel is therefore less. These facts explain the well-known

beneficial effect of manganese in counteracting the damage due to sulphur in iron and steel.

**Iron Phosphide.**—Iron forms at least one phosphide, having the formula  $\text{Fe}_3\text{P}$ , and this phosphide forms with iron a series of alloys, of which the eutectic contains 64 per cent of  $\text{Fe}_3\text{P}$  (10.2 per cent of phosphorus). Even 1 per cent of phosphorus will make the melting-point of iron very much lower, and it is for this reason that foundry irons are often desired with a high content of phosphorus. Even where there is a smaller amount of phosphorus there will be some of the phosphorus eutectic formed, and this remains in a molten condition for some time after the bulk of the steel has solidified. This liquid eutectic tends to migrate to the spaces between the crystals, where it remains after solidification and forms a very brittle network, which naturally makes the whole mass more or less brittle. For these reasons phosphorus is the greatest source of brittleness in steel, and especially brittleness under shock, and is thus a great enemy to the engineer and other users of the material.

Besides forming the eutectic, as I have described, phosphorus tends to produce coarse crystallization in steel, and this makes it both weak and brittle. It is a fact observed many times that the embrittling effect of phosphorus on steel is much less when the steel is very low in carbon, and as the carbon rises the brittleness caused by phosphorus rises. This and other effects of phosphorus have been explained by Prof. J. E. Stead in two very able papers. He has shown that a little phosphorus will dissolve in ferrite and that then the eutectic which produces the brittleness will not form, but as the carbon in the steel increases, it precipitates the phosphorus from the ferrite solid solution and therefore causes the eutectic to form. Hence, the more ferrite and the less cementite in steel, the less will be the brittleness produced by phosphorus.

**Iron Silicides.**—There seem to be three or more silicides of iron, but the one having the formula  $\text{FeSi}$  seems to be found most commonly in steel. It appears to increase very slightly the strength of steel, and also, to a limited extent, its hardness. The chief importance of silicon, however, as already pointed out, is in promoting soundness.

**Iron Oxides.**—Oxygen occurs in steel in at least three forms:  $\text{CO}$ ,  $\text{FeO}$  and  $\text{Fe}_2\text{O}_3$ . In either form its presence is very harmful, producing brittleness in both hot and cold steel, besides causing

the liability to blowholes already discussed. There is probably no constituent more harmful to steel than oxygen, and unfortunately the chemists are far behind in respect of not yet having found a satisfactory method of rapidly determining small traces of this gas. The effect of oxygen is somewhat similar to that of sulphur, and, in common parlance, makes the steel "rotten."

**Nitrogen and Hydrogen.**—Both nitrogen and hydrogen occur in steel, and one of the theories to explain the superiority of crucible steel is based upon the relative freedom of this material from these two gases. The amount of nitrogen and hydrogen present is usually very small. Hydrogen dissolves very easily in iron at a high temperature, but is evolved in part as the metal cools. In order to obtain entire freedom, however, it is necessary to heat and cool several times *in vacuo*. Nitrogen is important in connection with arc welding, when a needle-like constituent appears, which is thought to be a crystal of iron nitride. It makes the steel very brittle.

#### THE STRENGTH OF STEEL

The properties of steel most commonly desired are strength and ductility. Unfortunately there is more or less incompatibility between these two. That is to say, as the strength of steel increases, the ductility usually decreases; and, conversely, as the ductility increases, the strength usually decreases. There are other properties of steel which are likewise of importance, either because they are desired, or the reverse. Among these we shall especially discuss hardness, brittleness, electric conductivity, magnetic permeability, magnetic hysteresis, permanent magnetism and weldability. Pure iron has a tensile strength of about 38,000 lb. per square inch, when in its softest condition, at which the ductility is great, being about equal to that of copper (see Figs. 173 and 174, p. 330), and the malleability is equal to or greater than that of copper. Different authorities give varying estimates of the compressive strength, from 55,000 to 80,000 lb. resistance of a 1-in. cube. The variation depends largely on the opinion of the observer as to what constitutes the limit of "yielding" to compression, and this problem would seem to resolve itself into a matter of civil engineering rather than of metallurgy; that is, a question of strength of columns of different sizes and design, rather than the strength of a 1-in. cube of the metal. The



strength of iron is increased by the presence of several ingredients customarily accompanying it in industrial use, but the most important strengthener is carbon, because this will increase its strength with the least decrease in ductility.

The steel manufacturer must work to meet the specifications of the civil, mechanical, electrical or chemical engineer, as to strength, ductility, hardness, lack of brittleness, resistance to shock, etc. And, because the usual tests are admitted not to be perfect safeguards, the latter is permitted by custom to limit the percentage of such dangerous ingredients as sulphur, phosphorus, and (under certain circumstances) manganese. As the work of the chemist advances, it is also probable that upper limits may be placed on the allowable percentage of oxides and other sonims, as well as oxygen, hydrogen, nitrogen, CO, and other gases. But it is now generally recognized that, beyond this point, the purchaser has no right to trespass on the work of the metallurgist, who should be permitted to put into his product the proportion of carbon, etc., which will give the desired qualities. This agreement has been achieved in America largely through the efforts of the American Society for Testing Materials.

The metallurgist, then, must be an authority on the effect of the ingredients, in order that he may regulate the analysis of the product to meet the specifications. The first requisite is to know that the qualities of the steel depend on the process of manufacture: Bessemer, open-hearth and electric steel will differ in properties even when alike in analysis. The second is to recognize that the extent of reduction in rolling must be taken into consideration: Granted that the steel has had enough work to knead the crystals thoroughly, nevertheless plate of  $\frac{3}{8}$ -in. thickness will have higher strength than plate of  $\frac{5}{8}$ -in. rolled from the same ingot. The finishing temperature of rolling and the rate of cooling from rolling heat will also have their effect: For example, the web and flange of a railroad rail are stronger and harder than the metal of the head. Every manufacturer has tables, based on the experience of his plant, to adjust the chemical composition to the practice of his steel-making and rolling-mill. The general rules given below will then be varied to meet the conditions in each plant.

**Carbon.**—Each increase in carbon (cementite) gives an increase in tensile strength until we reach a maximum of about 0.8 to 0.9 per cent of carbon (12 to 13.5 per cent cementite).

With increase in cementite above 15 per cent there is a decrease in tensile strength. It is probable that the reason for this maximum tensile strength at approximately the eutectoid ratio of the steel is due largely to the small crystallization and the intimate mixture of the crystalline constituents when the steel is at, or near, the eutectoid proportions.<sup>1</sup> With less carbon the grains of pearlite are surrounded by a network of ferrite; with more carbon, the grains of pearlite are surrounded by network of cementite; and both of these networks have a weakening effect upon the material by decreasing the adhesion of the crystals.

TABLE XXXV.—EFFECT OF CARBON ON IRON  
(Other Elements Being Low)

	Carbon, per cent	Tensile strength of annealed metal		
		Ultimate, pounds per square inch	Elastic limit, pounds per square inch	Elonga- tion, per cent in 2"
Very mild steel.....	0.05-0.15	40,000- 48,000	24,000-30,000	34-28
Mild steel.....	0.15-0.25	48,000- 60,000	30,000-36,000	28-25
Low-carbon steel.....	0.25-0.40	60,000- 70,000	36,000-40,000	25-22
Medium-carbon steel..	0.40-0.60	70,000- 80,000	40,000-48,000	22-18
Higher-carbon steel...	0.60-0.70	80,000- 94,000	48,000-56,000	18-14
Spring steel.....	0.70-0.80	94,000-108,000	56,000-64,000	14- 8
Pearlitic steel.....	0.85	120,000	70,000	5

**The Work of W. R. Webster on Open-hearth and Bessemer Steels.**—H. H. Campbell and W. R. Webster have studied exhaustively the effect of carbon, manganese, and phosphorus on the strength of basic open-hearth and acid Bessemer steels, the two largest sources in America of rolled steel. Knowing these influences, the manufacturer has a good working basis, because the only other common ingredients are sulphur and silicon, and neither of these is present in rolled steel in amounts sufficiently variable to exert a controlling influence on the strength or ductility. Sulphur is limited by the purchaser to amounts which will ensure the ductility desired, and the manufacturer must limit it in order that the steel will roll well. In

<sup>1</sup> The still greater increase in strength when the two constituents of the pearlite (ferrite and cementite) are even more intimately associated is explained on p. 413.

TABLE XXXVI.—CARBON CONTENT OF WROUGHT IRON AND STEELS FOR DIFFERENT USES

	Material		Carbon	
	Usual	Preferred	Desired	Limits
Axles.....	B.O.H.	El.	0.40	0.25-0.70
Axles, cold-rolled.....	B.O.H.	O.H.	....	Not over 0.40
Alternate stress, resistance to.....	B.O.H.	El.	0.50	0.45-0.75
Boiler plate, steel.....	B.O.H.	A.O.H.	0.12	0.08-0.18
Boiler plate, wrought iron.....	W.I.	W.I.	0.10	0.08-0.18
Boiler tubes, steel.....	O.H.	A.O.H.	0.10	0.08-0.18
Boiler tubes, charcoal wrought iron.....	C.W.I.	C.W.I.	X	
Castings.....	O.H.	El.	....	0.12-0.30
Carpenter's tools.....	....	Steel	....	0.50-1.20
Carpenter's tools, hammers.....	M.C.I.	Steel	....	0.50-0.80
Carpenter's tools, wood-cutting tools.....	Steel	Cr.#	1.15	1.10-1.20
Case-hardening stock.....	O.H.	....	0.12	0.10-0.20
Chain, steel.....	B.O.H.	O.H.	Min.	0.04-0.15
Chisels, granite-cutting.....	Cr.#	Cr.#	1.05	1.00-1.10
Chisels, cold chisels.....	Cr.#	Cr.#	0.75	0.70-0.80
Cold-rolled steel.....	B.O.H.	....	....	Not over 0.40
Concrete-reinforcement bars.....	Bess.	O.H.	....	0.40-0.70
Culverts for water disposal.....	O.H.	El.	Min.	0.00-0.10
Crankpins for wearing resistance.....	O.H.	....	0.30	0.25-0.35
Crankpins for resisting shocks and reversals of stress.....	O.H.	El.	0.50	0.45-0.55
Dies, for making drop-forgings.....	B.O.H.	O.H.	0.65	0.60-0.70
Dies, for metal cutting.....	B.O.H.	El.	0.85	0.80-1.20
Dies, for thread cutting.....	Cr.	Cr.#	1.15	1.10-1.20
Dies, for wire drawing.....	Cr.#	Cr.#	1.50	1.30-2.00
Drills, rock drilling.....	Cr.#	Cr.#	0.85	0.80-0.90
Engravers' tools.....	Cr.#	Cr.#	1.35	1.30-1.40
Files for metal smoothing.....	Cr.#	Cr.#	1.25	1.20-1.30
Forgings, ordinary.....	B.O.H.	A.O.H.	0.25	0.20-0.30
Forgings, strong.....	B.O.H.	A.O.H.	0.40	0.35-0.60
Gears, except case-hardened.....	B.O.H.	O.H.	0.35	0.30-0.60
Lathe tools.....	Cr.#	Cr.#	....	1.00-1.20
Machinery steel.....	B.O.H.	O.H.	0.35	0.30-0.50
Machinists, tools.....	Cr.#	Cr.#	....	0.70-1.20
Nails, wire.....	Bess.	Bess.	0.10	0.08-0.15
Nails, cut.....	W.I.	W.I.	0.10	
Pipe, steel.....	Bess.	....	Low	
Pipe, wrought iron.....	W.I.	W.I.	....	
Plates, tank.....	Bess.	....	0.12	0.08-0.15
Plates, structural.....	B.O.H.	A.O.H.	0.30	0.25-0.40
Punches.....	....	Cr.#	....	0.80-1.00
Railroad car wheels, steel.....	B.O.H.	O.H.	0.70	0.60-0.85
Railroad rails, small sizes.....	Bess.	B.O.H.	....	0.37-0.50
Railroad rails, large sizes.....	B.O.H.	O.H.	....	0.50-0.75
Rivets.....	B.O.H.	B.O.H.	0.05	0.05-0.20
Screws for wood.....	Bess.	Bess.	0.10	0.08-0.16
Set screws.....	B.O.H.	Cr.#	0.65	0.60-0.70
Saws, band.....	Cr.#	Cr.#	0.75	0.70-0.80
Saws, circular.....	O.H.	Cr.#	0.85	0.80-0.90
Saws, for cutting steel.....	Cr.#	Cr.#	1.55	1.50-1.60
Shafting, for transmission purposes.....	B.O.H.	B.O.H.	....	Not over 0.4
Shafting, for crankshafts.....	O.H.	Cr.#	0.50	0.50-0.60
Staybolts, wrought iron.....	W.I.	W.I.	....	
Shock-resisting steel.....	O.H.	O.H.	0.50	0.45-0.55
Stone-cutting tools.....	Cr.#	Cr.#	1.35	1.30-1.40
Structural shapes, small.....	Bess.	O.H.	0.25	
Structural shapes, important structures.....	O.H.	A.O.H.	0.25	
Springs.....	B.O.H.	Cr.#	0.95	0.90-1.15
Tubing, steel.....	Bess.	O.H.	0.08	0.05-0.15
Tubing, wrought iron.....	W.I.	W.I.	....	
Valves for resisting wear.....	B.O.H.	O.H.	0.30	0.25-0.35
Wire, for electric conductivity.....	Bess.	Bess.	Min.	0.05-0.10
Wire, for fencing and chicken wire.....	Bess.	Bess.	Low	
Wire, for structural steel.....	A.O.H.	A.O.H.	0.80	0.75-0.85

A.O.H. = Acid open-hearth steel; B.O.H. = basic open-hearth steel; Bess. = Bessemer steel; Cr.# = Crucible or electric steel; El. = Electric steel; W.I. = Wrought iron; C.W.I. = Knobbled charcoal wrought iron; M.C.I. = malleable cast iron.

Bessemer steel it will usually not exceed 0.08 per cent, and its effect is taken into consideration by the metallurgist as a condition of the Bessemer steel problem. In basic open-hearth steel it will usually not exceed 0.05 per cent (except in special products whose strength and ductility are not controlling conditions).

W. R. Webster gives two working tables. See Table below, taken from Trans. Am. Inst. Min. Met. Engs., Vol. LXVII, 1922, pp. 227-8), which are given below for the guidance of metallurgists. From these tables it will be evident that the effect of the phosphorus is dependent on the others. We may summarize for carbon, as follows: When the phosphorus

TABLE XXXVII.—Steel Works A, Basic Open-hearth Steel

Phosphorus under 0.031 per cent; manganese 0.34 to 0.60 per cent, varying by 0.02 per cent; carbon 0.10 to 0.40 per cent, varying by 0.1 per cent. Average of actual tensile strength of  $\frac{3}{4}$ -in. round test bars rolled from test ingots.

When phosphorus is greater than 0.02 per cent the figures should be increased at the rate of 1000 lb. for each 0.01 per cent, that the phosphorus exceeds 0.02 per cent.

Per Cent, Carbon	Per Cent, Manganese														
	0.34	0.36	0.38	0.40	0.42	0.44	0.46	0.48	0.50	0.52	0.54	0.56	0.58	0.60	
Tensile Strength, Pounds per Square Inch															
0.10	50,145	50,585	50,980	51,300	51,700	52,100	52,440	52,720	53,000	53,400	53,600	54,200	54,600	55,000	
0.11	51,410	51,790	52,060	52,390	52,770	53,050	53,340	53,593	53,850	54,243	54,640	55,025	55,390	55,760	
0.12	52,675	53,040	53,325	53,640	53,940	54,240	54,470	54,700	55,000	55,340	55,675	56,000	56,325	56,640	
0.13	53,940	54,310	54,570	54,870	55,170	55,460	55,720	56,000	56,275	56,550	56,825	57,100	57,475	57,850	
0.14	55,210	55,570	55,820	56,100	56,380	56,650	56,925	57,200	57,475	57,750	58,025	58,300	58,575	58,850	
0.15	56,475	56,835	57,080	57,360	57,640	57,920	58,200	58,475	58,750	59,025	59,300	59,575	59,850	60,125	
0.16	57,740	58,100	58,350	58,630	58,910	59,190	59,465	59,740	60,015	60,290	60,565	60,840	61,115	61,390	
0.17	59,005	59,365	59,610	59,890	60,170	60,445	60,720	61,000	61,275	61,550	61,825	62,100	62,375	62,650	
0.18	60,270	60,630	60,880	61,160	61,440	61,715	62,000	62,275	62,550	62,825	63,100	63,375	63,650	63,925	
0.19	61,535	61,895	62,140	62,420	62,700	62,975	63,250	63,525	63,800	64,075	64,350	64,625	64,900	65,175	
0.20	62,800	63,160	63,410	63,690	63,970	64,245	64,520	64,800	65,075	65,350	65,625	65,900	66,175	66,450	
0.21	64,065	64,425	64,675	64,955	65,235	65,510	65,785	66,060	66,335	66,610	66,885	67,160	67,435	67,710	
0.22	65,330	65,690	65,940	66,220	66,500	66,775	67,050	67,325	67,600	67,875	68,150	68,425	68,700	68,975	
0.23	66,595	66,955	67,205	67,485	67,765	68,040	68,315	68,590	68,865	69,140	69,415	69,690	69,965	70,240	
0.24	67,860	68,220	68,470	68,750	69,030	69,305	69,580	69,855	70,130	70,405	70,680	70,955	71,230	71,505	
0.25	69,125	69,485	69,735	70,015	70,295	70,570	70,845	71,120	71,395	71,670	71,945	72,220	72,495	72,770	
0.26	70,390	70,750	71,000	71,280	71,560	71,835	72,110	72,385	72,660	72,935	73,210	73,485	73,760	74,035	
0.27	71,655	72,015	72,265	72,545	72,825	73,100	73,375	73,650	73,925	74,200	74,475	74,750	75,025	75,300	
0.28	72,920	73,280	73,530	73,810	74,090	74,365	74,640	74,915	75,190	75,465	75,740	76,015	76,290	76,565	
0.29	74,185	74,545	74,795	75,075	75,355	75,630	75,905	76,180	76,455	76,730	77,005	77,280	77,555	77,830	
0.30	75,450	75,810	76,060	76,340	76,620	76,895	77,170	77,445	77,720	78,000	78,275	78,550	78,825	79,100	
0.31	76,715	77,075	77,325	77,605	77,885	78,160	78,435	78,710	78,985	79,260	79,535	79,810	80,085	80,360	
0.32	77,980	78,340	78,590	78,870	79,150	79,425	79,700	79,975	80,250	80,525	80,800	81,075	81,350	81,625	
0.33	79,245	79,605	79,855	80,135	80,415	80,690	80,965	81,240	81,515	81,790	82,065	82,340	82,615	82,890	
0.34	80,510	80,870	81,120	81,400	81,680	81,955	82,230	82,505	82,780	83,055	83,330	83,605	83,880	84,155	
0.35	81,775	82,135	82,385	82,665	82,945	83,220	83,495	83,770	84,045	84,320	84,595	84,870	85,145	85,420	
0.36	83,040	83,400	83,650	83,930	84,210	84,485	84,760	85,035	85,310	85,585	85,860	86,135	86,410	86,685	
0.37	84,305	84,665	84,915	85,195	85,475	85,750	86,025	86,300	86,575	86,850	87,125	87,400	87,675	87,950	
0.38	85,570	85,930	86,180	86,460	86,740	87,015	87,290	87,565	87,840	88,115	88,390	88,665	88,940	89,215	
0.39	86,835	87,195	87,445	87,725	88,005	88,280	88,555	88,830	89,105	89,380	89,655	89,930	90,205	90,480	
0.40	88,100	88,460	88,710	88,990	89,270	89,545	89,820	90,095	90,370	90,645	90,920	91,195	91,470	91,745	

TABLE XXXVIII.—Steel Works A, Acid Bessemer Steel

Manganese 0.34 to 0.60 per cent, varying by 0.02 per cent; carbon 0.10 to 0.40 per cent, varying by 0.01 per cent. Average of actual tensile strength of  $\frac{3}{4}$ -in. round test bars rolled from test ingots.

Per Cent, Carbon	Per Cent., Manganese														
	0.34	0.36	0.38	0.40	0.42	0.44	0.46	0.48	0.50	0.52	0.54	0.56	0.58	0.60	
Tensile Strength, Pounds per Square Inch															
0.10	54,440	54,690	54,940	55,190	55,440	55,690	55,940	56,190	56,440	56,690	56,940	57,190	57,440	57,690	
0.11	55,695	55,945	56,195	56,445	56,695	56,945	57,195	57,445	57,695	57,945	58,195	58,445	58,695	58,945	
0.12	56,950	57,200	57,450	57,700	57,950	58,200	58,450	58,700	58,950	59,200	59,450	59,700	59,950	60,200	
0.13	58,205	58,455	58,705	58,955	59,205	59,455	59,705	59,955	60,205	60,455	60,705	60,955	61,205	61,455	
0.14	59,460	59,710	59,960	60,210	60,460	60,710	60,960	61,210	61,460	61,710	61,960	62,210	62,460	62,710	
0.15	60,715	60,965	61,215	61,465	61,715	61,965	62,215	62,465	62,715	62,965	63,215	63,465	63,715	63,965	
0.16	61,970	62,220	62,470	62,720	62,970	63,220	63,470	63,720	63,970	64,220	64,470	64,720	64,970	65,220	
0.17	63,225	63,475	63,725	63,975	64,225	64,475	64,725	64,975	65,225	65,475	65,725	65,975	66,225	66,475	
0.18	64,480	64,730	64,980	65,230	65,480	65,730	65,980	66,230	66,480	66,730	66,980	67,230	67,480	67,730	
0.19	65,735	65,985	66,235	66,485	66,735	66,985	67,235	67,485	67,735	67,985	68,235	68,485	68,735	68,985	
0.20	66,990	67,240	67,490	67,740	67,990	68,240	68,490	68,740	68,990	69,240	69,490	69,740	69,990	70,240	
0.21	68,245	68,495	68,745	68,995	69,245	69,495	69,745	69,995	70,245	70,495	70,745	70,995	71,245	71,495	
0.22	69,500	69,750	69,995	70,245	70,495	70,745	70,995	71,245	71,495	71,745	71,995	72,245	72,495	72,745	
0.23	70,755	71,005	71,255	71,505	71,755	72,005	72,255	72,505	72,755	73,005	73,255	73,505	73,755	74,005	
0.24	72,010	72,260	72,510	72,760	73,010	73,260	73,510	73,760	74,010	74,260	74,510	74,760	75,010	75,260	
0.25	73,265	73,515	73,765	74,015	74,265	74,515	74,765	75,015	75,265	75,515	75,765	76,015	76,265	76,515	
0.26	74,520	74,770	75,020	75,270	75,520	75,770	76,020	76,270	76,520	76,770	77,020	77,270	77,520	77,770	
0.27	75,775	76,025	76,275	76,525	76,775	77,025	77,275	77,525	77,775	78,025	78,275	78,525	78,775	79,025	
0.28	77,030	77,280	77,530	77,780	78,030	78,280	78,530	78,780	79,030	79,280	79,530	79,780	80,030	80,280	
0.29	78,285	78,535	78,785	79,035	79,285	79,535	79,785	80,035	80,285	80,535	80,785	81,035	81,285	81,535	
0.30	79,540	79,790	80,040	80,290	80,540	80,790	81,040	81,290	81,540	81,790	82,040	82,290	82,540	82,790	
0.31	80,795	81,045	81,295	81,545	81,795	82,045	82,295	82,545	82,795	83,045	83,295	83,545	83,795	84,045	
0.32	82,050	82,300	82,550	82,800	83,050	83,300	83,550	83,800	84,050	84,300	84,550	84,800	85,050	85,300	
0.33	83,305	83,555	83,805	84,055	84,305	84,555	84,805	85,055	85,305	85,555	85,805	86,055	86,305	86,555	
0.34	84,560	84,810	85,060	85,310	85,560	85,810	86,060	86,310	86,560	86,810	87,060	87,310	87,560	87,810	
0.35	85,815	86,065	86,315	86,565	86,815	87,065	87,315	87,565	87,815	88,065	88,315	88,565	88,815	89,065	
0.36	87,070	87,320	87,570	87,820	88,070	88,320	88,570	88,820	89,070	89,320	89,570	89,820	90,070	90,320	
0.37	88,325	88,575	88,825	89,075	89,325	89,575	89,825	90,075	90,325	90,575	90,825	91,075	91,325	91,575	
0.38	89,580	89,830	90,080	90,330	90,580	90,830	91,080	91,330	91,580	91,830	92,080	92,330	92,580	92,830	
0.39	90,835	91,085	91,335	91,585	91,835	92,085	92,335	92,585	92,835	93,085	93,335	93,585	93,835	94,085	
0.40	92,090	92,340	92,590	92,840	93,090	93,340	93,590	93,840	94,090	94,340	94,590	94,840	95,090	95,340	



is 0.02 per cent and the manganese 0.40 per cent, each 0.01 per cent of carbon will increase the tensile strength by 800 lb. per square inch. When the phosphorus is 0.08 per cent and the manganese 0.80 per cent, each 0.01 per cent of carbon added will increase the tensile strength by 1,000 lb. per square inch.

**Silicon.**—The effect of silicon on strength is probably very small in the case of rolled steel. In the case of castings, however, an important increase in tensile strength may be obtained by increasing the silicon to 0.3 or 0.4 per cent. This practice results in practically no decrease in ductility, but it is necessary to supply larger risers on account of the deep piping that will be produced. It is probable that the beneficial effect of silicon in this case is due very largely to its producing soundness.

**Sulphur.**—H. H. Campbell says that the effect of sulphur on the strength of acid and basic open-hearth steel is very small. It is probable, however, that this statement is only true when the sulphur is in the form of manganese sulphide, because the effect of iron sulphide would be to lower the strength and the ductility of the material. The worst effect of sulphur is undoubtedly its production of "red-shortness" and the liability to cause checking during rolling, or, in the case of a casting, during cooling.

**Phosphorus.**—Campbell's and Webster's results show that each 0.01 per cent of phosphorus increases the strength of the steel by 1,000 lb. per square inch. It should be observed, however, that this increase of strength is measured by the resistance of the material to stresses slowly applied and that it ceases with 0.12 per cent phosphorus and is reversed. In the case of vibratory stresses and sudden shocks, phosphorus is probably the most harmful of the elements, so that it is undesirable to increase the strength of steel by means of this element. This is the more true because of the brittleness produced by phosphorus, for an increase of strength obtained through this medium is accompanied by a much greater decrease in ductility than when the same increase in strength is obtained through the medium of carbon.

**Manganese.**—The beneficial effect of manganese on tensile strength begins only when the manganese is above 0.3 or 0.4 per cent. With less manganese than this, in the case of open-hearth and Bessemer steels, the presence of some other condition, probably iron oxide, masks the effect of manganese. It will be remembered that when the manganese is low, open-hearth and

Bessemer steels are harmfully charged with oxygen. Furthermore, the effect of manganese is dependent upon the amount of carbon present.

Webster uses a uniform figure of 170 lb. per square inch increase of tensile strength for each 0.01 per cent manganese added to basic open-hearth steel, beginning only at 0.30 per cent manganese. Campbell, on the other hand, estimates that the effect of manganese increases with the content of carbon. His results for acid and basic open-hearth steel are given below. It will be observed that, when the carbon is 0.20 per cent, his figure for manganese agrees exactly with that of Webster.

TABLE XXXIX.—EFFECT OF EACH 0.01 PER CENT MANGANESE ON OPEN-HEARTH STEEL

Percentage of carbon	On acid steel, pounds per square inch	On basic steel, pounds per square inch
0.05	...	110 <sup>2</sup>
0.10	80 <sup>1</sup>	130
0.15	120	150
0.20	160	170
0.25	200	190
0.30	240	210
0.35	280	230
0.40	320	250
0.45	360	
0.50	400	
0.55	440	
0.60	480	

<sup>1</sup> Beginning only with 0.4 per cent of manganese.

<sup>2</sup> Beginning only with 0.3 per cent of manganese.

In studying this table it will be interesting to note that some of the manganese added to basic steel is probably used up in neutralizing the effect of oxygen, before it can exert its influence in strengthening the steel itself. The result is that manganese in basic steel does not produce the same strengthening effect as the same percentage of manganese in acid steel.

**Residual Manganese.**—For this reason all open-hearth steel is now made with “residual manganese” left in the bath during the whole operation. This produces three effects:

1. It protects the bath from oxygen.
2. It leaves less oxygen in the final steel than can be accomplished by the usual manganese deoxidation.
3. It reduces by an amount equal to its own percentage the manganese necessary to add for deoxidation during recarburizing.

The amount of residual manganese is 0.10 to 0.20 per cent, and it is left in the bath by the practice of starting with an excess of manganese in the charge and then raising the temperature to the point where carbon begins to oxidize before all the manganese is consumed by the oxygen of the ore or flame. Another method recently used is to add manganiferous iron ore, instead of straight iron ore, for oxidizing purposes. This is an economic question, dependent on the relative price of the ore and of high-manganese pig iron. Under special conditions scrap from manganese steel manufacture may be used to a limited extent.

**Copper.**—Copper, up to at least 1 per cent, does not appear to have any important effect upon the strength or ductility of low- and medium-carbon steels, but increases the brittleness of steel containing 1 per cent carbon. When the sulphur is more than 0.05 per cent copper appears to make the steel roll less easily and above 0.5 per cent of copper appears to make high-carbon steel draw less easily into wire.

**Arsenic.**—Some steels contain arsenic, which does not appear to have any effect when it is below 0.17 per cent, but any larger quantity raises the tensile strength and decreases the ductility to a very important extent.

**Oxide of Iron.**—All Bessemer and open-hearth steels contain more or less oxide of iron, there probably being more in basic steel than in acid, and more in Bessemer steel than in basic open-hearth steel. It is probable that this oxide of iron has not any very marked effect upon strength, as Campbell quotes some steels containing quantities larger than usual whose strength is good. No data are given as to the ductility, however, and it is probable that oxide of iron has a deleterious effect upon this quality.

#### HARDNESS AND BRITTLINESS OF STEEL

In this place we shall discuss only the question of rolled or annealed steel. By means of heat treatment we may greatly harden all but the low-carbon steels, but this hardness is lost on annealing. The effect of carbon on hardness, and the effect of the heat treatment known as "hardening," is shown from

the following table, taken from Howe, "The Metallography of Steel and Cast Iron, page 598.

TABLE XL.—INCREASE OF THE BRINELL AND SHORE HARDNESS WITH THE CARBON CONTENT

(Based chiefly on the data of Brinell and of Shore)

No.	Carbon content, per cent	Shore scleroscope hardness			Brinell or ball hardness		Ratio: Brinell ÷ Shore hardness	
		Condition of the metal			Condition of the metal			
		An-nealed	Normal merchant-able	Hard-ened	An-nealed	Hard-ened	An-nealed	Hard-ened
1	2.04 <sup>c</sup>	.....	.....	...	286 <sup>c</sup>	Cracked		
2	1.75	40-45	50-55	110				
3	1.72 <sup>d</sup>	.....	.....	...	286 <sup>d</sup>	477 <sup>d</sup>		
4	1.50	37-40	47-50	110				
5	1.25	35	44	110	262 <sup>f</sup>	627 <sup>f</sup>	7.5	5.7
6	1.00	30-35	40	107	259 <sup>a</sup>	627 <sup>a</sup>	7.4-8.6	5.9
7	0.80	28-30	38	105	235 <sup>a</sup>	648 <sup>a</sup>	6.7-7.8	6.2
8	0.66	.....	.....	...	202 <sup>b</sup>	578 <sup>b</sup>		
9	0.65	.....	..	...	235 <sup>f</sup>	652 <sup>f</sup>		
10	0.60	27	36	102	225 <sup>a</sup>	628 <sup>a</sup>	8.3	6.2
11	0.50	26	34	96	204 <sup>a</sup>	579 <sup>a</sup>	7.8	6.0
12	0.45	.....	.....	...	194 <sup>f</sup>	555 <sup>f</sup>		
13	0.40	25	32	90	175 <sup>a</sup>	478 <sup>a</sup>	7.0	5.3
14	0.35	24	30	82	156 <sup>f</sup>	402 <sup>f</sup>	6.5	4.9
15	0.30	23	28	70				
16	0.25	22	27	58	143 <sup>f</sup>	311 <sup>f</sup>	6.5	5.4
17	0.20	21	26	50	115 <sup>f</sup>	196 <sup>f</sup>	5.5	3.4
18	0.15	20	25	43				
19	0.10	19	24	35	97 <sup>f</sup>	149 <sup>f</sup>	5.1	4.4
20	0.05	18	23	25				
21	0.01 <sup>e</sup>	.....	.....	...	75 <sup>e</sup>	{ 107- 112		

For footnotes to Table XL, see original reference.

As a general thing the hardness and brittleness of steel increase together. The chief commercial application of this property is in such articles as railroad rails and car wheels, bevel- and spur-



gears, axles and bearings, the wearing parts of crushing machinery, etc.<sup>1</sup> To produce hardness in these materials carbon is the chief agent used, because it gives the maximum hardness with the least brittleness. It is for this reason that railroad rails are now made up to 0.7 per cent carbon, and although this material is somewhat brittle and breakages occasionally occur, the high carbon is demanded in order that the head of the rail may be durable. Phosphorus increases both the hardness and the brittleness, especially under shock. Manganese likewise increases hardness, and especially the kind of hardness which makes it more difficult and more expensive to machine the metal. With more than about 1 per cent of manganese the steel becomes somewhat brittle. When the content rises above 2 per cent the steel is so brittle as to be practically worthless. In this connection a curious phenomenon is observed, in that a still further increase in manganese produces a reversal of its influence, and when we have more than 7 per cent the metal is not only extremely hard and practically impossible to machine commercially, but becomes, after heat treatment, very ductile and tough. This will be considered more fully in Chapter XVI.

**Silicon.**—Silicon makes the steel slightly harder, but apparently without increasing its brittleness, unless we have more than 0.5 or 0.6 per cent.

### ELECTRIC CONDUCTIVITY OF STEEL

The purer the material and the nearer it is to ferrite, the better will be its electric conductivity; therefore only wrought iron, or the softest and purest forms of steel, are used generally for wire for electric conduits.<sup>2</sup> The case is somewhat complicated when we come to third rails for electric railroads, which have now become a very important industrial product, because so pure a material will be very soft and will rapidly wear away under the abrasion of the contact-shoes. To increase the hardness of these rails with the least decrease in electric conductivity, it is best to avoid nickel and manganese, which decrease electric conductivity in greater proportion than the other elements, and to obtain the hardness as much as possible from phosphorus, and not from

<sup>1</sup> I purposely omit here the consideration of such hardness as that produced in springs, cutting tools, etc., by heating the steel to a bright-red heat and plunging into water, as this will be discussed in Chapter XV.

<sup>2</sup> Omitting, of course, the use of copper.

carbon, because phosphorus will give the greatest amount of hardness with the least decrease in the purity of the iron. As high phosphorus steels are difficult to roll, however, the section of the rail chosen should be as free as possible from sharp corners and thin flanges, in order that the tearing action in rolling may be as slight as possible.

### MAGNETIC PROPERTIES OF STEEL

Alpha ferrite is the chief magnetic constituent of iron and steel, and therefore the greater the amount of this constituent present, the greater will be the magnetic force and magnetic permeability and the less its magnetic hysteresis. On this account the cores of electromagnets, the armatures of dynamos, etc., are commonly made of Swedish wrought iron, which is the purest commercial form of iron made.<sup>1</sup>

Ferrite has no permanent magnetism, but immediately loses its magnetic force when it is out of contact with a magnet, or, in the case of cores of electric magnets, when the electric current is cut off. Permanent magnets are therefore made of a high-carbon steel (1 per cent), whose strength and permanency are increased if about 5 per cent of tungsten is present. This steel is heated above the critical temperature and hardened in water, after which it is magnetized by causing an electric current to flow around it for a short time. Steel so treated will retain the magnetic force for many years. Osmond has explained the permanent magnetism of steel in the following very ingenious manner: Each molecule of alpha ferrite is believed to have a north and a south magnetic pole, which, in the ordinary unmagnetized condition of the iron, will be oriented in many different directions, as shown in Fig. 182. When this piece of iron is placed in the magnetic field, however, the molecules arrange themselves in accordance with the lines of magnetic force, with their north poles all in one direction and their south poles all in the opposite direction, thus making the whole piece of iron a magnet. As soon as the magnetic force is removed, however, the molecules all return to their original orientation, and the whole piece of iron loses its magnetism. We have already learned that it is only the alpha molecules which have north and south magnetic poles, and if

<sup>1</sup> A silicon alloy of iron with a double-heat treatment discovered by R. A. Hadfield, and having a very high magnetic force and permeability, will be discussed under the head of "Alloy Steels."

the steel consists entirely of beta or gamma molecules, it is not capable of becoming magnetic. According to Osmond's theory, when steel is cooled rapidly from above the critical temperature, the shortness of the time taken in reaching the atmospheric temperature is such that only a part of the molecules are able to change to the alpha allotropic form, and the remainder are retained in the gamma form. This retention is assisted by the 1 per cent of carbon present, which acts as a brake to make the change slower. When, now, this hardened steel is subjected to the magnetic force,




FIG. 182.—Iron in an unmagnetized condition.




FIG. 183.—Iron in a magnetized condition.

the alpha molecules orient themselves with their north poles all in one direction; but when the magnetic force is removed there is a certain number of gamma molecules present to interfere with the free movement of the alpha molecules and prevent them from returning to the original unoriented position. This explanation implies that the magnetic force is sufficient to overcome the resistance of the gamma molecules and force the alpha molecules into a magnetic position, but that the force of the alpha molecules tending to return to their original position is not so great.

The welding of steel and the effect of different elements upon it will be discussed in Chapter XV.

## CHAPTER XIII

### THE CONSTITUTION OF CAST IRON

Practically all the cast iron which is not purified is used for making iron castings, so that a study of the constitution of cast iron resolves itself into a study of iron castings. The difference between cast iron and steel is that the former contains less iron and more impurities, especially carbon, silicon, phosphorus, and occasionally sulphur and manganese. The advantages of cast iron, and the reason it is used as much as it is, are its fluidity, lesser amount of shrinkage when cooling from the molten state, relative freedom from checking in cooling, and the ease with which very different properties are conferred upon it at will. Its disadvantages are its weakness and lack of ductility and malleability. The last-named deficiency renders it practically impossible to put any work upon cast iron; hence it can never be wrought to shape and must always be used in the form of castings. Its most important advantages are probably its ready fusibility, which makes it so easy to melt and cast, and its cheapness.

**Graphite.**—All of the characteristic qualities of cast iron are due to the presence of the large amount of impurities in it. These impurities are the same in kind as the impurities in steel, and differ only in amount, with the single exception of graphite. This constituent is almost never found in steel, or is found in a very small number of cases, those cases being confined to the high-carbon steels, the amount of which is relatively very small. In cast iron, however, graphite is the largest and one of the most important constituents. It occurs in thin flakes, in sizes varying from microscopic proportions to an eighth of a square inch in area,<sup>1</sup> disseminated through the body of the metal and forming an intimate mechanical mixture, a magnified section of which is shown in Fig. 187.<sup>2</sup> Each flake of graphite is composed of smaller flakes, built up somewhat like the sheets of mica with which all are familiar, but with very little adhesion between the small component flakes, so that the sheet of graphite may be split

<sup>1</sup> In rare and unusual cases the flakes of graphite may be as much as  $1\frac{1}{2}$  to 2 sq. in. in area, but practically never so large in commercial cast iron.

<sup>2</sup> P. 361.



apart with very little force. Graphite is very light in weight, having a specific gravity of only about 2.25 as compared with a specific gravity of 7.86 for pure iron; consequently although the percentage of graphite by weight is only 4 per cent or less of the iron, its percentage by volume may be, in normal cases, as much as 14 per cent. This may readily be seen by noting the amount of space occupied by the graphite flakes in Fig. 190.

**Combined Carbon.**—We have already discussed the solidification and slow cooling of cast iron, and it will be remembered that all the carbon which does not precipitate as graphite forms first as austenite, which later decomposes into ferrite and cementite. In short, all the carbon in slowly cooled cast iron will ultimately be found partly in the form of graphite and partly in the form of cementite. The carbon of cementite in cast iron commonly goes under the name of "combined carbon," but it must be remembered that cementite is the constituent which gives the observed effects. Unless the cooling is very slow, some carbon will be in the austenitic or dissolved form.

**White Cast Iron.**—In slowly cooled white cast iron the carbon, amounting often to 3 or 4 per cent, will all be in the form of cementite, which will therefore form 45 to 60 per cent of the material (Fig. 185). Consequently white cast iron will possess largely the properties of cementite. It is very hard and brittle, being machined only with the greatest difficulty and with special kinds of cutting tools, and resisting wear by abrasion very effectively. It is so brittle as to be readily broken by the blows of a hammer, and is weak because of the presence of very large plates of cementite, which adhere but slightly to one another. Consequently white cast iron has few uses and is employed usually only as a hard surface on the outside of gray-iron castings.

**Gray Cast Iron.**—Gray cast iron may have about the same total amount of impurities present as white cast iron, the only difference then being that the carbon is partly or wholly precipitated as graphite. The gray color of a freshly broken fracture, from which this material receives its name, is due altogether to the graphite present, for this constituent is so weak that the iron breaks chiefly through its crystals, which are rent asunder, leaving one part sticking to each side of the fracture. The weakness of gray cast iron as compared with steel is thus readily understood, since there is but a small proportion of metallic surface to be broken and the graphite splits so easily.

An interesting experiment is to take a freshly broken surface of gray pig iron and brush one-half of it for some time with a stiff brush. In this way the adhering crystals of graphite are partially removed and we get a surface which is almost as white as the fracture of white cast iron. This shows clearly that the gray color is due altogether to the graphite and that the metallic part is as silvery white as iron itself. The prevalence of the gray color also shows how completely fracture takes place through the graphite crystals.

Gray cast-iron castings are by far the more important, and the study of their constitution is the chief object of this chapter. These castings usually contain 2 per cent or more of graphite and less than  $1\frac{1}{2}$  per cent of combined carbon. It will be observed that this limit of combined carbon is also the range found in steel. Furthermore, it will be observed that the graphite is not a chemical component of the metallic body, but is mechanically mingled with it. In this sense, therefore, we may consider gray cast iron as a very impure steel,<sup>1</sup> mechanically mixed with graphite, and upon this reasoning the study of its constitution becomes much simpler,<sup>2</sup> as we may study first the properties of the metallic part, and next that of the graphite, and so be able to foretell to some extent the properties of the mixture. Indeed, the properties of the metallic part are already understood pretty well from our knowledge of the constitution of steel, and there is no new constituent or new condition except the larger amounts of silicon and phosphorus, which are of minor importance, because their effect is collectively far less than the weakening and embrittling effect of the graphite. Even though we had a very pure metallic constituent, the strength and ductility of this portion would not be sufficient to prevent the mass as a whole breaking under a small load and without exhibiting any practical ductility, because of the weakening effect of the crystals of graphite. In other words, it is the carbon which is the great

<sup>1</sup> The silicon in gray cast iron is usually between 0.75 and 3 per cent or, let us say, 10 times that in steel, while the phosphorus is usually from 0.5 to 1.5 per cent, or, again, about 10 times or more that in steel. The sulphur varies greatly, but is not infrequently as high as 0.15 to 0.2 per cent. Manganese is an exception and is usually no higher in iron castings than in steel.

<sup>2</sup> This theory of the constitution, which meets with very favorable acceptance in many quarters, was independently evolved by J. E. JOHNSON, JR. *American Machinist*, 1900; and H. M. HOWE, *Trans. A. I. M. E.*, 1901, vol. xxxi, pp. 318-339.

factor in determining the properties of cast iron, for this may be either all graphitic, or all combined, or part in both conditions.

**Total Carbon.**—By running the blast furnace very hot, we may extend the saturation point of the iron for carbon and thus get a slightly higher total carbon. This is not a very potent influence, however, for we seldom have total carbon more than 4.5 per cent, or less than 3.25 per cent. This control, such as it is, may be exercised either during the manufacture of the pig iron or during the remelting in the cupola, because in the latter furnace the liquid iron is in contact with coke and will absorb carbon up to its saturation point at the existing temperature (see Fig. 165, p. 326, for carbon absorption at high temperatures).

**Rate of Cooling.**—A far more potent effect on the properties of the metal is the transfer of carbon from the graphitic into the combined form, or *vice versa*, by rapid or by slow cooling from the molten condition. It will be remembered that the carbon is always dissolved in the iron when the mass is in a molten condition, that is, when it is above the lines *AB* and *BD* in Fig. 165. As we cool from the molten state, graphite precipitates, but this cooling must be very slow indeed for this normal chemical change to take place completely. If, therefore, we cool with great rapidity, as, for example, by pouring the iron into a metallic mold which “chills” it, or by some other form of artificial rapid cooling, we may prevent the precipitation of graphite, by denying the time necessary for the chemical reaction, and obtain a metal in which all the carbon is in the combined form,<sup>1</sup> *i.e.*, white cast iron. It is also evident that, by a rate of cooling intermediate between this rapid rate and the slow rate which permits the precipitation of the normal amount of graphite, we may obtain an intermediate amount of carbon in the graphitic form. Rapid cooling is a very important means of “chilling” the surfaces of gray-iron castings, whereby we may have a relatively soft gray iron in the interior of each article and a hard surface. For example, chilled-iron rolls are made in this way (see p. 371), and also railroad freight car wheels<sup>2</sup> which are cast against an

<sup>1</sup> The term combined here is used to include chemical combination or solution.

<sup>2</sup> In some countries it is usual to have the car wheels made of steel, as it is believed that the iron wheels are not sufficiently strong and ductile. The manufacture of pressed-steel car wheels is increasing in America; nevertheless, the chilled cast-iron wheels seem to give very good service on freight cars.

iron chill (see p. 371), giving nearly an inch depth of white iron around the tread and flange where the metal is to suffer abrasion in grinding over the rails, while the web and bore will be of gray cast iron, because cooled more slowly in the sand part of the mold, and thus will be less brittle, and better able to withstand the shocks of service and may be machined easily.

### THE EFFECT OF CARBON ON CAST IRON

The nature and constitution of gray cast iron is far more difficult to understand than that of steel, and even greater is the difficulty of predicting the effect of any change in composition or in constituents. The chief reason for this complexity is that a change in any one of the constituents of gray cast iron is liable to effect changes in several others as well. The simplest example of this is in the case of the carbon; we have total carbon, graphite and combined carbon, and if we change any one of these three, we must change either one or both of the other two, and it makes a great deal of difference which. Indeed, we almost never change the amount of graphite without making the reverse change in the amount of combined carbon, and *vice versa*. Thus a very loose system of speaking of these matters has come into vogue among foundrymen. For instance, it is very common to hear a foundryman say: "In order to soften your iron, increase the graphite;" but what he really means is: "In order to soften your iron, decrease the combined carbon." He knows that the one change usually follows from the other, and he speaks of it in this way, regardless of the fact that graphite can be increased (*i.e.*, by increasing the total carbon and leaving the combined carbon the same or a little higher), and yet the iron will not be made any softer, but may even be harder.

**Graphite and Shrinkage.**—The most important effect of graphite on cast iron, aside from causing weakness, is in decreasing the shrinkage. The reason for this will be understood when we consider what happens when cast iron solidifies. It will be remembered that when the eutectic forms, the cast iron breaks up into alternate plates of graphite and austenite. This separation of graphite from solution is the birth of a new constituent, and this constituent occupies space, so that there is an expansion of the mass as a whole in proportion to the amount of graphite that separates. If, therefore, we pour liquid cast iron into a mold, which is, of course, entirely filled at the moment when the



iron begins to solidify, the first action that takes place after the beginning of solidification is an expansion, due to the separation of graphite. The expansion continues for several moments until the chemical precipitation is completed, after which the metal begins to contract, as all metals do in cooling from a high temperature; but the preliminary expansion has been so great that the ultimate shrinkage may be only about one-half what it otherwise




FIG. 184.—Shrinkage curves.

would have been. We can thus control this shrinkage by controlling the amount of the expansion, through varying the graphite. This point will be more readily understood by referring to Fig. 184, which is taken from an article by Prof. Thomas Turner of England.<sup>1</sup>

**Explanation of Fig. 184.**—The point *O* marks the position occupied by the end of the bars at the moment of solidification. It will be seen that in the case of copper the metal contracts con-

<sup>1</sup> *Jour. Iron Steel Inst.*, No. 1, 1906, p. 57.

tinuously from this point, as shown by the continuous drop of the curve. In the case of white cast iron, the metal contracts continuously until we reach a certain point (which is at a temperature of about  $665^{\circ}\text{C}.$ ), when a momentary arrest of the shrinkage takes place, after which the metal again contracts. This arrest is common to all cast iron and steel and marks the decomposition of austenite at the point *S*, Fig. 165, p. 326. Now, see what a difference there is in the case of gray cast iron, which does not shrink immediately after freezing, but expands very appreciably, as shown by the rise in the curve. This expansion is due to the graphite that is being expelled from the metal and occupies space between the particles of iron.

Again, in the case of the Northampton iron, which is high in both graphite and phosphorus, the expansion is very long-continued, and the metal cools to almost a black heat before the bar has shrunk again to the size it had when first cast. This expansion is again due to the separation of carbon, and is assisted apparently by the phosphorus keeping the iron in a semifluid condition for a long time and thus allowing the graphite more easily to separate and make place for itself. Here, too, we have an explanation why phosphoriferous irons fill every crevice of the molds so perfectly. Being in a pasty condition for some time, and continually expanding, the semifluid metal is forced into the tiniest crevices of the molds, filling all the corners with astonishing sharpness.

It is evident that any increase in graphite, whether caused by an increase in total carbon or by a decrease in combined carbon, will produce less shrinkage. The extent of this may be judged by noting that gray cast iron expands so much in solidifying that no pipe is formed, such as occurs in the case of only slightly gray, or if it is a very large slight spongy place may be formed in the nearest approach to a shrinkage cavity that most iron castings.

Porosity.—It is evident also that an increase produced by an increase in total carbon or combined carbon, will increase the porosity of the casting, which is often disadvantageous, as in the case of other receptacles for holding liquids under pressure. The presence of much graphite usually is accompanied by a large number of graphite crystals, and therefore the crystals

of the mass, as revealed by the fracture, appear large and the grain is said to be "open."

**Graphite and Workability.**—When we come to consider the effect of graphite upon the softness or workability of the cast iron, it is evident that we must consider it in relation to other things; for if we increase the graphite by increasing the total carbon, then we increase the workability of the metal only in so far as the graphite acts as a lubricant for the tool that is doing the cutting. Evidently the tool will have no difficulty in cutting through the soft flakes of graphite; the chief resistance to it will be given by the metallic part of the mixture. Though the lubricating effect of the graphite undoubtedly helps the tool, its presence evidently cannot increase the actual softness of the metallic body with which it is mixed. But, on the other hand, if we increase the graphite by decreasing the combined carbon, then we have not only increased the amount of lubricant, but we have, in addition, increased the softness of the metallic part of the mixture by reducing the proportion of cementite in it.

**Graphite and Strength.**—Everything else being equal, it is evident that the more graphite we have in cast iron, the weaker it will be, for we have already shown that gray cast iron breaks by the ready splitting apart of the flakes of graphite. Thus, if we make no change in the combined carbon, but increase the total carbon of our castings, and consequently the graphite, we should expect a corresponding decrease in strength, and this is in fact found to occur. When, however, we increase the graphite and at the same time decrease the combined carbon, we may or may not get an increase in strength, this depending altogether on how much combined carbon there was before and after the change. For example, if we had 3 per cent of combined carbon and 1 per cent of graphite in a casting, that casting would be weak because of too high combined carbon. To decrease this and increase the graphite would have a beneficial effect on strength. On the other hand, if we had 1 per cent of combined carbon and 3 per cent of graphite, to decrease the combined carbon and increase the graphite would have a detrimental effect on strength. We must therefore consider the question of strength from a much larger viewpoint than by considering any one constituent alone.

**Combined Carbon and Shrinkage.**—Combined carbon has very little effect on the shrinkage of cast iron except in so far as it

changes the graphite. That is to say, if by increasing the combined carbon we decrease the graphite, we will get an increase in shrinkage, and *vice versa*.

#### THE EFFECT OF SILICON, SULPHUR, PHOSPHORUS, AND MANGANESE ON PIG IRON

The constitution of cast iron is, furthermore, very complicated because of the double influence of silicon, sulphur, phosphorus, and manganese. Each of these elements has a direct influence upon the properties of the material, which is in general similar to its influence upon steel. For example, silicon produces freedom from oxides and blowholes and makes the iron more fluid; manganese counteracts the effect of sulphur and increases the difficulty of machining the material; sulphur makes the metal very tender at a red heat, and therefore liable to checking if put under strain during this period. For example, if a casting in shrinking tends to crush the sand, this strain will be more liable to break it in case the sulphur is high. Sulphur also makes solidification take place more rapidly, and causes blowholes and dirty iron. On the other hand, founders sometimes object to too low a content of sulphur on the ground that the iron is soft and low in strength. Phosphorus makes the metal very fluid and reduces its melting-point. It also makes it more brittle under shock, especially when cold, and produces a fusible eutectic, a photomicrograph of which is shown in Fig. 181, p. 336. Phosphorus and sulphur increase the tendency to segregate.

Furthermore, the various compounds of the impurities with iron and with each other, which we find in steel, are also found in cast iron. Indeed, some of them are far more important in the latter than in the former, because the amount of the impurities is greater. This is especially true of manganese sulphide and iron sulphide, for the sulphur in cast iron is often large in amount, while the manganese is often intentionally small on account of the difficulty which this element produces in the machining of the casting. Therefore we are even more liable to find iron sulphide in cast iron than in steel.

But the direct effect of these impurities is usually far less important than their indirect effect, namely, their influence upon the carbon. After all, it is the carbon which is the chief factor in controlling the most important properties of the cast iron, and we may vary this either by increasing or decreasing the total



amount, or else leaving the total amount the same, by increasing the graphite and decreasing the combined carbon, or *vice versa*. It is the ease with which we may vary the amount or the condition of the carbon, and therefore the properties of the iron, that is one of the most important advantages of the material. But, strangely enough, although it is easy to keep this control, it can never be accomplished in a direct way. It will be remembered (see pp. 29 to 32), that the blast-furnace manager can vary the amount of silicon and sulphur in his pig iron at will; that he has only a small control over the manganese and practically none over the phosphorus or carbon, but that the metal always saturates itself with this latter element; and it has also been seen (see p. 354) that the limit of this saturation is small.

**Silicon.**—By means of his control over the silicon and sulphur, the metallurgist exercises indirectly his most important control over the condition of the carbon; for silicon acts as a precipitant of carbon, driving it out of combination and into the graphitic form, so that with about 3 per cent of silicon, slow cooling and very low sulphur and manganese, we may obtain a cast iron in which almost none of the carbon is in the form of cementite. That is to say, the presence of this amount of silicon acts so strongly that it may partially prevent the formation of austenite during solidification, and also cause graphite to precipitate instead of cementite at 690°C. (1,275°F.) when the eutectoid decomposes (point S, Fig. 165, p. 326), so that it decomposes into ferrite and graphite instead of ferrite and cementite. The maximum precipitation of graphite seems to occur with about 2.5 to 3 per cent of silicon. With each increase of silicon up to that point (the amount of sulphur, the rate of cooling, and other influential conditions remaining the same), we get an increase in the amount of graphite precipitation, but when the amount of silicon exceeds about 3 per cent it seems to reverse its effects, and each addition of silicon thereafter causes an increase in the proportion, not of graphite, but of combined carbon. At this point large amounts of various iron silicides ( $\text{Fe}_2\text{Si}$ ,  $\text{Fe}_2\text{Si}_2$ , etc.) make their appearance. Then the color of a freshly broken fracture begins to be bright like a mirror, in contradistinction to the white color of ordinary white cast iron, which has more nearly the appearance of frosted silver (see Figs. 186 to 189).

**Sulphur.**—The influence of sulphur upon the formation of graphite is almost the exact opposite of the influence of silicon.




FIG. 185.—White pig iron. 0.75 per cent Si. 0.120 per cent S. 50 diameters. Unetched.




FIG. 186.—Gray pig iron. 0.75 per cent Si. 0.012 per cent S. 50 diameters. Unetched.




FIG. 187.—Gray pig iron. 1.75 per cent Si. 0.025 per cent S. 50 diameters. Unetched.




FIG. 188.—Gray pig iron. 2.5 per cent Si. 0.012 per cent S. 50 diameters. Unetched.




FIG. 189.—Gray pig iron. 3.5 per cent Si. 0.025 per cent S. 50 diameters. Unetched.




FIG. 190.—No. 2 charcoal pig iron very slowly cooled. 50 diameters.  $\text{HNO}_3$ .

That is to say, each increase in the amount of sulphur present increases the amount of combined carbon in the iron (see Figs. 185 and 186). It is usually considered that each 0.01 per cent of sulphur will neutralize 15 times as much silicon (*i.e.*, 0.15 per cent) in its effect upon the condition of the carbon in the iron. It is also very important to note that when the sulphur is in the form of MnS, it is not so potent in increasing the combined carbon as when it is in the form of FeS. An interesting example of this is shown in the analysis of the two railroad car wheels given in Table XLI.

TABLE XLI.—PROXIMATE ANALYSES OF CAST IRON CAR WHEELS

	Fe	Total carbon	Si	Mn	P	S	Graphite	Combined carbon
Good wheel...	94.79	3.84	0.69	0.13	0.43	0.12	3.30	0.54
Poor wheel...	95.00	3.52	0.65	0.12	0.52	0.19	2.35	1.17

Good wheel required 150 blows of 25-lb. sledge to break it. Poor wheel required 8 blows of 25-lb. sledge to break it.

TABLE XLII.—ULTIMATE ANALYSES OF CAST IRON CAR WHEELS

Constituent	Good wheel, per cent	Bad wheel, per cent
MnS.....	0.206	0.195
FeS.....	0.121	0.315
FeSi.....	2.045	1.923
Fe <sub>3</sub> P.....	2.755	3.335
Pearlite.....	67.610	84.492
Free ferrite.....	23.963	0.000
Free cementite.....	0.000	7.390
Graphite.....	3.300	2.350
Totals.....	100.000	100.000

It will be observed that the poor wheel has more than twice as much iron sulphide as the good wheel, although the sulphur in the poor wheel is only about 50 per cent more than the sulphur in the good wheel, the other impurities being nearly the same. When we come to figure out the amount of MnS and FeS in the

two wheels, we find, however, the explanation of the large amount of free cementite in the poor wheel. We also have an explanation of the poor quality of this wheel in the increased amount of FeS present,  $\text{Fe}_3\text{P}$ , and absence of ferrite.

**Manganese.**—Manganese increases the total carbon in pig iron. Manganese also increases the proportion of the carbon that is in the combined form, but its influence in this respect is far less than that of the sulphur; moreover, the statement requires the following qualification: As much manganese as is combined with sulphur in the form of MnS does not increase the proportion of carbon in the combined form. Indeed, it has really the reverse effect, because it takes the sulphur out of the form of FeS, in which it is most powerful in increasing the combined carbon. In this sense, therefore, the manganese actually decreases the amount of combined carbon.

The excess manganese over that necessary to form MnS (that is, the manganese in the form of  $(\text{FeMn})_3\text{C}$ ) increases the proportion of carbon in the combined form, and also increases the amount of total carbon even more potently than does the manganese which is in the form of MnS. We therefore have a strange contradiction, in that when the manganese is high an increase in sulphur will, by decreasing the amount of  $(\text{FeMn})_3\text{C}$ , actually decrease the tendency of manganese to raise the total carbon as well as the combined carbon. To sum up, manganese and sulphur both tend to increase the total carbon and the combined carbon, and yet they neutralize each other in this respect.

**Phosphorus.**—The effect of phosphorus upon the carbon is somewhat self-contradictory; from a chemical standpoint it tends to increase the proportion of combined carbon, and this is especially true when the silicon is low and the phosphorus high (say above 1.25 per cent). But phosphorus also has the effect of lengthening the period of solidification. That is to say, it makes the iron pass through a somewhat mushy stage of solidification, and this mushy stage lasts for several minutes. This lengthening of the solidification period gives a longer time in which graphite can precipitate. Therefore, when the silicon is relatively high (at least over 1 per cent), and there is consequently a strong tendency for graphite to precipitate during solidification, this precipitation is actually aided by the phosphorus, and the graphite occurs not only more abundantly, but in larger-sized flakes. When, however, the amount of phosphorus is very large,



its chemical effect is great enough to retain the carbon in the combined form, in spite of the long period of solidification. We may sum this up by saying that if the chemical conditions are such that graphite is bound to precipitate, then the physical effect of the phosphorus makes this precipitation the more easy; but if there is enough phosphorus present to produce a strong chemical effect of its own, or if the other chemical influence is not very powerful (*i.e.*, if the silicon is low or sulphur is high), then phosphorus tends to keep the carbon in the combined form.

#### THE PROPERTIES OF CAST IRON<sup>1</sup>

Let us now consider the properties of cast iron, and summarize under the head of each the influence of the various elements and conditions upon them.

**Shrinkage.**—The shrinkage of cast iron is of more importance than might at first appear, because the greater it is the greater will be the strains set up in the cooling of the casting, and consequently the liability to check; also, the greater will be the allowance necessary in order that the casting may be true to the size called for by the drawings. Graphite is the most important impurity in this connection, because of the expansion which its separation causes. This separation should take place at the moment of solidification, but is usually not complete then, and therefore the precipitation continues during the fall of the temperature to several degrees below the freezing point. Furthermore, when the silicon is high, graphite instead of cementite separates at the lower critical point (*i.e.*, the line *PSK* in Fig. 165, p. 326). As silicon, sulphur and the rate of cooling are the chief influences which control the separation of graphite, they become the governing factors in the shrinkage of the iron. Indeed, when sulphur is practically normal and no other unusual conditions prevail, there is such a close relation between the size of the castings<sup>2</sup> and the percentage of silicon on the one hand, and the amount of shrinkage on the other hand, that any one of the three may be calculated when the other two are known.

Sulphur is important in this connection, and its effect is contrary to that of silicon, because of its tendency to retain the carbon in the combined form. Manganese and phosphorus each has a less important influence. Manganese, by increasing the total carbon, tends to increase graphite and therefore decrease

<sup>1</sup> See Table XLVI, p. 373.

<sup>2</sup> Which is the chief influential feature in the rate of cooling.

shrinkage. So far as it neutralizes sulphur, moreover, its effect is in the same direction. Phosphorus decreases shrinkage, both because it contributes to the fluidity of the metal and therefore gives a better opportunity for carbon to separate, and also because of the expansion caused when the phosphorus eutectic separates from solution. A hotter casting temperature of the iron has the effect of increasing combined carbon.

TABLE XLIII.—RELATION OF SHRINKAGE TO SIZE AND PERCENTAGE OF SILICON

Per cent of silicon	$\frac{1}{2}$ in. square	1 in. square	2 in. by 1 in.	2 in. square	3 in. square	4 in. square	Perpendicular readings show decrease due to increase in silicon.
1.00	0.183	0.158	0.146	0.130	0.113	0.102	Horizontal readings show decrease of shrinkage due to size.
1.50	0.171	0.145	0.133	0.117	0.098	0.087	
2.00	0.159	0.133	0.121	0.104	0.085	0.074	
2.50	0.147	0.121	0.108	0.092	0.073	0.060	
3.00	0.135	0.108	0.095	0.077	0.059	0.045	
3.50	0.123	0.095	0.082	0.065	0.046	0.032	

A table showing the relation between the size of the casting, the amount of silicon, and the shrinkage, is given above. Slight changes must be made in this table by each foundry for the conditions of sulphur, phosphorus, temperature, etc., obtaining there; but those given herewith will be found sufficiently accurate for all ordinary purposes where conditions are near normal.

**Shrinkage Tests.**—At many foundries it is the custom to make a shrinkage test of the iron from each cupola at least once a day. The simplest way of making these tests is to pour into a mold 12 in. long, with a sectional area approximately proportionate to the size of the castings made, some of the iron from about the middle of the cupola run. The casting must be poured flat, and the difference between 12 in. and the length of the cold bar is the shrinkage of the metal. This method is somewhat crude and, although it gives valuable results, has been greatly improved by W. J. Keep and Prof. T. Turner,<sup>1</sup> who have devised simple and inexpensive pieces of apparatus whereby the iron, after it begins

<sup>1</sup> Reference on p. 356.

its solidification, draws a curve showing first the expansion and later the contraction. It is by means of Professor Turner's apparatus that the curves shown in Fig. 184, p. 356, were made. With very little care these curves can be obtained to show with sufficient accuracy for all ordinary purposes the percentage of graphite and also (other conditions being normal, or nearly so) the percentages of silicon and combined carbon, and the strength, hardness, and porosity. Indeed the curves are more useful than many single tests, because they show at a glance the net effect of several varying conditions.

**Density.**—The maximum density of gray cast iron occurs with about 1 per cent of silicon. With less than that, the iron is liable to contain spongy spots, due to high shrinkage on account of low graphite. With more silicon the separation of graphite decreases density. Above 2 per cent of silicon, the grain of the iron becomes so open as to be actually porous and the density falls off by 12 per cent.

TABLE XLIV.—DENSITIES

	Specific gravity	Weight per cubic foot
Pure iron.....	7.86	490
White cast iron.....	7.60	474
Mottled cast iron.....	7.35	458
Light-gray cast iron.....	7.20	450
Dark-gray cast iron.....	6.80	425
Sample of gray cast iron when cold.....	7.17	448
Same, when liquid.....	6.65	416

Phosphorus has a double-acting influence on the porosity of cast iron: (1) It increases the size of the crystals, decreases shrinkage and causes a large expansion after solidification, as explained in connection with Fig. 184; but (2) it fills all the crevices between the crystals and in the interior of the iron, which, by decreasing the porosity, counteracts its first influence. When the phosphorus is high, the phosphorus and iron form a eutectic, which remains fluid for a long time and fills the tiniest crevices in the interior of the metal. For this reason iron for hydraulic work may run up to 0.7 per cent phosphorus, but above that the iron is liable to be weak and "cold-short," especially under

impact. In fact, where very strong iron is desired, the phosphorus should be kept down to 0.4 per cent at most.<sup>1</sup>

With the various amounts of impurities mentioned above the combined carbon will be in the neighborhood of 1 per cent and the graphite about 2.5 per cent, the exact amounts depending upon the thickness of the castings and the rate at which they are cooled. If we desire to keep the combined carbon the same and reduce the graphite it will be necessary to reduce the total carbon. This can be accomplished by mixing in steel scrap and melting fast in the cupola, or by melting in an air furnace instead of a cupola. This reduction in graphite results in a closing of the grain of the steel, with consequent increase in strength and density.

**Segregation.**—A common cause of porosity in castings is segregation, or the collection together of impurities in spots. This segregation is the greater the greater the amounts of phosphorus, sulphur, manganese and silicon. Phosphorus increases the segregation by making a fluid eutectic, which does not solidify until after the remainder of the casting, but then runs into that part of the metal having the loosest texture. This part is usually in the middle of the larger sections of the casting, and when the silicon is high and there are shrinkage spots the segregation will be excessive in the neighborhood of these spots. Manganese and sulphur are also liable to collect in the same way and place. These localities, where the segregation is high, and which are known, when very bad, as "hot spots," are sometimes porous or surrounded by porous parts of the casting. They are sometimes so extremely hard that no tool will cut them. One way of getting rid of them is to use very large risers, or headers, which solidify last and serve as feeders for the remainder of the metal. Under these circumstances the segregation occurs in the riser, and is thus temporarily removed. This method is not advisable as a regular practice, however, because these risers ultimately find their way back into the cupola as scrap and result in increasing the impurities in a subsequent set of castings.

Headers themselves increase the density of iron castings by feeding the metal and so preventing the porous spots, and also by keeping the metal under a pressure during solidification. This latter is especially serviceable when the phosphorus is high, which tends to make the metal expand during solidification, as I have shown.

<sup>1</sup> See Table XLVI, p. 373.



**Checking.**—The time when a casting usually checks is when it is just above the black heat, when the metal is in a weak and tender condition and, as shown by Fig. 184, p. 356, is under strain because it is contracting upon the sand. Sulphur greatly increases weakness at this temperature, because both sulphide of manganese and sulphide of iron are now in a pasty condition and therefore offer very little resistance to breaking. The sulphide of iron is much worse, however, because this is spread out in thin plates or membranes which offer much more extended planes of weakness than the sulphide of manganese, which is in small spots or bubbles, resembling blowholes in its effect. Phosphorus, by decreasing shrinkage, decreases the liability of checking, but phosphorus has another influence, shown in the production of large-sized crystals, and in this respect it increases the liability of the metal to check.

Manganese, by decreasing the size of crystals, tends to counteract partially the effect of the phosphorus. The size of crystals can also be decreased to some extent by chilling the weak points and feeding them well under a head of metal. Feeding all localities liable to check has the double advantage of lessening shrinkage and segregation, both of which increase the liability to checking.

**Softness, Workability, and Strength.**—It is the combined carbon which is the great hardener of cast iron, the other elements producing hardness chiefly in proportion as they produce combined carbon, except manganese, which not only produces combined carbon, but also produces a compound having the formula  $(\text{FeMn})_3\text{C}$ , which is very hard and difficult to machine.

Silicon, by decreasing combined carbon, decreases hardness. When we get above 3 per cent silicon, however, there begin to form new compounds with silicon which make the iron hard. Furthermore, silicon above 3 per cent increases combined carbon, instead of decreasing it.

The maximum softness of cast iron is obtained with about 2.5 to 3 per cent of silicon, the sulphur being not above 0.1 per cent and the manganese not above 0.4 per cent. In large or slowly cooled castings the silicon should be near the lower limit, and in small or rapidly cooled castings near the upper limit, in order that the combined carbon may be down below 0.15 per cent and the graphite more than 3 per cent. Such a cast iron would correspond to a soft steel, mechanically mixed with crystals of graphite. This soft steel would machine with great ease,

and the graphite would act as a lubricant for the cutting tool. The mixture will have a transverse strength of about 2,000 to 2,200 lb., will be low in density and open in grain. To increase the strength without increasing the hardness, the best way is to cut the sulphur and phosphorus down to a low point, if possible, because sulphur, and next to it phosphorus, are the impurities which weaken iron most (aside from their influence on carbon). Another way is to decrease the total carbon, and hence the graphite, because graphite crystals, especially if large, are great weakeners of cast iron.

The strength of steel is more than double the strength of cast iron, the difference being due almost altogether to the graphite in cast iron, because silicon in itself (aside from its influence on the carbon) is a strengthener of both iron and steel up to at least 4 per cent.

To a slight extent the total carbon may be reduced by melting steel scrap with the iron, or by decreasing the amount of manganese, provided that the manganese left be always at least twice the sulphur, otherwise the iron will be weak and brittle.

The strength of cast iron may be increased by increasing the combined carbon, but this is done at the expense of softness and workability. Cast iron containing from 1.5 to 2 per cent of silicon (depending upon the size of the castings and rate of cooling), 0.9 per cent of combined carbon, 0.5 per cent of manganese and not more than 0.08 per cent of sulphur and 0.3 per cent of phosphorus will work without difficulty in the machine shop and have a tensile strength of over 28,000 lb. per square inch. In many cases foundries are unwilling to go to the expense of such a low sulphur and phosphorus. In this case the strength must be obtained by raising the manganese, which is not advisable, as it decreases the softness more than any other element, causes dull iron and high total carbon.

An important point in connection with the strength of cast iron is the size of the crystals of graphite—the smaller these crystals are the greater the strength, because the smaller are the planes of easy rupture. A notable example of this is malleable cast iron, which may have a tensile strength of 50,000 lb. per square inch, even when the percentage of graphite or temper carbon is as high as 3 per cent. The very small sized flakes of the temper carbon do not reduce the strength as much as the same amount of the larger graphite crystals.

It is believed by many that smaller graphite crystals are obtained by mixing different brands of iron in the cupola, even though the analysis of the mixture may be the same. This, however, is denied by others, and no reliable data exist upon which we can base a definite statement. It is also believed by many that when the silicon is added to the cast iron immediately before pouring into the molds, the crystals of graphite are smaller than those formed when high-silicon irons are melted in the cupola. The practice of adding a small amount of ferrosilicon to the ladle of cast iron after it is received from the cupola is thus said to be doubly advantageous, because the silicon does not have to go through the cupola, where it suffers some oxidation, and it produces the desired softness by precipitating the graphite, but in a form which does not decrease strength so much.

TABLE OF CAST-IRON STRENGTH AND WORKABILITY

	Sili- con, per cent	Sul- phur, per cent	Phos- phorus, per cent	Man- ganese, per cent	Tensile strength, pounds	Trans- verse strength, pounds
Soft iron for pulleys, small castings, good tooling.....	2.20 to 2.80	Not over 0.085	Not over 0.70	0.30 to 0.70	28,000	2,200
Medium iron for en- gine cylinders, gears, etc.....	1.40 to 2.00	Not over 0.085	Not over 0.70	0.30 to 0.70	30,000	2,500
Hard-iron cylinders for ammonia, air- compressors, etc..	1.20 to <sup>1</sup> 1.60 to <sup>2</sup> 1.90	Not over 0.095	0.70 to 0.40	Not over 0.60	25,000	2,800

<sup>1</sup> If annealed.<sup>2</sup> If cooled fast.

To obtain high transverse strength, the silicon should be about 0.2 per cent lower and the combined carbon about 0.2 per cent higher than the figures given for tensile strength. Otherwise the effects are very similar.

**Chills.**—In the making of cast-iron rolls, railroad car wheels, anvils, etc., at least one surface of the casting is desired to have great hardness, to resist wear, and to be backed by metal which shall be stronger and not so brittle. This is accomplished by chilling the surface which it is desired to harden, and so producing white cast iron to varying depths, regulated at the will of the foundrymen. The making of this kind of casting is one of the most difficult problems of cast-iron metallurgy. The




FIG. 191.—Method of measuring the depth of clear chill in a cast-iron roll.

metal must be very close to the given composition, and the temperature of the mold, of the chill, and of the metal when cast must be regulated with care. Therefore, air furnaces<sup>1</sup> are often employed for melting in this class of work, or else uniform conditions of cupola melting are maintained with great care, and very little, if any, scrap which must necessarily be of somewhat uncertain analysis is used, except the return scrap from the foundry itself, that is, defective castings, sprues, gates, shot-iron spillings, etc., and also scrap castings of like nature, such as

<sup>1</sup> See p. 379.



worn-out car wheels and broken rolls. The most important factors in regulating the depth of the chill are the silicon and the sulphur, and in the following table is given the depth of clear chill from the surface for several different percentages of silicon and sulphur. The figures here given must only be taken as approximations, as they will vary to an important extent with different conditions in each foundry; but, starting with this as a basis, one can quickly prepare a table for himself to suit the practice in his foundry. Phosphorus has very little effect on the depth of chill, and manganese is also relatively less effective, although it increases the hardness of the chilled portion. The hotter the iron when cast the deeper the chill.

TABLE XLV.—DEPTH OF CLEAR CHILL FROM SURFACE IN INCHES

Silicon, per cent	Sulphur, 0.2 per cent	Sulphur, 0.15 per cent	Sulphur, 0.1 per cent	Sulphur, 0.075 per cent	Sulphur, 0.05 per cent
1.25	0.625	0.250	0.125	0.000	0.000
1.00	1.000	0.625	0.250	0.125	0.000
0.75	1.500	1.000	0.625	0.250	0.125
0.50	.....	1.500	1.000	0.625	0.250
0.40	.....	.....	1.250	1.000	0.625
0.30	.....	.....	.....	1.500	1.000

**Casting Temperature of Iron.**—The strength of cast iron is materially affected by the temperature at which it is cast. Langmuir found that the tensile strength of iron, when cast too hot, was 33 per cent less, and when cast too cold was 26 per cent less than the same metal cast at the correct temperature. For the cast iron with which he experimented, the correct temperature of casting seemed to be in the neighborhood of 1,230°C. (2,246°F.).

**Recommended Analyses.**—Dr. Richard Moldenke,<sup>1</sup> from a wealth of experience in making iron castings in a consulting capacity, suggests the percentages given in Table XLVI.

<sup>1</sup> *Proc. Am. Soc. Mech. Engs.*, 1920, Vol. 42, p. 170.

Castings	Light				Medium				Heavy						
	Si	Mn	S	P	T.C.	Si	Mn	S	P	T.C.	Si	Mn	S	P	T.C.
Acid-resisting.....	2.00	0.75	0.05*	0.20*	3.25*	1.50	1.25	0.05*	0.20*	3.25*	1.00	1.25	0.05*	0.20*	3.25*
Agricultural.....	2.50	0.60	0.06	0.75	3.75	2.25	0.70	0.08	0.70	3.50	2.00	0.80	0.10	0.60	3.25
Air cylinders.....	1.90	0.70	0.08	0.50	3.40	1.50	0.80	0.09	0.40	3.25	1.00	0.90	0.10	0.30	3.00
Annealing boxes.....	2.25	0.65	0.08*	0.40*	3.25*	2.00	0.20	0.08	0.20	3.50	1.50	0.80	0.10	0.30	3.00
Automobile cylinders.....	2.25	0.65	0.08*	0.40*	3.25*	2.00	0.75	0.08*	0.40*	3.25*	1.50	0.50†	0.15*	0.40*	3.75*
Balls for grinding.....	2.00	0.70	0.08	0.60	3.75	1.75	0.75	0.10	0.50	3.50	1.50	0.80	0.12	0.40	3.25
Bedplates.....	.....	.....	.....	.....	.....	2.00	0.80	0.06*	0.20*	3.50*	.....	.....	.....	.....	.....
Boiler castings.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	0.65	0.50	0.08	0.35	3.50
Car wheels.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	1.00	0.06*	0.20*	3.50*
Chilled castings.....	.....	.....	.....	.....	.....	1.00	0.50	0.05	0.20	3.00	.....	.....	.....	.....	.....
Chills.....	.....	.....	.....	.....	.....	1.00	1.00	0.04	0.20	3.00	0.80	1.25	0.06	0.20	3.25
Crusher jaws.....	.....	.....	.....	.....	.....	1.50	0.60	0.05	0.20	3.00	1.25	0.80	0.06	0.20	3.25
Dies for hammers.....	2.50	0.50	0.05	0.75	3.75	2.75	0.50	0.05	0.50	3.50	2.15	0.50	0.06	0.50	3.25
Dynamo castings.....	3.00	0.50	0.03	0.60	3.75	2.75	0.50	0.05	0.50	3.50	1.75	1.00	1.10	0.40	3.00
Electrical work.....	.....	.....	.....	.....	.....	2.00	0.60	0.08	0.50	3.50	.....	.....	.....	.....	.....
Engine frames.....	.....	.....	.....	.....	.....	2.00	0.80	0.06	0.20	3.25	1.25	0.70	0.08	0.30	3.25
Fire pots, grates.....	2.25	0.60	0.05	0.20	3.50	2.00	0.80	0.06	0.40	3.25	1.25	0.70	0.08	0.30	3.25
Flywheels.....	2.00	0.50	0.05	0.50	3.50	1.50	0.60	0.06	0.20	3.50	1.25	0.70	0.08	0.30	3.25
Friction clutches.....	2.40	0.60	0.10	0.70	3.75	2.00	0.70	0.12	0.50	3.50	1.25	0.70	0.08	0.30	3.25
Furnace castings.....	2.40	0.60	0.05	0.60	3.75	2.15	0.80	0.06	0.50	3.50	1.25	0.70	0.08	0.30	3.25
Gas-engine cylinders.....	2.00	0.70	0.08	0.40	3.25	1.50	0.80	0.09	0.30	3.00	1.25	0.90	0.10	0.20	2.85
Gears.....	2.25	0.60	0.08	0.70	3.75	2.00	0.80	0.09	0.60	3.50	1.50	1.00	0.10	0.50	3.25
Glass molds, pipe balls.....	.....	.....	.....	.....	.....	2.50	0.60	0.04	0.20	3.25	.....	.....	.....	.....	.....
Grate bars.....	.....	.....	.....	.....	.....	2.00	0.60	0.05	0.20	3.50	1.00	0.60	0.05	0.30	3.00
Gun iron.....	.....	.....	.....	.....	.....	1.50	0.50	0.05	0.30	3.25	.....	.....	.....	.....	.....
Hardware.....	2.50	0.70	0.08	0.80	3.75	2.00	0.80	0.06	0.20	3.25	1.50	1.00	0.06	0.20	3.00
Heat-resistant iron.....	.....	.....	.....	.....	.....	1.50	0.80	0.05	0.40	3.25	1.00	1.00	0.08	0.20	2.85
Hydraulic cylinders.....	.....	.....	.....	.....	.....	1.50	0.80	0.05	0.40	3.25	1.25	0.80	0.06	0.20	3.75
Ingot molds.....	.....	.....	.....	.....	.....	2.00	0.80	0.06	0.20	3.25	1.50	1.00	0.10	0.50	3.25
Machinery castings.....	2.50	0.60	0.08	0.70	3.75	2.00	0.80	0.09	0.60	3.50	1.25	0.80	0.10	0.50	3.25
Mine wheels.....	.....	.....	.....	.....	.....	0.90	1.00	0.10	0.20	3.00	.....	.....	.....	.....	.....
Ornamental castings.....	2.75	0.60	0.06	0.90	3.75	2.25	0.70	0.08	0.80	3.50	1.50	1.00	0.10	0.60	3.50
Pipe (water).....	2.25	0.60	0.06	0.80	3.75	2.00	0.80	0.08	0.70	3.50	1.50	1.00	0.10	0.60	3.50
Piston rings.....	2.00	0.70	0.05	0.60	3.50	1.75	0.80	0.06	0.50	3.25	1.50	1.00	0.10	0.60	3.50
Pulleys.....	2.40	0.50	0.05	0.70	3.75	2.15	0.60	0.07	0.60	3.50	1.90	0.70	0.09	0.50	3.25
Radiators.....	2.25	0.70	0.06	0.80	3.50	2.15	0.60	0.07	0.60	3.50	1.90	0.70	0.09	0.50	3.25
Rolls (chilled).....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....
Soft castings.....	2.60	0.50	0.06	0.60	3.75	2.40	0.80	0.06	0.40	3.25	.....	.....	.....	.....	.....
Soil pipe.....	2.25	0.60	0.08	0.80	3.75	2.00	0.80	0.10	0.60	3.50	1.25	1.00	0.10	0.30	3.50
Steam cylinders.....	2.00	0.60	0.08	0.50	3.50	1.60	0.80	0.09	0.40	3.50	1.25	1.00	0.10	0.30	3.50
Stove plate.....	2.50	0.50	0.06	1.00	3.75	2.25	0.60	0.08	0.80	3.50	1.25	1.00	0.09	0.30	2.85
Valves.....	2.25	0.60	0.07	0.50	3.25	1.75	0.80	0.08	0.40	3.00	1.25	1.00	0.09	0.30	2.85
White iron castings.....	.....	.....	.....	.....	.....	0.75*	0.20†	0.25*	0.75*	2.50†	.....	.....	.....	.....	.....

\* Below. † Above

## CHAPTER XIV

### MALLEABLE CAST IRON

Malleable cast iron has physical properties between gray iron and steel castings. Its tensile strength will vary between 50,000 and 60,000 lb. per square inch with an elongation of 10 to 15 per cent in 2 in. and a reduction of area of 5 to 12 per cent.<sup>1</sup> In a transverse test, a 1-in. square bar on supports 12 in. apart should bear a load at the center of at least 3,000 lb. with a maximum deflection of  $\frac{1}{2}$  in.; the maximum load may go as




FIG. 192.—Test lug for malleable cast iron.

high as 5,000 lb. and the deflection up to 2 in. or more. In respect of its resistance to repeated stresses and to blows which flatten the face of the material without extending their influence very deep, malleable cast iron is especially valuable. It also has malleability and (when very thin) is capable of being flattened out or bent double without cracking. A good test for malleable cast iron is the so-called test lug shown in Fig. 192. These are bent over in the form of a curled-up shaving by light blows of a hammer, beginning at the knife edge. The distance along the test wedge that

the piece will bend before it begins to break, and especially the maximum angle produced, will give a good idea of the softness.

Malleable iron castings are used very largely for railroad work. They have long been used for couplers, but are now being replaced to some extent by steel castings for this purpose. On the other hand, malleable cast iron is replacing gray cast iron for other parts, such as journal boxes. Malleable cast iron is also used very largely for parts of agricultural machinery, for

<sup>1</sup> In the case of iron very carefully melted and annealed in iron oxide, the elongation and reduction of area may exceed these figures.

pipe fittings—*i.e.*, elbows, unions, valves, etc.—for household and harness hardware and a great variety of work where many castings are to be made of the same pattern, especially castings of small size. Even hammers, hatchets, skates, wood chisels, etc., are often made of “black heart” malleable cast iron.

**Process of Manufacture.**—The process, which was invented by Réaumur in 1722, but has only been in practical use about 100 years, and of importance less than 50, is still followed out in substantially its original form in England and Europe to

make what is known as “white heart” malleable castings. In America this process has been modified to make the so-called “black heart” castings, as follows: The metal is melted and cast into molds of the desired shape and size, and after cooling its fracture will be entirely white, or else white with a small area of mottled iron in the center of pieces 1 in. thick or heavier. In short the composition of the metal is such that it is just on



FIG. 193.—Annealed malleable cast iron. Magnified 50 diameters. Unetched.

the line between the precipitation of graphite and its retention in the form of cementite and dissolved carbon. In all cases the majority of the carbon must be dissolved or combined. After careful cleaning, the castings are reheated to a temperature of 625 to 875°C. (1,250 to 1,600°F.), which is roughly 450°C. below their melting-point. They are kept at this temperature for some 60 hr. and under these conditions occurs the precipitation of graphite, which normally should have occurred during the first cooling. In the majority of cases almost all the combined carbon throughout the body of the casting is changed to graphite. But the graphite does not here form in flakes, as in ordinary gray cast iron, but in a finely comminuted condition, like a powder, to which the name of “temper carbon” or “temper graphite” is given (see Fig. 193). In this form it is not nearly so weakening or embrittling to the casting as flakes of graphite would be.<sup>1</sup>

<sup>1</sup> We may liken this to two samples of putty, in one of which had been embedded a large number of plates of mica, and in the other the same amount of mica ground to powder.



A broken fracture of such an annealed casting will have a black center with a rim of white,  $\frac{1}{64}$  to  $\frac{1}{16}$  in. thick around the outside. The dark center owes its appearance to the precipitated temper carbon, and the white outer rim consists of iron from which the carbon has not been only precipitated, but actually removed.<sup>1</sup> That is, the metal of this outer rim corresponds to a soft steel impregnated with a great number of tiny cavities formerly occupied by carbon and which act as a cushion to shocks and battering blows of service. This outer rim is the portion of the casting in which the metallic crystals have formed perpendicularly to the cooling surface as explained on p. 213. The crystalline form in this location favors the reaction for the mechanical removal of carbon which will be explained later.

**The Manufacture of Réaumur, or White Heart Malleable.**—In the original, and present European, process of making malleable castings, they are made very thin; they are then annealed at the higher temperatures given above and for a period nearly twice as long, with the result that the conditions described above as prevailing in the outer rim extend here throughout the entire casting. In short, the carbon is mechanically removed, even from the center portion. White heart castings are not as strong as black heart and rarely, if ever, are above  $\frac{1}{2}$  in. in thickness.

**Manufacture of All-black Castings.**—In America pipe fittings and other castings not requiring much strength are sometimes annealed in lime, fire-clay, or some other substance which decarburizes only a thin skin of the metal. This results in the carbon being deposited as temper carbon, but not being removed. The castings are several thousand pounds per square inch lower in tensile strength, and have substantially no white rim.

**Iron Used.**—The analysis of the “hard castings,” that is, the white castings before the annealing process, should run as in Table XLVII. This analysis is obtained by mixing pig iron with varying amounts of cast iron and steel scrap.

Not more than about 20 per cent of bought scrap is used on the average in American practice, and a good deal of this is steel, on account of the desirability of lower total carbon, and because iron scrap is too impure, too variable, and too uncertain in sampling and chemical analysis for castings requiring strength, such as those for railroads and machinery. There is, however, always

<sup>1</sup> By the material in which they are packed according to the following reaction:  $3C + Fe_2O_3 = 3CO + 2Fe$ .

TABLE XLVII.—ANALYSES OF “HARD CASTINGS” FOR MALLEABILIZING

	If melted in cupola	If melted in air furnace or open hearth
Silicon, per cent.....	0.75 to 1.25	0.45 to 1.00
Manganese, per cent <sup>2</sup> .....	0.20 to 0.60	0.20
Phosphorus, per cent <sup>1</sup> .....	under 0.225	under 0.225
Sulphur, per cent <sup>1</sup> .....	0.04 to 0.30	0.04 to 0.07
Total carbon, per cent.....	about 2.75	about 2.75

<sup>1</sup> In European practice the phosphorus and sulphur are often much higher than this.

<sup>2</sup> The manganese must be at least twice the sulphur.

a large amount of “return scrap” from the foundry, consisting of defective castings, sprues, gates, etc., which, in the case of small castings, may be greater in weight than the castings themselves. This return scrap is low in total carbon and silicon and high in sulphur, as a result of having already suffered the melting changes. Steel scrap is, of course, a prime factor in reducing the total carbon. The return scrap should all be cleaned from adhering sand to avoid difficulty in melting. The pig iron bought for malleable-iron work is known in the trade under the name of “malleable Bessemer” (see p. 37).

**Silicon.**—The proportion of silicon will depend upon the size of the casting and the amount of total carbon, because the greater each of these is the less will be the amount of silicon that will cause a precipitation. Furthermore, cupola metal requires more silicon by about 0.25 per cent than air furnace metal because of the difficulty with which it yields to the annealing operation. It might at first appear that the less silicon the better; but this is not altogether so, because temper carbon will not come out during annealing unless a certain amount of silicon is present; and the more there is the more quickly, easily, and completely will the precipitation occur. For air-furnace castings 1 in. thick the silicon may be as low as 0.35 per cent; but this is unusual, as  $\frac{3}{4}$  in. thickness is rarely exceeded. For  $\frac{1}{2}$ -in. castings the silicon will be about 0.90 per cent, and for very thin and light castings with low total carbon and high sulphur (say 0.2 to 0.3 per cent), the silicon may be up to 1 per cent. To the percentage of silicon desired in the castings, we must add

the amount which will be burned out in melting. In the cupola this will be about 0.2 to 0.25 per cent, and in the air furnace from 0.15 to 0.5 per cent, depending on the length of time the metal is kept in the furnace after melting. The hotter we want the iron, the longer this time must be, and therefore the higher the silicon in the original mixture charged.

**Sulphur.**—Sulphur increases the tendency of castings to check, which is especially important in malleable work on account of the contraction of white iron being nearly double that of gray iron. Sulphur also reduces the strength and the ease of annealing. For this reason over 0.06 per cent should not be permitted in castings requiring strength, but it actually runs up to 0.2 and 0.3 per cent in inferior metal, both in America and England, and especially in small castings, which do not need strength so much, and which, having less length for contraction, are not so liable to be checked by cooling strains.

**Manganese.**—Low manganese is preferred by many foundries, and one of the highest authorities in America places the limit at 0.3 per cent. It should be remembered, however, that the manganese should be at least twice the sulphur, and preferably three times, except when the sulphur is as high as 0.3 per cent. Manganese of 0.5 per cent tends to decrease checking. It also protects silicon from oxidation, both during melting and annealing, and on this account hastens and makes more complete the precipitation of temper carbon. It also protects the iron itself from oxidation during annealing and thus prevents the formation of "scaled" castings. More than 0.6 per cent manganese makes the iron hard and difficult to machine, which is disadvantageous, especially for pipe fittings, which must be threaded with great economy in order to meet the trade competition. It also makes the castings difficult to anneal.

**Phosphorus.**—Phosphorus makes the metal fluid, which is especially desirable where total carbon and silicon are low, or where sulphur and manganese are high. On the other hand, it diminishes two of the most valuable properties of the material: Its malleability and resistance to shocks. It also makes the metal hard, difficult to machine, and liable to check, and amounts over 0.225 per cent should never be permitted by engineers where the castings are subjected to strain.

**Total Carbon.**—Total carbon below 2.65 per cent gives trouble in annealing and therefore makes the castings weak. It also

makes the metal more sluggish. In air furnace practice the total carbon may be reduced as much as necessary, but it is difficult to keep carbon out of iron in cupola melting. By mixing in large percentages of steel scrap and allowing the metal to run from the cupola as fast as melted, we may get total carbon slightly below 3 per cent. The annealing process also removes carbon, even in the interior of thin castings. The lower the total carbon in annealed castings, the better the quality.

**Melting in the Air Furnace.**—The commonest melting furnace for malleable cast iron is the air furnace. After the metal is melted it is retained in this furnace for 15 min. to 1 hr. longer, and test ingots are poured at intervals, from the fracture of




FIG. 194.—Air furnace.


which and the temperature of the iron we determine the correct moment for tapping. The fracture of the test plug should be a clear white throughout, except when the castings are to be of very light section, in which case the metal might be tapped when the test sample shows a few specks of graphite in the center. The practice of judging from test plugs is different in each foundry, but there must be some system which insures that the metal shall be of such a composition when tapped that the castings will have not more than a trace of graphite if any at all (say, less than 0.15 per cent in small castings and a little more in larger ones). If more than this the annealed castings will be very weak, almost "rotten."

The diameter of the test plug should be at least as large as any section of casting that is to be poured. The usual size is  $1\frac{1}{2}$ -in. diameter.

**Air Furnace.**—The air furnace is a reverberatory furnace on the hearth of which pig iron is melted by radiation from the flame



of a soft-coal fire, or, more rarely, from a gas flame. The furnace is charged by means of a large side door, or by removing the roof in sections bound together with iron, or by taking out the end;



FIGS. 195 and 196.—Air-furnace.

and in some cases, to effect an economy in labor, mechanical devices are employed for charging. Several designs of air furnaces are shown in Figs. 194 to 202 inclusive.





FIG. 197.—Air furnace with bungs and forced draft.

**Lining.**—The lining of the bottom is made of silica sand of about the same composition as the acid open-hearth furnace, *i.e.*, containing 95 per cent or more of silica, with just enough

lime to frit the mass together at the heat of the furnace. A layer about 1 to 2 in. thick is spread all over the hearth and then set



FIGS. 198-202.—Details of air furnace.

on as described in the chapter dealing with the open-hearth process. About five layers are put on in this way, and the bottom lasts on an average of 6 to 12 heats, although some foundries

regularly make up a bottom after the third heat; and in other cases the bottoms last as many as 30 heats. Longer life will be obtained if the material is charged carefully so as not to break the sand, and if a strongly reducing flame is maintained during the melting period, when there is not a bath of liquid iron to protect the bottom from the corrosive iron oxide. Mixing broken fire bricks of good quality and refractoriness with the sand seems to give more durable bottoms.

**Charging.**—The sprues and small scrap are first charged and spread evenly over the hearth and next the pig iron is piled in carefully. The roof of the furnace not being high, the pig iron must be stacked in order to get the necessary amount into the available space. Moreover, when the pig iron is stacked, individual pigs can be pushed down into the liquid bath from time to time so that it will not all melt together. Thus it can be handled more easily and the slag comes up better. The steel scrap is charged after the pig and scrap is melted and the slag has come up. This prevents the steel scrap from being oxidized.

**Conduct of the Operation.**—The purpose of the furnace is to melt the iron and bring it to the proper temperature for casting. Some refining by oxidation is unavoidable, but this is not an intentional feature and the object should be to get the desired analysis by mixing pig iron, scrap, and steel, and not by the oxidation of silicon and carbon. A long time in the furnace after melting is especially to be avoided, as the iron is liable to be oxidized and the silicon reduced below the desired point, making the iron "high." After the slag is up it should be skimmed off, and this may be repeated once or twice. When the test plug shows large, clear, white crystals without any pin holes on the rim, and only a slight amount of mottling, the bath is ready to tap. If there are pin holes in the rim of the test plug it indicates that the metal has been "burned," as it is called. It will usually be dull and there may even be gas in the metal, in which case the iron should be poured into pigs and used over again in small amounts in subsequent heats. If the test plug is mottled, it shows either that the silicon is too high or that the temperature is not high enough, for it will be remembered that the colder the iron the more likely is graphite to separate and *vice versa*. If the iron is too "high," on the other hand, some ferrosilicon should be added and rabbled into the bath. The smaller the castings,

the more rapidly will they be chilled and therefore the more silicon should we have in the metal.

American furnaces usually vary in size from 10 to 45-ton capacity, but they are built as small as 3 tons. It takes from about  $3\frac{1}{2}$  to 9 hr. to melt down a charge of from 5 to 35 tons respectively, and the waste of metal by oxidation will be about 2 to 5 per cent of the charge. The fuel used should be a good grade of bituminous coal, and the amount about one-fourth of the weight of the charge.

**Tapping the Charge.**—The more rapidly the metal can be gotten out of the furnace and poured, the more uniform will be its composition. Moreover, the metal at the top of the bath is hotter than that at the bottom. For this reason, in many furnaces, there are additional tap-holes at a higher level, which are opened first, and also holes on both sides of the furnace which are used simultaneously.

**Cupola vs. Air-furnace Melting.**—Cupolas used for melting malleable cast iron are similar to those already described but the amount of fuel is larger than for most gray-iron work on account of the higher melting-point of the iron and the very small size of castings into which it is usually poured. The fuel ratio will be about one of coke to four of iron.

The advantages of the cupola for malleable cast-iron work are: (1) That we get metal having practically the same composition at all times of the heat except the slightly higher sulphur at the beginning and end; (2) the temperature is more uniform throughout the heat; (3) it is cheaper to install and operate and requires less skill for melting labor; (4) it can be started and stopped more readily; (5) we can get hotter iron without prolonging the heat with the resultant danger of burning which exists in the air furnace.

The advantages of the air furnace are: (1) That there is not so much sulphur absorbed; (2) with proper manipulation there is not so much liability for the metal to be burned except just at the thin edge of metal near the fire bridge; (3) the metal anneals more easily and is stronger; (4) it is also easier to get a lower total carbon by proper mixing since there is no contact between coke and iron, and therefore not so much opportunity for absorption of carbon; (5) we can work closer to a desired analysis in the air furnace than we can in the cupola.

This latter circumstance, as well as the lower sulphur, is the reason why air furnaces are so largely used also for melting what



is known as chilled iron castings, such as rolls, etc. The analysis of this chilled iron must be so closely confined within limits that the outside may be white iron where it comes in contact with metallic chills and the interior consist of gray cast iron.

The explanation of the more difficult annealing experienced with cupola metal over air furnace and open-hearth metal has never been made entirely clear. In general, cupola metal is high in sulphur which opposes annealing, but it is believed that even when the metal is of the same analysis in sulphur it requires at least 150°F. higher temperature to anneal it. Another circumstance in cupola metal is that it is usually higher in total carbon. Consequently the carbon must be more strongly held in combination to prevent some of it precipitating as graphite in the hard castings. This condition may cause it to yield less completely to the annealing process.

**Open-hearth Furnaces.**—Open-hearth furnaces of small size, but in other respects like the open-hearth steel furnaces, are used for melting iron for malleable castings in a few important foundries in the United States. The great drawback of this furnace is that it should be operated continuously, day and night, which means more floor space on which to set molds ready for pouring, because molding cannot well be done during the night, as the artificial light casts shadows that make the work of finishing up molds more difficult and confusing.

The advantage of the regenerative open-hearth furnace over the air furnace is better control of the operation, and especially of the temperature, shorter heats, and greater fuel economy. The average time of melting in the open-hearth furnace will be 2½ hr. for a 10-ton heat, and 4 hr. for one of 20 tons. The amount of fuel is about 300 to 350 lb. per ton of iron, or twice as much if melting only on the day turn. The lining will certainly last much longer on account of the better control of the character of flame. Moreover, oil can be used for melting in a regenerative furnace, because it is introduced into a very hot atmosphere, which is not practicable in the air furnace, since the fuel condenses in the cooler atmosphere of this furnace, especially when the furnace is cold or when there is a cold charge on the hearth. The disadvantages are high cost for installation, more skilled labor and more repairs. Open-hearth linings are best made of dolomite, which enables a basic slag to be produced in the furnace and a reduction in phosphorus and sulphur. Cheaper pig iron and

iron scrap can then be used. This basic lining is not attacked by the iron oxide and slag produced in melting and will last for hundreds of heats if not allowed to cool off too frequently. Basic linings cannot be employed in air furnaces because dolomite contracts and expands so much on cooling and heating that the bottoms are soon cracked to pieces, for air furnaces are not operated continuously.

**Molding and Pouring.**—Malleable-iron castings are usually made in great quantities from the same pattern, so that this industry offers a special field for molding machines, match plates, etc. It is also a type of molding in which a great many





FIG. 203.—Tumbling barrel.

cores are used and especially cores of small size, so that core-making machines are especially advantageous where applicable. The gates and sprues are usually large in size because the metal has a relatively high melting-point and is consequently more liable to chill. For the same reason the metal is poured into the mold as fast as possible and the great bulk of the work is done with hand-ladles holding 40 or 50 lb. apiece.

**Annealing Boxes.**—After the castings are cooled they are carefully cleaned from all adhering sand by tumbling them around in a tumbling-barrel (in which they are mixed with star-shaped pieces of metal something like children's jackstones), or by sand-blast, or by some other suitable method. They are then packed in the cast-iron or steel "saggers" or annealing pots, or boxes, together with the packing. Sometimes, though rarely, the tops

of the saggars are closed by means of an iron cover, sometimes by a thick layer of the packing in the upper part, and sometimes



FIGS. 204-206.—Malleable cast iron annealing furnace.

by clay or wheel-swarf. These pots last only from 7 to 20 heats before they are largely oxidized away.

**Annealing Ovens.**—The boxes are then placed in the annealing ovens in such a way that the flame may play around them as completely as possible. The general form of ovens is shown in Figs. 204 to 206. The flame usually comes in at the top and goes out at the bottom along the side, and thence through flues underneath the oven. The fuel used may be coke, coal, oil or gas, the latter being preferable on account of the better control of the temperature, which should be increased at a very gradual and uniform rate during the heating up, and kept as constant as possible during the annealing period.

**Annealing Practice.**—It takes about  $6\frac{1}{2}$  days for the American annealing operation, including heating up and cooling down. Sometimes this can be shortened a little by decreasing the time at the full annealing heat, and by cooling rapidly or drawing the saggars out of the oven and dumping them while the contents are still at a dull-red heat. This practice is not conducive to a good quality of castings and should never be permitted in important cases. The time at the full heat should never be less than 60 hr. and preferably it should be more than that. If less, the temperature of annealing must be higher, and this decreases the strength and ductility of the castings. Annealing should not occupy too long a time, however, because the temper carbon tends to draw together to larger flakes; besides which the metal may become over annealed or else oxidized between the grains, *i.e.*, “burnt.” Air-furnace castings should be annealed at 675 to 760°C. (1,250 to 1,400°F.), and cupola metal at 825 to 875°C. (1,500 to 1,600°F.). The saggars are cooled as slowly as possible in the furnace; when they are at a black heat they are removed, cooled further and then dumped.

**Packing.**—As originally planned, the castings were annealed in a packing of iron oxide crushed to a size less than a quarter of an inch in diameter. The packing must surround the castings at every place, both inside and out, and no two castings must touch. Iron ore, mill scale, “bull-dog” and similar forms of iron oxide are used for this purpose.

Annealing in iron oxide produces a white skin where the casting has been deprived of its carbon, and a black interior, due to the temper carbon; whence the name of “black heart malleable” for this material. Tests have shown that the casting with this white skin upon it is much stronger than a similar one which has not been decarburized on the surface, and therefore the packing in



iron oxide is advantageous, even though not an essential feature of the operation. When the castings are packed in some non-oxidizing material, such as sand, clay or lime, they may receive as perfect an annealing, as far as the production of temper carbon is concerned, but will be without much white skin and of a lower strength.

**Shrinkage.**—Hard castings contract in solidifying much like steel, so that, wherever the metal is not “fed,” it draws away, leaving cracks or cavities. Therefore the castings may be considered as a continuous shell of metal on the outside with an interior full of cracks and planes of separation. In malleable cast-iron work this is known as “shrinkage.” It is a source of weakness in malleable castings, and is more effective in round than in square bars because the latter have a thicker solid skin on the corners which reduces the area of the cracked portion.

**Contraction.**—The contraction of the hard casting is almost as great as that of steel, because almost no graphite forms. The amount of silicon and the sectional area of the castings are still the determining factors in this connection. Indeed, by means of the measurement of the section and percentage of silicon we may estimate the contraction, or by means of the section and the contraction we may estimate the silicon very closely, other conditions and impurities being normal. The following table gives the necessary data for these estimations:

TABLE XLVIII.—CONTRACTION IN INCHES PER FOOT OF LENGTH

Percentage of silicon	$\frac{1}{4}$ in. square	$\frac{1}{2}$ in. square	$\frac{3}{4}$ in. square	1 in. square
0.35	0.225	0.200	0.190	0.175
0.50	0.220	0.195	0.183	0.170
0.75	0.215	0.190	0.176	0.162
1.00	0.211	0.183	0.137	0.102

**Expansion Due to Temper Carbon.**—It is a very interesting fact that when the malleable cast iron is annealed and the temper carbon precipitates, the casting expands to an amount approximately equal to that which would have occurred if the graphite had separated during solidification and gray cast iron had been produced in the first instance. In other words, the temper car-

bon, although in a very finely powdered condition, occupies about the same amount of space as an equal weight of graphite, and causes about the same ultimate difference in size between the original pattern and the annealed casting as when gray cast iron is made. An interesting example of this expansion in annealing is shown in Fig. 207, which is a swivel snap for hitching straps. Casting No. 1 is first poured, cooled and cleaned. It is then embedded in the sand of a mold and casting No. 2 is poured around the shank of it, as shown in No. 3 of Fig. 207. Casting No. 2 shrinks upon the shank of No. 1 so as to make a close fit, and no swiveling is possible, but the combined casting is now sent to the annealing ovens and annealed. This causes the expansion referred to, and as casting No. 2 is larger in diameter, it expands the more, and now turns very easily around the shank of No. 1.




FIG. 207.—Harness snap buckle.

**Miscellaneous Iron Products.**—In the form of small castings malleable cast iron and similar products often masquerade under the name of steel, because under that name the producer finds a readier market for them. On account of their fluidity they may be cast very cheaply in small sizes, and therefore the temptation to use them as a material for “cast-steel hammers,”<sup>1</sup> “hard-steel” bevel gears, “semi-steel castings,” and even automobile “steel” drop-forgings, is a strong one. Engineers are warned to be on their guard against a deception of this kind, for legal redress has been sought many times in vain. It is usual for the manufacturer when putting material of this kind upon the market to qualify the name “steel” with some other letters or name, such as “P. Q. steel,” “Smith steel,” etc., but they all differ from true steel in that they were not “cast into an initially malleable mass.”

<sup>1</sup> The trade would ordinarily understand by this name hammers made of crucible steel, so the use of this name is really a fraud.

Some are made by melting a large proportion of steel with cast iron, after which the cooled metal may or may not be annealed in iron oxide. Others are made by a long or thorough annealing of ordinary malleable castings in iron oxide, by means of which the metal is decarburized to some depth, and is then carburized again by a cementation process. This makes a very good material for some purposes, such as small bevel gears not requiring strength or much ductility, but it ought not to be called "steel." If the purpose for which it is to be used does not require any other properties than malleable cast iron possesses, then it should be used under its true name; but if it is to be used under circumstances where it is liable to strain, calling it "steel" will not enable it to stand up under the work any better. The confusion is the more easy because genuine steel is made by the cementation of wrought iron, and wrought iron goes in England under the name of malleable iron. In America we seldom call wrought iron "malleable iron," but we often abbreviate malleable cast iron to "malleable iron," or even to "malleable."

**Delicate Adjustment of Conditions.**—In no metallurgical process must the conditions of chemical composition, furnace work, heating temperatures and lengths of operation be adjusted more delicately than in the manufacture of high-grade malleable cast iron, as may be seen by the following changes that the metal undergoes during the final, *i.e.*, annealing, process, as revealed by the appearance of the fracture. The metal as originally cast will have the so-called *crystalline fracture* of white cast iron, with perhaps a little mottle. This fracture should be changed to a black heart after the annealing process, and the metal will have good strength and ductility. If, however, the composition of the metal was wrong in the first instance, it may quite resist the annealing process and precipitate little or none of its combined<sup>1</sup> carbon. Or else, if the silicon were too high, the castings may have already precipitated too much graphite before the annealing process begins, and the deposition of temper carbon may take place so readily during annealing that the castings will be mushy and lacking in strength.<sup>2</sup>

<sup>1</sup> The term combined is used here to represent carbon in solution or any chemical combination with the metal.

<sup>2</sup> Iron too high in silicon will precipitate too much graphite during its first cooling, and is technically known as low iron; on the other hand, iron with very little silicon is known as high iron.

If, however, the composition of the metal and the melting conditions were correct, a good grade of black heart casting may be produced by a proper anneal, but, should the temperature of annealing be too high, or be continued too long, the black heart fracture may change to a *steely fracture*, showing an iron in which the precipitated carbon has returned to the combined form. Nor is this all; if the annealed castings are cooled too fast after the anneal, or if the black heart castings, after being successfully made, are reheated and hammered, or reheated and quenched in water, the black heart fracture will change to steely. Even the heating to which the finished castings are subjected when they are dipped in spelter for a galvanizing process and then quenched in water will produce a steely fracture with consequent brittleness if the composition of the metal is not within very narrow limits. There is but one remedy for castings having a steely fracture and that is to reanneal them and produce the so-called Réaumur or white heart castings. In other words, white heart malleable iron is the end of a series of changes through which the carbon passes during a long annealing process.

**Theory of the Black Heart Process.**—By referring to the diagram of Fig. 165,\* it will be observed that graphite should normally separate from irons high in carbon during and shortly after solidification. This reaction is avoided in making malleable castings, by cooling the metal rapidly through this range of temperature. The first effect of the annealing process, however, is a slow readjustment of conditions by the occurrence of the reaction which was previously suppressed. That is to say, the carbon is now precipitated within the solid metal. The temperature at which this reaction occurs during the annealing is not as high as the normal temperature for it, but is in the region where cementite ( $\text{Fe}_3\text{C}$ ) normally should be produced according to the diagram. If, therefore, the annealing is continued too long, the carbon precipitation is *followed* by its recombination to form the carbide of iron. As the metal is then slowly cooled, this carbide of iron separates and we get the steely fracture, characteristic of over-annealed malleable castings.

If, on the other hand, we have obtained a good black heart casting and this is reheated into the region where cementite normally forms, and suddenly cooled, we produce a metal which consists of cementite, mostly dissolved in an iron matrix. This


\* P. 326.



reasoning fails to explain why the rapid cooling of castings, after a proper annealing, will sometimes produce the steely fracture, and so far as I know, this occasional result yet lacks an explanation.

The reason why cast iron too high in silicon precipitates its carbon too readily and gives a mushy iron is readily explained, since it is known that the presence of silicon will promote the separation of graphite, and especially will make the iron open-grained and cause graphite to separate in larger flakes.

**Theory of the Réaumur Process.**—In the original Réaumur process the castings are packed in iron oxide during the anneal, and this operation is carried on at a temperature of about 800 to 875°C. (1,472 to 1,607°F.) for a period of 4 or 5 days after reaching full temperature. In the first part of this annealing process conditions are produced which tend to result in black heart castings; then the next step results in conditions that would produce the steely fracture; still the anneal is protracted at the high temperature and, at the end of the 100 hr. or so, we have castings in which the white rim of black heart metal extends to the very center—the castings being only  $\frac{1}{2}$  in. or less in thickness. This white rim, as already explained, is iron from which the carbon has been actually removed bodily, and this decarburization results from a reaction between the iron oxide in contact with the skin of the casting and the carbon in it. Whether the carbon migrates to the surface and is there oxidized by the oxide:



or whether oxygen penetrates the metal through its pores in the form of CO gas, or penetrates chemically by forming iron oxide which is acted upon by the carbon:



is a matter on which authorities cannot agree. The first theory is the one which seems to have the preponderance of evidence in its favor. That carbon will migrate in solution is proven in the cementation processes and, at the annealing temperature, the carbon is normally all in solution, whether it be as free carbon, or as carbide. Even the white rim of an ordinary black heart casting contains some carbon in solution.

## CHAPTER XV

### THE HEAT TREATMENT OF STEEL

We have already discussed the heat treatment of cast iron under other heads, namely: (1) The rapid cooling from the molten state, or "chilling," and (2) the annealing of malleable cast iron. Heat treatment is of much greater importance in connection with steel, because nearly 99 per cent of all the steel made is heated either for the purpose of bringing it into the mobile condition in which it can be readily wrought, or for annealing. Indeed, the great majority of steel is heated several times, and some steel is subjected to two or three different kinds of heat treatment.

#### IMPROPER HEATING OF STEEL

**Overheating.**—If steel be heated to a high temperature, say  $1,100^{\circ}\text{C}$ . ( $2,010^{\circ}\text{F}$ .), and then cooled (either slowly or rapidly) without being subjected to strain, it will be "coarse-grained" as it is called, that is, its crystals will be relatively large in size. This can be readily seen by breaking it and examining the fracture, which will be bright and sparkling if the crystals are coarse, or dull-looking and fine-grained if they are small (see Fig. 215).<sup>\*</sup> The bright fracture is technically called "crystalline" or "fiery," while the fine-grained one is called "silky" or "sappy." The size of the crystals may also be learned with great accuracy by means of the microscope (see Figs. 208 to 213). Now, if the steel which was coarse-grained after heating to  $1,100^{\circ}$  be heated instead to  $1,200^{\circ}$ , the crystals will be still larger in size; if heated to  $1,300^{\circ}$  they will be larger still, and so on. The size of the crystals will depend first upon which of these high temperatures it was heated to, and second upon the amount of carbon it contains. Low-carbon steel is normally larger in crystal-size than high-carbon steel.

Even the best quality of steel, if rendered coarse-grained by "overheating," will suffer in its valuable properties, and may become quite unfit for use. Medium- and high-carbon steel will

<sup>\*</sup>P. 402.




FIG. 208.—No. 1A. Steel of 0.05 per cent carbon rolled. Magnified 40 diameters.




FIG. 211.—No. 1B. Steel of 0.50 per cent carbon rolled. Magnified 60 diameters.



FIG. 209.—No. 2A. Same as No. 1A. Overheated to 1420°C. (2588°F.) Magnified 60 diameters.




FIG. 212.—No. 2B. Same as No. 1B. Overheated to 1420°C. (2588°F.) Magnified 60 diameters.




FIG. 210.—No. 3A. Same as No. 2A. Reheated slightly above  $AC_3$ . Magnified 40 diameters.




FIG. 213.—No. 3B. Same as No. 2B. Reheated slightly above  $AC_{2-3}$ . Magnified 60 diameters.

Series A by F. C. Wallower in the Metallographic Laboratory of Columbia University, Department of Metallurgy.

Series B by G. Rocour in the Metallographic Laboratory of Columbia University, Department of Metallurgy.

lose both strength and ductility; low-carbon steel will lose strength even up to 50 per cent of the original, but does not seem to be materially damaged in ductility unless the overheating is continued for a long time or at a very high temperature.

**Cure for Overheating.**—Let our first example be steel containing 0.85 per cent carbon, that is, steel consisting entirely of pearlite. If this be heated from some point below the line *PSK* in Fig. 165, page 326, to some point above that line, a new crystallization will occur and will largely obliterate previous crystallization. It seems as if dissolving the ferrite and cementite in each other produces forces which obliterate almost all existing crystalline forms. So, if this particular steel has been made coarse-grained by overheating, we may make that grain fine again by reheating the steel from below the line *PSK* to just above it. This process is known as “restoring,” or, by some writers, “refining” the steel. It is an operation which should be thoroughly understood by every metallurgist and engineer. When we reheat the steel we must be careful not to go to a high temperature again, for a new crystal-size is born at the line *PSK*, and the crystals grow with every increase in temperature. The researches of Professors Howe and Sauveur indicate that the size of the crystals is almost directly proportional to the temperature reached above the line *PSK*. If, therefore, we barely cross the line, we will obtain the smallest grain-size that the steel is capable of (see Fig. 215, p. 402).

The cure for coarse crystallization in steel with less than 0.9 per cent carbon is to reheat it from below the line *PSK* to above the line *GOS*, at which the last of the ferrite goes into solution (see Figs. 210 and 213). That is to say, the correct temperature for restoring the grain-size will depend upon the amount of carbon in the steel; low-carbon steel must be heated to nearly 900°C. (1,650°F.); 0.4 per cent carbon steel must be heated to nearly 800°C. (1,470°F.); and so on.<sup>1</sup> We can never get as small a grain-size in steel with less than 0.9 per cent carbon as we can in that which is exactly 0.9 per cent carbon, because a new grain-size begins to grow after we have crossed the line *PSK*, and yet we cannot entirely eliminate the old grain-size until we cross the line *GOS*. Where the lines *GOS* and *PSK* are near

<sup>1</sup> It is to be remembered that the changes indicated by the lines in Fig. 165 occur at a higher temperature on heating than on cooling; so it is well to heat the steel about 25°C. higher than the points on those lines.



together (say, with 0.7 per cent carbon), the new grain-size does not have much chance to grow before the restoration is complete, and therefore we may obtain steel with a pretty small grain; but where they are far apart (as in the low-carbon steels) the restoration can never be very thorough, because we have to go so far above *PSK* to obliterate the old grain-size that the new grain-size will have attained ample proportions. But the evidence seems to show that the best net result is obtained by going just above the line *GOS* in all cases.

In the case of steel with more than 0.9 per cent carbon a somewhat similar condition exists: We must reheat the steel above the line *Sa* in order to produce complete elimination of the previous grain-size but a new grain-size begins to grow from the crossing of the line *PSK*. But here we disregard the line *Sa*, and restore our steels in every case by reheating them over the line *PSK*, just as in the case of pure pearlite. The reason for this is that the lines *Sa* and *PSK* diverge so rapidly that we have to heat very far above the line *PSK* before we cross *Sa*, and therefore the new grain-size has grown greatly. Furthermore, the only object of heating above the line *Sa* is to take the excess cementite into solution; for the ferrite and cementite in the pearlite all went into solution as soon as we crossed the line *PSK*, but the amount of excess cementite is always small in proportion, and therefore in its influence on restoration. Even with steel containing 2 per cent of carbon the excess cementite is only 16 per cent. This is different from the low-carbon steels, where the excess-ferrite will be usually over 80 per cent.

**Evidence of Overheating.**—A piece of steel may be heated many times above the line *PSK* and cooled again, but obviously only the latest heating will leave its impression on the structure, because each crossing of the line on the way up removes the effect of previous heat treatment.<sup>1</sup> The relation between the size of the crystals and the temperature above *PSK* is so constant that we may determine what this temperature was from the analysis of the steel and an examination of the grain. To do this it is

<sup>1</sup> This is only true in a qualified sense, in that the previous overheating must not have been very close to the melting-point. We shall discuss this point under the head of "Burning." Indeed, even where burning has not occurred, a skilful microscopist may sometimes discern the effect of overheating after the steel has been restored by reheating; because, although the crystals are all small, they are arranged in groups which show the form of the previous large crystals.

usually necessary to get a piece of steel of the same analysis, heat different pieces of it to various temperatures, and compare (see p. 402). The analysis must be approximately the same not only in carbon but also in phosphorus, sulphur, silicon, and manganese, as well as in any alloying elements, if present, such as nickel, chromium, tungsten, etc., because all of them have an effect upon the size of grain and also upon the change in size of grain by overheating. Generally, it is not important to know the exact temperature of overheating, but only whether or not overheating in some degree has occurred; and this is not difficult to prove, because almost all who use steel are familiar with the normal fracture of steels of different carbon and can tell at a glance if the grain is large; those who are not so familiar with its appearance may easily become so. The grain being large is proof that overheating was the cause, provided chemical analysis shows everything about normal, especially phosphorus and silicon.

Steel members of bridges or other structures sometimes break and disclose a crystalline fracture which is often attributed to the effect of vibration. The same thing occurs with points or shanks of rock drills and similar implements. It is the more general opinion among metallurgists that the crystalline fracture in all these cases is due to faulty heat treatment during manufacture, and especially to finishing the forging or rolling while the temperature is still too high. The manufacturers of steel like to maintain the opposite opinion, for obvious reasons, but I do not know of there ever having been any reliable proof offered that vibration had caused, or is capable of causing, large-sized grain in steel. It may be possible, but the more we learn about the subject the more we are inclined to believe that improper manufacture is the cause, and that the grain was large before the steel was put in service, although its nature was not disclosed until the break occurred.

**Mechanical Cure for Overheating.**—When steel is to be rolled or forged it is frequently heated to a temperature of 1,100 to 1,350°C. (2,010 to 2,460°F.), and it might be thought that this treatment would seriously damage it. So it would, but for the circumstance that the subsequent mechanical pressure upon the metal breaks down the crystals and reduces them to a small size. The result is that the final size of the crystals is dependent upon the temperature of the material at the finish of the mechanical operation. In other words, steel finished at 900°C. (1,650°F.)

has a finer structure than the same steel finished at 1,100°C. (2,010°F.). We do not feel warranted in stating numerically the exact relation between the finishing temperature and the grain-size, as we have not yet sufficient evidence, but several rules affecting the final size of grain seem to be virtually established: (1) It is more advantageous to have the mechanical work applied continuously from the highest temperature employed down to the finishing temperature, rather than to have long waits during which the steel cools; and especially is this true when the amount of work put upon the metal at the lower temperature is small. In other words, if the steel is formed roughly to shape and size at a high heat, is then allowed to cool, and a little work is done upon it at the lower temperature, the grain will not be its best. (2) It is best for the metal to be worked by several passes through the rolls, or many blows of the hammer, rather than to effect the same amount of reduction by a lesser number of heavy drafts. (3) The greater the amount of reduction the better; that is, to work a large piece down to the desired article gives a better structure. (4) The best temperature at which to finish the work is probably upon, or slightly below, the lines *GOS* or *SK* in Fig. 165, p. 326 (see Figs. 102 and 103, p. 228).

**Action in Rolling.**—The exact crystalline action that takes place under mechanical treatment is not definitely known. In the case of rolling Professor Howe<sup>1</sup> has tentatively assumed the conditions graphically shown in Fig. 214,<sup>1</sup> in which the line *DG* represents the size of grain at the different temperatures. At 1,400°C. (2,550°F.) the grain-size is represented by the distance of the line from the axis *OO*. On the first passage through the rolls the grains are crushed to a very small size, but on emerging again they grow very rapidly. Meanwhile, however, the metal has been cooled, and this fact, as well as the inability of the grains to grow instantly, causes the new size of grain to be smaller than before. Therefore, each passage through the rolls renders the crystals smaller in size, the final size depending upon the temperature and the amount of pressure in the last pass. The only abnormal assumption in this argument is that the crystals grow rapidly after the crushing, whereas we know that when steel is heated to any of these high temperatures, the growth is relatively slow. This objection is not strong enough alone to refute the theory, but other hypotheses may be advanced for those who

<sup>1</sup> P. 263 of Ref. 1.

require further explanation. For example, it may be supposed that the steel is so mobile at the very high temperatures that it yields to distortion, not altogether by the crushing of the crystals, but by the sliding of the crystals past one another; as the temperature becomes lower, however, the mobility of the mass be-




FIG. 214.—Size of grain in metals as affected by pressure in rolling.

comes less, and less sliding is possible, so that more crushing of the crystals takes place.

**Finishing Temperatures.**—William Campbell has studied the finishing temperature of steel containing 0.5 per cent carbon and finds that the very best qualities are produced in the steel if mechanical work is ended just at the time when ferrite begins



to separate from solid solution, that is to say, just when the steel is below the line *GOS* in Fig. 165, page 326. Work below that temperature greatly increases the brittleness of the material, while finishing the work at a higher heat results in lower strength. Upon the evidence at hand, we may tentatively assume like conditions for steels of any carbon, and expect the best results if mechanical work is ended when the steel is at a temperature which brings it exactly upon the line *GOS* or *SK*, but reserving, perhaps, the right to change this statement slightly when more data are obtained.

**Hammer Welding.**—This brings us to the subject of welding, or the joining of two pieces of wrought iron or steel by pressing or hammering them together while at a very high temperature. In this way a joint may be made which cannot be seen by the eye unless the steel is polished and etched with acid, which usually develops the junction line very clearly. The exact temperature of welding is not known, but probably it is very near the melting-point, where the steel is in a soft and almost pasty condition. Low-carbon steel welds most easily; moreover, all impurities, especially silicon and sulphur, reduce weldability. The procedure in welding is very simple, and consists in heating the two pieces that are to be welded to a high temperature, dissolving off the iron oxide, and then pressing the two pieces together forcibly. The dissolving off of the oxide is usually accomplished by rubbing the metal in some flux, such as borax. At the present time various patented "welding plates" are sold. These consist of thin plates of flux which are put between the two pieces to be welded and so get rid of the oxide, the pieces being hammered together with the plate between them.

In the actual manipulation for welding the two pieces that are to be joined together are usually "upset," or in some way enlarged in size, so that, after the junction, the part of the bar right at the weld is larger in size than the remainder. This part is then hammered continuously until the metal is at a red heat, the object being to break up the coarse crystals produced by the high temperature, and, by having a low "finishing temperature," to obtain a small grain-size. With proper welding this object will be attained so far as the metal immediately adjacent to the weld is concerned, but there is always a spot within 6 in. or so of the weld which must necessarily have been overheated without subsequently receiving mechanical treatment, *i.e.*, "ham-

mer refining," down to the proper finishing temperature. Thus it is that most welded pieces break at a point not far from the junction and under a strain much less than the original strength of the bar. Blacksmiths and experienced welders are wont to declare that if a welded bar does not break in the weld itself, then it must be as strong as the original metal. However, this is by no means true. In a welding test carried on with great care in this country by skilful and experienced welders who were placed upon their mettle,<sup>1</sup> the strength and elastic limit of the welded bar was almost never as great as the original bar, and in some cases was less than half. In ductility even worse results were obtained. In a similar test carried on at the Royal Prussian Testing Institute the average strength of welded bars of medium steel was only 58 per cent of the original, that of softer steel only 71 per cent, and of puddled iron only 81 per cent, while the poorest results were only 23, 33 and 62 per cent respectively. It was seen that bad crystallization adjacent to the weld was the cause of the damage.

Welded steel and iron bars should therefore always be reheated after cooling to a temperature just above the line *GOS*, in order to restore by heating the grain-size of all parts.

**Burning.**—In the vernacular of the trade, all overheated steel is termed "burnt," but this is not correct usage, because true burning takes place only when the overheating is most abusive, and, indeed, when the metal is heated almost to its melting-point. It is probable that steel is burnt only when it is heated above the line *Aa* in Fig. 165, p. 326. Alfred Stansfield has studied this question very ably, and distinguishes three stages of burning. The first stage is reached when the steel barely crosses the line *Aa*, that is, when the first drops of melted metal begin to form in the interior of the mass. They segregate to the joints between the crystals and cause weakness. Stansfield thinks that steel burned only to this stage may be restored by reheating it first to a high temperature, cooling, and then heating again to a temperature just above the lines *GOSK*. The second stage in burning is reached when these liquid drops segregate as far as the exterior and leave behind a cavity filled with gas. Stansfield thinks that steel burned to this stage might be restored by combined reheating and forging. As a matter of

<sup>1</sup> See pp. 401 to 406 of Ref. 2.

safety, however, I believe it would be well to remelt all such material; in other words, send it to the scrap pile. The third and last stage of burning is reached when gas collects in the interior of the metal under sufficient pressure to break through the skin and project liquid steel, which produces the well-known scintillating effect at this temperature. Into the openings formed by these minute explosions air enters and oxidizes the interior. There can be no remedying of steel which has been burned to this extent, except remelting.

**Metcalf Test.**—A very interesting experiment is the “Metcalf test,” originated by William Metcalf. It is best performed upon a bar of high-carbon steel, because this material shows the



(Courtesy, William Campbell)

FIG. 215.—Metcalf test. Fractures of steel of 1 per cent of carbon.

differences in structure so readily to the eye. A bar of steel about 12 in. long is notched with a hack-saw or chisel at intervals of 1 in. One end is then placed in a fire and heated to a temperature at which it scintillates, while the other end is at a black heat. Then it is removed and cooled. It is immaterial whether the cooling be rapid or slow, but time may be saved by plunging it into water. It is then broken at every notch, and an examination of the fractures will show a very large size of crystals at the end which is burnt, gradually decreasing until a fine and silky appearance is presented where the metal was exactly at the temperature of restoration, while beyond that point the fracture will be the same as that of the original bar. In case this test is made upon low-carbon steel it should not be notched before treatment, but afterwards it should be cut apart with a hack-saw at intervals of 1 in., and then polished and examined under the microscope, because soft steel will not break without bending, and this bending destroys the indications of the fracture. This Metcalf test is very serviceable in case we desire to

compare one steel, suspected of being overheated, with another of like analysis, to determine the degree of overheating.

**Castings Do not Burn.**—It might be thought that every steel casting would suffer the injuries due to burning because it is cooled through the space between the lines *AB* and *Aa*. Such injury, however, does not ordinarily take place, and this fortunate circumstance is explained in part by each of three differences existing between the heating and cooling of steel: (1) When steel is heated into the area where burning takes place, it is subjected longer to the burning temperature, because it generally takes longer to heat steel than to cool it. (2) When steel is being heated, the heat is traveling inward from the outside, and therefore all parts are expanding, and there is some opportunity for the crystals to draw apart and form cavities. On the other hand, when it is cooling from the molten state, the outside layers are the cooler, and tend to contract upon the interior and hold the crystals more firmly together, as well as to prevent drops oozing out. (3) When steel is cooling from a molten state, it is constantly giving off from solution hydrogen and other deoxidizing gases which are soluble in it while liquid, and these gases prevent the oxidation of the crystal faces by the percolation of air into the interior.

**Ingotism.**—I have already discussed ingotism and said that the crystals in cast steel are larger than those of rolled steel, due to growth while the metal is at a high temperature, and I have stated that sometimes these crystals are very large, because the conditions of casting cause the steel to occupy a longer time in cooling from the liquid state down to a black heat. It is probable that ingots and castings do not show the effects of ingotism to any marked extent unless they are a long time above  $1,100^{\circ}\text{C}$ . ( $2,010^{\circ}\text{F}$ .). In case these coarse crystals do form, they may be restored to some extent by reheating the casting to a point just above the line *GOS*.

**Stead's Brittleness.**—In addition to the damage caused by overheating, steel very low in carbon (say under 0.15 per cent) is subject to another and peculiar danger, for if this soft steel be held for a very long time at temperatures between  $500$  and  $750^{\circ}\text{C}$ . ( $930$  and  $1,380^{\circ}\text{F}$ .), the crystals become enormous and the steel loses a large part of its strength and ductility. Fortunately it takes a very long time, in fact days, to produce this effect to any alarming degree, so that it is not liable to occur,



even through carelessness, during manufacture or mechanical treatment. But steel is sometimes placed in positions where it may suffer this injury, for example, in the case of the tierods of furnaces, supports for boilers, etc., so that the danger should be borne in mind by all engineers and users of steel. I recall an instance where the breaking of a piece of chain that supported one side of a 50-ton open-hearth ladle caused a loss of life under the most horrifying conditions, due to the fact that the wrought-iron chain had been heated up many times to a temperature above  $500^{\circ}\text{C}$ . ( $930^{\circ}\text{F}$ .), and had finally reached a condition of coarse crystallization, so that it was unable to bear the strain upon it when the ladle was full of metal.

This phenomenon of coarse crystallization in low-carbon steel is known as "Stead's brittleness," after J. E. Stead, who has explained its cause. The effect seems to begin at a temperature of about  $500^{\circ}\text{C}$ ., and proceeds more and more rapidly with an increase in temperature until we reach  $750^{\circ}\text{C}$ ., above which no growth seems to take place. The damage may be repaired completely by heating the steel just above the line *GO*. In other words, the remedy for coarse crystallization in this case is the same as that for coarse crystallization due to overheating, and all steel which is placed in positions where it is liable to reach these temperatures frequently should be restored at intervals of a week or a month, or as often as may be necessary.

#### HARDENING OF STEEL

If steel be raised to a bright-red heat and then rapidly cooled, as, for example, by plunging it into water, it becomes very much harder and at the same time stronger and more brittle. One circumstance is absolutely necessary to produce the increase in hardness, namely, that the temperature from which rapid cooling takes place shall be above the critical temperature of the steel. Take, for example, steel containing 0.9 per cent carbon; we may heat this ever so little below the point *S* in Fig. 165, p. 326, and no increase in hardness will take place, even though we cool with extreme rapidity. On the other hand, if we cool the same steel rapidly from ever so little above the point *S*, it will be hard enough to scratch glass and brittle enough to fly into pieces under a blow of the hammer. This is the maximum practical hardness which can be obtained in this steel, for if we quench it at a higher temperature, the only result of importance is to damage it by

increase in grain-size. In case we have less than 0.9 per cent carbon in our steel, the best temperature for hardening is just above the line *GOS*, because that gives the maximum hardness and also the best grain-size. The best temperature from which to harden steel with more than 0.9 per cent carbon is just above the line *SK*, because that gives the best grain structure, although it is true that greater hardness is obtained if we cool from above the line *Sa*.

**Carbon and Hardness.**—The hardness of steel increases with every increase of carbon. This applies to the hardness of steel in its natural state, and still more appropriately to its hardness after heat treatment. Although iron free from carbon is hardened by rapidly cooling from above the point  $A_{c_2}$  ( $760^{\circ}\text{C.} = 1,400^{\circ}\text{F.}$ ), and a little more so when rapidly cooled from above  $A_{c_3}$  ( $900^{\circ}\text{C.} = 1,650^{\circ}\text{F.}$ ), yet this degree of hardness is so slight as to be perceptible only by means of laboratory tests. With 0.10 per cent carbon the hardness begins to be perceptible by crude tests (see Table XL, p. 347), but it is only when we get above 0.75 per cent carbon that ordinary steel acquires sufficient hardness for the process to be used commercially—for example, for springs, saws, etc. Metal-cutting tools are usually made of steel containing 1 per cent or so of carbon, while very hard implements, such as files, etc., will contain 1.2 per cent or slightly more (see Table XXXVI, p. 342).

**Rate of Cooling and Hardness.**—The degree of hardness of steel also varies with the speed of cooling from above the critical range of temperature. When the cooling is very slow, as, for example, when it takes several days to cool, the steel will be as soft as it is possible to make it. When it is cooled by being taken out of the furnace and suspended in the air, or thrown upon a sand floor, it will still be relatively soft. When cooling is still more rapid, as, for example, when it is taken out of the furnace at a bright-red heat and plunged into a heavy oil with a low conducting power for heat, it becomes quite hard and springy, provided its carbon is in the neighborhood of 0.8 per cent or above. Quenching in a thin oil from the same temperature makes it still harder. Quenching in water makes it harder still; and so on, the degree of hardness increasing as we quench in liquids which take the heat away from it faster and faster, such as ice-water, ice-brine, ice-sodium chloride solution, and mercury near its freezing-point ( $-39^{\circ}\text{C.} = -38^{\circ}\text{F.}$ ). (See pp. 417 and 418).

TABLE XLVIX.—THE EFFECT OF CARBON ON THE MECHANICAL PROPERTIES OF STEEL AFTER HARDENING IS SHOWN BELOW<sup>1</sup>

Carbon, per cent	Tensile strength in soft state			Tensile strength when hardened		
	Ultimate, pounds per square inch	Elastic limit, pounds per square inch	Elongation in 2 in., per cent	Ultimate, pounds per square inch	Elastic limit, pounds per square inch	Elongation in 2 in., per cent
0.10	60,300	36,300	29	66,400 <sup>2</sup>	40,300	24
0.14	61,500	35,200	27	73,100 <sup>2</sup>	39,600	22
0.23	66,500	41,200	26	99,400 <sup>2</sup>	54,000	14
0.52	97,800	52,600	20	132,100	81,400	9
0.60	116,400	66,500	14	153,400	102,100	4
0.72	130,700	75,800	9	180,100	105,500	0

<sup>1</sup> See E. F. Lake, *Comp. & Heat Treatment of Steel.*"

<sup>2</sup> The increase in strength in these low carbon steels is due in large part to the finer size of grain produced by rapid cooling through the critical range.

**Theories of Hardening.**—One essential feature of hardening is that the steel must be heated to a temperature above the line *PSK*, that is to say, to a point where at least some of the solid solution of iron and carbon is formed. There are several different theories to explain the hardness produced by rapid cooling from this point, the two most important being the "carbon theory" and the "allotropic theory." Both of these theories depend upon the following line of reasoning: At temperatures above the critical range the molecules of steel are in a hard condition.<sup>1</sup> As they cool from this point and cross the critical range of temperature, the molecules change from the hard state to a soft state, but this change is not rapid and requires time for its accomplishment; rapid cooling does not afford the necessary time, and so perpetuates the hard state of the molecules. This line of reasoning leaves only one point in doubt, namely, what causes the molecules to be hard when the steel is above the critical temperature, *i.e.*, when iron and carbon are dissolved in each other?

**The Carbon Theory.**—The carbon theory assumes that the hardness of steel is due altogether to the carbon dissolved in it,

<sup>1</sup> It is difficult for some to understand how molecules of steel can be in a hard condition at a temperature at which we know that the mass as a whole is soft and mobile; but this can be explained by the following comparison: A ball of wet sand and clay is soft and mobile as a whole, because the particles move by each other readily and the mass changes its shape under pressure; yet the individual particles composing this mass are many of them hard enough to scratch glass with ease.

and in evidence its advocates point to the extreme hardness of one form of carbon—the diamond. This theory has the advantage of simplicity, and has in its favor the fact that the hardness varies almost directly with the amount of carbon. Against the theory, it is urged that the amount of carbon is really too small to produce such a great degree of hardness in the whole mass of metal. Furthermore, although carbon is found in many metals it does not confer hardness on any of them except iron.

**The Allotropic Theory.**—We have already learned that in the solid solution the iron is present in the gamma allotropic form, and the majority of metallurgists attribute the hardness of steel to the allotropic form, and deny that carbon is the sole factor. It has been shown, by very delicate laboratory tests on iron practically free from carbon, that the gamma and beta allotropic modifications are harder than the alpha modification. These did not show how great was the increase of hardness of one form over another, because it was not possible to cool the iron fast enough to prevent it changing back in part to the alpha form. In the absence of carbon the change from gamma to beta and from beta to alpha is very rapid, so that cooling has to be almost instantaneous in order to prevent it, and this, of course, is impossible. The “allotropists” explain the greater hardness of high-carbon steel as compared with low-carbon steel upon the basis that the presence of carbon makes the change from gamma to beta and to alpha iron slower, and therefore enables more of the iron to be retained in the gamma and beta forms by the rapid cooling.

An additional argument in favor of the allotropic theory is that when steel cools slowly through the critical range, it loses its hardness slightly before the carbon comes out of solution. This would indicate that the allotropic change took place before the carbon change, and that the allotropic change was the cause of hardness. What is true of the loss of hardness is also true of the other physical changes which take place at the same time. That is to say, the steel regains its magnetism, decreases in electric resistance, and increases in thermo-electric power in a large part before much carbon is separated from the solution.

**The Compromise Theory.**—Several theories have been advanced which are a compromise between that of “the carbonists” and that of “the allotropicists.” The simplest of these, and the theory now most generally accepted, is that the hardness of the molecules of steel above the critical range is due



partly to the allotropic form in which the iron exists, and partly to the fact that we have a solid solution of iron and carbon.<sup>1</sup> In other words, the hardness is due to the fact that we have a solid solution of carbon in an allotropic form of iron.

**The Stress Theory.**—In cooling through the critical range steel undergoes a great internal stress, which leaves it in a strained condition unless the cooling is very slow. During the past 50 years several attempts have been made to prove that this internal stress is more than sufficient to account for the hardness induced by sudden cooling. It is well known that this stress is so great as to cause steel tools to burst sometimes when cooled in cold water during the critical range.


**Tempering.**—Hardened steel is too brittle to be used without some degree of tempering, except for a small variety of purposes, such as the points of armor-piercing projectiles, the face of armor plate, etc. In order to understand just what tempering does, let us consider the exact condition of hardened steel: It is in a hard and brittle condition which is not natural to it at atmospheric temperatures, but which has been brought down with it from a higher temperature by means of rapid cooling. Theoretically, when the temperature fell below 690°C. (1,272°F.), the molecules of steel should have changed over to the soft form. Their hard condition is not in equilibrium at the lower temperature, in the same sense that ice is not in equilibrium in hot weather. Why, then, does not the steel change back into the soft form? Ice, if given time enough, will all change into water when the temperature is above 0°C. (32°F.). The reason the change does not take place in the steel after we have cooled it to the atmospheric temperature is that the mass as a whole becomes too rigid and immobile at the lower temperature to permit any alteration in its molecules to take place.

However, it is only necessary to decrease this rigidity in order to permit a slight change. For example, if a piece of hardened steel be kept in boiling water for some days it will lose a part of its hardness; if it be heated a little more, it will lose more hardness

<sup>1</sup> Where I speak of a solution of carbon and iron, I intend to include under this also the solution of iron and a carbide of iron. That is to say, we have two substances, iron and carbon, and they are dissolved in each other. It may be that the carbon is united with part of the iron to form a carbide, and then that this carbide is dissolved in the rest of the iron; but I use the term "solid solution of iron and carbon" to cover either this condition or that of elemental carbon dissolved in iron.

and lose it much more quickly. Each loss in hardness is accompanied by a loss in brittleness as well. If it be heated to about  $200^{\circ}\text{C}$ . ( $392^{\circ}\text{F}$ .), quite a little of the brittleness will be lost and a part of the hardness.<sup>1</sup> It is now in condition to be used for steel engraving tools, lathe tools, and other implements to cut metals. If we heat to  $250^{\circ}\text{C}$ . ( $480^{\circ}\text{F}$ .), we temper still further, and so on (see Fig. 216).

It is interesting to note that when hardened steel is tempered, the physical changes produced by the tempering—the decrease in hardness and brittleness, increase in electric conductivity, etc.—precede the separation of carbon from the solid solution. By



(From Howe, "The Metallography of Iron and Steel," Fig. 123, p. 599)

FIG. 216.—Progress of the Loss of Hardness in Tempering Steel.

tempering we may lose 70 per cent of the hardness, 93 per cent of the electric resistance, and nearly 100 per cent of the thermoelectric power produced in the steel by the hardening operation, when only 13 per cent of the carbon has been changed from the dissolved form.<sup>2</sup>

**Hardening, Tempering and Annealing.**—Only quenching in water, or in some other medium which takes the heat away as fast or faster, goes under the name of hardening. Quenching in heavy oil, melted lead, etc., cools the steel less rapidly, and makes it less hard and less brittle than quenching in water, so to this operation the name of "tempering" is given. Cooling in sand, in the furnace, or by any other slow method, is called "annealing."

<sup>1</sup> After the heating it is immaterial whether cooling is fast or slow, as the same result will be produced.

<sup>2</sup> See footnote, p. 408.

**Magnetism and the Lines GOSK.**—It will be remembered that iron is present in the solid solution in the gamma allotropic form, and therefore the solid solution is non-magnetic. Therefore all the steels to the right of the point *O* in Fig. 165, p. 326, lose the last of their magnetism at the same time as they cross the lines *OSK*. These steels comprise all containing 0.4 per cent of carbon and more. To harden, anneal, or restore such steels we may guide our work of heating by means of an ordinary horse-shoe magnet, which makes a most accurate and simple tool. Let the magnet hang outside of the furnace and take a sample of steel out at intervals to test it. When it no longer attracts the magnet, begin to cool it. For steels with less than 0.4 per cent carbon we can use the magnet to tell us when the temperature corresponding to the line *MO* is reached, for all iron loses its magnetism at that point, and then it is a comparatively simple matter to judge by eye the relatively short temperature intervals above that point which it is necessary for the steel to traverse before it crosses the line *GO*. If this method is followed I think it will be found in many works that annealing temperatures have been much too high, and that better steel will be obtained in future. We do not get the steel any softer by annealing it hotter, but only by slower cooling from the correct temperature.

#### THE CONSTITUENTS OF HARDENED AND TEMPERED STEELS

It is now generally admitted by metallurgists that austenite is the solid solution of gamma iron and carbon. When this cools slowly through the critical range it decomposes into ferrite and cementite. It is also very generally admitted that the decomposition does not take place spasmodically, but progresses by stages, and many believe that the substances identified under the microscope as martensite, troostite and sorbite are the products of these stages. That is to say, martensite is the first stage of decomposition of austenite, troostite is the second, sorbite is the third, and pearlite is the consummation. If this is so, then austenite will be found in the steels cooled with the greatest rapidity, martensite will be found in those cooled with the next degree of rapidity, troostite will be found in the next intermediate steels, sorbite in the next, and pearlite in those slowly cooled.

**Austenite.**—Austenite can be obtained at atmospheric temperatures in ordinary carbon steels only when three conditions are collectively present: (1) The brake action of carbon must be



FIG. 217.—No. 1A. Steel of 0.34 per cent carbon overheated to about 1,300°C. (2,372°F.). Magnified 250 diameters.




FIG. 217A.—No. 2A. Same as No. 1A. Reheated slightly above  $AC_3$ . Magnified 250 diameters.




FIG. 218.—Steel of 1 per cent carbon burnt. Magnified 265 diameters.






FIG. 219.—Martensite. Steel quenched above  $Ac_{3-2-1}$ .



(Courtesy, H. C. Boynton)

FIG. 220.—Martensite (white) and troostite (dark). Magnified 500 diameters. Etched lightly with tincture of iodine.



(Courtesy, William Campbell)

FIG. 221.—Austenite (white) and troostite (dark). Magnified 60 diameters. Steel of 1.41 per cent carbon. Etched with picric acid.



very strong, that is, there must be above 1.1 per cent of carbon present; (2) the steel must be cooled with the greatest rapidity, as by quenching it in iced solutions at, or a few degrees below,  $0^{\circ}\text{C}.$ ; and (3) it must be cooled from above  $1,000^{\circ}\text{C}.$  ( $1,830^{\circ}\text{F}.$ ). Even then austenite cannot be preserved throughout the whole mass of the steel, but at least a part of it will be decomposed to other products (see Figs. 219 to 222), while cementite will separate also if the carbon is very high. Under the microscope austenite may be differentiated from martensite by its white color after etching with a 10 per cent solution of hydrochloric acid. Better results are obtained if the etching is aided by electrolysis, the steel being made the anode, or positive pole, and a piece of platinum being made the cathode. Austenite does not occur often in cold commercial carbon steels, but is found frequently in alloy steels.

**Martensite.**—Martensite is the chief constituent of ordinary hardened steels, that is, of steels quenched from above the critical range in water or in an iced solution. Its structure is shown in Fig. 219. It is even harder than austenite, for a steel needle drawn across the surface of a polished piece of steel will scratch the austenite plainly without making a mark upon the martensite. Its structure is developed by the "polish attack" method of F. Osmond (see p. 409). Martensite is also found very largely in the tempered steels, to which they doubtless owe their quality of hardness. It was long thought to be the solid solution itself, and is still spoken of as such in several books upon the subject; but the microscope shows positively that it is not free from some decomposition.

**Hardenite.**—Hardenite is the name sometimes given to "saturated martensite," that is, martensite containing 0.8 to 0.9 per cent carbon. It is often found in German and French, and occasionally in English and American books.

**Troostite.**—Troostite is obtained in one of three ways: (1) By quenching steel in water when it has cooled just to the line *PSK* in Fig. 165, p. 326; (2) by quenching steel from a higher temperature in boiling water, oil, or some other of the tempering mediums; and (3) by hardening in the usual way and then tempering by reheating. In other words, troostite is a product of the usual tempering operations, and is found abundantly in tempered steels. Under the microscope it may be distinguished by the "polish attack" (p. 409) or by etching with tincture of iodine.

It appears as yellow, brown, blue or black colorations on the borders of the martensite, and often between the martensite and sorbite. The division between it and the martensite is very sharp, but it shades very gradually into the sorbite (Fig. 220).

**Sorbite.**—Sorbite is very close to pearlite, and differs from it chiefly in that the crystals of ferrite and cementite are not quite perfectly developed and segregated from one another (see Fig. 222). It might at first seem almost like splitting hairs to differentiate between the two, but this is not so, because of the importance of sorbite, due to its having greater strength than pearlite. Pearlite has a finer and more intimately entangled structure than any other slowly cooled steel, and to this we attribute the fact that pure pearlite steel (0.8 per cent carbon) is stronger than any of them. But the structure of sorbite is even finer than that of pearlite, and sorbitic steels are correspondingly stronger than pearlitic steels.




FIG. 222.—Ferrite and sorbite in rail steel. Magnified 250 diameters. Etched with picric acid.

Sorbite may be obtained by quenching the steel immediately below, or just at the end of, cooling through the critical range, or by cooling the steel pretty fast through the critical range without actually quenching, or by rapid cooling and then reheating to about 600°C. (1,110°F.).

**Summary.**—We may summarize the constituents of hardened and tempered steels in the following table, which is adapted from one designed by Howe:



(Courtesy, William Campbell)

FIG. 222A.—Ferrite network with troostite in martensite matrix. Carbon steel of about 0.15 to 0.20 per cent carbon. Rivet stock. Quenched from white heat. Etched. Magnified 90 diameters.

TABLE L.—STAGES OF THE TRANSFORMATION FROM AUSTENITE INTO PEARLITE

Name	Constitution
Austenite.....	Solid solution of an iron carbide in gamma iron.
Martensite, a transition substance..	The next step. Some of the gamma iron is changed to beta and to alpha iron. It is harder than austenite.
Troostite, a transition substance....	The third step. The quantity of gamma and beta iron constantly decreasing, that of alpha iron constantly increasing.
Osmondite (?).....	Solid solution of iron carbide in alpha iron (?)
Sorbite, a transition substance.....	A mixture of a constantly decreasing quantity of osmondite with a constantly increasing quantity of pearlite, too fine to be resolved by the microscope.
Pearlite.....	A conglomerate, or a mechanical mixture of free alpha iron (alpha ferrite) with the iron carbide, $\text{Fe}_3\text{C}$ , cementite.

## PRACTICE IN ANNEALING, HARDENING, AND TEMPERING

**Furnaces.**—There is not space here to discuss the many different types of furnaces used for heating for these purposes, but a good descriptive chapter on the subject will be found in Reference 149. The requisites of such a furnace are: (1) That it shall be of a uniform temperature in all parts of the heating chamber; (2) that it shall heat the pieces uniformly from all sides; (3) that its temperature shall be readily under the control of the operator. It is very desirable also that the temperature should be indicated by means of some scientific instrument instead of the unaided eye of the operator. Skillful as these operators are, it is now generally admitted that a good pyrometer will give more reliable results, and they have the further advantage of giving an autographic record of the temperature which may be kept for future reference. (4) That the metal shall not come in contact with solid fuel, because the carbon or injurious impurities in this fuel, such as sulphur and phosphorus, will be absorbed by the metal and vitiate it. The usual means of heating these furnaces is the flame from combustion of solid fuel, gas or oil, or heat converted from electric energy. Electric heat, although expensive, gives the most effective control of the temperature and also enables us to get with ease, either the highest or lowest temperatures. (5) That ready access to the pieces being heated shall be had so that they may be removed quickly and easily; (6) that the pieces shall be so supported as not to bend under their own weight at the heat to which they are subjected. (7) That means shall be provided, where possible, to prevent oxidation of the iron. This is of major importance in the case of small pieces, or of pieces which are to be treated after machining, or cold rolling, so that they shall be left with a bright surface and good corners. The means for accomplishing this object are usually to heat the pieces inside of muffles around the outside of which the combustion takes place, or else to pack them in air-tight boxes, and sometimes inside these boxes or muffles a stream of reducing gas is led to prevent oxidation, or else the metal is packed in lime or other neutral material, and sometimes a few pieces of charcoal are put inside the muffle or mixed with the lime to unite with any oxygen which finds its way into the interior. Another method of heating to prevent oxidation, which method has the further advantage of obtaining uniform



temperature, heating the piece uniformly on all sides and giving an excellent control of the temperature, is to have the pieces immersed in baths of oil, lead, barium chloride, or other substances in a molten condition. These baths are then uniformly heated and transmit their temperature to the metal.

**Heating for Annealing, etc.**—Annealing has for its object the treble purpose of (1) relieving any strains put upon the metal during its cooling, or by mechanical treatment or otherwise; (2) restoring the grain of the metal to that minute size which gives it the best possible qualities, or (3) softening it after hardening. We may accomplish these three objects, or any of them, in one annealing operation. The usual temperatures of annealing lie between 700 and 1,000°C. (1,290 and 1,830°F.). Temperatures from 200 to 500°C. (930°F.) are sufficient to relieve strains in the metal and to soften it after mechanical treatment or hardening. It is only when we desire to produce a new grain-size that we heat above the critical temperature, and we have already explained that for this latter purpose it is best not to exceed the critical temperature any more than is necessary, with, however, the qualifications noted on pp. 401 and 402, in the case of very bad overheating or ingotism. Where we have obtained by means of cold rolling, wire drawing, or other mechanical work in the cold, a grain-size already small, it is bad practice to form a new grain-size, and therefore the steel should then be heated only to that low temperature which will soften it.

**Hardening Practice.**—When a piece of steel is rapidly cooled, tremendous strains are developed in it as it passes through the critical temperature. We have already studied the phenomenon of recalescence, or liberation of heat within the metal by the chemical reaction of the separation of ferrite and cementite.

The recalescing steel, which has been rapidly contracting due to the falling temperature, now tends to expand because of this liberation of heat. But, as cooling takes place from the outside inward, the outer shell of steel passes through the recalescence period first, and is already beyond that point and contracting further when the interior begins to liberate heat and tend to expand. This brings a double pressure on the steel, and the strains are so large as frequently to cause what are known as "water cracks" in the hardened steel. Sometimes the outer shell of steel actually flies to pieces under the strain, or "bursts," as it is called. Again a long cavity will be opened down the

center of the piece. In the case of armor plate, for example, the appearance of cracks after the hardening of the steel is often welcomed, as it shows that the strains produced in the metal have been relieved to some extent, and a curved turret will actually be stronger under impact after cracking than before, because the latent strains are relieved. The operator must take these matters seriously into consideration, remember that the greatest strains are produced by uneven cooling which may occur through: (1) The juxtaposition of thick and thin sections; (2) uneven temperature of the piece which is heated up, which may best be avoided by the slow heating of large pieces; (3) uneven temperature of the bath in which the steel is quenched, or (4) careless immersion in the bath. An uneven temperature of the bath may be avoided by having small-sized baths with abundant circulation of the quenching medium therein, or else by quenching the objects in a voluminous spray of liquid, such as is practiced in the hardening of armor plate, for example. The operator should move the piece around in the bath as much as is necessary to prevent vapor accumulating next the steel and thus forming a place where the cooling is not so rapid, and the piece must be held in tongs and not allowed to drop to the bottom of the quenching tank.

Hardened pieces occasionally warp as a result of the strains set up. This may be prevented to some extent by having the thickest parts of the piece enter the bath first, and also by annealing the specimen at a relatively low temperature before heating for hardening, in order previously to remove all strains. It may be necessary to clamp pieces of very intricate shape in order mechanically to prevent their warping.

**Quenching Baths.**—The object of the quenching bath is to take the heat away from the metal at the rate of speed best suited for the hardness or other qualities desired to be given to it. Nothing from the bath enters the steel, and it has no virtues other than to remove the heat. It may be, however, that certain baths will cool steel rapidly through the critical range and then slowly thereafter, or *vice versa*, and there may sometimes be virtue in this property. Saturated solutions of certain salts might deposit their dissolved substance uniformly on the surface of the steel and this incrustation may have the effect of cooling the steel more slowly at a lower temperature. Further than this characteristic, the speed of cooling will depend upon the following

factors: (1) Temperature of the bath; (2) heat conductivity of bath; (3) viscosity of the bath. (The importance of viscosity results from the circumstance that liquids carry heat away largely by convection); (4) specific heat of the bath, because the greater the specific heat of substances, the more heat will be absorbed in a given time by the layers adjacent to the quenched body. Furthermore, the greater the specific heat, the greater amount in heat will the bath absorb without rising in temperature; (5) the volatility of the liquid, because the more readily it forms vapor when heated, the more liable is there to be a cushion of vapor between the quenched body and the body of the liquid itself. Mercury, because of its low melting-point, can be refrigerated to a low point and this makes an effective hardening medium. Solutions of calcium chloride will act in the same way. On the other hand, liquid air, in spite of its low temperature, is a poor quenching medium because of its ready volatility.

**Combined Hardening and Tempering.**—If steel be cooled from above the critical range by quenching in some slow heat-conducting liquid in the first instance, as cylinder oil, or melted solder at 200°C. (392°F.), the same intermediate hardening and embrittling effect will be produced upon it as if it were first hardened in water and then tempered a certain amount. Therefore the quenching in oil and similar mediums has come to be called “tempering.” Another method of combining hardening and tempering after only one heating is used in the tempering of the cutting edges of chisels and similar tools: The end of the tool is first heated just above the critical range, and then the extreme point only is quenched in water until it is black, after which it is withdrawn and rubbed bright upon a piece of sandpaper, or upon a brick. This is done merely to give a bright surface upon which to observe the play of temper colors. The heat from the shank now begins to creep down into the point which takes the various temper colors in order, beginning with, the lemon. When the desired degree of tempering is reached—say, the pigeon-wing color—the whole tool is put into water. This is merely to “put out the fire” and stop more heat coming down into the tempered point; it has nothing to do with the tempering operation itself.

**Reheating for Tempering.**—A more accurate method of tempering, because it enables pyrometers to be used and because the operation can be conducted more slowly, is to allow the

hardened piece to cool and then reheat it to a desired temperature at which its temper is to be drawn. By this means also we can reheat the piece in baths of lead-tin alloys, melting at low heats, which insures accurate control and that all parts of the piece are uniformly heated.

**Temper Colors.**—Nature has provided a ready means of determining the temperature of steel between 200 and 300°C (390 and 570°F.) without the aid of thermometers or other instruments, and, since this is the range of temperatures in which practically all of the tempering of hardened steel takes place, this

TABLE LI.—TEMPERATURES FOR TEMPERING VARIOUS TOOLS

	Degrees Fahren- heit	Degrees Centi- grade	
Scrapers for brass.....	Light 437	Lemon 225	Color Steel-engraving tools.
Light turning tools.....			Hammer faces.
Planers for steel.....	to	to	Planers for iron.
Ivory-cutting tools.....			Paper cutters.
Wood-engraving tools.....	455	235	Drills.
Bone-cutting tools.....			Milling cutters.
Wire-drawing plates.....	456	236	Boring cutters.
Leather-cutting dies.....			Screw-cutting dies.
Taps.....	to	to	Chasers.
Rock drills.....			Mill chisels and picks.
Penknives.....			Punches and dies.
Reamers.....			Shear blades.
Half-round bits.....			Planing and molding cut-
Gouges.....			ters.
Plane irons.....	482	250	Stone-cutting tools.
Twist drills.....	483	251	Flat drills.
Wood borers.....			Pressing cutters.
Cup tools.....	to	to	Coopers' tools.
Edging cutters.....	527	275	
Wood bits and augers.....	528	276	Cold chisels for steel.
Dental and surgical instruments			Axes and adzes.
Hack-saws.....	to	to	Cold chisels for cast iron.
Saws for bone and ivory.....			Chisels for wood.
Needles, gimlets.....			Framing chisels.
Circular saws for metal.....	572	300	Screw drivers.
Saws for wood.....			Springs.
	Blue	Color	



provision is a most fortunate one. It comes about through the oxidation of the metal at those different points. At 200°C. (390°F.) a thin film of oxide forms upon the steel, but is not sufficient to hide entirely the white color underneath, so that the combination produces a light-lemon color. As the temperature rises the film of oxide becomes thicker and the yellow color darker until, at about 225°C. (437°F.), it has changed to faint straw.

In Table L are the temperatures and other phenomena relating to the treatment of steel and the temperatures for tempering various tools.

#### CASE-HARDENING, CARBONIZING, OR CEMENTATION

Steel low in carbon is soft and tough but will not withstand wear or abrasion; hard steel, on the other hand, is brittle except, of course, such a steel as manganese alloy steel, whose use is limited by price. Where a steel has to resist a combination of stresses consisting of penetration or abrasion and violent shocks, such a combination of stresses, in other words, as is brought to bear upon armor plate, plowshares, certain gears and pinions, crankshafts, pivots in moving machinery, etc., or a combination of cutting and shocks, such as that which jail bars and burglar-proof safes might have to resist, it is customary to have a combination of metals as explained on p. 233. Or else, we may produce a high-carbon surface on a piece of soft steel by the process known as case-hardening or carbonizing. This case-hardened metal is then heat treated by a hardening or tempering process which makes the outside very hard but leaves the interior tough and ductile. The high carbon of the outside is obtained by virtue of the so-called cementation process.

**Theory of Cementation.**—The principle upon which case-hardening depends is the slow absorption of carbon by iron or steel at a bright-red heat as already partially explained on p. 79. If a piece of soft steel be immersed in melted potassium cyanide at a temperature of 900°C. (1,650°F.), the carbon contained in the cyanide will slowly penetrate the metal. It enters the steel in the form of a solid solution and the amount of carbon and the depth to which it penetrates will depend upon the following conditions in the order to their importance:

1. The temperature of cementation.
2. Time during which it proceeds.
3. The kind of cement material used; for example, potassium cyanide gives a quicker penetration than pure charcoal.

4. The kind of steel used; that is to say, manganese, chromium, tungsten, molybdenum, etc., in the steel increase the rate of cementation, while silicon, aluminum, nickel, titanium, etc., decrease it.

**Temperature of Cementation.**—The cementation process takes place with extreme slowness below the critical temperature of steel, and increases rapidly with the temperature above that point. It is not advisable, however, to carry it on at a very high temperature because the long overheating gives the core of the steel a coarse structure and makes it weak and brittle. Lake gives the following table for the speed of cementation with different substances at varying temperatures.

TABLE LII.—RATE OF PENETRATION OF CARBON INTO STEEL

Temperature in degrees Fahrenheit	Materials used and rate of penetration in inches in 8 hr.				Temperature in degrees Centigrade
	Charcoal 60 per cent + 40 per cent of carbonate of barium	Ferrocyanide 66 per cent + 34 per cent of bichromate	Potassium ferrocyanide alone	Powdered wood char- coal alone	
1,290	.....	.....	.....	.....	700
1,475	0.020	0.033	0.020	0.020	800
1,650	0.088	0.069	0.079	0.048	900
1,830	0.128	0.128	0.128	0.098	1,000
2,010	0.177	0.177	0.198	0.138	1,100

A very usual temperature for cementation is 900°C. (1,650°F.).

**Influence of Time on Cementation.**—The following two tables from Lake also show the influence of the time on the depth of penetration of the carbon for different materials.

TABLE LIII.—RATE OF PENETRATION OF CARBON INTO STEEL

Length of time in hours	Materials used and rate of penetration in inches at 100°C.				
	Carbon 60 per cent + 40 per cent of car- bonate	Ferrocyanide 66 per cent + 34 per cent of bichromate	Powdered wood char- coal alone	Charcoal and carbonate of potassium	Unwashed animal black
1	0.031	0.033	0.028	0.059	0.035
2	0.039	0.037	0.053	0.078	0.059
4	0.047	0.049	0.063	0.094	0.088
6	0.078	0.074	0.072	0.011	0.106
8	0.118	0.128	0.098	0.138	0.128

TABLE LIV.—RATE OF PENETRATION OF CARBON INTO STEEL

Length of time in hours	Materials used and rate of penetration in inches at 900°C.		
	Charred leather	Ground wood charcoal	Barium carbonate and wood charcoal
2	0.045	0.028	0.055
4	0.062	0.042	0.087
8	0.080	0.062	0.111
12	0.110	0.070	0.125

**Carbonizing Material.**—Iron has been carbonized by means of a diamond as early as 1815 without melting the metal, which shows that pure carbon alone may accomplish the result. However, more impure forms of carbon give much more rapid carbonization, and for commercial purposes the materials used are generally charcoal from wood, with which is mixed other substances; powdered bone; charred leather or sugar, this latter being valuable because of the absence of injurious impurities; horn, animal black, lampblack, anthracite, graphite, etc. In the lampblack process it is common to deposit the soot on the surface to be carbonized by means of a smoky gas or oil flame. Gases containing carbon may also be used for cementation, of which carbon monoxide is one of the best; acetylene is also effective. We may also use liquids containing carbon, such as melted potassium cyanide, ferrocyanide of potash (Prussian blue or ferroprussiate of potash). It would appear that the presence of nitrogen assists in the absorption of carbon by the steel and for this reason the various animal and vegetable products mentioned above are preferred to charcoal from the purer materials. It is also common in some cases to introduce gases containing nitrogen, such as ammonia, etc., into the receptacles where the cementation is being carried on.

A very important consideration in case-hardening is that the carbonized material shall penetrate the steel at all points alike and this is assisted by the more intimate contact between the two, so that carbonizing with gas is often preferred to packing the steel in solid materials. Carbonization in liquid cyanides has the same advantage, and doubtless the nitrogen in these

cyanides is an important element in their efficiency. The potassium cyanide bath is a very common means of cementation on account of the convenience of its use and readiness of control. One objection to it, however, is the very bad and poisonous fumes coming from this melted liquid.

**Steel Carbonized.**—We ordinarily carbonize a steel running from 0.10 to 0.22 per cent of carbon in order to have a very tough core and also to avoid the ill effects of overheating of the core which increases with the amount of carbon. The manganese in the steel should be low, because this not only increases the overheating by lowering the critical temperature, but tends to make the outside case brittle. The amount of manganese should generally be under 0.35 per cent and preferably less than 0.25 per cent. Chromium makes the outer surface harder, and refines the grain of the steel besides raising the temperature at which overheating occurs. It increases the strength of the material, but makes it harder to machine. Many pieces for case-hardening contain from 0.50 to 1.50 per cent of chromium. Vanadium and titanium are said to counteract to some extent the effect of chromium in making steel difficult to machine, and to increase its resistance to shock. Nickel is very valuable in case-hardened steel because it increases its strength, decreases the brittleness and the tendency of cracks to spread. From 2 to 3.50 per cent of nickel is commonly used for high-grade material which can stand the extra price. The amount of silicon is usually kept as low as possible on account of its decreasing the depth and speed of cementation, and phosphorus should be under 0.035 per cent as this makes the metal brittle under shock.

**Percentage of Carbon Added.**—On the very surface of the case-hardened material, the amount of carbon will usually be nearly 1 per cent or more, and will run as high as 2.50 per cent in the case of a very long cementation as in the manufacture of armor plate, for example. Lake cites the case of a round bar that was carbonized to the depth of  $\frac{3}{16}$  in. and showed the following percentages of carbon in each  $\frac{1}{16}$  in. turned off the outside: 1.24, 0.85, 0.24 and 0.13 per cent.

**Heat Treatment for Carbonizing.**—In some cases it is customary, in order to save time and expense, to quench out the pieces as they come from the cementation furnace, but it is much better practice to cool them down to a black heat and then reheat and



harden in a separate operation, because this causes a somewhat better diffusion of the carbon at the point where the case-hardening joins the core. This junction line is always a line of weakness, and when the pieces are quenched out from the quenching furnace, there is a distinct line of demarkation, which is notably shaded when the metal is reheated for hardening. Moreover, the reheating restores the grain of the steel which has been somewhat damaged by overheating during the cementation process.

## CHAPTER XVI

### ALLOY STEELS

We have already described ordinary steel (which to distinguish it from the so-called alloy steels is often known as "carbon steel") as an alloy of iron and carbon. But there is another class of materials to which the specific name of "alloy steels" is applied. This comprises steels to which a controlling amount of some alloying element in addition to the carbon is added.

**Definitions.**—The International Committee upon the nomenclature of iron and steel defines alloy steels as "those which owe their properties chiefly to the presence of an element (or elements) other than carbon." The distinction between an element added merely to produce a slight benefit to ordinary carbon steel and the same element added to produce an alloy steel is sometimes a very delicate one. For example, manganese is added in amounts usually less than 1.50 per cent to all Bessemer and open-hearth steels for the sake of getting rid of oxygen and neutralizing the effect of sulphur. Likewise silicon is sometimes added in amounts of 0.1 to 0.2 per cent to get rid of blowholes. But neither of these additions produce what is known as an alloy steel. When we make "manganese steel" containing 11 to 14 per cent manganese, the material has new properties quite different from the same steel without manganese and we therefore get an alloy steel. Similarly "silicon steel" containing 2 or 3 per cent of silicon will have an entirely new set of properties due to the silicon, and will therefore become an alloy steel.

**Influence of Alloying Elements.**—The metals or metalloids added to carbon steel operate to produce one or more of the following changes:

1. To modify the effect of heat treatment, either by changing the temperature of the critical ranges, or the mode of occurrence of the critical changes.

This effects:

- (a) Suppression of the critical range, thus giving austenitic steel at atmospheric temperatures;

- (b) Change in the rate at which critical changes occur; thus giving extra-hard martensitic steel, or else sorbitic steel; etc.;
  - (c) Suppression of the damage due to overheating, thus permitting quenching from near the melting-point.
2. To form compounds or solid solutions with the carbon, or with the iron.
  3. To remove oxides or gases.
  4. To change the form in which carbon occurs.

Almost all alloy steels are used in a heat-treated condition, and they have this peculiarity in common: That they retain a fair degree of ductility as represented by the reduction of area even when hardened so as to be very strong.

**Ternary Alloys.**—A ternary alloy, or three-part alloy, is an alloy composed of iron, carbon, and one other influential element. This class includes the alloy steels which are used most abundantly by man and the most important of which are nickel steel, manganese steel, chrome steel, tungsten steel, molybdenum steel, silicon steel, etc. There are several other ternary steels which have been investigated and used to a small extent, such as boron steels, cobalt steels, etc. The field of useful ternary steels has not yet been fully investigated, and a wide scope is left for future inventors. There are many elements whose influence on steel has not yet been studied, and even among those which are commonly used, there are some of which only limited proportions have been employed.

**Quaternary Steels.**—Quaternary, or four-part, steels consist of iron, carbon, and two other alloying elements. The commonest and most important of these are nickel chromium steels, chrome vanadium, tungsten chromium, nickel manganese, manganese silicon, tungsten molybdenum, nickel vanadium steels, etc. The result produced by adding an alloying element to ordinary carbon steel is astonishing and incapable of being predicated, and that obtained by a combination of two alloying elements is far more so. New products result with properties entirely different, and in some cases almost the opposite, of those of its constituents, so that almost any combination at random may lead to a surprise, even when the effect of different combinations of the same components is known. Therefore the possibilities of quaternary steels seem to be very great and the field has, as yet, hardly been touched.

**Manufacture of Alloy Steels.**—The manufacture of alloy steels is usually very simple and calls for no special comment here. As a general thing the alloying element is added like the recarburizer. For example, in the manufacture of manganese steel the requisite amount of ferromanganese will be added at the end of the process; in the manufacture of nickel steel we may add ferronickel in the same way, but it is more common here to add shotted-nickel during the process and allow it to dissolve in the steel bath and remain there until the metal is tapped; tungsten steels and tungsten chrome steels are often made by the crucible process and the requisite amount of ferrochrome and ferrotungsten, or of metallic chromium and metallic tungsten, is placed on top of the charge when the crucible is filled.

The treatment of some of the alloy steels is not so simple: Nickel steel may be heated, rolled and forged without any great precaution, but these operations are performed upon manganese, tungsten, and some of the other alloy steels only after great difficulty and experience. Under the head of these different steels, I shall describe the proper method of treatment.

### NICKEL STEELS

Nickel steels are the most abundantly used of all the alloy steels. In the ordinary commercial alloys the nickel ranges from 1.50 to 4.50 per cent and usually from 2.00 to 3.75 per cent, while the carbon is usually from 0.20 to 0.50 per cent, and usually between 0.25 to 0.35 per cent. Not counting armor plate, which is really a quaternary steel, containing both nickel and chromium, the most important uses of nickel steel are for structural work in bridges, railroad rails, especially on curves, steel castings, ordnance, engine forgings, shafting, especially marine shafting, case-hardening stock for gears, etc., frame and engine parts for automobiles and aeroplanes, wire cables, connecting rods, axles, especially for automobiles and railroad cars, etc. We can best learn the reasons for these particular uses by discussing the distinctive properties conferred by the nickel, and their usefulness.

**Tensile Properties.**—The chief distinction between nickel steel and carbon steel is the higher elastic limit of the former, and especially the fact that this higher elastic limit is obtained with only a slight decrease in ductility. About 3.50 per cent of nickel added to carbon steel will increase the elastic limit nearly 50




per cent, while reducing the ductility only about 15 to 20 per cent. It is this increase in elastic limit which is probably the chief reason for the increased resistance of nickel steel to what is known as "fatigue," that is to say, its resistance to repeated stresses and alternating stresses<sup>1</sup> under which all steel will ultimately break down, even though the load is far less than that it can bear indefinitely if constantly applied. It is probable that the minute structure of nickel steel is also advantageous in this same connection. About 3.50 per cent of nickel will give steel approximately six times the life in resistance to fatigue. The records of shipping show that the great majority of accidents to vessels at sea come from the breaking of the propeller shafts, which is doubtless due to alternate stresses, because these long shafts are put out of alignment by each passing wave; so now practically all large vessels use hollow nickel steel shafts. It is the higher elastic limit that is responsible also for the use of nickel steel in bridges, ordnance, automobile and aeroplane parts, and wire cables, for we may obtain equal strength with less weight or greater strength with the same weight. Besides the elastic limit the ultimate tensile strength of nickel steel is increased also by the addition of nickel. The increase is not so great in this particular, and consequently the elastic ratio, *i.e.*, the ratio of the elastic limit to the tensile strength, is increased still more greatly. The elastic limit of ordinary rolled carbon steel should be at least one-half of the tensile strength, while that of 3.50 per cent nickel steel should be at least 60 per cent.

**Heat Treatment.**—By means of heat treatment, the strength, hardness and ductility of nickel steel may be increased together. The heat treatment consists of quenching in water from 840° (1,554°F.), which is safely above the top of the critical range, and then reheating to 550°C. (1,022°F.), which is about 200°C. below the point at which the lower critical change begins on heating. This change is the beginning of conversion of pearlite to austenite.

**Crystalline Structure.**—The crystalline structure of nickel steel is more minute than ordinary carbon steel, and this is prob-

<sup>1</sup> Repeated stresses are stresses put upon a body at intervals and relieved meanwhile, while alternate stresses are stresses first in compression and then tension, such, for instance, as the stresses in a wire that is bent backward and forward, or in a rotating shaft that is not absolutely in alignment.

ably one of the chief causes for the toughness of nickel steel, and also for the fact that cracks develop in it relatively slowly; in the yielding of steel to fatigue the damage starts by the opening of a crack of microscopic proportions through the cleavage planes of the crystals, and this crack grows and spreads from crystal to crystal until it is visible to the unaided eye, after which it proceeds with still greater rapidity. As already stated, this development is much slower in nickel steel than in carbon steel. Furthermore, if an armor plate is struck by a projectile, it does not crack so easily, and the cracks do not extend so far if the plate is made of



(From "Steels and Alloys for Special Purposes," Published by Crucible Steel Co. of Amer.)


FIG. 223.—Mechanical properties of nickel steel after double heat treatment.

nickel steel. This fact and the greater strength of nickel steel are the chief reasons for the 3.25 per cent of nickel in all modern armor plate.

**Modulus of Elasticity.**—The modulus of elasticity of nickel steel containing not more than 4 or 5 per cent nickel is about the same as that of carbon steel, namely, about 29,500,000 lb. per square inch. With higher contents of nickel, however, and especially with more than 20 per cent of nickel, the modulus of elasticity is lower. This results in the steel being much more resilient or springy, and this is one of the important reasons why not more than 4 per cent of nickel is put into structural steels,

for a bridge built of steel which was resilient, even though strong, would vibrate so much with the motion of a passing load as to be unpleasant, and even unsafe on account of the repeated stresses set up. The price of nickel, of course, enters into the limitations of the amount used in structural material as well, and it is found that 3.50 per cent can be added without great expense and with beneficial results.

**Hardness.**—Nickel steel is harder than carbon steel, though not so much so but that it can be machined without difficulty. This is taken advantage of in the use of nickel steel railroad rails for curves and other locations where the steel soon wears out.



(From "Steels and Alloys for Special Purposes," Published by Crucible Steel Co. of Amer.)  
FIG. 224.—Mechanical properties of nickel steel after double heat treatment.

The additional strength of the nickel steel is also an advantage in this connection and nickel steel rails have been tried with success upon the famous horseshoe curve of the Pennsylvania Railroad and other places. The hardness of nickel steel is also accompanied by a lower coefficient of friction, and those properties, together with the additional strength, are taken advantage of in the use of nickel steel in axles for automobiles, locomotives and railroad cars. Equal strength can be obtained in an axle of

smaller size which has, of course, less bearing surface, and therefore still further reduced friction. The hardness of nickel steel as compared with carbon steels, in treated and untreated conditions, will be observed by comparing Tables XL and LV and Figs. 223 and 224.

**Soundness.**—Nickel steel castings are relatively free from blowholes and this together with the strength is a reason for the use of this material for castings. They also have a lower melting-point and run more easily in the molds.

**Expansibility.**—The coefficient of expansion of nickel steel is one of its most astonishing and unusual characteristics, for in different samples it varies all the way from practically zero up to the ordinary figure for carbon steels.

Colby gives the following figures for the average coefficient of expansion for each 1°C. temperature:

Carbon steel.....	0.00001036 (Guillaume)
Carbon steel (0.25 per cent C).....	0.00001150 (Charpy)
Soft carbon steel.....	0.00001078 (Browne)
5.00 per cent nickel steel.....	0.00001053 (Guillaume)

**Invar.**—The coefficient of expansion with the ordinary atmospheric changes of temperature becomes less and less as the percentage of nickel increases until, when we reach 36 per cent of nickel, it is less than any metal or alloy known and amounts practically to zero. This alloy is patented and sold under the name of "Invar" and is used for scientific instruments, pendulums of clocks, steel tape-measures for accurate survey work, etc. In a paper read before the American Association for the Advancement of Science, in December, 1906, it was stated that tapes made of invar used experimentally for United States Government survey work showed a very great increase in accuracy over ordinary steel tapes, and also in rapidity of use. These tapes varied an infinitesimal amount during the first few months, after which they became practically constant in length. The cause of this peculiar effect of nickel upon the dilation of steel with an increase in temperature is a result of the effect of nickel upon the critical ranges of the steel, which we shall describe later.

**Platinite.**—As the amount of nickel increases beyond 36 per cent, there is a slight increase in the coefficient of expansion so that when we reach about 42 per cent of nickel, the steel has the same coefficient of expansion and contraction with the atmospheric temperature as has glass. It can therefore be used



for the manufacture of "armored glass," *i.e.*, a plate of glass into which a network of steel wire has been rolled and which is used for fire-proofing, etc., because even though the glass should break, it is held together by the steel network. It can also be used for the electric connections passing through the glass plugs in the base of incandescent electric lights. Platinum has been used altogether for this latter purpose, in spite of its very high cost, because it was the only metal hitherto known that had the correct coefficient of expansion and contraction, and therefore the name of "platinite" has been given to this patented nickel steel alloy.

**Corrodibility.**—Nickel steel corrodes less than carbon steel, both in the presence of the atmosphere, fresh and salt water, the ordinary acids, the smoke of locomotives, etc. Moreover, the degree of corrodibility decreases with each increase in the amount of nickel present. For this reason 30 per cent nickel boiler tubes have been used, especially in marine boilers. The great expense of this material is, however, an obstacle to its common adoption.

**Other Properties.**—Ordinary nickel steel containing about 3.50 per cent of nickel has several other properties which distinguish it from carbon steel, among which we may mention its higher compressive strength and greater toughness under impact. This latter makes nickel steel especially resistant to shocks, for it not only takes a greater blow to bend it but it will bend through more of an angle before cracking. Nickel steel also has a greater shearing strength, which makes it advantageous for rivets, because smaller rivets may be used and this means smaller holes in the structural members that are being joined, and consequently a greater area of these members left to support the strains upon them. In this connection, however, it should be remembered that nickel steel does not weld as well as carbon steel, and therefore greater care is required in upsetting the rivets during the processes of construction. Nickel segregates very little in iron and it also has the advantageous property of hindering the other elements from segregation, so that nickel steel is less liable to these irregularities than carbon steel. In steel over 0.50 per cent carbon, nickel has a tendency to make the carbon come out as graphite.

**Critical Changes.**—Nickel has a very important effect upon the critical changes of iron and steel. This fact will readily be believed because it is known that many of the elements added to

steel produce important changes in the critical points. G. B. Waterhouse, while investigating the effect of 3.80 per cent of nickel upon iron, showed that this amount of nickel did not make any appreciable difference in the mode of occurrence of the critical points on cooling, but it did reduce the temperature at which these critical points occurred by about  $75^{\circ}\text{C}$ . ( $167^{\circ}\text{F}$ .).

As the amount of nickel in the alloys increases the temperatures at which the critical ranges occur become lower and lower until we reach 24 per cent of nickel with 0.40 per cent carbon, when the critical ranges occur below the atmospheric temperature. That is to say, the steel does not ordinarily cool to the point at which the solid solution is decomposed and the beta and alpha allotropic modifications are assumed.

**Irreversible Transformations.**—The great peculiarity of the critical changes of the nickel steel alloys with less than 24 per cent of nickel is that they are irreversible. By this we mean that the change which takes place at one temperature on cooling is not reversed on heating at the same temperature, or anywhere near that temperature. In other words, when we cool a nickel steel containing 20 per cent nickel the solid solution is not decomposed and the alpha allotropic modification is not assumed until we get below  $100^{\circ}\text{C}$ . ( $212^{\circ}\text{F}$ .). But having cooled the steel to that point and decomposed the solution, we can now heat it nearly to  $600^{\circ}\text{C}$ . ( $1,112^{\circ}\text{F}$ .) before the reverse change takes place and we again form the solid solution and the gamma allotropic modification. In other words, it is possible to have a sample of nickel steel between 100 and  $600^{\circ}\text{C}$ . which shall be in either condition we like. With 20 per cent of nickel, nearly 1 per cent of carbon and 1.40 per cent of manganese, the transformation point on cooling is  $188^{\circ}$  below  $0^{\circ}\text{C}$ . ( $306^{\circ}$  below  $0^{\circ}\text{F}$ .), while the transformation point on heating is well above the atmospheric temperature. Therefore at atmospheric temperature we may have such a piece of steel in either condition we like, and a very interesting experiment is formed by having a bar of this steel one end of which has been cooled more than  $188^{\circ}$  below  $0^{\circ}\text{C}$ ., while the other end has not. The end that has been cooled will be magnetic and the other end non-magnetic.

**Micro-structure of Nickel Steels.**—The effect of nickel on critical changes also shows in the micro-structure of the steel, as will be seen from the following (Fig. 225).

This figure is interpreted as follows: Steels very low in carbon have the pearlitic structure until the nickel reaches about 10 per cent, when the structure becomes martensitic. As the carbon increases, the martensitic structure appears with less and less nickel. With 30 per cent of nickel, even low-carbon steels are austenitic in micro-structure. This accounts for the non-magnetic character of steels of high-nickel content.

When we have more than 40 per cent of nickel in our steels, the critical transformations are reversible like ordinary steels. That is to say, they occur at nearly the same temperature on heating as the reverse change does on cooling. It is an interesting fact




FIG. 225.—Constitution at atmospheric temperatures of slowly-cooled steels with varying percentages of nickel and carbon.

that the steels in which the irreversibility of the transformation is most marked—that is to say, the steels from 12 to 25 per cent of nickel—have the highest strength and elastic limit; at about 25 to 30 per cent of nickel, where the irreversible transformation is most erratic, and beyond that point, the strength is much lower.

**Occurrence of Nickel.**—Waterhouse tested his steel containing 3.80 per cent of nickel and found that a part of the nickel was dissolved in the cementite which had the formula  $(\text{FeNi})_3\text{C}$ . The amount of nickel in the cementite was not, however, as great as that in the ferrite. That is to say, the steel, as a whole, contained 3.80 per cent nickel, while the cementite contained only

1.86 per cent, showing that the nickel dissolves more easily in the ferrite than it does in the cementite.

**Electric Resistance Wire.**—Steel of 24 to 30 per cent nickel is used for electric heating purposes in cookers, irons, heat-treating furnaces for temperatures below 1,100°C. (2,012°F.). This steel has an electrical resistance eight to nine times that of ordinary steel.

### MANGANESE STEEL

We owe the discovery of manganese steel to the untiring ingenuity of Robert A. Hadfield, of Sheffield, England, and its story will be an inspiration to every inventor, for it resulted in a material whose properties are not only the opposite of what we might reasonably have expected on logical grounds, but whose combination of great hardness and great ductility was hitherto unknown and might readily have been believed to be impossible. Constant study and perseverance must have been the qualities that led to this revolutionary invention, and it has established beyond question the principle that because a given amount of any element produces a given effect upon steels, it does not follow that a different amount will give the same effect in a different degree. Indeed a different amount may give an entirely different, and perhaps an exactly contrary, effect, as is the case of the effect of manganese upon steel.

When the manganese in steel is over 1 per cent the metal becomes hard and somewhat brittle, and these qualities increase in intensity with every increase of manganese until, when we have 4 to 5.50 per cent the steel can be powdered under the hammer. But as the manganese is increased from this point, these properties do not increase and when we reach 7 per cent, an entirely new set of properties begin to appear. These are well marked at 10 per cent of manganese, and reach a maximum at 12 to 15 per cent.

**Composition.**—Manganese steel usually contains about 11 to 14 per cent of manganese and 1.0 to 1.3 per cent of carbon.<sup>1</sup> With this amount of manganese the strength and ductility of the material reaches its maximum. The silicon is 0.3 to 0.8 per cent, the phosphorus under 0.08 per cent and the sulphur very low, on account of the easy washing out of sulphur by manganese. The melting-point of this steel is 1,325°C. (2,417°F.).

<sup>1</sup> Manganese steel that is to be forged or rolled is made lower in carbon than this.



A cheaper manganese steel is made with 7 to 8 per cent of manganese. It has lower ductility, but greater elastic limit than the 13 per cent grade.

**Treatment.**—After manganese steel has been cast into an ingot or casting, and slowly cooled, it is almost as brittle as glass. But it is then reheated to a temperature of more than  $1,000^{\circ}\text{C}$ . ( $1,832^{\circ}\text{F}$ .) and rapidly cooled by plunging it into water. The temperature from which it is necessary to quench it can readily be determined, for it must be so high that when the steel is quenched little blue flames of hydrogen will appear on the surface of the water. These are due to the decomposition of water into hydrogen and oxygen by the intense heat of the steel at the moment of touching it. The steel which was very brittle before this treatment is afterward as ductile as soft carbon steel or wrought iron, while its tensile strength is about three times as great. Thus the sudden cooling, which produces brittleness in ordinary steel, produces ductility in manganese steel. The hardness of the manganese steel is about the same in the slowly cooled and in the quenched condition, and is so great that it is not commercially practicable to machine it and there is no method known of making it softer.

Manganese steel must be heated very slowly and uniformly lest it crack. It is also very difficult to forge it, and this can only be accomplished within a narrow range of temperature above a red heat and by beginning with very light taps of the hammer. After a little working it becomes so tough that it can be rolled, although somewhat gingerly.

**Manufacture.**—The metal is first purified in the Bessemer, electric or open-hearth furnace, and then manganese added in the form of melted ferromanganese, as in ordinary recarburizing, except for melting and the extra quantity used. Most of the manganese steel made is used in the form of castings, because of the difficulty of forging or rolling, but railroad rails are rolled, and some plate to be perforated and used for screening, etc.

**Effect of Working.**—Cast manganese steel, after treatment, will have a tensile strength of about 80,000 lb. per square inch, with an elongation of 20 per cent in 8 in. The same material, if forged or rolled and heat treated, will increase to 140,000 lb. tenacity and 50 per cent elongation. If rolled cold the strength may increase to 250,000 lb. with elastic limit of 230,000 lb., but without appreciable ductility.

**Uses.**—Manganese steel is used chiefly for the jaws and wearing parts of rock-crushing and digging or quarrying machinery, for railroad frogs and crossings, for railroad rails on curves, mine car wheels, and burglar-proof safes. Its life in these classes of service is very many times that of all other kinds of steel, because it is not only extremely hard but is without brittleness. There is a famous curve on the Boston elevated railroad where carbon steel rails were worn out in a very short time and the use of manganese steel rails has proved very advantageous and economical. The use of the steel for burglar-proof safes is also very advantageous, because there is no known method of making the steel soft enough to be penetrated by a drill. The uses of manganese steel are limited chiefly because the metal must ordinarily be formed by casting, since machining and cutting to shape is practically out of the question, and forging is difficult. For structural work the advantages of its high combination of strength and ductility are somewhat offset by its low elastic limit, which is only about 35 per cent of its ultimate tensile strength. One peculiarity of manganese steel is that when it yields to tensile stresses it is elongated more uniformly over its whole length than carbon steel, which suffers its greatest elongation near the point of final rupture where a certain amount of "necking" takes place. It will be remembered that wrought iron stretches more uniformly over its whole length than steel; manganese steel has this property in a still more marked degree even than wrought iron.

**Critical Changes.**—The hardness of manganese steel is due, in part, to the hardness of manganese, but still more potently to the fact that the steel is in the austenitic condition. That is to say, the manganese has reduced the temperature at which the critical changes occur below that of the atmosphere, and therefore manganese steel consists entirely of austenite. It is, of course, non-magnetic.

### CHROME STEEL

Chromium has the effect of making the critical changes of steel take place at a higher temperature and much more slowly. For the latter reason chromium steels are capable of greater hardness, because rapid cooling is able more completely to prevent the decomposition of austenite. They contain usually 0.5 to 2 per cent of chromium and from 0.70 to 2 per cent of carbon and are used in the hardened state. On account of their hardness and

TABLE LV—EFFECT OF DOUBLE-HEAT TREATMENTS ON TERNARY STEELS

Name	Analysis <sup>1</sup>					Heat treatment			Tensile strength, pounds per square inch					Hardness		Authority
	C	Si	Mn	Ni	Cr	First		Second	Ultimate	Elastic limit	Elonga- tion in 2 in., per cent	Reduction of area, per cent	Brinell	Shore		
						Degrees Centi- grade	Degrees Fahren- heit								Degrees Centi- grade	
Simple chrome steels	0.70	0.09	0.54	....	0.70	816 W	.....	593	1,100	129,000	121,700	21	60	235	..	Hibbard <sup>2</sup>
						816	1,500	649	1,200	110,900	105,300	26	63	195	..	Hibbard <sup>2</sup>
						816	.....	754	1,400	88,000	73,000	36	68	168	..	Hibbard <sup>2</sup>
	0.40	0.54	0.78	....	0.92	816	1,500	538	1,000	143,500	131,600	18	56	242	..	Hibbard <sup>2</sup>
						816	1,500	714	1,317	103,200	90,200	26	69	201	..	Hibbard <sup>2</sup>
	0.64	0.18	0.27	....	1.01	870 O	1,600	400	752	228,000	170,000	5	14	478	..	Camp <sup>3</sup>
						870	1,600	500	932	212,500	155,500	8	20	445	..	Camp <sup>3</sup>
						870	1,600	600	1,112	186,500	128,000	10	22	389	..	Camp <sup>3</sup>
	0.37	0.22	0.61	3.27	....		Steel as rolled			113,000	69,000	23	48	229	32	Camp <sup>3</sup>
						760	1,400	(Annealed)		99,000	60,000	25	48	183	26	Camp <sup>3</sup>
Simple nickel- steel (see also Fig. 223)						815 W	1,499	427	800	185,000	165,000	13	51	352	50	Camp <sup>3</sup>
						815	1,499	538	1,000	148,000	135,000	16	55	293	44	Camp <sup>3</sup>
						815	1,499	704	1,300	98,000	67,000	28	59	179	29	Camp <sup>3</sup>
						815 O	1,499	427	800	168,000	150,000	4	47	331	48	Camp <sup>3</sup>
						815	1,499	538	1,000	133,000	118,000	21	57	262	40	Camp <sup>3</sup>
"Silico- manganese"						815	1,499	704	1,000	95,000	62,500	29	52	179	26	Camp <sup>3</sup>
		1.25 to 2.50	0.50 to 0.70	.....	.....	.....	.....	...	.....	250,000	230,000	9	40	Over 400	..	Hibbard <sup>2</sup>
										195,000	175,000	9	28	...	..	C. S. A.

<sup>1</sup> Sulphur and phosphorus below 0.03 per cent, and usually under 0.02 per cent. Repetitions of analyses avoided for simplicity, but will be understood as following down.

<sup>2</sup> Hibbard, Manufacture and Uses of Alloy Steel, N. Y., 1919.

<sup>3</sup> Camp, See No. 7.

W = Quenched in water.

O = Quenched in oil.

C. S. A. = Crucible Steel Co. of America, "Steels and Alloys," Pittsburgh, 1919.

also their very high elastic limit, they are used for parts of crushing machinery, and for very hard steel plate. This latter is not ordinarily used by itself, but is made into three-ply and five-ply plate for plows and burglar-proof safes, as described on page 233, for if the hardened chrome steel were used alone, its brittleness would cause it to be shattered. A common use is for shoes and dies for gold-stamping machinery, for which purpose the steel is used in the annealed condition, with 0.8 to 0.9 per cent carbon and 0.4 to 0.5 per cent chromium. Another use is ball and roller bearings, for which purpose treated chrome steel is especially adapted on account of its great compressive strength, hardness and resiliency. For this use it is heated to 774°C. (1,425°F.) for small balls and 802°C. for large balls, which do not cool so rapidly. After quenching in water from these temperatures, the hardness is drawn very slightly by heating for  $\frac{1}{2}$  hr. to 190°C. (375°F.). In these balls the carbon is 1.10 per cent and the chromium 1 to 1.5 per cent. For extra hard metal for cold rolling other metals chromium steel of 0.9 per cent carbon and 2 per cent chromium is used in the hardened and untempered condition. Table LV shows some chrome steels of high tensile strength, formerly used for automobile parts, but now largely replaced by chrome nickel steels, on account of greater ductility of the latter.

**Stainless Steel.**—A patented steel containing about 12 per cent of chromium is non-corrodible, non-tarnishable, not oxidized when heated to the usual tempering temperatures, and not attacked by several acids, including nitric, or by the corrosive gases from the exhaust of gas engines, etc. It is therefore coming into use for table cutlery, heads of golf clubs, skates, rifles, stirrups and other harness hardware, as well as for exhaust valves on automobile engines, steam traps, water meters, parts of pumps for acid waters, etc. It goes under the trade name of stainless steel.

#### SELF-HARDENING AND HIGH-SPEED TOOL STEELS

**Self-hardening Steel.**—Self-hardening steel is steel which is hard without being subjected to any heat treatment or other process for making it so. It is steel which cannot be made soft, or annealed, by any process known at present. It is often called "air-hardening steel" because when it cools in the air from a red heat or above, it is not soft like ordinary steel, but is hard and



capable of cutting other metals. Manganese steel is a typical self-hardening steel and so obviously is any steel which is in the austenitic condition at atmospheric temperatures—that is to say, whose critical temperature is below the atmospheric temperature. All the self-hardening steels are therefore non-magnetic.

**Mushet Steel.**—The name “self-hardening” steel was first applied to an alloy steel invented by Robert Mushet and which owed its self-hardening properties to the simultaneous presence of both tungsten and manganese. The analyses varied greatly, but were probably limited to between 4 and 12 per cent of tungsten with 2 to 4 per cent of manganese and 1.50 to 2.50 per cent of carbon. A typical sample and one having excellent qualities contained about 9 per cent of tungsten, 2.50 per cent of manganese, and 1.85 per cent of carbon. This steel is incapable of being made soft by any known process and is non-magnetic. It is one of those curious phenomena met in the metallurgy of steel, where a combination of two elements will produce a result entirely different from anything that might be predicated: Tungsten does not lower the temperature of the critical change in steel and 2.50 per cent of manganese has but a slight effect in that direction. Nevertheless the combination of these two reduces the critical point below the atmospheric temperature.

Mushet steel has been, for many years, a famous tool steel because of its capacity for performing a large amount of heavy cutting work. It is very hard and durable and will retain its cutting edge for a long time and under very severe service. It, or its equivalent, is used very largely at the present time for very heavy, or deep, cuts and especially for cutting extra hard metal, such as the roughing cuts on armor plate and other hard alloys. The cutting speed of which it is capable is not much, if any, greater than ordinary carbon tool steel, but the economy of its use is due to the fact that it will take such deep cuts and last so long without regrinding.

**Other Self-hardening Tool Steels.**—The 2.50 per cent of manganese in Mushet steel can be replaced by 1 or 2 per cent of chromium and again produce a self-hardening tool steel which has the advantageous properties of Mushet steel. This result is even more astonishing than the self-hardening properties of Mushet steel, because chromium has a tendency to raise the temperature at which the critical change comes, and yet the addition of 1 or 2 per cent of chromium to a tungsten steel, which

was not previously self-hardening and whose critical temperature was about 600°C. (1,112°F.), reduces the critical temperature to below the atmosphere. We may also replace the 9 per cent of tungsten in Mushet steel with 4 to 6 per cent of molybdenum, and it is stated that this latter change produces a self-hardening tool steel which is a little tougher than Mushet steel.

**Taylor and White.**—Frederick W. Taylor and Maunsel White of the Bethlehem Steel Works experimented for a long time with the self-hardening steels existing in 1899 and previously, for the purpose of improving them by heat treatment. The full record of these and other researches were presented by Taylor in his presidential address to the American Society of Mechanical Engineers in 1906, and form one of the most interesting records of the kind ever presented to the world. The result of these experiments was to produce a wholly new kind of steel which has fairly revolutionized the machine shop industry of the world. Taylor and White found that by applying a new method of heat treatment to the self-hardening tool steels, they gave them much greater toughness at a red heat, so that they could do their cutting work at a speed so fast that the point of the tool would become red hot with the heat of friction and the great chips of steel, which were thick and heavy on account of the depth of cut which could be made, were raised to a temperature of nearly 300°C. (572°F.). In other words, the steel tool never lost its temper nor its toughness at a red heat. The heat treatment which Taylor and White employed consisted in raising the steel almost to the melting point and then plunging it in a bath of molten lead at a temperature between 700 and 850°C. (1,300 and 1,550°F.), where it was kept until it was of the same temperature as the bath, and then removed and cooled by plunging into oil. They usually followed this cooling by reheating the steel to a temperature between 370 and 670°C. (700 and 1,240°F.).

The first public exhibition of the Taylor and White steel was made at the Paris Exposition in 1900 and created first incredulity and then astonishment. The amount of work performed by a tool was unheard of, as also was the speed at which the tool was made to travel through the metal it was cutting, and the length of time that elapsed before it was necessary to regrind it. It was realized that a new epoch in the tool-steel industry had been inaugurated. The fact that the method of heat treatment used by Taylor and White was subsequently shown to be unnecessary

and that therefore the manufacture of high-speed steel tools, having qualities like theirs, was begun by everybody, in no way lessens the credit due them for teaching the world how to produce a new kind of metal and effecting a tremendous decrease in the price of machine work.

**High-speed Steels.**—The name “high-speed steels” was not given by Taylor and White to their product, but has subsequently been adopted for all steels capable of these rapid-cutting speeds which theirs had. Soon after they had shown the world what could be done, it was found that the only heat treatment necessary to give the steel its peculiar hardness and toughness at a low-red heat was to raise it to a temperature very near its melting-point and then cool it with moderate rapidity, as for example, by holding it in a blast of cold air until it was below a red heat. The essential feature seems to be that the steel shall attain a high temperature ( $1,260^{\circ}\text{C.} = 2,300^{\circ}\text{F.}$ ), which is so great that melted oxide forms on it, and it is almost ready to scintillate—that is to say, it has almost crossed the line *Aa* in Fig. 165, p. 326. After this heating it sometimes suffices merely to allow the steel to cool in air, but in this case its hardness is not so great, and cooling in oil is more usual. For some purposes it is reheated slightly above  $550^{\circ}\text{C.}$  ( $1,022^{\circ}\text{F.}$ ) to increase its toughness.

**Composition.**—It was also soon found that the composition of the self-hardening steels was not the best one for high-speed steel. Tungsten was the element which gave the steel the properties of hardness and toughness at a red heat. After the peculiar heat treatment had been learned and the presence of manganese or chromium in addition to the tungsten was shown to be unnecessary, it was found that more durable qualities could be obtained by increasing the percentage of tungsten, and steels have been put upon the market with as high as 24 per cent of this element, but 15 to 20 per cent is the usual proportion at present. At the same time the carbon was greatly reduced and at the present usually varies from 0.55 to 0.75 per cent in the best high-speed steels.<sup>1</sup> The manganese is low, 0.15 to 0.35 per cent; silicon, 0.10 to 0.25; chromium, 4 per cent; vanadium, 1 per cent.

<sup>1</sup> It is commonly stated in the trade that tungsten will take the place of carbon in producing hardness, but this is not true. It is far more correct to say that tungsten will assist carbon in producing hardness and therefore with high tungsten steels we may have lower carbon. This distinction

**Forging.**—High-speed steels can only be forged at temperatures above a bright-red heat, that is to say, from 1,050 to 1,150°C. (1,922 to 2,100°F.) and higher.

**Annealing.**—The heating and annealing of high-speed steels requires a great deal of care. They must be heated up to the annealing temperature (say about 800°C. = 1,472°F.) with extreme slowness, and cooled down in lime or ashes or in the furnace. They are then soft enough to be machined easily, but not as soft as carbon steel.

**Tempering.**—Tungsten and molybdenum prolong the critical range of temperatures of steel on slow cooling; that is to say, instead of the critical range coming in the neighborhood of 690°C. (1,285°F.), as with the carbon steels, it begins, when the cooling is slow, at about 700°C. and spreads out all the way down to 300 or 400°C. (572 or 752°F.), or even lower. Molybdenum is more active than tungsten in causing this prolongation of the critical range. But if the steels are first heated to a very high temperature (1,000 to 1,100°C. for molybdenum steel and 1,260°C. for tungsten = 1,832 to 2,012 and 2,300°F. respectively) and then cooled moderately fast, this treatment suffices to prevent the critical changes altogether and preserves the steel in the austenitic condition. We know that this austenitic condition is one of hardness and toughness and its peculiarity under these circumstances is that it is not transformed into the pearlitic condition until the steels are heated above 550°C. (1,022°F.).

**Rationale of High Speed.**—The reason offered for the hardness of high-speed steel up to the red heat is the following, according to Hibbard: At temperatures above 1,200°C. (2,192°F.) the affinity of carbon for tungsten (or molybdenum) exceeds that for iron, and the carbon present forms a double carbide with the tungsten and chromium. This carbide does not separate from solution in iron(austenite) unless the cooling is very slow indeed, and it is stable up to temperatures of 550°C. (1,022°F.). Therefore simple cooling in a blast of air, or slightly accelerated cooling

may appear merely academic, but it is well worth recognition by those who expect to make a study of these steels. No amount of tungsten or any other element will make steel hard in the absence of carbon, or even when the carbon is low. The tungsten produces hardness by its effect upon the condition of the carbon—that is, by helping to retain the carbon in its solid solution—and not by any effect of its own. It is for this reason that a lesser amount of carbon will produce hardness in the presence of tungsten or some similar agent.



in oil, suffices to preserve the special austenite formed by heating to  $1,260^{\circ}\text{C}.$ , and the steel must be heated above  $550^{\circ}\text{C}.$  to decompose it.

**Magnet Steel.**—Strictly speaking, the steel used for permanent magnets is not high-speed steel, because, of course, magnets are never used for cutting work, but as their composition is so similar it seems well to introduce them here. A permanent magnet is made by putting a piece of hardened steel in a magnetic field for a few moments, as, for instance, by winding an insulated wire around it and passing an electric current through. The magnetic force which it obtains in this way will remain in it for a very long period of time. It is found that a steel containing about 6 per cent of tungsten and 0.50 to 0.70 per cent of carbon, if heated to a red heat (say  $800^{\circ}\text{C}.$  =  $1,472^{\circ}\text{F}.$ ) and quenched in water, will retain its magnetism better than ordinary hardened carbon-steel. Sometimes about 0.40 per cent of chromium is added to the alloy also, which increases the permanency but decreases the magnetic force, the reason being no doubt that there are more gamma and less alpha molecules (see p. 350).

#### SILICON STEELS

The genius of Hadfield has also given us a silicon steel alloy of importance and usefulness. In 1888 Hadfield investigated many alloys of iron and silicon and although these showed some remarkable properties, especially in the matter of tempering and cutting qualities, they did not lead to any alloy steels that were produced in abundance. At a later period, however, Hadfield developed a silicon steel which, after a double-heat treatment, showed some truly remarkable magnetic qualities. It had always been believed that pure iron had the highest magnetic force and permeability of any known substance or of any combination that could be produced, but Hadfield's new silicon steel, whose composition and treatment is shown below, had not only a greater magnetic permeability than the purest commercial iron, but also, characteristic of silicon steels, it had a high electrical resistance. Its hysteresis is, of course, low, this property always accompanying a high permeability. It is therefore a very valuable material for use in electromagnets, and in electrical generating machinery is the most efficient material known. Its high magnetic permeability gives high motor efficiency, and in addition its high electrical resistance reduces the "eddy currents" which are a source of waste.

**Composition and Treatment.**—Hadfield's patent covers silicon from 1 to 5 per cent, but the alloy now usually made contains 4 to 4½ per cent of silicon and the smallest possible amounts of carbon, manganese and other impurities. Before the steel is ready for use, it is subjected to a double heat treatment by first heating it to between 900 and 1,100°C. (1,652 and 2,012°F.) and cooling quickly, and then reheating to between 700 and 850°C. (1,292 and 1,562°F.) and allowing to cool very slowly. In some cases his second cooling has been extended over several days. He finds the best results by heating first to 1,070°C. (1,958°F.) and cooling quickly to atmospheric temperature and then heating to 750°C. (1,382°F.) and cooling slowly, after which he sometimes again reheats to 800°C. (1,472°F.) and then cools slowly.

**"Silico-manganese" Steel.**—Steel containing 1.25 to 2.50 per cent silicon and 0.50 to 0.70 per cent manganese is used, after a double-heat treatment, for springs. It has a higher strength, fiber stress and lower deflection under load than carbon steel, but is cheaper in price than chrome vanadium, and other special spring steels. Some of its qualities are shown in Table LV.

#### DOUBLE-HEAT TREATMENTS OF TERNARY STEELS

Under the head of ternary steels commonly subjected to double heat treatment we may include:

Simple nickel steel—3½ per cent;

Simple chrome steel—½ to 1 per cent;

"Silico-manganese" steel.

The latter is really a silicon steel, with manganese of normal proportions for commercial steels. The double heat treatment consists in first accelerated cooling from above the lower critical point,  $A_{c1}$  = the line *PSK* in Fig. 165, p. 326, followed by a letting-down, or drawing, of the extreme strength and hardness by reheating to temperatures approaching, but always below, the line *PSK*.

The temperature of the first heating will depend on two considerations: (1) The position of the line *PSK* will depend on the steel, for it is different with each alloy steel. (2) The higher above the line *PSK* we go the stronger and harder will the steel be, provided we do not heat so high as to produce a coarse crystalline structure. The actual temperature of the first heating is between 800 and 900°C. (1,472 and 1,652°F.).

The second heating is usually above the tempering range for tool steels, but never so high as to again cross the line *PSK*. It ranges between 200 and 725°C. (392 and 1,382°F.), but drawing temperatures below 400°C. (752°F.) are used only when toughness is to be sacrificed to strength.

Table LV illustrates the effect of different double treatments on ternary steels.

### NICKEL CHROME STEELS

Chrome nickel, or nickel chromium, steels used to find their most extensive employment in naval armor plate, because of the intense hardness of the carburized and heat-treated surface, to which the presence of chromium contributed; because of the minute crystalline structure with its resultant resistance to development of cracks, induced largely by the nickel; and, finally, because of the great strength combined with ductility which is characteristic of nickel chromium steels. No superior has been found to this steel for the purpose, but not much armor plate is now being made (1923). The formula included about 4 per cent nickel, 2 per cent chromium, and 0.33 per cent carbon. Nickel chrome steel is used also in most armor-piercing projectiles.

Automobile nickel chrome steels comprise nearly a score of combinations of carbon 0.15 to 0.55 per cent; nickel 1.25 to 3.50 per cent; and chromium 0.60 to 1.50 per cent. The amount of nickel and chromium used will depend on the relative importance of strength with ductility versus cost. A general idea of the properties may be gained from Table LVI, and from the fact that a nickel chrome steel may be had with 12 per cent elongation in 2 in., 45 per cent reduction of area and elastic limit over 200,000 lb. per square inch.

### CHROME VANADIUM STEELS

If the purpose for which steel is to be used does not require ductility greater than 12 per cent elongation in 2 in. and 45 per cent reduction of area, then the highest strength and elastic limit may be obtained with a chrome nickel steel. But if we want the best combination of reduction of area with elastic limit, then the chrome vanadium steels excel. This will be illustrated by the figures in Table LVI. By suitable heat treatment, which will be evident from Table LVI, hardened chrome vanadium steel may

Name	Analysis <sup>1</sup>						Heat treatment				Tensile strength			Hardness		Authority							
	C	Si	Mn	Ni	Cr	V	Degrees Centigrade		Degrees Fahrenheit		Pounds per square inch		Elongation in 2 in.	Reduction of area	Brinell		Shore						
							First	Second	First	Second	Ultimate	Elastic limit											
Nickel chrome castings	0.30	....	0.41	3.64	1.49	0.0	Annealed	Annealed	Annealed	Annealed	91,500	45,550	17	24	...	..	Hibbard <sup>2</sup>						
	0.33	....	0.39	3.58	1.61	0.0					90,500	46,500	19	27	...	..	Hibbard <sup>2</sup>						
	0.30	....	0.20	2.50	0.50	0.0	Heat treated	Heat treated	Heat treated	Heat treated	110,000	80,000	20	30	...	..	Hibbard <sup>2</sup>						
	0.39	0.18	0.52	1.18	0.58	0.0					99,000	59,000	26	54	208	29	Camp <sup>4</sup>						
Low nickel chrome rolled steels	0.20	....	0.65	1.25	0.60	0.0	As rolled	As rolled	As rolled	As rolled	89,000	54,000	30	57	70	25	Camp <sup>4</sup>						
											845 O	427	1,550	1,000	139,000	114,000	16	51	331	42	Camp <sup>4</sup>		
											845 S	538	1,550	1,000	113,000	88,000	18	60	255	54	Camp <sup>4</sup>		
											845 S	649	1,550	1,200	108,000	81,000	25	65	229	31	Camp <sup>4</sup>		
											845 S	704	1,550	1,300	97,000	70,000	27	68	207	29	Camp <sup>4</sup>		
											845 W	427	1,550	1,000	174,000	158,000	14	57	363	46	Camp <sup>4</sup>		
											845 S	538	1,550	1,000	140,000	125,000	20	55	285	44	Camp <sup>4</sup>		
											845 S	649	1,550	1,200	110,000	91,000	26	66	229	33	Camp <sup>4</sup>		
											845 S	704	1,550	1,300	90,000	70,000	34	69	187	25	Camp <sup>4</sup>		
											870	214	1,598	1,400	160,000 <sup>2</sup>	120,000 <sup>2</sup>	15	53	275	45	S. A. E. Specifications		
											870	538	1,598	1,000	100,000 <sup>2</sup>	74,000	25	74	185	36	S. A. E. Specifications		
											870	649	1,598	1,200	84,000 <sup>2</sup>	60,000	32	72	160	30	S. A. E. Specifications		
High chrome nickel rolled steel	0.40	....	0.65	1.25	0.60	0.0	As rolled	As rolled	As rolled	As rolled	75,000	50,000	35	73	150	28	S. A. E. Specifications						
											870	214	1,598	1,400	220,000 <sup>2</sup>	190,000	8	27	375	55	S. A. E. Specifications		
											870	649	1,598	1,200	100,000 <sup>2</sup>	84,000	18	60	225	38	S. A. E. Specifications		
											0.34	0.20	0.64	3.65	1.24	0.0	172,500	138,000	12	27	444	57	Camp <sup>4</sup>
Chrome vanadium rolled steels	0.19	0.05	0.49	0.0	0.96	0.23	As rolled	As rolled	As rolled	As rolled	125,000	78,000	18	47	255	38	Camp <sup>4</sup>						
											845 O	427	1,550	1,000	166,000	133,000	23	50	415	55	Camp <sup>4</sup>		
											845 S	649	1,550	1,200	117,000	99,000	23	65	255	37	Camp <sup>4</sup>		
											845 W	427	1,550	1,000	164,000	152,000	18	56	375	51	Camp <sup>4</sup>		
											845 S	649	1,550	1,200	120,000	60,000	17	58	369	36	Camp <sup>4</sup>		
											850	574	1,562	1,065	146,900	137,200	20	58	...	...	Camp <sup>4</sup>		
											850	749	1,562	1,380	101,400	91,200	27	69	...	...	Camp <sup>4</sup>		
											850	574	1,562	1,065	132,400	125,800	20	64	...	...	Camp <sup>4</sup>		
											850	749	1,562	1,380	88,640	78,960	29	77	...	...	Camp <sup>4</sup>		
											815	427	1,499	800	177,500	155,000	11	36	...	...	Camp <sup>4</sup>		
O = Quenched in oil; W = Quenched in water.	0.57	0.27	0.84	0.0	1.36	0.31	Untreated	Untreated	Untreated	Untreated	118,000	101,000	23	60	...	...	Camp <sup>4</sup>						
											0.46	0.20	0.45	0.0	1.17	0.14	142,000	114,000	14	42	...	...	Camp <sup>4</sup>
											0.18	0.18	0.32	0.0	0.74	0.20	125,000	95,000	20	55	...	...	Camp <sup>4</sup>
											65,000	47,000	23	62	...	...	Camp <sup>4</sup>						

O = Quenched in oil;

W = Quenched in water.

<sup>1</sup> S and P below 0.03 %, and usually below 0.02 %.<sup>2</sup> Minimum requirement.<sup>3</sup> "Mfg. & Uses of Alloy Steel," N. Y., 1919.<sup>4</sup> "Making, Shaping and Treating of Steel," 2nd Ed., 1920.





be had with tensile strength of 250,000 lb. per square inch, and elastic limit of 210,000 lb.

Chrome vanadium steels are largely used in automobile and aeroplane construction, especially for crankshafts, case-hardened gears and other wearing parts, and all parts under great strain, like axles, shafts, piston rods, pins, etc. Also in other machinery of costly construction.

Most static structural chrome vanadium steels contain chromium 0.80 to 1.10 and vanadium not under 0.15 per cent, but usually not over 0.25 per cent. For spring steel the chromium will be 1 to 1.25 per cent, and the carbon will be above the structural steel limit, *i.e.*, it will be 0.50 to 0.65 per cent.

### ALLOY STEELS OF HIGHEST QUALITIES

**Steels of Highest Strength with Safety.**—A large American manufacturer gives the following table of heat-treated steels, based on the highest strengths obtainable with safety, which he predicates as elongation not under 12 per cent and reduction of area not under 45 per cent:

TABLE LVIII.—EXTRA STRONG STEELS

	Tensile strengths			
	Pounds per square inch		Elongation in 2 in., per cent	Reduction of area, per cent
	Ultimate	Elastic limit		
Aeroplane" alloy steel (composition "not given).....	245,000	220,000	11	45
Chrome nickel gear steel.....	235,000	208,000	12	45
Chrome nickel gear steel.....	192,000	165,000	14	45
Chrome vanadium forging steel.....	165,000	150,000	16	45
Simple nickel forging steel.....	200,000	178,000	14	45
Carbon forging steel.....	155,000	135,000	12	45

All these steels have been forged; steel castings cannot be made of this quality.

If steels are wanted with greater ductility, for which some strength must be sacrificed, their composition and heat treatment may be learned from Tables LV and LVI.

**Steel for Springs.**—The highest obtainable elastic limit without brittleness is the desideratum for springs. Some of the heat-treated chrome nickel steels which have been treated with vanadium have been used with success and are recommended

where price is not a limiting factor. A manufacturer gives the following data:

TABLE LVIX.—DEFLECTION TEST OF STEELS FOR SPRINGS<sup>1</sup>

	Deflection at elastic limit	Load in pounds	Fiber stress per square inch	Tensile strength			
				Pounds per square inch		Elongation in 2 in., per cent	Reduction in area, per cent
				Ultimate	Elastic limit		
Alloy steel (composition not given).....	1.006	3,280	301,000	220,000	200,000	13	45
Alloy steel (composition not given).....	0.953	3,120	286,000	210,000	180,000	15	40
Chrome vanadium steel....	0.855	2,800	256,000	190,000	175,000	11	30
Silico-manganese steel.....	0.860	2,820	258,000	195,000	175,000	9	28

<sup>1</sup> This deflection test applied the load midway between supports 10.25 in. apart on a specimen  $2\frac{1}{2} \times 0.259 \times 15$  in.

## CHAPTER XVII

### THE CORROSION OF IRON AND STEEL

Iron offers so little resistance to rusting or corrosion that there are almost no circumstances of service in which it can safely be placed without some means of protection from the elements. Certain parts of machinery, in situations where rusting is not very rapid, and where the metal will receive constant cleaning and oversight, are used without any protective coating, but structural work, in and outside of buildings, tin roofs,<sup>1</sup> wire fences, pipes and other metallic structures, all require to be protected by some coating, such as paint, galvanizing,<sup>2</sup> tinning, nickel plating, oxidizing, etc. Boiler tubes and the inside of boilers tanks, and pipes it is usually impossible to protect by paint, galvanizing, etc., and there is an annual loss of doubtless many thousands of tons of iron and steel from the decay of these classes of articles alone.

#### THE CAUSE AND OPERATION OF CORROSION

The brown powder with which we are all far too familiar under the name of rust is a hydroxide of iron—ferric hydroxide,  $\text{FeO}_3\text{H}_3$ . It is formed wherever iron is exposed to the action of water and air. Neither dry air nor water free from oxygen has any effect upon it alone, but as air is always moist and ordinary water contains some oxygen in solution, the conditions for corrosion practically always prevail against the iron in service. The alternate attack of oxygen and water within a brief period is far more destructive than the attack of either one. For example, heavy rains, the splashing of water intermittently upon piers and columns, the rise and fall of the tide, etc., corrode the metal much faster than exposure all the time to either damp air or oxygenated water alone. Acids, while not essential to corrosion, greatly hasten its action, so that the presence of carbonic acid in the air, sulphurous, sulphuric and hydrochloric acids in the smoke from locomotives and other fires, all greatly increase the


<sup>1</sup> Tin plate consists of a thin sheet of steel or wrought iron covered with metallic tin.

<sup>2</sup> *I.e.*, coating with metallic zinc.




speed of rusting. It seems evident also that at least some weak electrolysis is essential for any corrosion to occur. I shall show later that this electrolytic action will always take place where iron and water are in contact with each other, but it is very small in amount under these conditions. Where a greater electric force exists, as for example where pipe lines run close to trolley tracks and receive a leak of electricity so as to carry a part of the current, the electrolytic action is increased and corrosion much hastened. As the use of electricity today is far more general than ever before and the amount of coal burned and consequently the amount of corrosive gases in our atmosphere is much larger, it follows that the question of corrosion is of constantly increasing importance. Affairs have indeed reached such a state that the subject is now occupying a great deal of attention from metallurgists and engineers in the hope of getting better means of protection. Pipe lines embedded in the earth, which are alternately wet and dry, supports in tunnels, subways, and other damp places, wire fences and tin roofs are all suffering severely from decay.

**Theories of Corrosion.**—In an able research, Allerton S. Cushman has studied the current theories that have been advanced to account for the corrosion of steel. He shows that the theory that carbonic acid, or some other acid, is necessary is wrong, and that corrosion will take place even in weak alkaline solutions. He also shows that hydrogen peroxide is not the agency producing the rust. By means of a series of extremely careful and accurate experiments he demonstrated the probability, if not, indeed, the certainty, that the two factors without which the corrosion of iron is impossible are electrolysis and the presence of hydrogen in the electrolyzed or "ionic" condition. In brief, it is the ions of hydrogen which first cause the metal to pass in solution:




Ions of hydrogen are electropositive to iron, and when the reaction takes place, they transfer their electric charge to the metal. This is, of course, an electrolytic action and the hydrogen which takes part in it is converted from the electrolyzed (or ionic) condition to the atomic (or gaseous) condition. Therefore it is evident that the action must take place in the presence of oxygen,



or some other oxidizing agent that will complete the electrolysis, else the formation of ferrous hydroxide will soon cease. This explains why the presence of oxygen so greatly increases the corrosion of iron, although it is not the oxygen itself which, after all, is the cause of the primary attack.

Unfortunately traces of ionic hydrogen are always present even in the purest water, and larger amounts in ordinary water. Substances which increase the hydrogen ions, such as oxides, promote the rusting, and the same may be said of anything which increases the electrolytic action, while substances which restrain the formation of hydrogen ions will decrease corrosion. Indeed, dipping a piece of bright iron into a solution of potassium bichromate and then wiping it off will put it into an apparently oxidized condition in which it will resist corrosion for days or even weeks. Cushman, therefore, suggests dissolving a small amount of chromic acid or potassium bichromate in boiler waters in order to restrain corrosion of the metal.

**Rust.**—Ferrous hydroxide ( $\text{FeO}_2\text{H}_2$ ) is soluble in water and its formation and solution is the first step in the production of rust. Because of its solubility, however, it does not ordinarily make its presence known until a further reaction occurs:



The rust,  $\text{FeO}_3\text{H}_3$ , so formed precipitates from solution.

**Segregation.**—Evidently anything that increases the electrolytic activity will increase the attack by hydrogen and therefore the formation of rust. Unfortunately even the purest piece of iron will show differences of electric potential at different parts and therefore produce an electrolytic effect. When the metal is impure or is badly segregated, these differences in potential will be quite large, and when several pieces of steel are joined together, as in a bridge or other structure, the difference in potential between the different parts may be great. It is probable that each of the different microscopic constituents of iron and steel has a different electric potential and therefore either assists or retards the progress of rusting. Also scale, the slag in wrought iron, etc.

**Self-protection from Corrosion.**—It is generally believed that certain constituents in iron and steel assist in protecting underlying layers of the metal from attack. For example, the graphite which forms such a large proportion (say 10 per cent or more) of the volume of cast iron, slag which forms nearly 4 per cent of

the volume of wrought iron, and cementite in steel, all corrode less rapidly than the pure metal, and it is probable that they are beneficial in protecting it. It must not be forgotten, however, that they likewise cause a difference in potential and to that extent probably tend to hasten corrosion. Their net effect can be learned only by experiment. Scale or foreign substances on the surface of the metal would also produce large differences in potential.

**Relative Corrosion of Iron and Steel.**—It is generally believed that cast iron corrodes less rapidly than either wrought iron or steel and, for this reason, cast-iron pipe is greatly preferred for city water mains and like uses where great strength is not required. The belief is a reasonable one, since it might well be expected that the presence of graphite would be a protection, but it is only right to remark that the theory rests upon no experimental evidence and that there are other circumstances connected with cast-iron pipe which may not have given rise to the belief but which are not inherent in the material itself. These conditions are (1) the common practice of dipping cast-iron pipe in asphaltum, paint or some similar protecting material, before it is sold, thus putting it in a condition to be in service for a long time before the metal itself is subjected to the corrosive influences. (2) When the iron is cast in the sand there seems to take place some union between the metal and the inside surface of the mold, whereby a very resisting silicious coating or "skin" is formed on the casting. Some believe that after this skin is worn away, cast iron corrodes as rapidly as wrought iron or steel. (3) Cast-iron pipe is thicker than the same diameter of wrought-iron and steel pipe, because of the difficulty of making castings with thin sections of metal; therefore such pipe would remain in service much longer than steel or wrought iron, even though the rate of corrosion were the same. I have cited the above facts not to argue against the belief in the slow corrosion of cast iron, but merely to explain the situation as it exists, for we have as yet no scientific data upon which to form an opinion either way.

**Wrought Iron vs. Steel.**—There is also a very prevalent and widespread conviction that steel corrodes much more rapidly than wrought iron. This opinion too rests upon no very exact experimental evidence, although there are not lacking incidents which make in favor of it, while others make in the opposite

direction, but it seems to be based principally upon the fact that corrosion is very much more rapid today, when steel is the world's great metal, than it was some years ago when wrought iron was chiefly used! But I have already shown that conditions today are more conducive to rapid corrosion than they were at any previous time.<sup>1</sup>

Opposed to this popular belief is the result of a great many scientific tests which have shown, in almost every case, that the difference in the speed of corrosion between wrought iron and steel is very small, although favorable to wrought iron in the case of sea water and alkaline water and to steel in the case of acids and acidulated water. As has been pointed out, however, these scientific tests are not altogether reliable as a basis for commercial comparison, because they have not usually been carried to the point where either one material or the other becomes unfit for service, but merely allow corrosion to proceed for several months and then show the relative loss in weight. Neither have these experiments taken into account sufficiently the localized, *i.e.*, "pitting," corrosion to which badly made material is especially subject. It is immaterial whether or not the metal has lost but little weight, provided it has pitted in any one spot sufficiently to fail, or to have become dangerously thin. This pitting is believed to be due chiefly to blowholes and possibly to segregation resulting in a local increase in electric potential.

**Manganese and Corrosion.**—It has been suggested that the presence of manganese in steel causes an increase in the rate of corrosion, but this assertion is based upon no reliable evidence so far as I am aware. It was brought forward to explain the supposed rapid corrosion of steel as compared with wrought iron, but if it is a true influence in this direction, then steel should corrode in acids faster than wrought iron, which it apparently

<sup>1</sup> Indeed I hardly think that this argument ought to have anything like the weight that is popularly given to it. It is not at all uncommon to hear the statement that wrought iron made 20 years ago is still in service in places and conditions alongside of steel which has been replaced several times. But I am informed by a testing engineer of much experience and reputation that he has a steel fence upon his property which has been in service many years and has outlasted several other steel fences under similar conditions, but formed of steel made recently. From this he argues that the steel made today is more subject to corrosion than the steel made many years ago. If this is so, we are permitted to ask: Is the wrought iron made today more subject to corrosion than the wrought iron made several years ago?



does not if the steel has been made with due care and is free from blowholes and much segregation.

**Badly Made Material.**—There can be no doubt that badly made steel is much more liable to corrosion and to pitting than well made steel, and it may be from this cause that the bad name which steel is popularly given comes. There can also be no doubt that badly made wrought iron is extraordinarily subject to rusting, and of this kind of material we are today getting a good deal. As noted on p. 78, probably more than half of the wrought iron produced in America is made by "busheling" scrap into a pile, rolling it down and marketing it as wrought iron. This material is of good quality so long as the scrap from which it is made is good, but when the scrap is collected from almost any source, and especially when it contains steel, as it sometimes does, we should expect great differences in potential and therefore rapid corrosion.

**Coating.**—Wrought iron has one advantage over steel in the case of articles which are to be coated, because its rough surface gives a better opportunity for the paint to adhere than the comparatively smooth and even surface of steel.

**Summary.**—Badly made steel and badly made wrought iron corrode faster than any other material; next in order come well-made steel and well made wrought iron, between which two classes the difference is probably very slight, and has not been determined by any sufficiently lengthy or convincing series of tests; the next in order is probably cast iron, although as yet we cannot be quite certain that this corrodes more slowly than wrought iron and steel, except in so far as it is protected by its natural or artificial coating or both. Steel and wrought iron are both liable to pitting, which may greatly shorten their life in service even though the average rate at which they corrode is slow. Several causes may produce this pitting, such as blowholes, segregation, bad welding in places, particles of oxide, scale or dirt, etc. When pits or holes are found with a smooth, hollow surface, it is altogether probable that they are due to blowholes and sometimes these pits may be 1 in. or more in diameter and extend  $\frac{1}{8}$  in. into the plate, even before the remainder of the surface has become severely attacked. Numerous efforts are being made at the present time to improve the quality of steel and to turn out a more uniform grade of product. It is quite certain that painting is not so good today as it was in years

past and that the quality of paint used is also worse, on the average, as shown by the fact that paint does not last so well on wooden structures. The better adherence of paint gives an advantage to wrought iron, which, however, only applies where work is so placed as to be capable of being painted.

### PRESERVATIVE COATINGS FOR IRON AND STEEL

The oxidized surface which all steel retains after hot working is in itself a certain protection against corrosion, but this is only limited in effect, because the oxide is more or less porous and so allows the corrosive agencies to penetrate it and attack the surface underneath. Moreover, the scale does not adhere firmly in some places, and as its coefficient of expansion and contraction is different from that of the metal, it is liable to loosen and fall off in places and so expose the iron or steel.

**Preparation of Surfaces for Coating.**—It is not advisable to coat wrought iron or steel until its surface has been carefully prepared, for any rust or other product of corrosion, scale, grease, dirt, or moisture underneath the coat will either start corrosion or else, by becoming loosened, will cause the paint or galvanizing to fall off and so expose the metal underneath. The opposite is the case with cast iron, because when this metal is poured liquid into the mold a skin is formed, consisting of a chemical union of silica and oxide of iron, very firmly united to the metal and capable of being relied upon to adhere beneath the paint or other coating and serve as additional protection from corrosion. So much mill scale as adheres to wrought iron and steel with great force is permitted by some engineers to remain underneath the protective coating, but others insist upon the removal even of this upon the ground that it may become loosened later by expansion and contraction, and then spall off.

**Priming Coat.**—A difference of opinion exists as to the advisability of having wrought-iron and steel surfaces prepared at the mill and there given a priming coat, or else having the priming coat applied under the direction of the engineer of construction, or else of omitting the priming coat altogether and not painting the structure at all (except such parts of it as will be inaccessible after erection) until the metal has been exposed so long that the weather has loosened all the scale. This will occupy perhaps 6 months to 1 year, depending upon the corrosive conditions. During that time no great damage can be

done by corrosion although the structure will, of course, look very shabby. After that period the scale is removed with sand blast, wire brushes, pneumatic hammers, or chisels, and after the surface is perfectly clean and dry, it is given a priming coat and at least two other good coats of paint, each one being allowed to dry thoroughly before the next is spread. For indoor work one coat of paint upon the priming coat is often considered sufficient.

**Shop vs. Field Painting.**—The advantage of painting the steel at the shop is that it can be done inside of some building and there is therefore less liability of hygroscopic moisture under the coating. If the shop coat is put on with care and skill it unquestionably has certain advantages, but it is too true that the shop painting and the preparation of surfaces at the shop is often carelessly done, for the manufacturer has not the interest in preserving the metal from decay that the consumer feels. Furthermore it undoubtedly saves expense to allow the structure to stand from 6 months to 1 year, provided that it is then very thoroughly cleaned and well painted when absolutely dry. If otherwise the whole work may have to be done over again at the end of a short interval.

**Pickling.**—To remove scale it is customary in many cases to pickle the steel or wrought iron, *i.e.*, to immerse it in dilute sulphuric acid (say 10 per cent) preferably heated to boiling so as to act more quickly. After a few minutes the scale is removed, when the metal is washed once in boiling water, once in cold water, and finally in lime water to neutralize the last traces of the acid. It should remain in the lime water until it is ready for the application of the coating, when it should first be washed free of lime, and then heated slightly above 100°C. (212°F.) to drive off all the moisture. Pickling is therefore applicable only when the metal is to be coated at the shop, either with the priming coat of paint or with zinc, tin, etc.

**Comparison of Methods.**—Pickling costs less than the other methods of removing scale and accomplishes the work very thoroughly. Sand blast is the next cheapest method. This latter does not get off all the scale unless it is very thorough, while if it is too thorough, it leaves the surface in a smooth condition so that the paint does not stick so well. On the other hand, pickling must be done with great care or it may leave hydrogen upon the surface of the metal which will greatly hasten corrosion so that

pickled surfaces sometimes corrode more rapidly than those which have been cleaned in any other way. Cleaning with wire brushes is more expensive than sand blasting, but if performed with great care is more effective and leaves the surface in a rougher condition which assists the adherence of the paint.

**Kinds of Paint Used.**—There is a great difference of opinion as to the best paint for preserving iron and steel, but some few things seem certain: (1) That no one kind of paint is suitable protection against all corrosive influences. For example, the best paint to withstand the action of the open air may fail when exposed to the elements in a damp tunnel, or when used on the parts of piers under sea water, while a good protection against this latter influence might be inefficient when exposed to the oxidizing gases in locomotive smoke, etc.; (2) that whatever paint is used must be sufficiently elastic to expand and contract with the changes in temperature of the metal without cracking; and (3) that it must contain nothing which will attack the metal and so commence corrosion. In this last connection we must especially avoid all oxidizing influences. The reader will find in the *Annual Proceedings* of the American Society for Testing Materials a very full interchange of opinions between experts in paint manufacture and engineering which will doubtless help him to form an opinion as to the best paint to use in each case.

There are two parts to every paint: (1) The vehicle which carries the pigment and undergoes a change to the solid state when the paint dries, and (2) the pigment or originally solid part of the preservative coating. These two must form a firm impervious coating upon the surface of the metal, but must not be so solid as to be inelastic or brittle.

**Linseed Oil.**—Linseed oil is a very good and common vehicle. It is what is known as a "drying oil." That is to say, an oil which when exposed to the atmosphere will change from a liquid to an elastic or leathery consistency. This action takes place not by evaporation but by a process of oxidation, whereby the oil absorbs oxygen to the extent of from 10 to 18 per cent of its weight and expands in volume, so that a coat of linseed oil spread upon glass will wrinkle up upon drying. It is because linseed is the best of all the drying oils that it is so much preferred as a paint vehicle, but when allowed to dry in the raw state it requires too long a time and the drying is therefore hastened by boiling it and adding some oxidizing agent, known as a "drier," of which the



best, as far as iron and steel preservation is concerned, are the salts of lead or manganese, used without rosin. It will readily be understood how dangerous it is to use driers (*i.e.*, oxidizing agents) in steel paints indiscriminately, because so many of them will oxidize the steel and so cause the very corrosion which it is the object of the paint to prevent.

**Purity of Linseed.**—This brings us to the question of the purity of linseed oil, for the usual adulterants are all harmful to steel work and cause in the end more painting and more of the expensive cleaning of structures to receive the coating, out of all proportion to their lesser first cost. Freedom from adulterants probably cannot be obtained except by constant watchfulness and frequent chemical analysis on the part of the consumer. Some impurity arises from the presence of a few per cent of foreign seeds with the linseed, which is not always avoidable, but the greater harm comes from the fact that the oil is obtained from the linseed by pressing it while hot, in which way a larger amount of product is extracted than if cold pressure is applied, because some of the solid part of the seeds are thereby extracted together with the oil. Cold pressed linseed oil has a golden yellow color and remains clear in cold weather as distinguished from the yellowish-brown color of the hot pressed oil which also has a more acrid taste, is not so fluid, and contains more solid fats, solid organic matter and fatty acids, all of which are harmful either because they attack the metal or else because they make a pervious paint.

**Pigments.**—The pigment is not so important as the vehicle and many different ones can be chosen, provided they are chemically inert to the steel. Red lead has been very much used and is very good especially for the priming coat, for it seems to form with the linseed oil a very dense, impervious coating. For the outer coats, however, it is generally well to mix the red lead with some substance that will reduce its weight, such as graphite. Ferric oxide ( $\text{Fe}_2\text{O}_3$ ) and other oxides of iron in the form of iron ore are very cheap and withstand the action of sulphur gas better than the red-lead paints. They are very good for outer coats where locomotive smoke and similar gases are liable to be present. Sulphate of lead, white lead (a mixture of oxide and sulphate of lead with often some sulphate of zinc) and sulphate of zinc are all good white paints although expensive. Pulverized asphaltum and other hydrocarbons are also used with

success as pigments, especially where the metal is exposed in damp ground or under water.

**Other Paints.**—Pipe is often coated very cheaply by dipping it in melted asphaltum or pitch. The objection to this coat is that it is very hard and brittle when cold and in time it forms a network of myriads of cracks through which the atmosphere attacks the metal. For cast-iron pipe it is very useful, however, because this is protected by its natural skin. Dipping in tar would form an elastic coating, but unfortunately tar contains certain acids and oxidizing agents which attack the metal. There is a paint made by distilling off the creosote and other volatile components of tar until the solid asphaltum is left. This is then redissolved in two of the distillates, neither of which will attack iron work, and thus a paint is obtained which is said to be practically tar without any of its harmful constituents. It forms a very elastic coating which does not crack after years of exposure nor does it disintegrate under the action of the sun as the linseed oil paints sometimes do.

**Galvanizing.**—Galvanizing is the process of coating with metallic zinc and where this coating adheres firmly, it undoubtedly forms a very efficient means of protecting iron from corrosion. As zinc is electrically positive towards iron, whatever electrolysis exists would tend to corrode the zinc and protect the iron. Indeed advantage is taken of this fact by some engineers who hang pieces of zinc in their boilers, by means of a wire connected to the steel work, so that the electrolytic action shall corrode the zinc and protect the wrought iron or steel.

Galvanizing is usually applied to wire and wire products, thin sheets, especially corrugated sheets used for the outside of buildings, etc., tubes, hollow ware, and a great variety of articles, after the surfaces have been cleaned by pickling. There are three methods by which the galvanizing is effected, known respectively as cold galvanizing hot galvanizing and dry galvanizing.

**Cold Galvanizing.**—In the cold-galvanizing process zinc is deposited electrolytically upon the surface of metallic articles which are made the cathode of an electroplating cell. The zinc is first dissolved in sulphuric acid and water and this solution is made the electrolyte. The anode is a piece of zinc, so that as fast as the electricity deposits zinc upon the surface of the article being galvanized, it replenishes the electrolyte by dissolving zinc

from the anode. The coating is about 0.0003 to 0.0005 in. thick, equivalent to about 0.2 to 0.3 oz. of zinc per square foot of surface.

**Hot Galvanizing.**—In the hot galvanizing process, which is the commonest one used, the articles to be galvanized are dipped into a bath of molten zinc at a temperature of 425 to 460°C. (800 to 860°F.), *i.e.*, slightly above the melting-point (419°C. = 786°F.). The metal is exposed to the zinc bath usually about  $1\frac{1}{2}$  to  $7\frac{1}{2}$  min., depending upon the thickness of coating desired, which will vary between 0.0003 and 0.0010 in. or about 0.2 to 0.6 oz. of zinc per square foot of surface covered, or about 0.3 to 0.6 oz. per pound of wire. In the case of wire the iron or steel is drawn slowly through the bath of melted zinc and usually passes over a wiper as it comes out, which removes the still molten zinc and causes the zinc remaining to stick a little more firmly and have a more uniform thickness. The coating on this wiped wire is not so liable to crack and break off when the wire is bent and twisted as the coat of unwiped wire but, on the other hand, it is thinner and gives but little protection against corrosion. Sometimes articles to be galvanized are first dipped in a bath of melted lead and then in the melted zinc. This gives a cheaper coating.

**Dry Galvanizing.**—The process of dry galvanizing is a recent invention and consists in heating the articles to be galvanized inside a closed vessel and while they are covered with what is known as “blue powder,” which is a zinc dust containing some oxide of zinc and relatively cheap in price because it is a by-product in the metallurgy of zinc. The temperature is about 300°C. (575°F.), and, although this is below the melting-point of zinc and of iron, it is sufficiently high to produce an alloy between the two, forming, it is said, a very resisting coating which is more thoroughly attached to the surface of the metal and therefore much more durable against cracking off.

**Comparison of Galvanizing Methods.**—Cold galvanizing deposits a thinner coating of zinc which, if improperly performed, is liable to be porous or spongy, but it gives a better connection between iron and zinc and therefore a more durable coating. Hot galvanizing necessitates the use of a flux on the bath of melted zinc in order that the zinc may not be oxidized by air, and these fluxes probably have the effect of sometimes beginning the corrosion of the iron underneath the layer of zinc. The process of dry galvanizing is too new yet for any comparison to be drawn.

**Tinning.**—A large amount of metal is coated with tin in order to give protection against organic acids, such as those present in cooked foods, and also in order to give a more effective resistance to the elements. Thus cooking utensils, roofing sheets, tin cans for preserves, and many such articles are coated with tin in preference to zinc, either because zinc would not withstand so long the corrosive influence, or else would not resist it at all. In the tinning operations the metal sheets are usually drawn through a bath of liquid tin by four to six pairs of rolls which are immersed in it. Each pair of rolls presses the tin which has solidified on the surface of the iron firmly upon the metal and the result is a smooth, bright, adhering coat which protects the metal very successfully. Tin plating is more expensive than galvanizing, chiefly on account of the additional cost of the tin.

**Terne Plate.**—Sometimes sheet metal is coated with a mixture of two-thirds lead and one-third tin and then goes under the name of terne plate, which is used very largely for roofing and out door purposes. It is applied by the same method as tinning but is less expensive.

**Nickel Plating.**—Articles requiring a very high polish and which are to be subjected to handling, etc., are often plated with nickel. This is an electrolytic process, similar to the general operation described under the electrolytic galvanizing. Nickel plating is more expensive than galvanizing or tinning, but gives a more highly resisting surface.

**Oxidized Coating.**—There are one or two processes by which a black oxidized surface can be given to iron and steel which will resist rust for years and form what are known as “black iron” objects. It is used chiefly for fancy iron work in house decorations, etc.

**Enameling.**—A number of articles, such as bath tubs, wash-bowls, cooking utensils, are made of cast iron or steel and then coated with a white or variously colored film known as enamel. Enameling processes are more or less secret, but usually consist in powdering the enamel upon the surface of the metallic article which has been heated to a red heat. At this temperature the mixtures forming the enamel melt and spread themselves uniformly over the surface where they chill and harden. Enamel must be insoluble in water and in chemicals with which they are liable to come in contact, and must also be sufficiently elastic to expand and contract with the metal without breaking off.



## CHAPTER XVIII

### THE METALLOGRAPHY OF IRON AND STEEL

Metallography in its larger sense is the description or study of the structure of metals. That branch of the subject which comes under the head of microscopic metallography is, however, the most important because the structure of most metals, especially iron and steel, is discernible only when magnified. We shall see, however, that the observation of structure by eye—known as macroscopic metallography—is not without great value.

Microscopic metallography has now reached that stage of importance where it is viewed almost on a par with chemical analysis and physical testing. In the United States practically every large steel works is well equipped for the microscopic analysis of its product, and important laboratories of the universities and of consulting metallurgists devote much attention to the study. Although only a little more than 25 years have elapsed since the art first received attention, it has advanced so far as to have become by now another and a very serviceable tool in the hands of the expert. I take this opportunity, however, of offering a word of warning: Reputations have more than once suffered severely because of erroneous deduction made from microscopic evidence, and history has shown that those who “rush in where angels fear to tread” are sure to be caught sooner or later. The wise man is he who never bases an opinion upon a sample whose chemical analysis is unknown to him: Who never bases an opinion upon a micro-photographic negative or print, and who polishes and etches his own specimens, or has these operations performed by some one well known to him and working under his immediate direction. With these precautions the microscope is a very reliable index to an experienced mind.

#### PREPARATION OF SAMPLES FOR MICROSCOPIC EXAMINATION

Samples of iron and steel for microscopic analysis can be cut out of soft samples by means of a hack-saw, lathe, or other machine, and broken out of hard and brittle samples by means of a hammer. A good rule to follow is to have the surface that is to

be polished about  $\frac{3}{8}$  to  $\frac{1}{2}$  in. on a side. If larger than that, it requires excessive labor for polishing. On the other hand, it is not advisable to polish too small an area, because the surface will be liable to convexity and therefore very difficult to get into focus, especially for high powers.

**Rough Polishing.**—After the proper size of a specimen is obtained the next step is to give its surface a bright mirror-like polish, free from any scratches discernible even with high powers of the microscope (1,000 diameters or so), and this result is achieved with the greatest economy in labor by proceeding by gradual steps:

If the surface contains deep gouges, or marks produced by cutting or breaking it out, it should first be brought to a plane surface by rubbing across a rough file, a grindstone or an emery wheel. For my own work I much prefer to rub the specimen across a file rather than to put it in a vise and draw a file across it, for I believe the former method produces a more even—*i.e.*, less rounded—surface and therefore conduces to economy of labor in the later operations. It is best to hold the specimen lightly in the fingers and draw it back and forth across the file in a straight line, avoiding any circular motion and therefore having the polishing marks all parallel and straight across the specimen.

When a plane surface has been produced in this way the specimen should be rubbed on a very smooth file. In this operation the specimen should again be held in the fingers and rubbed in a straight line back and forth, and should be turned 90 deg. from the first rubbing so that the marks now made will cut vertically across the first scratches. In this way it is very easy to tell when the scratches made by the first file are entirely eliminated and the operation on the second file should be continued to at least this point no matter how short and faint the old scratches may prove to be. It only takes a minute or two to remove the last scratches on this smooth file, but it would take several minutes to remove them by means of one of the later polishing mediums, and the greatest economy is obtained by having each stage of the operation absolutely complete.

After coming off the smooth file, the specimen is again turned 90 deg., so that the marks now to be made run in the same direction as those made on the rough file, and rubbed across a sheet of ordinary 00 emery paper cut to about  $3\frac{3}{8}$  in. wide by 9 in. long and pinned with thumb tacks upon a piece of planed,  $\frac{1}{2}$ -in.

board. This operation is continued until the last marks from the smooth file are removed.

**Fine Polishing.**—The polishing then proceeds in the same manner by steps upon French emery paper of gradually increasing fineness, each piece being cut to about  $3\frac{3}{8}$  in. by 9 in. and mounted on a smooth board. Of the Hubert brand the grades are designated 0, 00, 000, and 0000.

After the 0000 French emery, the surface is very smooth and bright and is given a final burnishing by rubbing across a piece of broadcloth or baize stretched over a piece of wood, moistened with water and covered with a very thin liquid paste of water and best washed rouge. This should leave the specimen polished as bright as a mirror and free from all scratches. It may be, however, that the eye or a hand magnifying glass would discover microscopic rounded furrows in the specimen. These are due to scratches made in the early stages of polishing, which have not been eliminated, but whose corners have been rounded off by the finer grades of polishing mediums. Never permit a specimen containing these furrows to be used as the basis of any opinion.

**Preparation of Rouge.**—The best jeweler's rouge purchasable is not good enough for polishing, as it contains very fine particles of dirt and grit which produce scratches in the surface of the specimen during the final stages of the process. It is best washed by the metallographer himself. This is best done upon samples of not more than one teaspoonful of rouge at a time stirred in about a glassful of water in a flat pan or dish until thoroughly wetted. After allowing to settle for about 5 min. the water is poured into an ordinary chemist's wash bottle where it is kept until ready for use. The last dregs of the water, containing a good deal of coarse rouge and grit, are thrown away. A little experience soon teaches one to get the maximum amount of good rouge from a sample, without any particles that would produce scratches. The rouge in the wash bottle is protected from dust and dirt and can be poured out of the glass tube on to the broadcloth polishing board as needed. For the preparation of special powders for the very finest grades of polishing, the reader is referred to the references at the end of this chapter.

**Precautions as to Polishing.**—Do not rub the specimen too hard on the polishing mediums. This does not produce the desired effect any more rapidly and may distort the structure of the metal so as to lead to erroneous conclusions.

Do not allow the specimen to become heated by the polishing. This is especially true of hardened steel and other heat-treated specimens which may become tempered and so altered even upon gentle heating.

Rub a piece of hard steel over each piece of polishing paper and broadcloth before using it for polishing your specimen. This is to get rid of grit.

Do not lay polishing boards down where dust will get on them, but let them stand with the full height upward inside a closed box or a small closet.

Never form an opinion upon a specimen that retains scratches or polishing marks.

**Mechanical Polishing.**—Instead of rubbing the specimen across different mediums by hand, we can press them against the emery papers and rouge-cloth mounted upon wooden discs about 8 in. in diameter, revolving at speeds of about 600 r.p.m. This method saves time and the necessary apparatus is very simple to make, or can be purchased complete. Hand-polishing is preferable except upon the rouge, because of the liability to heating the specimens with the higher surface-speed, and to damage of the specimen by having it snatched out of one's fingers.

## DEVELOPING THE STRUCTURE FOR EXAMINATION

To develop the structure of iron and steel so as to differentiate between the constituents, four methods are available:

1. Polishing in bas-relief.
2. Etching with chemicals.
3. "Polish attack," and
4. Heat tinting.

**Polishing in Bas-relief.**—Where some of the constituents are less durable than others the method of polishing that I have described, upon a soft background, produces a bas-relief, since the softer constituents are worn to a greater depth than the harder ones. The parts thus worn down appear darker than the higher places which reflect the light better. It is by this method that graphite is best distinguished in pig iron and slag in wrought iron, because the attack by acids is liable to produce other dark spots which may not be readily differentiated. It is by the bas-relief



method that F. Osmond developed so beautifully the structure of pearlite shown in Fig. 167.<sup>1</sup> This method has the disadvantage, however, of rounding of the edges of the harder constituents and so causing the softer ones to appear larger than they really are.

**Etching with Chemicals—Nitric Acid.**—This method is probably the commonest one of developing the structure of steel. Many different strengths of acid are used by different metallographers from 0.1 per cent up to 20 per cent, and the length of time that is necessary to expose the specimen will depend upon this factor and upon the amount of carbon present. High-carbon steel will require a longer time than soft steel and may take as much as  $2\frac{1}{2}$  min., although this is very rare. The nitric-acid solutions are usually made with alcohol instead of with water, in order to dry more quickly. Some metallographers prefer to immerse their specimens in the acid for a given length of time, and others prefer to hold the specimen in the hand with the polished surface upward, and then deposit a few drops of the etching fluid upon it with a piece of rubber tubing on the end of a glass rod. In any event it is usually better to etch a shorter time than is estimated as suitable, examine under the microscope, and then etch again if necessary. After every etching it is necessary to wash the specimen off with alcohol and dry as quickly as possible. This drying is best accomplished by absorbing all the liquid left on the surface after the alcohol wash with a piece of soft cloth and then holding in a stream of air. Some metallographers wash the specimen after etching with alkali, and then with water and then with alcohol. Sauveur immerses his specimen in the strongest nitric acid for a few seconds and then places it in a stream of running water, washes with alcohol and dries. As the strong nitric acid puts the steel in a passive state, the length of attack by this method is only momentary, so that it is necessary to repeat it a few times. It results in a very even etching of the surface.

**Iodine Etching.**—Some investigators use iodine for etching, by rubbing a few drops over the surface until a film covers it, and allowing it to remain until the iodine color has disappeared, after which the iodine is washed off with alcohol and dried. A good iodine solution for this purpose is the ordinary tincture of iodine diluted with an equal volume of alcohol. It is also well to have an auxiliary solution of about one-fourth this strength for lighter etching work.

<sup>1</sup> P. 327.

**Picric-acid Etching.**—I have found the 5 per cent of picric acid in alcohol, which Igevsy used for hardened and annealed steels, very useful also for wrought iron, very low-carbon steels and pearlite.

**Polish Attack.**—The method of "polish attack," advised and used by Osmond, consists in rubbing the specimen upon a piece of parchment stretched over a piece of soft wood and moistened with a 2 per cent solution of ammonium nitrate. This method gives very beautiful results in Osmond's hands and is especially valuable for developing the structure of martensite, troostite, pearlite and sorbite.

**Heat Tinting.**—Heat tinting consists in warming the steel until it becomes oxidized. The different constituents are oxidized at a different rate and so may be distinguished from one another. It is most serviceable in distinguishing the phosphide of iron from the carbide, for by heating until the carbide is red, the phosphide ( $\text{Fe}_3\text{P}$ ) will be yellow. The phosphorus eutectic may be distinguished from pearlite in the same way, because the former will be yellow when the latter is blue. The heat tinting must be accomplished in such a way as not to expose the metal directly to a flame. The simplest method is to put the specimen upon an iron plate heated from beneath.

#### MICROSCOPE AND ACCESSORIES

It is hardly desirable to describe here the different forms of microscope and accessories used for metallographic work, as the manipulations cannot well be learned, except by practice, and the catalogues of the manufacturers of scientific instruments of all iron-producing countries now give full data. A photograph of a common illuminating device, microscope and camera, is shown in Fig. 226. Those who expect to take up the subject should procure a book upon it and study it much more fully than we have space for here. The chief difference between the microscopic examination and photography of iron and steel, and of biological specimens, botanical specimens, thin rock sections, etc., arises from the non-transparency of the metal. It is necessary to illuminate them from above, since we cannot cause the light to pass through the specimen and into the instrument. This necessitates special forms of illuminators and powerful lights. For magnifications of about 500 diameters, the Welsbach mantle gives sufficient illumination. The Nernst lamp is also very




FIG. 226.—Part of the micro-photographic apparatus in the metallographic laboratory, Department of Metallurgy, Columbia School of Mines. *A*, Le Chatelier microscope; *B*, Le Chatelier microscope; *C*, Welsbach camera; *D*, Sauveu camera; *E*, electric arc illumination.



Figs. 227 and 228.—Etching tests on a steel rail (Frémont).  
(From Guillet and Portevin, "Metallography and Macrography.")



useful, but for very high powers it is necessary to use the electric arc lamp. This introduces especial difficulties, because the focus which gives good definition to the eye by means of the arc light will be blurred upon the photographic plate. The use of a light-yellow screen in front of the light assists in this difficulty, but a good deal of experience is required to get good results. A mercury light avoids this difficulty.

### MAGROSCOPIC METALLOGRAPHY

An experienced eye may get a very good idea of the size of crystals in iron and steel by examining a freshly broken fracture,



(From Guillet and Portevin, "*Metallography and Macrography*")

FIG. 229.—Sulphur print on bromide paper showing segregation in mild carbon steel.

and this is one of the branches of magroscopic metallography. For the most accurate results, however, it is not as good as microscopic examination (Figs. 212 and 215).

It is also possible to get other information by etching a polished surface for many hours with dilute hydrochloric acid. For this purpose the polishing need only go as far as the commercial 00 emery paper, following the smoother file. In this way the center

of ingots, because of their looser texture, will be eaten away much more rapidly, and this will be evident to the unaided eye. Also the interior sections of large area will be attacked more than the outside, which has become harder through the work of rolling. Some blowholes, which cannot be seen by eye or have been par-



(From Guillet and Portevin "*Metallography and Macrography*")

FIG. 230.—Sulphur print on bromide paper showing segregation of sulphur to center of steel bar.

tially welded up, may often be discovered because the etching action is more severe in their neighborhood, and the same is true of spots where segregation has occurred (Figs. 229 and 230). After etching and examination, permanent records may be kept of the indications by covering the etched surface with printers' ink and then pressing it with a letter press on to a piece of cardboard or heavy paper. A few examples of records made in this way are shown in Figs. 227 to 230.

## CHAPTER XIX

### METALLURGICAL FUELS

Metallurgical fuels may for convenience be divided into three classes: (1) Solid fuels, which include wood, charcoal, anthracite coal, bituminous coal and coke; (2) liquid fuels comprising chiefly crude petroleum and its products, pulverized coal conveyed in a stream of air, and tar; and (3) gaseous fuels, including natural gas, producer gas, water gas and special manufactured gases.

**Wood.**—Wood burns rapidly with a long flame and is therefore adapted for reverberatory furnace heating, but requires a good deal of labor for firing. The flame from wood has the advantage of being relatively free from sulphur which is a harmful impurity in the flame from bituminous coal. In Table LX is shown Gruener's classical Classification of Solid Fuels, from which it will be observed that the volatile matter of wood is relatively very high and that the fixed carbon is relatively low in comparison with the other solid fuels.

**Charcoal.**—Charcoal is made from wood by driving off the volatile matter and leaving the fixed carbon. This process of manufacture, which is known as "charring" or carbonizing, is accomplished by heating the wood out of direct contact with the air. The resulting product is a porous, black, non-lustrous material, pulverulent, without strength. It consists chiefly of carbon with traces of residual volatile matter and small amounts of ash, the latter representing the inorganic solid matter initially contained in the wood. Charcoal burns substantially without flame, and is therefore inapplicable to reverberatory and similar furnaces, but is valued in direct-contact furnaces, such as crucible furnace, cupolas, blast furnaces, etc., on account of its porosity and also its relative freedom from objectionable impurities, such as sulphur and phosphorus. The lack of strength of charcoal limits its usefulness in cupolas and blast furnaces because it cannot support a heavy burden of super-incumbent material. It will be remembered that the solid fuel is the only unmelted

material below the melting zone of blast furnaces and cupolas, and that it therefore has to support as much of the weight of the material in the shaft as is not held up by the pressure of the blast. Charcoal is used in some iron blast furnaces of small size because of its purity. This is especially true in Sweden, where coke is very costly, and where the advantage of pure iron ores would be to some extent nullified if an impure material like coke were used for smelting.

**Peat, Lignite, Etc.**—Peat, lignite, brown coal, etc., represent stages in the natural carbonization of wood to coal in the bosom of the earth. In the majority of cases, these fuels are too impure and too high in ash to be burned on grates. They are sometimes converted into gas in gas producers, and they are often crushed, washed and agglomerated into briquettes, which make an admirable substitute for bituminous coal and are rapidly growing in the amount used yearly.

**Bituminous Coals.**—On account of the volatile matter in bituminous coals, they burn with a flame, and are therefore well adapted to use in reverberatory furnaces. The richest in gas are often used for the manufacture of illuminating or city gas, by a simple process of driving off volatile matter by means of heat, but this is a too expensive gas to use ordinarily for metallurgical purposes. Some of the bituminous coals on being heated soften and swell as they give off the volatile components. The softening is sufficient to cause these coals to cake together under the pressure of their own weight, and consequently to form porous, coherent masses of a silvery-gray material, known as coke, which contains only traces of residual volatile matter, together with ash, representing chiefly the inorganic matter originally contained in the coal. The chief chemical constituent of coke is carbon, amounting often to 87 per cent or more of the mass. Coke bears approximately the same relation to bituminous coal that charcoal does to wood.

**Coke.**—Coke is made by distilling the volatile matters from bituminous coal; this distillation takes place in chambers in which only enough air is admitted supposedly to burn the volatile matters, or else in chambers from which the air is excluded completely. The chambers into which a limited amount of air is admitted are called "beehive ovens," on account of their form, which is shown in Fig. 231. The chambers into which no air is admitted are known as "retorts," of which a cross-section is



TABLE LX.—GRUNER'S CLASSIFICATION

Name of fuel	Chemical composition				Volatile matter				Fixed carbon (coke)		
	C	H	O	Ratio O:H	Total	Gas liquor	Crude tar	Gas	Per cent	Structure	Luster
Cellulose.....	44.44	6.17	49.39	7	.....	.....	.....	.....	28-30	Pulverulent	Dull
Wood.....	50-51.75	6-6.3	44-41.95	.....	70-65	46-41.4	5.5-7.4	18.4-17.5	30-35	Pulverulent	Dull
Peat.....	58-63	6-5.5	36-31.5	6-5	.....	.....	.....	.....	35-40	Pulverulent	Dull
Brown coal.....	65-75	6-4	29-21	5	60-50	20-15	16-14	24-21	40-50	Pulverulent	Often lus- trous
Bituminous Coal	Dry, long flame, non-caking (splint).	75-80	5.5-4.5	19.5-15	4-3	50-40	12-5	18-15	20-20	Pulverulent or slightly coherent	
	Fat, long flame. Gas coal.	80-85	5.8-5	14.2-10	3-2	40-32	5-3	15-12	20-17	Caked, but very friable	
	Fat, properly so- called, steam fur- nace coal.	84-89	5-5.5	11-5.5	2-1	32-26	3-1	15-10	16-15	Caked, moderately compact	
	Fat, long flame, coking coal.	88-91	5.5-4.5	6.5-4.5	1	26-18	1-1	10-5	15-12	Caked, very com- pact, little friable	Lustrous
	Lean, anthracitic coal.	90-93	4.5-4	5.5-3	1	18-10	1-0	5-2	12-8	82-92	Fritted or pulver- ulent
Anthracite.....	93-95	4-2	3	1-0.75	10-8	.....	.....	.....	90-92	Pulverulent	Lustrous

Bituminous Coal

shown in Fig. 234. In Europe and England, the retort oven is commoner, but America makes more coke in beehive ovens, which is a far more wasteful method, since only 66 per cent of coke is obtained from a ton of coal, and no "by-products;" whereas, in retort ovens, we obtain a yield of 75 per cent of coke and also by-products consisting of tar, ammonia, excess gas, etc., equal in total value to about one-third of the value of the coke. In the United States there are some 60,000 beehive ovens, producing, in 1920, 20,511,000 net tons of coke; and about 10,881 by-



FIG. 231.—Standard American beehive oven.

product ovens, producing, 30,833,951 net tons of coke. The production of by-product ovens was 60 per cent of the total in the United States in 1920.

**Coking in Beehive Ovens.**—The crushed coal is poured into the oven through the "eye" at the top, and carefully levelled. Combustion is started at the middle of the top circle of coal, and gas begins to be distilled off by the heat; air is admitted through the arch of the lower door, and flame soon fills the dome and sends a black, sooty smoke out of the eye. The heat from the flame distils the volatile matter from the coal, advancing layer by layer from the top; this causes the coal to swell and rise slightly. At the end of the coking a 5-ton charge of coke 28 in. thick will have risen to 34 in. thick. When distillation is complete to the

bottom of the charge, the combustion is stopped by quenching the coke with a stream of water, this action taking place inside the oven itself in order that air may not oxidize the surface of the



FIG. 232.—Batteries of beehive ovens.

coke and dull its silvery color. The coke breaks up into long pieces, as shown in Fig. 233. A small amount (say 2 to 2½ per cent) of fine particles, or “breeze,” is formed which cannot be marketed.




FIG. 233.—Structure of beehive coke.

**Coking in Retort Ovens.**—In retort ovens the coal is completely enclosed during distillation, which accomplishes three purposes: (1) It enables the gas distilled from it to be led off into by-product-saving apparatus; (2) it protects the fixed carbon in it from

contact with air, which would burn it and reduce the yield, and (3) it puts it under greater pressure during the swelling operation, so that some coals which will not cake into a coherent mass in beehive ovens will make good strong coke in retorts. The retorts




FIG. 234.—Horizontal section through a retort of a by-product oven.

are made of firebrick, and are heated by burning gas outside of them on three sides. Good coking coals will yield from 5,000 to 12,000 cu. ft. of gas per ton. In the beehive oven this is all burned; in retort ovens we burn about one-half of it to produce



FIG. 235.—Otto-Hoffmann by-product, or retort, coke ovens.

the heat required for the coking operation, and the remainder is available for sale, or other purposes. In all the retort ovens of the United States in 1920, an average of nearly 10,800 cu. ft. of excess gas was obtained per ton of coal used; together with about



8 gal. of tar, ammonia products equal to over 21 lb. and light crude oil equal to 2.5 lb. The total value of by-products recovered was equal to about \$2.12 per ton of coal coked.




FIG. 236.—Longitudinal Section of Semet-Solvay retort coke oven.

**Surplus Gas Obtained.**—The analysis of the gas given off by the coal will vary with the time of coking—that is, the first gas distilled off, which is given up more readily, will be richer than that given off later.





FIG. 237.—Transverse section of Semet-Solvay oven.


The coal also parts with its volatile matter more freely at first—there is more gas given off per hour; secondly, the components of the gas which give the most illuminating power ( $C_mH_n$ ) are relatively higher in the gas first given off than in the later gas, and therefore the candlepower of the gas decreases as coking progresses; thirdly, the calorific power of the gas decreases also, but

not at so rapid a rate as the candlepower, especially excepting the last few hours of the operation. Now, if all the gas distilled off in coking a charge of coal was stored in a reservoir it would not be rich enough to use for illuminating purposes for cities, but, if we should store the first gas given off in one reservoir, and the later gas in another, we would have a supply of sufficiently rich gas and a supply of poorer gas. This admirable arrangement, a result of the genius of Dr. Schniewind, is in fact adopted at several by-product coke plants, the rich gas being sold to cities for illuminating purposes, and the poorer gas used for heating the retorts in the coking operation. Before either gas is used, however, it is freed from tar and ammonia. When retort coke is made at metallurgical works, the surplus gas may be used in open-hearth furnaces, or in heating furnaces at the rolling plant, or burned in gas engines for the production of power. When using this gas in furnaces, the high content of hydrogen causes some difficulty in burning out the brickwork unless care and experience is employed.

**Producer Gas.**—If air be blown through red-hot carbon the following reaction takes place:



but if the bed of fuel is deep, the carbon dioxide enters into a further reaction, as follows:



In other words, if air be made to blow through a deep bed of red-hot carbon, there will be produced carbon monoxide gas which has combustible value:



Producer gas for open-hearth and reverberatory furnaces is usually thus made from bituminous coal, because the hydrocarbons contained in this coal enter into the gas and thus give it illuminating power, which makes it much more efficient in the furnace, because the heating takes place by radiation chiefly. Such a gas




FIG. 238.—Cross-section of retort. Structure of by-product coke.

will contain 3 to 5 per cent of hydrocarbons, 20 to 25 per cent of CO, 55 to 60 per cent of nitrogen, and 2 to 8 per cent of carbon dioxide.

The two latter components produce no heat and are therefore worse than useless, because they carry heat away from the furnace up the chimney stack. The nitrogen comes from the air, of course, but the CO<sub>2</sub> is theoretically absent. Its presence is due to irregularities in the gas-producer operation, such as





FIG. 239.—The Otto-Hoffmann coke oven. (Schniewind type.)

vertical channels forming in the bed of fuel, up which the CO<sub>2</sub> gas passes without being brought into contact with carbon; or the rapid passage of the gas does not permit time for the reactions to be completed; or irregularities in the fuel bed, whereby the fuel will be red-hot much higher on one side than on the other.

The air is usually blown through the fuel by means of a steam jet, which results in a certain amount of steam passing into the producer with the air; but this is rather an advantage than otherwise as the steam is decomposed by the red-hot carbon and enriches the producer gas:






FIG. 240.—Morgan water-sealed gas producer.



**Gas Producers.**—The gas producers are the furnaces in which the fuel is contained while the air is passed through it. The main objects to be accomplished are: (1) To pass the air uniformly




FIG. 241.—Hughes mechanically poked gas producer.

through the bed; (2) to remove ashes and charge fresh fuel without interrupting the production of gas; and (3) to preserve the deep bed of incandescent carbon, having level upper and lower surfaces. There are three horizontal zones in the gas producer: The first is the ash zone, which is deep in order that the air may be

slightly preheated in passing through it and that any unburned carbon which gets into it may have a strong liability of being burned. Next above that is the  $\text{CO}_2$  zone, in which the oxygen and carbons are first combined; and above that the CO zone, in which the  $\text{CO}_2$  is reduced by more carbon. The top of this zone should be at a dull-red heat.

**Volume and Calorific Power.**—The volume of producer gas obtained from a ton of coal will be about 150,000 to 170,000 cu.




FIG. 242.—Butterfly reversing valve.

ft., having a calorific power of 33 to 36 calories per cubic foot, or 130 to 145 B.t.u. per cubic foot.<sup>1</sup> These figures will, of course, depend upon the quality of the coal gasified, but the calorific power is no more important than the amount of heat that it will radiate, which depends upon the luminosity of the flame.

**Luminosity.**—The luminosity of flames depends upon the amount of hydrocarbons, and especially of heavy hydrocarbons, burned to produce them. It is therefore necessary, if the producer gas is made from bituminous coal low in hydrocarbons or from coke or anthracite, to increase its illuminating power by

spraying oil into it. The luminosity is produced by the deposition of a myriad of tiny particles of carbon, which are heated to incandescence and then radiate energy in the form of light. It




FIG. 243.—Mushroom reversing valve.




FIG. 244.—Water-sealed reversing valve.

is probable that this action is produced by the relatively light hydrocarbons, such as methane ( $\text{CH}_4$ ), breaking up first into

ethylene ( $C_2H_4$ ), and then into acetylene ( $C_2H_2$ ), which deposits the carbon particles or soot. It is for this reason that the pure acetylene flame has such intense luminosity.

**Gas Mains.**—The gas mains leading from the producer plant to the open-hearth furnace should be lined with brick and be at least large enough for a man to pass through. Beyond this, a good rule is 1 sq. ft. of area of cross-section of gas main for every 8 sq. ft. of total combined area of gas-producer grates. The gas loses heat by radiation in the mains and deposits the tarry constituents, *i.e.*, the nearly solid hydrocarbons, in both ways losing heating power.

**Natural Gas.**—In those districts, like Pittsburgh, where natural gas occurs, it is a great boon to the open-hearth steel industry, because of its high calorific power and the cheapness with which it may be obtained. About 80 wrought-iron plants and 90 steel plants in America use it. It is drawn from the earth, and has a calorific power of 970 to 1,010 B.t.u. per cubic foot (equivalent to 225 to 250 calories per cubic foot or 8,600 to 9,000 calories per cubic meter). In the Pittsburgh district the amount of natural gas used per ton of steel made ranges from 4,000 to 11,000 cu. ft., averaging about 5,500. This includes the gas used in the furnace and the small amount necessary for heating the ladles. The natural gas is usually introduced through two pipes at each end of the furnace, which are located close to the bottom of the gas-ports and deliver the fuel about  $3\frac{1}{2}$  ft. back from the hearth. The natural gas is therefore applied without any loss in gas mains, reversing valves, regenerators, etc., and is cheaper in labor on the furnace floor itself. The Pittsburgh natural gas averages about 70 to 90 per cent of methane ( $CH_4$ ) or marsh gas, the remainder being hydrogen with a fraction of a per cent of carbon dioxide and a very few per cent of nitrogen.

On account of its high calorific power, it is not necessary to pre-heat this gas, and this is the more fortunate, because the amount of hydrocarbon is so great that if the gas be passed through regenerative chambers, it decomposes and deposits soot on the checker-work.

**Oil.**—On the continent of Europe, and in parts of the United States distant from the natural gas and bituminous coal regions, many open-hearth furnaces are heated by petroleum. The United States has many deposits of fuel oil, besides which it is sometimes possible to obtain a refuse from the oil refineries which



is excellent for this purpose. There are therefore many different grades employed, but they will usually average from 7.8 to 8.3 lb. per gallon, with a calorific power of 14,000 to 17,000 B.t.u. per pound. From 35 to 60 gal. of oil are required per ton of steel treated in the open-hearth furnace.

The crude petroleum is vaporized by atomizing it with a jet of steam or compressed air. The method of application is by a blow-pipe introduced through the brickwork at the end of the furnace, and special forms of blow-pipe are now on the market for




FIG. 245.—Oil blow-pipe for open-hearth furnace.

this purpose. It is necessary to pump the oil to the blow-pipe or else to store it in an overhead tank, from which gravity will carry it, but the labor in connection with this is much less than the labor on gas producers.

Whether oil is used or not will depend principally upon freight, because it may be transported much more cheaply than any other form of fuel. It gives a longer flame than either natural or producer gas, and one very great advantage of using it is a saving of the roof of the furnace; the oil flame may be directed so accurately by means of the blow-pipe that it does not impinge directly on the roof, and the brickwork therefore lasts very much longer. On the other hand, it spreads out horizontally and causes a greater wear on the front and back walls of the furnace. It gives a more uniform heat, a more oxidizing flame, and no danger of losses or difficulties, in case there is a leak in the walls between

the gas and air regenerators, which is not an infrequent occurrence with gas.

**Tar.**—Tar has a calorific power slightly greater than that of oil *viz.*, 17,000 to 18,000 B.t.u. per pound. It may be used very much like fuel oil, but must be kept warm in storage tanks and







FIG. 246.—Water-gas producer.

feed lines, and requires a special form of burner. This is due to its viscosity. Tar is cheap; it is a by-product from coke ovens, and other processes and its use is increasing.

**Water-gas.**—If steam be made to pass through a bed of red-hot carbon, the product is a gas containing slightly less than 50 per cent each of hydrogen and carbon monoxide and having a high calorific power:




The result of this reaction is a reduction of the temperature of the fuel bed, which is rapidly reduced until another reaction begins to take place:



(From Camp, "The Making, Shaping and Treating of Steel")

FIG. 247.—Burner for pulverized coal fed by compressed air.

Therefore some means must be employed to raise the temperature at intervals, and this is ordinarily accomplished by interrupting the passage of steam and passing air through the fuel bed, which raises the temperature and at the same time forms pro-



(From Camp, "The Making, Shaping and Treating of Steel")

FIG. 248.—Burner for pulverized coal fed by gravity.

ducer gas which is used for other purposes. Usually, it is necessary to blow air through for 12 to 15 min. and then steam for 4 or 5 min. Consequently, the manufacture of water-gas is intermittent and the method is not very satisfactory for open-hearth work, although the gas is used to some extent on account

of its high calorific power. This operation produces roughly 35,000 cu. ft. of water-gas and 80,000 cu. ft. of producer gas per ton of coal. Water-gas has about 2,600 calories per cubic meter, or say, 290 to 300 B.t.u. per cubic foot.

**Mond Gas.**—In the Mond process a mixture of water-gas and producer gas is made continuously. For every ton of fuel burned there is forced into the producer about 3 tons of air and 2.5 tons of steam, the latter being produced by absorbing the sensible heat of the gas in the boiler. It gives about 150,000 cu. ft. of gas per ton of fuel burned, containing about 25 per cent of hydrogen, 12.5 per cent of CO, 45 to 50 per cent of nitrogen, and 12.5 per cent of CO<sub>2</sub>. This gives a slightly higher calorific power than ordinary producer gas, and is used in some steel works.

**Pulverized Coal.**—If bituminous coal be ground until it passes through a 100-mesh sieve, and more than 70 per cent through a 300-mesh sieve, it may be injected into a furnace with a current of air and burned like fuel oil or gas. It is cheaper than either oil or producer gas, and this is its chief advantage. Its greatest handicap is the costly installation necessary for pulverizing and handling. Two types of burners used for pulverized coal are shown in Figs. 247 and 248.





## APPENDIX

### GENERAL TEXT-BOOKS AND REFERENCE BOOKS ON THE METALLURGY OF IRON AND STEEL

1. H. M. HOWE: "Iron, Steel and Other Alloys," 1903. This book contains three chapters upon the "Manufacture of Iron and Steel" and ten chapters upon its constitution and properties, especially from the standpoint of metallography.
2. H. H. CAMPBELL: "The Manufacture and Properties of Iron and Steel," 4th ed., New York and London, 1907. This is a great reference book by one of the best of the practical American metallurgical engineers. It is the best American reference book upon the manufacture of iron and steel, but is not intended especially for beginners or those without technical education.
3. A. LEDEBUR: "*Handbuch der Eisenhuettenkunde*," 5th ed., Leipzig, 1906. This is an excellent reference book for those who read German, and contains a very complete account of the metallurgy of both iron and steel, and of their properties. There are also classified lists of the literature upon each of the branches of the subject.
4. SIR I. LOWTHIAN BELL: "Principles of the Manufacture of Iron and Steel," London, 1884. This book well accomplishes its aim, namely, to elucidate the principles of iron and steel manufacture, and no man can be either so well informed or so ignorant as not to understand the metallurgy of these metals better after reading it.
5. H. P. TIEMANN: "Iron and Steel. (A Pocket Encyclopedia)," New York and London, 2d ed., 1923. There is a wealth of general information in this book arranged for ready reference because in alphabetical order. It is in fact an encyclopedia of the iron and steel industry, with a sufficient explanation of all the terms and processes and products likely to be met with by those interested in the industry or trade.
6. JOSEPH W. RICHARDS: "Metallurgical Calculations," Part I, Introduction, Chemical and Thermal Principles, Problems in Combustion, 1917; Part II, Iron and Steel, 1910. These problems not only teach how to calculate many very important things in connection with furnaces and their efficiency, but give a good insight into the principles of the processes themselves.
7. JAMES M. CAMP and C. B. FRANCIS: "The Making, Shaping and Treating of Steel," 2d ed., Pittsburgh, 1920. This is an excellent practical treatise on the making, treating and properties of iron and steel, according to the practice of the Carnegie Steel Co.
8. BERNARD OSANN: "*Lehrbuch der Eisenhuettenkunde*." 2 vols., Leipzig, 1915 and 1921. Contains an extended bibliography.  
"Directory to the Iron and Steel Works of the United States," embracing the Blast Furnaces, Rolling Mills, Steel Works, Forges, and

Bloomaries in every State and Territory. Prepared and published by The American Iron and Steel Institute. The first edition of this book appeared in 1873, and the 19 edition in 1920. The data given are very complete and are classified for convenient reference.

9. JAMES M. SWANK: "History of the Manufacture of Iron in All Ages, and Particularly in the United States from 1585 to 1892," Philadelphia.
- "Ryland's Coal, Iron, Steel, Tin-plate, Metal, Engineering Hardware and Allied Trades' Directory (For Great Britain only) with Brands and Trade Marks," published by Eagland & Co., Ltd., London, 1922.
10. *The Journal of the Iron and Steel Institute*, vol. i, London, 1869. This periodical appears twice a year and contains not only many original articles of great value, but an almost complete collection of abstracts of the literature of iron and steel that is published anywhere, classified under headings for convenient reference. Anyone beginning research in any branch of iron and steel metallurgy should commence with this journal, as soon as the textbooks have been consulted.
11. *Stahl und Eisen*, vol. i, Dusseldorf, 1881. This is the best German periodical on iron and steel, and contains not only many valuable original articles and abstracts, but also translations. It is particularly useful in this latter connection, because of its translations of many articles from the Swedish.
12. *Revue de Metallurgie*, vol. i, Paris, 1904. This is a very valuable periodical for those who read French, not only for its original articles, but also for its abstracts. Upon the more scientific side of metallurgy, that is to say the properties and constitution of iron and steel, alloy steels, etc., it is without an equal.
13. *The Mineral Industry*.—Its statistics, technology and trade, vol. i, New York, 1892 to vol. xxxi, 1923. This contains a review every year of the technology and trade of each of the metals listed alphabetically, as well as the statistics of production, price, etc. The articles usually include a review of the progress of the metallurgy during the year.
14. *The Iron Age*, vol. i, New York, 1869. This is the oldest and largest of the American iron and steel technical magazines, and deals not only with the scientific and technical side of the subject, but also acts as a sort of a weekly newspaper upon the condition of the iron trade and recent happenings of interest.
15. *Transactions of the American Institute of Mining and Metallurgical Engineers*, vol. i, New York, 1871. The American Institute is the leading aggregation of both mining engineers and metallurgists in America. These transactions contain many original articles of value.
- 15A. "*Mining and Metallurgy*," The monthly publication of the A. I. M. E.
16. *Year Book of the American Iron and Steel Institute*, Contains annually accounts of recent American practice and innovations.

17. *Iron Trade Review*, Cleveland, Ohio. Although this magazine aims to deal principally with iron trade conditions, it contains also a great many technical articles of importance.
  18. *Jernkontoret Annaler*, vol. i, Upsala, Sweden, 1846. For many years this has been the standard iron and steel technical magazine of Sweden, representing the iron and steel makers there.
  19. *Proceedings*, and also *Specifications of the American Society for Testing Materials*, vol. i, of *Proceedings, Philadelphia*, 1899 to 1902. The *Standard Specifications* are published every third year, as 1918, 1921, etc. The *Proceedings* contain many published monographs and researches on iron, steel and their properties, testing and treatment. The specifications are widely recognized and used.
- Transactions of the American Society for Steel Treating*, vol. i, Cleveland, Ohio, 1920. Much of the publications is very elementary in character, but recent volumes contain valuable data, especially on the practical side of heat treating.
- Metal Statistics. Published annually in New York. Gives some prices, production statistics, etc.
- Comité des Forges de France*. The Bulletin and some other publications of this Society which appear somewhat irregularly, give valuable data on the iron and steel industry of France.

#### THE MANUFACTURE OF PIG IRON

20. SIR I. LOWTHIAN BELL: "Chemical Phenomena of Iron Smelting," London, 1872. The classical treatise on the chemistry of the blast furnace reactions.
21. J. E. JOHNSON, JR. "Blast Furnace Construction in America," New York, 1917. The best book extant on this subject.
22. J. E. JOHNSON, JR.: "The Principles, Operation and Products of the Blast Furnace," New York, 1918. The best recent American book on this subject.
23. ROBERT FORSYTHE: "The Blast Furnace and the Manufacture of Pig Iron," 2d ed., revised and enlarged by CARL A. MEISSNER AND J. A. MOHR, New York, 1922. An elementary treatise of great usefulness for students and furnacemen.
24. LOUIS E. GRUNER: "Studies of Blast Furnace Phenomena," Translated by L. D. B. GORDON, Philadelphia, 1874. A standard treatise on the theory of blast furnace smelting.

#### STEEL AND THE PURIFICATION OF PIG IRON

30. HENRY M. HOWE: "The Metallurgy of Steel," vol. i. 1890. New York. This is the recognized standard authority on the metallurgy of the Bessemer and crucible steel processes, and upon the properties of steel as far as they were known and understood at the time when this book was written. It will long remain a classic. There have been many editions of different dates, but no change in text since 1890.



31. F. W. HARBORD: "The Metallurgy of Steel," 6th ed., London, 1918. With a Section on Mechanical Treatment by J. W. HALL. Next to No. 30, this is the most complete and thorough book on steel ever written, and, for English readers, will be the first source of reference for those desiring recent practice. The section on mechanical treatment is the best extant.
32. DAVID CARNEGIE: "Liquid Steel, Its Manufacture and Cost," assisted by SIDNEY C. GLADWYN, 2d ed., New York, 1918. This is the best reference for labor and costs of manufacture.

#### THE BESSEMER PROCESS

See Nos. 1, 2, 6, 7, 30, 31, 32, and also:

50. HERMANN WEDDING: "The Basic Bessemer or Thomas Process," Translated by WILLIAM B. PHILLIPS and ERNST PROCHASKA, New York, 1891.

#### THE OPEN HEARTH PROCESS

See Nos. 2, 7, 31, 32, and the following:

60. ALPHONSE BARBEROT: "*Fabrication de l'Acier au Four Martin*," Paris, 1923.
61. KARL DICHTMAN: "The Basic Open Hearth Steel Process," Translated by ALLEYNE REYNOLDS, New York, 1911.
62. W. M. CARR: "Open Hearth Steel Castings," 1907.

#### ELECTROMETALLURGY OF IRON AND STEEL

70. DORSEY A. LYON AND ROBERT M. KEENEY: "Electric Furnaces for Making Iron and Steel," Washington, 1914. Contains some important theoretical data.
71. PAUL NICOU: "*Le Haut Fourneau Electrique*," Paris, 1913.
72. WILLIAM RODENHAUSER J. SCHOENAWA AND C. H. VOM BAUR: "Electric Furnaces in the Iron and Steel Industry," Translated by C. H. VOM BAUR, 3d ed., New York, 1920.
73. COLIN C. GOW: "The Electrometallurgy of Steel," London, 1921.
74. JEAN G. ESCARD: "*L'Ectrometallurgie du Fer et de ses Alliages*," Paris, 1920. Especially good on ferro-alloys.
75. ALFRED STANSFIELD: "Electric Furnace for Iron and Steel," New York, 1923.

#### MECHANICAL TREATMENT

See especially Nos. 7 and 31.

#### IRON AND STEEL FOUNDING

100. *The Foundry*. Published monthly in Cleveland, Ohio.
101. *Transactions of the American Foundryman's Association*.
102. PENTON'S Foundry List: A list of iron, steel, brass, etc., foundries in the United States and Canada. Editions appear at intervals.
103. JOHN HOWE HALL: "The Steel Foundry," 2d ed., New York, 1922.
104. RICHARD MOLDENKE: "Principles of Iron Founding," New York 1917.

105. THOMAS TURNER: "Lectures on Iron Founding," London, 1904.
106. PAUL OBERHOFFER: "*Das Schmiedbare Eisen konstitution und Eigenschaften*," Berlin, 1920.
107. ENGELBERT LEHER: "Die Herstellung des Tempergusses und die Theorie des Glühfrischens Nebst Abriss über die Anlage von Tempergiessereien;" handbuch für den praktiker und Studierenden, Berlin. 1919.
108. JOHN M. SNODGRASS AND F. H. GULDNER: "An Investigation of the Properties of Chilled Iron Car Wheels," Illinois, 1922.  
*Giesserei-handbuch; hrsg. vom Verein deutscher eisengiessereien gies-sereiverband in Dusseldorf, München, 1922.*
109. ERNST A. SCHOTT AND A. EINENKEL: "*Giesserei-materialkunde*," Berlin, 1920.  
ERNST A. SCHOTT: "*Die Metallgiesserei*," 2d ed., Leipzig, 1920.  
*Foundrymen's Handbook*, based on data sheets from The Foundry, rev. and supplemented to represent and interpret modern practice, 1st ed., Cleveland, O., 1922.  
*La Fonderie Moderne; revue mensuelle*, vol. i, Paris, 1907.  
*Giesserei-Zeitung*. . . (semi-monthly) vol. i, Berlin, 1904.  
BERNHARD OSANN: "*Lehrbuch der Eisen—und Stahlgesserei*," verfasst für den gebrauch beim unterricht, beim selbststudium und in der praxis, 5th rev. ed., Leipzig, 1922.
- ALEXANDER HUMBOLET FEXTON AND J. S. G. PRIMROSE: "Principles of Iron Founding (and foundry metallography)." London, 1911.
- EDWIN S. CARMEN: "Foundry Moulding Machines and Pattern Equipment," a treatise showing the progress made by the foundries using machine moulding methods, 2d ed., Cleveland, 1920.

#### THE SOLUTION THEORY OF IRON, STEEL AND ALLOYS

See No. 1, and the following:

110. ALBERT SAUVEUR: "The Metallography and Heat Treatment of Iron and Steel," 2d ed., New York, 1916. With great clearness this book teaches the principles of the solution theory as applied to iron and steel, upon which theory all modern conceptions of their nature are based.
111. HENRY M. HOWE: "The Metallography of Steel and Cast Iron." New York, 1916. A comprehensive study of the theory and practice of the solution theory, constitution and metallography of iron and steel.
112. SAMUEL F. HOYT: "Metallography." In two parts. Part I, "Principles," Part II, "The Metals and Common Alloys," New York, 1920 and 1921.
113. *Reports of the Alloys Research Committee of the Institution of Mechanical Engineers* (England). No. 1, 1891; No. 2, 1893; No. 4, 1897; No. 5, 1899; No. 6, 1904; No. 7, 1905. In this may be followed the development of the first application of the theory to metallography.
114. WALTER ROSENTHAL: "An Introduction to the Study of Physical Metallurgy," New York, 1915.

## THE CONSTITUTION OF STEEL

See Nos. 1, 19, 30, 31, 110, 111, and the following:

120. WILLIAM KENT: "Mechanical Engineers' Pocket Book," 10th ed., New York, 1923.
121. ARTHUR W. JUDGE: "Aircraft and Automobile Materials of Construction," New York, 1921.
122. CHARLES A. EDWARDS: "The Physico-Chemical Properties of Steel," London, 1916.
123. LESLIE AITCHISON: "Engineering Steels," London, 1921.

## THE CONSTITUTION OF CAST IRON

See Nos. 19, 22, 100, 101, 105, 107, 110, 111 and the following:

130. WILLIAM H. HATFIELD: "Cast Iron in the Light of Recent Research," 2d ed., London, 1918.

## MALLEABLE CAST IRON

See 106, and the following:

140. RICHARD MOLDENKE: "The Production of Malleable Castings," Cleveland, Ohio, 1911.
141. HARRY A. SCHWARTZ: "American Malleable Cast Iron," Cleveland, Ohio, 1922.

## THE HEAT TREATMENT OF STEEL, CARBURIZING AND WELDING

See Nos. 7, 31, 110, 111, and the following:

150. HARRY BREARLEY: "The Heat Treatment of Tool Steel," 2d ed., London, 1916.
151. HARRY BREARLEY: "Case Hardening of Steel," London, 1921.
152. FEDERICO GIOLITTI: "Heat Treatment of Soft and Medium Steels," Translated by E. E. THUM, New York, 1921.
153. FEDERICO GIOLITTI: "The Cementation of Iron and Steel," Translated by JOSEPH W. RICHARDS and CHAS. A. ROUILLER, New York, 1915.
154. JOHN W. URQUHART: "Steel Thermal Treatment," London, 1922.
155. DENISON K. BULLENS: "Steel and Its Heat Treatment," 2d ed., New York, 1916.
156. FRED H. COLVIN AND K. A. JUTHE: "The Working of Steel, Annealing, Heat Treating and Hardening of Carbon and Alloy Steel," 2d ed., New York, 1922.

## ALLOY STEELS

See No. 12 and all the publications of SIR ROBERT A. HADFIELD, for which consult the index of No. 10. See also No. 7, 122, 124, 156 and the following:

160. THOMAS H. BURNHAM: "Special Steels," London, 1923. Chiefly founded on the researches regarding alloy steels of SIR ROBERT A. HADFIELD.
161. HENRY D. HIBBARD: "Manufacture and Uses of Alloy Steels," New York, 1919.

162. "Steels and Alloys for Special Purposes," Pittsburgh, 1919. This is a shop book published by a manufacturing company, but contains much very valuable material of a technical character on this subject.
163. GRESWOLD VAN DUKE: "Shop Handbook on Alloy Steels," Chicago, 1921. This is a shop book, like the preceding.

THE METALLOGRAPHY OF IRON AND STEEL

See Nos. 1, 7, 12, 110, 111, 113, 123, 124, 141 and the following:

180. F. OSMOND: "The Microscopic Analysis of Metals," Edited by J. E. STEAD.
181. "Research and Methods of Analysis of Iron and Steel at Armeo" 2d ed., Middletown, Ohio, 1920.
182. N. T. BELAIEV: "Crystallisation of Metals," London, 1923. References at the end of each chapter.
183. ERNST PREUSS: "*Die Praktische Nutzenanwendung der Prüfung des Eisens durch Ätzverfahren und mit Hilfe des Mikroskopes.*" 2d ed. rev. and enl., Edited by G. BERNDT AND COCHIUS, Berlin, 1921.
184. HENRY S. RAWDON: "Metallographic Features Revealed by the Deep Etching of Steel," Washington, D. C., 1920.
185. ULICK RICHARDSON EVANS: "Metals and Metallic Compounds," New York, 1923.
186. LEON GUILLET AND A. PORTEVIN: "Introduction to the Study of Metallography and Macrography," London and New York, 1922.
187. WILLIAM THOMAS HALL AND ROBERT S. WILLIAMS: "The Chemical and Metallographic Examination of Iron, Steel and Brass," 1st ed., New York, 1922.
188. HANS FREIHERR JÜPTNER VON JÖNSTORFF: "*Beziehungen Zwischen den Mechanischen Eigenschaften, der Chemischen Zusammensetzung, dem Gefüge und der Vorbehandlung von Eisen und Stahl,*" 2d ed., rev., Leipzig, 1919.
189. FRIEDRICH RUDOLF SCHENCK: "The Physical Chemistry of the Metals," 1st ed., New York, 1919.
- LÉON GUILLET: "*Les Méthodes d'Étude des Alliages Métalliques,*" Paris, 1923. Bibliography at the end of each chapter.





## INDEX

### A

Acid Bessemer process (*see* Bessemer process, acid).  
 electric process, 188, 190, 191  
 open-hearth process (*see* Open-hearth process, acid).  
 processes vs. basic, 53, 59, 90, 121, 152, 155, 188, 191  
 steel distinguished from basic, 66  
 After-blow, basic Bessemer process, 118  
 Air furnace, 371, 379  
 Air-furnace vs. cupola melting, 383  
 Air-hardening steel, 439  
 All-black malleable castings, 376  
 Allotropic modifications of iron, 333  
 theory of steel hardening, 407  
 Alloy steels, bibliography, 498  
 chrome, 437, 438  
 chrome-nickel, 446, 447  
 chrome-vanadium, 446, 447  
 definition, 425  
 effect of alloying elements, 425  
 extra strong, 449  
 highest qualities, 449  
 high-speed steel, 442  
 invar, 431  
 magnet steel, 444  
 manganese, 435, 439  
 manufacture, 427  
 molybdenum, 443  
 Mushet steel, 440  
 nickel, 427, 438  
 nickel-chrome, 446, 447  
 platinite, 431  
 quaternary, 426, 447  
 self-hardening, 439  
 silico-manganese, 438, 445  
 silicon, 444  
 spring steel, 443, 449  
 ternary, 426, 438, 445

Alloy steels, tool steels, 439  
 tungsten, 439, 442, 444  
 vanadium, 446, 447  
 Alloys, freezing, 309, 311  
 Alpha iron, 333, 349, 407  
 Aluminum, use as a deoxidizer, 208  
 use in lessening segregation, 217  
 Analyses, tables of, cast-iron car wheels, 362  
 cast iron for malleablizing, 377  
 for various uses, 373  
 ferro-alloys, 7, 37  
 pig iron, 7, 37  
 slag, Bessemer process, 106  
 blast furnace, 31  
 puddling process, 77  
 Annealing, 254, 335, 409, 410, 416, 443  
 practice, malleable cast iron, 385  
 Armor plate, 255, 256, 446  
 Armored glass, 432  
 Arsenic, effect in steel, 346  
 Atha, Hebert B., 269  
 Austenite, 321, 324, 410, 414, 437  
 photomicrograph, 411  
 Automobile steel, 227, 427, 439, 446

### B

Bars, 227, 233  
 Basic Bessemer process (*see* Bessemer process, basic).  
 open-hearth process (*see* Open-hearth process, basic).  
 processes vs. acid, 53, 59, 90, 121, 152, 155, 188, 191  
 steel distinguished from acid, 66  
 Beehive coking process, 477  
 Bell, Sir I. Lowthian, 56  
 Bell-Krupp process, 56, 118  
 Bench, wire-drawing, 254  
 Bertrand-Thiel process, 164, 166

- Bessemer converter, bottoms, 94  
  construction, 91  
  corrosion, 95  
  eccentric and concentric, 92, 94  
  lining, 92  
  operation, 96  
  repairs, 95  
  section, 50, 92, 93, 94  
Bessemer ore, 14  
Bessemer process, acid, analysis of  
  metal and slag during blow,  
    105, 109  
  calorific equation, 116  
  chemistry, 101  
  deoxidizing, 97, 114  
  loss, 113, 119  
  recarburizing, 97, 114  
  removal of impurities, 105, 106  
  thermochemistry, 116  
  vs. basic, 90, 121  
basic, after-blow, 118  
  analysis of metal during blow,  
    118  
  calorific equation, 120  
  chemistry, 117  
  deoxidizing, 119  
  loss, 119  
  operation, 117  
  recarburizing, 119  
  removal of impurities, 118  
  thermochemistry, 120  
  vs. acid, 90, 121  
Bessemer process, bibliography, 496  
  blow, 88, 105, 118  
  chemistry, 101, 115, 117  
  comparison with open hearth, 61  
  converter (*see* Bessemer con-  
    verter).  
  critical temperature, 104  
  description, 50  
  diagram, blow, 105, 109, 118  
  flame, 111  
  gases, 109  
  ladles, 98  
  mixer, 87  
  operation, 96  
  pig iron used, 87  
  pouring, 97, 100  
  slag, 104, 106, 110, 115  
Bessemer steel, acid, identification,  
  66  
  basic, identification, 66  
  comparison with open hearth, 61,  
    69, 304  
  field of use, 69  
  production, 91, 124  
Beta iron, 333, 407  
Bibliography, 493  
Bituminous coal, 475  
Black-heart castings, 375, 391  
Blast, cupola, 288, 303  
Blast furnace, accessories, 17  
  bell and hopper, 15  
  blast, 20, 24, 32  
  blowing engines, 19, 20, 25  
  bosh, 18  
  charcoal pig iron, 42  
  charge calculation, 43  
  charging, 15  
  chemistry, 24, 26  
  critical temperature, 32  
  dimensions, 41  
  discharge holes, 18  
  distribution of stock, 17  
  dry blast, 32  
  freezing, 40  
  gas, 22  
  handling material, 15  
  hanging of charge, 40  
  hot blast, 20  
  iron disposal, 34  
  irregular working, 38  
  labor, 47  
  loading, 15  
  machine casting, 36  
  manganese reduction, 30  
  operation, 22  
  phosphorus behavior, 30  
  power from gas, 22  
  practice, 22  
  products, 22  
  sand casting, 38  
  scaffolding, 40  
  section, 16, 23, 26  
  skip hoist, 15, 16  
  slag, 31, 33, 34  
  smelting zone, 26, 29  
  stoves, 20

- Blast furnace, sulphur behavior, 30  
   tapping, 33, 34  
   tuyeres, 17  
 Blister steel, 79, 80  
 Blooming rolls, 241, 246, 247, 250  
 Blooms, 241, 249, 250, 251  
 Blower, pressure, 287  
 Blowholes, cause, 206  
   ingots, 203, 206, 207  
   location, 207  
   prevention, 207  
   steel, 51, 60  
 Blowing engines, blast furnace, 19,  
   20, 25  
 Books on iron and steel, 493  
 Bottom casting, 211, 219  
 Brinell, J. A., 207  
 Brittleness, Stead's, 403  
   steel, 253, 338, 339, 346, 435  
 Bundled scrap, 78  
 Burners, oil, 488  
   pulverized coal, 490  
 Burning steel, 396, 401, 403  
 By-product coking process, 478
- C
- Calculation, blast-furnace charge, 43  
   chimney draught, 132  
 Calorific equation, acid Bessemer  
   process, 116  
   basic Bessemer process, 120  
 Calvert and Johnson, 75  
 Campbell, H. H., 27, 31, 111, 153,  
   341, 344, 346  
 Campbell, Wm., 399  
 Campbell open-hearth furnace, 138  
   processes, 164  
 Cannon, forging, 229  
 Carbide, iron (*see* Cementite).  
 Carbon, characteristics, 5  
   content in iron and steel for differ-  
   ent uses, 342  
   effect in iron and steel, 5, 340, 347,  
   405, 406  
   in cast iron, 352, 354, 355, 358, 369  
   penetration rate in cementation,  
   421  
 Carbon theory of hardening, 406  
 Carbon-iron alloys (*see* Iron-carbon  
   alloys).  
 Carbonizing steel, material, 422  
   process, 420  
 Carburizing, bibliography, 498  
   wrought iron, 78  
 Carpenter and Keeling, 5  
 Car wheels, cast iron, analyses, 362  
 Case-hardening, 420  
 Casting (*see also* Founding).  
   bottom, 211, 219  
   large end up, 211  
   temperature, iron, 372  
 Castings, all-black, 376  
   black-heart, 375, 391  
   blowholes, 206  
   burning, 403  
   chilled, 371  
   defects, types, 203  
   direct, 282  
   dry- vs. green-sand molds, 271  
   flakes, 212  
   ingotism, 214  
   malleable iron (*see* Malleable  
     cast iron).  
   piping, 204, 208  
   segregation, 215  
   sonins, 205  
   top and bottom pouring, 211, 219  
   white-heart, 375, 376, 392  
 Cast iron, analyses, 362, 373  
   carbon in, 352, 354, 355, 358,  
   369  
   characteristics, 1  
   checking, 368  
   chilled, 354, 371  
   constitution, 351  
   cooling rate, 354  
   corrosion, 454  
   definition, 5  
   density, 366  
   electric melting, 194  
   field of use, 68  
   freezing, 321  
   graphite in, 351, 355  
   gray, photomicrograph, 361  
   properties, 352  
   heat treatment, 354, 371, 385,  
   393



- Cast iron, impurities, 352, 359  
 malleable (*see* Malleable cast iron).  
 manganese, effect of, 363  
 melting, 282  
 phosphorus, effect of, 359, 363, 366  
 photomicrographs, 361  
 porosity, 357  
 production, 49  
 properties, 364  
 segregation, 367  
 shrinkage, 355, 358, 364  
 silicon, effect of, 360, 365  
 softness, 358, 368  
 strength, 358, 368  
 sulphur, effect of, 259, 260  
 uses, analyses, 373  
 varieties, 6  
 white, photomicrograph, 361  
   properties, 352  
   workability, 358, 368
- Cast steel (*see* Crucible steel and Founding, steel).
- Cement, manufacture from slag, 33
- Cementation, carbon, amount of, 423  
 furnace, 78, 79  
 heat treatment, 423  
 material used, 422  
 process, steel manufacture, 79  
 rate, 421  
 steel carbonized, 423  
 temperature, 421  
 theory, 420  
 time, 421
- Cementite, 325, 327, 328, 329, 335, 336, 352
- Chandler, Charles F., 113
- Chaplets, 274, 275
- Charcoal, 474  
 fineries, 57  
 iron, manufacture, 42  
   photomicrograph, 361
- Charging, blast furnace, 15  
 cupola, 294
- Checking, castings, 368
- Cheek, 265
- Chemistry, acid Bessemer process, 101  
 acid open-hearth process, 153  
   basic Bessemer process, 117  
   basic open-hearth process, 145  
   blast furnace, 24, 26  
   crucible process, 85  
   cupola, 291  
   deoxidizing steel, 115  
   puddling process, 74  
 Chilled cast iron, 354, 371  
 Chill molds, 273  
 Chimney draught, calculation, 132  
 Chrome-steel, 437, 438  
 Chrome-nickel steel, 446, 447  
 Chrome-vanadium steel, 446, 447  
 Classification, electric furnaces, 196  
   fuels, 474, 476  
   iron and steel, 2  
 Cleaning of blast-furnace gas, 22  
 Coal, 475  
   pulverized, 489, 490  
 Coatings, preservative, 456, 457  
 Cogging rolls, 241  
 Coke, 475  
 Coke-malleable pig iron, 377  
 Coke-oven gas, 480  
 Coking, beehive process, 477  
   retort process, 478  
 Colby, E. A., 177  
 Colby-Kjellin furnace, 178  
 Cold galvanizing, 461  
 Cold-pressing, 256  
 Cold-working vs. hot-working, 257  
 Colors, steel tempering, 419  
 Commercial iron and steel, varieties, 1, 5, 49  
 Conductivity, steel, 348  
 Constitution, cast iron, 351, 498  
   steel, 331, 498  
 Continuous heating furnaces, 259, 260  
 Contraction, malleable cast iron, 388  
 Converter, Bessemer (*see* Bessemer converter).  
   long-tuyere, 306  
   side blown, 305  
   Tropenas, 305

- Cooling curves, 316
  - iron, pure, 334
- Cope, 264, 265, 274
- Copper, effect in steel, 346
  - effect of working on properties, 330
- Cores, founding, 265, 272, 274, 280
- Corrosion, badly made material, 456
  - cast iron, 454
  - cause, 451
  - electrolysis, 452
  - hydrogen rôle, 452
  - manganese effect, 455
  - nickel steel, 432
  - pitting, 455, 456
  - protection, coatings, 451, 456, 457
    - enameling, 463
    - galvanizing, 461
    - nickel plating, 463
    - oxidized coating, 463
    - painting, 457, 459
    - pickling, 458
    - relative amounts, 454
    - scale removal, 457, 458
    - segregation effect, 453
    - self-protection, 453
    - stainless steel, 439
    - steel vs. iron, 454
    - theory, 452
    - tinning, 473
    - wrought iron, 454
- Cort, Henry, 53
- Costs, electric iron smelting, 171, 172
- Cracking, steel, 416
- Cracks in ingots, 212
- Critical changes, manganese steel, 437
  - nickel steel, 432
  - tungsten and molybdenum steel, 443
- Critical range, steel, 325, 334, 393, 395, 406, 428
- Critical temperature, Bessemer process, 104
  - blast furnace, 32
- Crucible process, chemistry, 85
  - comparison with others, 62
  - crucibles, 80
  - fuel, 86
  - Crucible process, furnaces, 80, 81
  - ingot molds, 85
  - killing, 83
  - losses, 86
  - melting, 83
  - metal used, 82
  - physic, 82
  - pouring, 84
  - pulling, 83
- Crucible steel, comparison with other steels, 62, 68
  - field of use, 68
  - grading, 85
  - identification, 65
  - manufacture (*see* Crucible process).
  - prices, 67
  - production, 49, 91, 124
- Crucibles for steel manufacture, 80
- Crystallization, 309, 395
  - nickel steel, 428
  - steel, 222, 395, 397, 404, 428
- Cupola, blast, 288, 303
  - blower, 287
  - burdening, 294
  - charge, 290, 294
  - \*chemical changes, 291
  - fluxing, 291
  - fuel, 290, 298
  - gases, 292
  - height of fuel bed, 303
  - \*losses, 288
  - \*melting action, 290, 303
  - practice, comparative, 298, 300
  - run, 289
  - scrap used, 289
  - section, 283 286
  - \*speed of melting, 303
  - stack, 287, 298
  - tuyere ratio, 298
  - tuyeres, 288
  - vs. air furnace, 383
  - zones, 282
- Cushman, Allerton S., 452

## D

- Daelen, R. M., 236
- Defects in ingots and castings, 203
- Definitions, ferrous metals, 5

De Geer, Gerard, 169, 170  
 Deoxidizers, 206  
 Deoxidizing, Bessemer process, 97,  
     114  
     electric steel, 183  
     steel, 206, 208  
 Dendrites in ingots, 215  
 Density, cast irons, 366  
 Dies, wire drawing, 254  
 Dimensions, blast furnace, 41  
 Direct castings, 282  
 Distinguishing kinds of iron and  
     steel, 64  
 Dolomite, 135  
 Domnarfvet Steel Works, electric  
     smelting, 169, 174  
 Double bell and hopper, 15  
 Drag, 264, 265  
 Draught, chimney, calculation, 132  
 Draw-bench, 254  
 Drawing, effect on steel, 253  
 Driers in paint oils, 459  
 Drop-forging, 226  
 Dry blast, 32  
     galvanizing, 462  
 Drying ovens, 267  
 Ductility, steel, 221, 331, 401  
 Duplex process, 160  
     steel, production, 91  
     Talbot process, 163

## E

Efficiency, thermal, electric fur-  
     naces, 199  
 Elasticity, nickel steel, 429  
 Electric cast-iron melting, 194  
     furnaces (*see* Furnaces, electric).  
     melting, foundry work, 194  
     pig iron, synthetic, 175  
     resistance wire, nickel steel, 435  
 Electric smelting, iron ore, carbon  
     used, 168  
     composition control, 174  
     costs, 171, 172  
     difficulties, 173  
     Domnarfvet Steel Works, 169, 174  
     economics, 171  
     electrode consumption, 171  
     Electric smelting, furnace, 170, 171,  
         172  
         power consumption, 169  
 Electric steel, acid process, 188,  
     190, 191  
     acid vs. basic, 188, 191  
     basic process, 186, 191  
     deoxidizing, 183  
     ferrosilicon addition, 185  
     field of use, 68  
     fluorspar use, 188  
     fluxing, 188  
     furnaces, 177, 195  
     identification, 66  
     pig-iron refining, 194  
     pouring, 184  
     practice, 167  
     process, operation, 55, 181  
     production, 49, 91, 124  
     recarburizing, 192  
     scrap melting, 185, 186, 191  
     slag, 183, 192  
     sonims, 184, 191  
     super-refining, 167, 176, 181, 193  
 Electrodes, carbon vs. graphite, 198  
     furnace, 197  
 Electrolytic action in corrosion, 452  
 Electrolytic iron, character, 3  
     direct from ore, 201  
     effect of hydrogen, 200  
     of working, 330  
     refining, 199  
 Electrometallurgy, iron and steel,  
     bibliography, 496  
     processes, 167, 168  
 Enameling, 463  
 Engines, rolling mill, 246  
 Etching, 468  
 Eustis, Frederick A., 201  
 Eutectics, 315, 318, 327  
 Eutectoid, iron-carbon, 326  
 Expansion, malleable cast iron, 388  
     nickel steel, 431

## F

Fatigue of steel, 428  
 Ferrite, 331, 336, 349, 413  
     photomicrographs, 413, 414

- Ferro-alloys, prices, 67  
Ferro-chrome, analysis, 7  
Ferromanganese, analysis, 7, 37  
    prices, 67  
    use, 150  
Ferro-phosphorus, analysis, 37  
Ferrosilicon, analysis, 7, 37  
    prices, 67  
    use, 185  
Ferrous metals, 1, 5, 49  
Fettling, open-hearth furnace, 135  
    puddling furnace, 71  
Fields of use of various classes of  
    iron and steel, 68  
Finery fire, 56  
Finishing temperature, steel work-  
    ing, 397, 398, 399  
Fir-tree crystals, 217  
Flakes in ingots, 212  
Flame, Bessemer process, 111  
    luminosity, 485  
Flask, 263, 267  
Fluted ingots, 213  
Forge iron, 7, 70  
Forging, bars, 227  
    cannon, 229  
    drop-forging, 226  
    effect, 224  
    hammer, steam, 225, 226  
    nature, of 224  
    razors, 229  
    temperature, 225, 228  
Founding, bibliography, 496  
    chaplets, 273, 274  
    checks, 280  
    cheek, 265  
    chill molds, 271  
    contraction, 280  
    cope, 264, 274  
    core machines, 280  
    cores, 265, 272, 274  
    cupola (*see* Cupola).  
    drag, 264, 265  
    dry-sand molds, 267, 271  
    electric melting, 194  
    flask, 263, 267  
    gating, 275  
    green-sand molds, 267, 271  
    ladles, 283  
    Founding, loam molding, 263  
    machine molding, 276, 277  
    melting (*see also* Cupola), 282  
    steel, 303  
    mold making, 263  
    multiple molds, 279, 280  
    pattern design, 280  
    molding, 263, 266  
    permanent molds, 274  
    ramming, 266  
    risers, 267, 275  
    shrinkage cavities, 281  
    skin-dried molds, 269  
    steel, acid vs. basic open hearth,  
        304  
        Bessemer vs. open hearth, 304  
        converter gases, 307  
        sizes, 307  
        long-tuyere converter, 306  
        melting, 303  
        open-hearth furnaces, 303  
        vs. Bessemer, 304  
        Tropenas converter, 305  
    stripping plate, 279  
    vibrator, 279  
    washes, 269  
Fractures, steel, 402  
Freezing, alloys, 309, 311  
    blast furnace, 40  
    cast iron, 321  
    iron and steel, 319  
    iron, effect of silicon, 323  
    effect of sulphur, 324  
    metastable, 322  
    steel, 320  
Freezing diagram, gold-silver alloys,  
    310  
    iron-carbon alloys, 320  
    lead-tin alloys, 311, 317, 318  
    nature of, 309  
Fritz, John, 233  
Fuel oil, 487  
Fuels, classification, 474, 476  
    metallurgical, 474  
Furnaces, annealing, hardening, and  
    tempering, 415  
    continuous, heating, 259, 260  
    electric, arc, direct, 197  
    arc, indirect, 196



Furnaces, electric, classification, 196  
 Colby-Kjellin, 178  
 connections, 197  
 efficiency, 199  
 electrodes, 197  
 Girod, 177, 179  
 hearth, conducting and non-conducting, 198  
 heating, low temperature, 201  
 Heroult, 55, 177, 178, 182, 184, 186  
 induction, 177  
 iron smelting, 170, 171, 172  
 Kjellin, 178, 180  
 pig iron, 170, 171, 172  
 power charges, 199  
 resistance heating, 195  
 Roechling-Rodenhauser, 180, 195  
 tilting, 199  
 types, 177, 195  
 heat treatment, 415  
 heating, for steel working, 258  
 open hearth (*see* Open-hearth furnace).  
 regenerative (*see* Regenerative furnace).

## G

Galvanizing, 461  
 Garnina iron, 333, 407  
 Gas, blast-furnace, 22  
 coke-oven, 480  
 Mond, 491  
 natural, 487  
 producer, 481  
 water, 489  
 Gas producers, 123, 484  
 Gases, Bessemer process, 109  
 converter, side-blown, 307  
 cupola, 292  
 in steel, 207  
 Gating of patterns, 275  
 Gayley, James, 32  
 Girod furnace, 177, 179  
 Gold-silver alloys, freezing curve, 310  
 Grain size, steel, 393, 397, 398, 404

Graphite, effect in cast iron, 351, 355, 364, 366, 369  
 electrodes, 198  
 in steel, 351  
 washes, 269  
 Gray cast iron, definition, 6  
 photomicrograph, 361  
 properties, 352  
 Gruner's classification of fuels, 476

## H

Hadfield, Robt. A., 435, 444  
 Hall, J. W., 53, 230  
 Hammer refining, 398  
 welding, 400  
 Hammer, steam, 225, 226  
 Hammering, effect, 224, 398  
 Hanging of blast-furnace charge, 40  
 Hardened steel, constituents, 410  
 Hardening steel, carbon effect, 405, 406  
 combined hardening and tempering, 418  
 cooling rate, 405  
 cracking, 416  
 method, 404  
 practice, 416  
 tempering, 408, 418  
 theory, 406  
 Hardenite, 412  
 Hardness, cast iron, 371  
 steel, 346, 430, 435, 442, 447  
 Heat balance (*see* Calorific equation).  
 Heat treatment, annealing, 254, 335, 409, 410, 416, 443  
 bibliography, 498  
 carbonizing, 423  
 cast iron, 354, 371, 385, 393  
 chrome steel, 437, 438  
 constituents of steel, 410, 414  
 crystallization, 395  
 double, quaternary steels, 447  
 ternary steels, 437, 444  
 furnaces, 415  
 grain size, 393, 398  
 hardening (*see* Hardening).  
 high-speed steel, 442

- Heat treatment, ingotism, 403  
 magnetism, 410  
 manganese steel, 436  
 molybdenum steel, 443  
 nickel steel, 428, 429, 430, 438  
 overheating, 393, 396  
 practice, 415  
 quaternary steels, 447  
 quenching, 405, 409  
   baths, 417  
 refining of grain, 395  
 self-hardening steel, 441  
 silicon steel, 445  
 temper colors, 419  
 temperature, 393, 395, 397, 416, 419  
 tempering, 408  
 ternary steels, 438, 445  
 tungsten steel, 443
- Heating furnaces, steel working, 258  
 practice, for working steel, 261
- Hematite, 8
- Hering, Carl, 195
- Heroult furnace, 55, 177, 178, 182, 184, 186
- Heyl and Patterson pig-casting machine, 38
- Hibbard, H. D., 443
- High-speed steel, 442
- Hoesch process, 165, 166
- Hot blast, 20
- Hot-pressing, 255
- Hot-working vs. cold-working, 257
- Howe, H. M., 210, 218, 326, 347, 395, 398
- Hughes gas producer, 484
- Hydraulic press, 256
- Hydrogen, in electrolytic iron, 200  
 in steel, 339  
 rôle in corrosion, 452
- I
- Igevsky, 469
- Induction furnaces, 177
- Ingot iron, 68  
 molds, 85, 99, 102
- Ingotism, 214, 403
- Ingots, blowholes, 203, 206, 207
- Ingots, casting, 211, 219  
 cracks, 212  
 defects, 203  
 dendrites, 215  
 flakes, 212  
 fluted, 213  
 ingotism, 214  
 liquid compression, 212  
 piping, 204, 208  
 saddening, 215  
 scabs, 214  
 segregation, 215  
 shape, 213, 215, 220  
 size, 219  
 sonims, 205  
 taper, 220  
 top and bottom pouring, 211, 219
- Invar, 431
- Iodine etching, 468
- Iron, allotropic modifications, 333  
 carbon, effect of, 5, 341, 347  
 cast (*see* Cast iron and Castings).  
 casting temperature, 372  
 classification of varieties, 2  
 commercial varieties, 1, 5, 49  
 cooling curve, 334  
 corrosion (*see* Corrosion).  
 electrolytic (*see* Electrolytic iron).  
 fields of use, 68  
 forge, 7, 70  
 founding (*see* Founding).  
 freezing, 319, 322  
   curve, 334  
   effect of silicon, 323  
   sulphur, 324  
 ingot, 68  
 knobbled, 57, 65  
 magnetism, 410  
 malleable, 6  
 manufacture, diagram, 48  
 metallography (*see* Metallography).  
 metastable freezing, 322  
 nickel effect, 432  
 Northampton, 356, 357  
 ores (*see* Iron ore).  
 pig (*see* Pig iron).  
 prices, 67  
 production, 4, 49

- Iron, puddled (*see* Wrought iron).  
 pure, 3, 200  
 smelting (*see* Blast furnace).  
 solution theory, 308, 497  
 Swedish, 9  
 welding, 400  
 wrought (*see* Wrought iron).
- Iron carbide (*see* Cementite).
- Iron-carbon alloys, decomposition  
 curves, 325  
 eutectoid, 326  
 freezing, 320  
 heating changes, 328  
 pearlite, 327, 328  
 photomicrographs, 327  
 Roberts-Austen, Roozeboom dia-  
 gram, 328
- Iron-carbon diagram, 320, 325, 328,  
 329
- Iron-carbon solid solution, 324
- Iron ore, Bessemer and non-  
 Bessemer, 14  
 boats, Lake transport, 13  
 deposits, U. S., 9, 10  
 electric smelting (*see* Electric  
 smelting).  
 handling at furnace, 15  
 hematite, 8  
 Lake Superior, 12  
 magnetite, 8  
 map, U. S. deposits, 11  
 mining, 12  
 phosphorus content, 14  
 prices, 14, 67  
 reserves, 9, 10  
 siderite, 10  
 spathic, 10  
 Sweden, 9  
 transportation, 11  
 U. S. deposits, 9, 10  
 unloading, 13  
 varieties, 8
- Iron oxides in steel, 338, 346  
 phosphide in iron, 336, 338  
 rust, 451, 453  
 silicides in iron, 451, 453  
 sulphide in iron, 337
- Irreversible transformations in  
 nickel steel, 433
- J
- Johnson, J. E., Jr., 32  
 Johnson and Calvert, 75
- K
- Keeling and Carpenter, 5  
 Keep, W. J., 365  
 Killing steel, 83, 183  
 Kjellin, F. A., 179  
 Kjellin furnace, 178, 180  
 Knobbed iron, 57, 65  
 Krupp purification process, 56, 118
- L
- Labor, blast furnace, 47  
 open-hearth furnace, 150  
 Ladles, teeming, 98  
 Lake Superior ore deposits, 12  
 Lancashire process, 59  
 Lap-welded tubing, manufacture,  
 252  
 Lead coatings, 463  
 pigments, 460  
 Lead-tin alloys, freezing, 311, 317,  
 318  
 strength curve, 318  
 Lignite, 475  
 Lime, 46, 118, 144, 147  
 Limestone, 27, 28, 43, 144  
 Lining, air furnace, 380  
 Bessemer converter, 92  
 open-hearth furnace, 134  
 puddling furnace, 71  
 Linseed oil, 459  
 Literature on iron and steel, 493  
 Loading, blast furnace, 15  
 ore boats, 13  
 Loam molding, 263  
 Long-tuyere converter, 306  
 Losses, in Bessemer process, 113, 119  
 in crucible process, 86  
 in cupola, 288  
 in open-hearth process, 148, 158  
 in puddling process, 77  
 Low-carbon steel, melting for, 153  
 Luminosity of flame, 485

## M

- Magnesia, 43  
Magnesite, 135  
Magnetic permeability, silicon steel, 444  
    properties, steel, 349  
Magnetism, heat treatment, 410  
Magnetite, 8  
Magnet steel, 444  
Magnets, 349  
Magroscopic metallography, 472  
Malleable cast iron, adjustment of conditions, 390  
    air furnace, 379  
    all-black, 376  
    analysis, 377  
    annealing practice, 385  
    bibliography, 498  
    black-heart, 375, 391  
    carbon content, 378  
    contraction, 388  
    definition, 6  
    electric melting for, 194  
    expansion, 388  
    field of use, 68  
    impurities, 378  
    iron used, 376  
    manufacture, process, 375, 391, 392  
    molding and pouring, 385  
    open-hearth furnace melting, 384  
    packing, 387  
    photomicrograph, 375  
    production, 49  
    properties, 374  
    Réaumur, 375, 376, 392  
    shrinkage, 388  
    silicon effect, 377  
    test lug, 374  
    theory of process, 391  
    tumbling barrel, 385  
    uses, 374, 389  
    white-heart, 375, 376, 392  
Malleable iron, definition, 6  
Manganese, effect in cast iron, 363  
    effect in corrosion, 455  
    in malleable cast iron, 378  
Manganese, effect in steel, 343, 344, 345, 435, 439, 455  
    in Bessemer process, 87, 104, 105, 114, 115, 117  
    in blast furnace, 30  
    in open-hearth process, 143, 146, 149, 153, 157  
    residual, 345  
Manganese steel, 435, 439  
    sulphide in iron, 336, 337  
Manganiferous cementite, 335, 336  
Manipulators, 240, 244  
Map, iron ore deposits, 11  
Martensite, 412, 414  
    photomicrographs, 411, 414  
Mathews, John A., 448  
Mellhiney, Parker C., 269  
Mechanical treatment of steel (*see* Working).  
Melting, air furnace, 379, 383  
    cast iron, 282  
    cupola vs. air furnace, 383  
    electric furnace, 194  
    finery, 57, 58  
    open-hearth furnace, 384  
Merchant bar, 55  
Mesabi iron ore, 13  
Metallography, bibliography, 499  
    etching, 468  
    heat tinting, 469  
    magroscopic, 472  
    microscope and accessories, 469  
    polish attack, 469  
    polishing, 465  
        in bas-relief, 467  
    preparation of samples, 464  
    rouge for polishing, 466  
    scope and limitation, 464  
    structure development for examination, 467  
    sulphur prints, 472  
Metastable freezing, cast iron, 322  
Metcalf, Wm., 402  
Metcalf test, 492  
Microconstituents of steel, 331  
Microphotographic apparatus, 469, 470  
Microscopic examination (*see* Metallography).



Microstructure, nickel steel, 434  
 Mills, rolling, 232  
   parts, 238, 241, 243  
 Mining, iron ore, 12  
 Mixers, 87  
 Moldenke, Richard, 372  
 Molding, chaplets, 274, 275  
   chill molds, 271  
   dry sand, 267  
   dry- vs. green-sand molds, 271  
   gating, 275  
   green sand, 267, 269  
   loam, 263  
   machines, 276, 277  
   multiple, 279, 280  
   pattern, 263, 266  
   permanent molds, 274  
   ramming, 266  
   risers, 267, 275  
   skin-dried, 269  
   stripping plate, 279  
   tools, 268  
   vibrator, 279  
   washes, 269  
 Molds, ingot (*see* Ingot molds).  
 Molybdenum steel, 443  
 Mond gas, 491  
 Monell process, 163  
 Moore, E. T., 187  
 Morgan gas producer, 483  
 Mottled pig iron and cast iron,  
   definition, 6  
 Muck bar, 54, 55  
 Mushet, Robt., 439  
 Mushet steel, 440

## N

Natural gas, 487  
 Neumann's lines, 223  
 Nickel, effect in iron, 432  
   form of occurrence in steel, 434  
 Nickel-chrome steel, 446, 447  
 Nickel plating, 463  
   steel, 427, 438  
 Nitric-acid etching, 468  
 Nitrogen, in blast furnace, 24  
   in steel, 339  
 Non-Bessemer ore, 14

Northampton iron, 357  
 Norway iron, 332  
 Nozzles, steel ladles, 98, 99

## O

Oil burner, 488  
   fuel, 487  
   linseed, 459  
 Oolitic hematite, 8  
 Open-hearth furnace, bottom, 134  
   Campbell type, 138  
   diagram, 52  
   draught and chimney, 132  
   hearth, 134  
   iron melting, 384  
   labor, 150  
   life, 133  
   ports, 131  
   regenerators, 126  
   repairs, 135, 152  
   roof, 133  
   section, 127  
   size, 140  
   steel founding, 303  
   tap-hole, 136  
   temperature, 139  
   tilting, 138  
     vs. stationary, 137  
   valves, 130  
   Wellman type, 138  
 Open-hearth process, acid, charge,  
   158  
   charging, 152  
   chemistry, 153  
   comparison with basic, 59, 69  
   description, 51  
   diagram, 154  
   fuel, 159  
   high-carbon steel, 155  
   loss, 158  
   mild steel, 153  
   operations, 155  
   removal of impurities, 154  
   slag, 158  
   special features, 155  
 all-scrap process, 142

- Open-hearth process, basic, charge,  
143, 148  
charging, 142  
chemistry, 145  
comparison with acid, 59  
with Bessemer, 61  
description, 53  
diagram, 146  
flame control, 151  
fluxes, 144  
loss, 148  
oreing down, 145  
pigging up, 142, 145, 152  
pig iron used, 144  
purification, 146, 151  
recarburizing, 149  
removal of impurities, 146, 151  
rephosphorization, 149  
slag, 146, 147  
functions, 145  
sulphur removal, 147  
types, 141  
Bertrand-Thiel process, 164, 166  
bibliography, 496  
Campbell processes, 164  
casting pit, 126  
charging, 125, 142, 144, 152  
duplex process, 160  
Talbot process, 163  
fuels, 125, 139  
furnace (*see* Open-hearth furnace).  
gas producers, 123  
Hoesch process, 165, 166  
labor, 150  
melting platform, 123, 125  
molten charge, 141  
Monell process, 163  
operations, 122  
pig-and-ore process, 141  
pig-and-scrap process, 142  
plant, 122, 123  
special processes, 159  
Talbot processes, 162  
triplex process, 161  
two-furnace processes, 164  
types, 141  
Open-hearth steel, acid and basic,  
comparison, 49, 59, 66, 69, 91,  
124, 304  
Open-hearth steel, comparison with  
Bessemer steel, 61, 69, 304  
effect of different elements on  
properties, 341  
field of use, acid and basic, 69  
identification, acid and basic, 66  
production, 49, 91, 124  
residual manganese, 345  
Open pass in rolling, 238, 239  
Ore, iron (*see* Iron ore).  
boats, 13  
Osmond, F., 333, 349, 468, 469  
Osmondite, 414  
Otto-Hoffmann coke oven, 479, 482  
Overheating steel, 393, 396  
Oxidation, carbon and phosphorus,  
56  
in Bell-Krupp process, 56, 118  
in cupola, 288  
in finery fire, 57  
in making steel, 49, 101, 118, 141,  
145, 151  
wrought iron, 53, 71  
of phosphorus, 53, 56, 118, 145  
Oxide in steel, 207, 338, 346
- P
- Painting to prevent corrosion, 457,  
459  
Pass-over rolling mill, 232  
Pattern molding, 263, 266  
Patterns, design, 280  
gating, 275  
Pearlite, 325, 326, 328, 413, 414  
photomicrographs, 327, 336  
Peat, 475  
Penetration of carbon into steel,  
rate, 421  
Perin, Charles P., 201  
Permanent molds, 274  
Petroleum, 487  
Phosphide in iron, 336, 338  
Phosphorus, behavior in blast fur-  
nace, 30  
content in iron ores, 14, 91  
effect in iron, 359, 363, 366  
in malleable cast iron, 378  
in steel, 338, 344

- Phosphorus, in open-hearth process,  
146, 149, 152  
oxidation and removal, 53, 56,  
118, 145
- Photomicrographic apparatus, 469,  
470
- Photomicrographs, austenite, 411  
cementite, 336  
charcoal iron, 361  
crystals, steel, 222  
effect of forging temperature,  
228  
eutectics, 327  
ferrite, 336, 413, 414  
iron phosphide, 336  
malleable cast iron, 375  
manganese sulphide, 336  
martensite, 411, 414  
Neumann's lines, 223  
pearlite, 327, 336  
pig iron, 361  
slip bands, 223  
sonims, 84  
sorbite, 413  
steel, 222, 327, 336, 394, 411, 413,  
414  
troostite, 411, 414  
wrought iron, 76
- Pickling, 458
- Picric-acid etching, 469
- Pig iron, analysis, 7, 37  
Bessemer, 87  
bibliography, 495  
carbon, effect of, 352, 354, 355,  
358, 369  
eharcoal, 42  
coke-malleable, 377  
definition, 5  
electric melting and refining, 194  
grades, 7, 37  
impurities, 359  
manganese, effect of, 363  
manufacture, 7, 495  
mechanical molding, 36  
open-hearth, basic, 144  
phosphorus, effect of, 359, 363,  
366  
photomicrograph, 361  
prices, 67
- Pig iron, production, world's, 4  
purification, 48, 495  
sileon, effect of, 360, 365  
sulphur, effect of, 359, 360  
synthetic, 175  
utilization, 49  
varieties, 6, 7, 36, 37
- Pig-and-ore process, 141
- Pig-and-scrap process, 142
- Pig-casting machine, 36
- Pigging up, open-hearth process,  
142, 145, 152
- Pigments for painting iron and steel,  
460
- Pinions, rolling mill, 242, 243
- Pipe, rolling, 250, 251, 252
- Piping, ingots and castings, 204, 208
- Pitting, corrosion, 455, 456
- Plates, rolling, 248
- Platinite, 431
- Polishing for microscopic examina-  
tion, 465
- Porosity, cast iron, 357
- Ports, open-hearth furnace, 131
- Pouring, top and bottom, 211, 219
- Power, from blast-furnace gas, 22
- Preservative coatings, 456, 457
- Pressing, steel, 255
- Prices, iron and steel, 67  
iron ore, 14
- Priming coat, 457
- Producer gas, 123, 481
- Production, iron and steel, 4, 49,  
91, 124  
pig iron, 4  
steel, 91, 124
- Properties, cast iron, 364  
malleable cast iron, 374  
nickel steel, 427, 429, 430, 438  
quaternary steels, 447  
spring steels, 450  
steel, 339  
ternary steels, 438  
welded bars, 401
- Puddled iron (*see* Wrought iron).
- Puddling furnace, 54, 70, 78  
process, chemistry, 74  
description, 53, 71  
fuel, 74

Puddling process, losses, 77  
 mechanical furnace, 78  
 removal of elements, 75  
 slag, 77  
 squeezers, 74  
 Pull-over rolling mill, 232  
 Pulverized coal, 490, 491  
 Purification, iron, 48  
 processes, comparison, 59

## Q

Quaternary steels, 447  
 Quenching, 405, 409, 417  
 Quenching baths, 417

## R

Rails, etching, tests, 471  
 prices, 67  
 rolling, 248, 249  
 Réaumur, 375  
 Réaumur cast iron, 376, 392  
 Recalescence, 416  
 Recarburizing, acid Bessemer process, 97, 114  
 basic Bessemer, 119  
 electric steel, 192  
 open-hearth process, basic, 149  
 Recuperative heating furnace, 260  
 Red-shortness, 344  
 References on iron and steel, 493  
 Refining of grain in steel, 395  
 Refining steel, 160, 161, 167, 176, 181, 193  
 Regenerative furnace, 87, 126, 258, 261  
 diagram, 52  
 Regenerators, open-hearth furnace, 126  
 Repairs, Bessemer converter, 95  
 open-hearth furnace, 135, 152  
 Rephosphorization of steel, 149  
 Reserves, iron ore, 9, 10  
 Residual manganese, 345  
 Resistance wire, nickel steel, 435  
 Restoring of grain in steel, 395  
 Retort coking process, 478  
 Reversing mills, 235

Richards, J. W., 117, 133  
 Risers on castings, 267, 275  
 Roberts-Austen, Sir William, 5, 329  
 Roberts-Austen, Roozeboom diagram, 328  
 Roebling-Rodenhauser furnace, 180, 195  
 Rolling, action, crystalline, 398  
 effect on grain size, 397, 399  
 engines, 246  
 electric drive, 246  
 finishing temperature, 397, 398, 399  
 guards, 244  
 heating, 258  
 manipulators, 244  
 mills, 232  
 mills, parts, 238, 241, 243  
 multiple-ply plate, 233  
 pinions, 242  
 pipe, 250, 251, 252  
 plates, 248  
 practice, 247  
 pull-over mill, 232  
 rails, 248, 249  
 reduction of size, 230  
 reversing mills, 235  
 rolls (*see* Rolls).  
 shape of ends, 231  
 size of mills, 247  
 speed, 231, 241  
 temperatures, 262, 397, 399  
 three-high mills, 233, 235  
 transfer tables, 244, 245  
 troubles, 247  
 tubing, 250, 251, 252  
 Universal mill, 236  
 Rolls, cast iron vs. steel, 239  
 cogging, 241  
 diameters, 240  
 making, 241  
 pass shape, 238, 239  
 speed, 240  
 types, 238, 239  
 vertical, 236  
 Roozeboom, 5  
 Roozeboom diagram, 328  
 Rouge for polishing, 466  
 Rust, iron, 451, 453



## S

- Saddening, 215  
 Sand-casting, blast furnace, 38  
 Sauveur, Albert, 395  
 Scabs on castings, 266  
 Scaffolding, blast furnace, 40  
 Scale removal, 457, 458  
 Scrap, use in making cast iron, 49, 289  
     use in making malleable cast iron, 376  
     use in making steel, 49, 52, 82, 98, 141, 152, 155, 175, 185, 191  
 Seamless tubes, manufacture, 252  
 Seede, J. A., 187  
 Segregation, 215, 367  
     effect in corrosion, 453  
 Self-hardening steels, 439  
 Semet-Solvay coke oven, 480  
 Semi-steel castings, 389  
 Shaping of metals, 221  
 Shear-steel, 80  
 Shingling, 74  
 Shrinkage, cast iron, 335, 358, 364  
     curves, 356  
     malleable cast iron, 388  
 Side-blown converter, 305  
 Siderite, 10  
 Siemens-Martin process (*see* Open-hearth process).  
 Silica wash, 269  
 Silicides in iron, 338  
 Silicon, effect in iron, 323, 360, 365  
     effect in malleable cast iron, 377  
     steel, 344, 348, 444  
     in blast furnace, 29, 30, 41  
 Silicon steel, 444  
 Silico-manganese steel, 438, 445  
 Silico-spiegel, analysis, 7, 37  
 Silver-gold alloys, freezing curves, 310  
 Skin-dried molds, 269  
 Slag, Bessemer process, 104, 106, 110, 115  
     blast furnace, 31, 33, 34  
     content in wrought iron, 3, 76  
     electric steel, 183, 192  
     Slag, open-hearth process, 145, 146, 147, 159  
     puddling process, 77  
 Slip bands, 223  
 Smelting, electric (*see* Electric smelting).  
     iron (*see* Blast furnace).  
 Soaking pits, 103, 259, 261  
 Solid solutions, freezing, 309  
     iron and carbon, 324  
     nature of, 308  
 Solution theory of iron and steel, 308, 497  
 Sonims, 65, 84, 184, 191, 205  
 Sorbite, 413, 414  
 Spathic iron ore, 10  
 Specifications, steel, 340  
 Spiegeleisen, analysis, 7, 37  
     use, 97  
 Spring steel, 445, 449  
 Squeezers, 74  
 Stainless steel, 439  
 Stansfield, Alfred, 401  
 Stead, J. E., 217, 333, 338, 404  
 Stead's brittleness, 403  
 Steam hammer, 225, 226  
 Steel, air-hardening, 439  
     alloy (*see* Alloy steels).  
     annealing, 254, 335, 409, 410, 416, 443  
     Bessemer (*see* Bessemer steel).  
     bibliography, 493, 495  
     blister, 79, 80  
     blowholes in, 51, 60  
     brittleness, 253, 338, 339, 346, 435  
     burning, 396, 401, 403  
     carbon content for different uses, 342  
     case-hardening, 420  
     castings (*see* Castings).  
     cementation, 79, 420  
     characteristics, 1  
     classification, 2  
     colors, temper, 419  
     conductivity, 348  
     constituents, 331, 410, 414  
     constitution, 331, 498  
     corrosion (*see* Corrosion).  
     cracking, 416

- Steel, crucible (*see* Crucible steel).  
 crystallization, 222, 395, 397, 404, 428  
 definition, 6  
 distinguishing between kinds, 64  
 drawing, effect, 253  
 drop-forging, 226  
 duplex (*see* Duplex steel).  
 effect of various elements, 335, 340  
   (*see also* Alloy steels).  
 electric (*see* Electric steel).  
 fields of use, 68  
 forging (*see* Forging).  
 fractures, 402  
 freezing, 320  
 grain size, 393, 397, 398, 404  
 hammering, effect, 224  
 hardening (*see* Hardening and Hardness).  
 heat treatment (*see* Heat treatment).  
 high-speed, 442  
 identification, 65  
 killing, 83, 183  
 low-carbon, comparison with wrought iron, 63  
   melting, acid process, 153  
 magnet, 349, 444  
 magnetic properties, 349, 410  
 manufacture, diagram, 48  
 mechanical treatment, 221  
 Metcalf test, 402  
 microconstituents, 331  
 Mushet steel, 440  
 open-hearth (*see* Open-hearth steel).  
 overheating, 393, 396  
 photomicrographs, 222, 327, 336, 394, 411, 413, 414  
 pipe, 250, 251, 252  
 plates, 248  
 pressing, 255  
 prices, 67  
 production, 49, 91, 124  
 properties, 339  
 quaternary, 447  
 quenching, 405, 409, 417  
 rails (*see* Rails).  
 recalescence, 416  
 Steel, red-shortness, 344  
   restoring and refining of grain, 395  
   rolling (*see* Rolling).  
   seamless tubes, 252  
   self-hardening, 439  
   shear, 80  
   solution theory, 308, 497  
   sonins, 65, 84, 184, 191, 205  
   specifications, 340  
   spring, 443, 449  
   stainless, 439  
   strength, 339  
   super-refining, 167, 176, 181, 193  
   tempering, 408, 418  
   ternary, 426, 438, 445  
   tool, 439  
   transformations, irreversible, 433  
   tubing, 250, 251, 252  
   uses, carbon contents, 342  
   varieties, 64, 91, 124  
   welding, 400  
   wire-drawing, 253  
   working (*see* Working).  
 Stoughton converter, 306  
 Stoves, blast-furnace, 20  
 Strain, effect in steel, 223  
 Stripping ingots, 100, 102  
 Sulphides in iron, 336, 337  
 Sulphur, effect in iron, 324, 359, 360  
   effect in malleable cast iron, 378  
   in steel, 344  
   elimination in mixer, 90  
   in blast furnace, 30  
   in open-hearth process, 147  
 Sulphur prints, 472  
 Super-refining, steel, 167, 176, 181, 193  
 Swedish iron and steel, 9, 349  
 Swedish Lancashire process, 59  
 Synthetic pig iron, 175
- T
- Talbot, Benjamin, 140, 217  
 Talbot process, 162  
 Tar, 489  
 Taylor, Frederick W., 441  
 Teeming, 97, 100

Temper carbon, 375  
 colors, 419  
 Tempering, 408, 418  
 Ternary steels, 426, 438, 445  
 Terme plate, 463  
 Thermochemistry, Bessemer process, 116, 120  
 Three-high rolling mills, 233, 235  
 Tilting furnaces, 137, 138, 199  
 Tin-lead alloys (*see* Lead-tin alloys).  
 Tinning and tinplate, 463  
 Titanium as a deoxidizer, 207  
 Tool steels, 439  
 Top and bottom pouring, 211, 219  
 Transformations in nickel steel, 433  
 Transportation, iron ore, 11  
 Triplex process, 161  
 Troostite, 412, 414  
   photomicrographs, 411, 414  
 Tropenas converter, 305  
 Tubes, manufacture, 250, 251, 252, 255  
 Tumbling barrel, 385  
 Tungsten, effect in steel, 442  
 Tungsten steel, 439, 442, 444  
 Turner, Thomas, 356, 365  
 Tuyeres, Bessemer converter, 94  
   blast furnace, 17  
   cupola, 288, 298

## U

Uehling pig-casting machine, 37  
 United States iron ore deposits, 9, 10  
 Universal mill, 236  
 Unloading iron ore, 13  
 Use, fields of, various classes of iron and steel, 68

## V

Valves, gas producer, 485, 486  
   open-hearth furnace, 130  
 Vanadium as a deoxidizer, 206  
 Vanadium steel, 446, 447  
 Varieties of iron and steel of commerce, 1, 5, 49  
 Vertical rolls, 236

## W

Walloon process, 59  
 Washes, foundry, 269  
 Water gas, 489  
 Waterhouse, G. B., 433, 434  
 Webster, W. R., 341, 343  
 Welding, bibliography, 498  
   hammer, 400  
 Wellman open-hearth furnace, 138  
 White, Maunsel, 441  
 White cast iron, definition, 6  
   photomicrograph, 361  
   properties, 352  
 White-heart castings, 375, 376, 392  
 Wire drawing, 253  
 Wood, 474  
 Work, effect on copper, 330  
   effect on electrolytic iron, 330  
   on steel, 221, 223  
 Working steel, blue heat, 257  
   comparison of methods, 257  
   crystallization, 222  
   drawing, 253  
   drop forging, 226  
   effect, 221, 223  
   finishing temperature, 397, 398, 399  
   forging, 224  
   hammering, 224, 257  
   heating furnaces, 258  
   hot vs. cold, 257  
   manganese steel, 436  
   pressing, 255, 257  
   rolling, 230, 257  
 World's iron ore reserves, 10  
 World's production, pig iron, 4  
   steel, 124  
 Wrought iron, carburization, 78  
   characteristics, 3  
   comparison with low-carbon steel, 63  
   corrosion, 454  
   definition, 6  
   field of use, 68  
   furnace (*see* Puddling furnace).  
   identification, 65  
   manufacture (*see* Puddling process).

- Wrought iron, photomicrograph, 76  
pig iron used, 70  
prices, 67  
production, 49  
puddling, 71
- Wrought iron, slag content, 3, 76  
squeezing, 74
- Z
- Zinc (*see* Galvanizing).  
Zones, in blast furnace, 28, 29  
in cupola, 282, 284



Don't see

furnace

saddling pro-











PLEASE DO NOT REMOVE  
CARDS OR SLIPS FROM THIS POCKET

---

UNIVERSITY OF TORONTO LIBRARY

---

TN  
705  
S88  
1923

Stoughton, Bradley  
The metallurgy of iron and  
steel 3d ed.

Mining

~~ENGINE STORAGE~~

